



Barcode label with the letter 'Z'.

Maybe weak because of the holes in the cross member.

<--- Place jack in this spot.