

Software update information

File name: UPD01006.bin

Content

The content of the software update depends on the status of the software installed in your vehicle. See the description below for details of the content of the update and the devices supported.

From those listed below, the version that is appropriate for your vehicle is installed:

- ▷ MX-3.5.4, TX-3.5.6
- ▷ TX-2.6.6
- ▷ MX-1.12.0

Conditions

The software update is available only for certain vehicles equipped with a USB audio interface. In these vehicles, the main menu "Settings" includes the menu item "Software update".

Further information is provided in the Owner's Handbook for Vehicle under Software Update.

Go to www.bmw.com/update or the compatibility matrix at www.bmw.com/bluetooth to find out whether your vehicle is supported.

Installation

Installation of the software update requires agreement with the terms and conditions of use. For further information, see www.bmw.com/update. For the purposes of installation, save the software update file in the main directory of a USB device. Observe the additional instructions in the Owner's Handbook under Software Update. Following installation of the software update, the new software

status is shown in the vehicle under "Show current version".

Notes

Once the software has been updated, the software in the vehicle is restarted and data transferred from the USB device resynchronised where necessary. Wait a few minutes until the USB device is operational again.

Tracks or playlists played before the software update must be selected again. This is also necessary is the previous version of the software is restored using "Restore previous version".

Before you start a Teleservice update, make sure that mobile wireless reception quality is good by checking the status indicator on the control display.

Software update (MX-3.5.4, TX-3.5.6)

Content

- ▷ Office: Improved support for email messages. Improved display of text-message sender on iPhone devices with iOS6.
- ▷ Telephone: Improved USB connection for iPhone devices with iOS 5. Improved connectivity of certain devices. For certain devices, better display and stability during calls. Improved Bluetooth connection with HTC devices. Improved sorting of the phone book in Android devices in Japan.
- ▷ Multimedia: Improved display of additional album and track information. Improved con-

nection and control in Bluetooth audio devices.

- ▷ Improved functionality of TeleService, BMW Online and Internet for iPhone devices with iOS 5.

Supported devices

The software update improves the compatibility of the following devices:

Multimedia

- ▷ All USB devices
- ▷ Apple: iPod touch, iPhone
- ▷ Archos: 3 Vision
- ▷ Creative: MuVo V100
- ▷ Iriver: E100
- ▷ Palm: Pre
- ▷ Sony Ericsson: C905
- ▷ Symbian Foundation: S60
- ▷ Yari: U200

Phone

- ▷ Apple: iPhone 3GS, 4, 4S, 5 (iOS 5, iOS 6)
- ▷ Blackberry (OS 6.x), Pearl, 9800, 9900
- ▷ DoCoMo: Galaxy S SC-02B, NEC MEDIAS N-04C, Samsung Galaxy S II SC-02C, Sharp Aquos phone SH-12C, Xperia Acro SO-02C, Xperia Arc SO-01C
- ▷ HTC: Sensation, Trinity
- ▷ LG: Enlighten VS700
- ▷ Motorola: DROID RAZR 4G
- ▷ Nokia: C7, N8, X7
- ▷ Samsung: Galaxy S II (Android 2.3.3), Nexus S
- ▷ Sharp: au IS03
- ▷ Sony Ericsson: W205
- ▷ Verizon Wireless: Casio C781, ZTE F450, Pantech 8992

Notes

Following installation of the software update, the following software status is shown in the vehicle under "Show current version":

- ▷ MX-3.5.4
- ▷ TX-3.5.6

Software update (TX-2.6.6)

Content

- ▷ Office: Improved support for email messages. Improved display of text-message sender on iPhone devices with iOS 6.
- ▷ Telephone: Improved USB connection for iPhone devices with iOS 5. Improved connectivity of certain devices. For certain devices, better display and stability during calls. Improved Bluetooth connection with HTC devices. Improved sorting of the phone book in Android devices in Japan.
- ▷ Improved functionality of TeleService, BMW Online and Internet for iPhone devices with iOS 5.

Supported devices

The software update improves the compatibility of the following devices:

Phone

- ▷ Apple: iPhone 3GS, 4, 4S, 5 (iOS 5, iOS 6)
- ▷ Blackberry (OS 6.x), Pearl, 9800, 9900
- ▷ DoCoMo: Galaxy S SC-02B, NEC MEDIAS N-04C, Samsung Galaxy S II SC-02C, Sharp Aquos phone SH-12C, Xperia Acro SO-02C, Xperia Arc SO-01C
- ▷ HTC: Sensation, Trinity
- ▷ LG: Enlighten VS700
- ▷ Motorola: DROID RAZR 4G
- ▷ Nokia: C7, N8, X7
- ▷ Samsung: Galaxy S II (Android 2.3.3), Nexus S
- ▷ Sharp: au IS03

- ▷ Sony Ericsson: W205
- ▷ Verizon Wireless: Casio C781, ZTE F450, Pantech 8992

Notes

Following installation of the software update, the following software status is shown in the vehicle under "Show current version":

- ▷ TX-2.6.6

Software update (MX-1.12.0)

Content

- ▷ Improves the speed and stability of music playback from a USB device that is connected to the USB audio interface in the centre armrest and contains multiple playlists.

Supported devices

The software update improves the compatibility of the following devices:

Multimedia

- ▷ All USB devices

Notes

Following installation of the software update, the following software status is shown in the vehicle under "Show current version":

- ▷ MX-1.12.0