COMPILED AND EDITED BY COBRADAY - COURTESY OF KoTR @ bimmerdrivers.com

	COMPILED AND EDI	TED BY COBR	RADAV - COURT	FESY OF KoTR @ bimmerdrivers.com
Category	SIBs (SI B## ## ##)	<u>Date</u>	<u>Application</u>	<u>Title</u>
Maintenance and General Hints	00 04 02	March-08	All	BMW Group Technical Hotlline (rpl 1/08)
Maintenance and General Hints	00 06 03	November-03	All	General info on TIS Website
Maintenance and General Hints	00 01 05	June-06	All	New Vehicle Preparation and Maintenance Requirements (Supercedes Jan 06)
Maintenance and General Hints	B000105ATT_VehChk	P/O 00 01 05	525/530	Quality Certification Form
Maintenance and General Hints	00 02 06	March-07	All	New Vehicle Preparation and Maintenance Requirements (MY07) (Rpl 11/06)
Maintenance and General Hints	00 01 07	May-08	ALL	New Vehicle Preparation and Maintenance Requirements (rpl 3/8 adds M3 DCT and 1 series)
Maintenance and General Hints	00 03 07	August-07	ALL	PuMA Enhancements for TeileClearing Process
Maintenance and General Hints	00 04 07	March-08	X3, X5	New Vehicle Preparation and Maintenance Requirements (rpl 12/07 adds X6)
Maintenance and General Hints	00 08 07	October-07	All	Construction Group Changes
Maintenance and General Hints	00 01 08	March-08	BMW Centers	BMW Center Technical Support Overview
Maintenance and General Hints	00 02 08	March-08	E82/E88	E82, E88 (1 Series) Quality Control Information
Maintenance and General Hints	00 03 08	April-08	E71 (X6)	E71 (X6) Quality Control Information
		·		
	09 na			
Morronty	01 02 03	Contombor 02	BMW Centers	BMW Maintenance Program 4 Years - 50,000 Miles
Warranty		September-03 January-07		· · · · · · · · · · · · · · · · · · ·
Warranty	01 07 03		BMW Centers	BMW Center Administered Customer Assistance Program (CACAP)
Warranty	01 02 04	November-06	BMW Centers	BMW Tire Center Target Satisfaction Program
Warranty	01 06 05	March-05	BMW Centers	BMW Maintenance Program 2005 Laminated Reference Chart and Mouse Pad
Warranty	B010605Attachment.	P/O 01 06 05	BMW Centers	Chart of Warranty Codes/Services
Warranty	01 07 05	March-05	BMW Centers	Warranty Claims Processing – "Overnight Payments"
Warranty	01 10 05	August-05	BMW Centers	TCU ESN Registration via DCSnet
Warranty	B011005Attachment.	P/O 01 10 05	BMW Centers	FAQ's for TCU Claims
Warranty	01 01 06	January-08	BMW Centers	BMW Warranty Policy and Procedures Manual – Updates from 01/01/05 through 12/21/07)
Warranty	B010106Attachment	P/O 01 01 06	BMW Centers	BMW Warranty Policy and Procedures Manual – Updates from 01/01/05 through 12/21/05 rev notes
Warranty	01 02 06	February-06	BMW Centers	BMW Electronic Archiving System (EAS) Evaluation and Certification
Warranty	B010206EAS_Flowchart.	February-06	BMW Centers	EAS Flowchart
Warranty	01 03 06	February-07	BMW Centers	Warranty Claims for Software Update Programming (Progman) (Replace NOV 06)
Warranty	01 04 06	April-06	BMW Centers	Reasons for Vehicle Update Programming Reminder Magnet
Warranty	01 09 06	February-07	BMW Centers	Defect Code for Programming Prior to Accessory Retrofit (Supercedes 12/06)
Warranty	01 03 07	June-07	BMW Centers	New Pricing Plan and Program Enhancements - Maintenance Program Upgrade
Warranty	01 02 08	February-08	BMW Centers	BMW Performance Line of Accessories
Warranty	01 03 08	May-08	BMW Centers	OEM Tire Manufacturer Warranty Coverage CD-ROM
Warranty	01 05 08	July-08	BMW Centers	Certified Pre-Owned (CPO) Reconditioning Changes
After Sales Business Development	02 01 05	October-05	All	BMW Assist changes for September 2005
After Sales Business Development	B020105KeyBenefitChart	P/O 02 01 05	7 (1)	BMW Assist - Key Benefits
After Sales Business Development	02 01 06	February-06	All	Updated DCSnet Vehicle History Inquiry Information on BMW Assist™ (Supercedes Jan 06)
After Sales Business Development				
•	02 02 06	November-06	All	BMW Assist™ Service Extension Incentive Program (Supercedes 02/06)
After Sales Business Development	02 01 07	February-07	All	Mobile Assistance Program
T. 1. 1	04.00.05		F00/F00	7 0 1 10
Tools and Equipment	04 02 05	January-05	E60/E63	Zero-Coded Cover
Tools and Equipment	04 04 05	January-05	E60	Antenna Knife
Tools and Equipment	04 07 05	April-05	N52 Engine	N52 Special Tools
Tools and Equipment	04 08 05	February-05	E60/E63	Aluminum Body Tools
Tools and Equipment	04 13 05	March-05	E61	Tailgate Support
Tools and Equipment	04 14 05	April-05	E60/E63	CD Eject Tool
Tools and Equipment	04 15 05	May-05	E90	DME Test Cable
Tools and Equipment	04 29 05	November-05	E60/E63	AC Sprayer Wand
Tools and Equipment	04 02 06	January-06	M - S85 engine	Backlash Gauge
Tools and Equipment	04 04 07	April-07	Turbocharged	Turbocharger Diagnostic Tool
Tools and Equipment	04 07 07	December-07	All	Fuel Injection and Induction System Cleaning
Tools and Equipment	04 01 08	January-08	S65/M3	New Special Tools
	thru - 2106 no value 0107-0307/0507-0607/ & 0807-2807 no value			
	0107-0307/0307-0607/ & 0607-2607 No Value			
Information Systems	05 01 05 end	September-05	All	Teleservice Changing a Customer's Preferred Home Dealer
Service Roundtable	06 01 06	September-06	ALL	Service Roundtable – September 2006 Show
Service Roundtable	06 02 06	October-06	ALL	Service Roundtable – October 2006 Show
Service Roundtable	06 03 06	November-06	ALL	Service Roundtable – November 2006 Show
Service Roundtable	06 04 06	December-06	ALL	Service Roundtable – December 2006 Show
Service Roundtable	06 01 07	January-07	ALL	Service Roundtable – January 2007 Show
Service Roundtable	06 02 07	February-07	ALL	Service Roundtable – February 2007 Show
Service Roundtable	06 03 07	March-07	ALL	Service Roundtable – March 2007 Show
Service Roundtable	06 04 07	April-07	ALL	Service Roundtable – April 2007 Show
Service Roundtable	06 05 07	May-07	ALL	Service Roundtable – May2007 Show
Service Roundtable	06 06 07	June-07	ALL	Service Roundtable – June 2007 Show
Service Roundtable	06 07 07	July-07	ALL	Service Roundtable – July 2007 Show
Service Roundtable	06 08 07	August-07	ALL	Service Roundtable – August 2007 Show

Category	SIBs (SI B## ## ##)	<u>Date</u>	<u>Application</u>	<u>Title</u>
Service Roundtable	06 09 07	September-07	ALL	Service Roundtable – September 2007 Show
Service Roundtable	06 10 07	October-07	ALL	Service Roundtable – October 2007 Show
Service Roundtable	06 11 07	November-07	ALL	Service Roundtable: November 2007 Show
Service Roundtable	06 12 07	December-07	ALL	Service Roundtable: December 2007 Show
Service Roundtable	06 01 08	January-08	ALL	Service Roundtable: January 2008 Show
Service Roundtable	06 02 08	February-08	ALL	Service Roundtable: February 2008 Show
Service Roundtable	06 03 08	March-08	ALL	Service Roundtable: March 2008 Show
Service Roundtable	06 04 08	April-08	ALL	Service Roundtable: April 2008 Show
Service Roundtable	06 05 08	May-08	ALL	Service Roundtable: May 2008 Show
Service Roundtable	06 06 08	June-08	ALL	Service Roundtable: June 2008 Show
Service Roundtable	06 07 08	July-08	ALL	Service Roundtable: July 2008 Show
Service Roundtable	06 09 08	September-08	ALL	Service Roundtable: September 2008 Show
General	07 02 96	June-07	BMW Centers	CD42: Updated DISplus & GT1 Software (update to Mar 07)
General	07 03 02	June-04	BMW Centers	Optical Testing & Programming System - OPPS
General	07 05 02	June-05	BMW Centers	Online Update
General	07 02 04	November-04	BMW Centers	Optical Programming System - OPS
General	07 01 05	December-05	BMW Centers	Software Service Station r2 (SSSr2)
General	07 01 06	August-06	BMW Centers	Next Generation Workshop Technology – iBase Server Readiness Project
General	07 03 06	October-06	BMW Centers	Next Generation Workshop Technology 3G
General	07 04 06	January-07	BMW Centers	Use Agreement for 3G Workshop Technology
General	07 04 00	March-07	BMW Centers	DIS V49 Corrections Based on Diagnosis Feedback
General	B070107_Feedback PDF 07 03 07	March-07	BMW Centers	B070107Diagnosis_Feedback_Corrected_DIS_V49.
General		June-07	BMW Centers	DIS V50 Corrections Based on Diagnosis Feedback
General	B070307_Feedback PDF	4	D1414 0 /	DIOVERS 11 D. 1
General	07 04 07	August-07	BMW Centers	DIS V51 Corrections Based on Diagnosis Feedback (Update to June 07)
General	07 05 07	June-07	BMW Centers	DIS V50 Release Notes
General	07 06 07	August-07	BMW Centers	Diagnosis Process
General	07 08 07	August-07	BMW Centers	DIS V51 Release Notes
General	07 10 07	October-07	BMW Centers	Importance of Using the Most Current Diagnostic / Programming Software
General	07 11 07	November-07	BMW Centers	DIS V52 Corrections Based on Diagnosis Feedback (December 2007 Release)
General	07 13 07	December-07	BMW Centers	DIS V52 Release Notes
General	07 15 07	January-08	E60/E63/E90/E92/E70	Diagnosis via D-CAN Not Possible
General	07 01 08	March-08	BMW Centers	DIS V53 Changes Based on Diagnosis Feedback (March 2008 Release)
General	07 02 08	March-08	BMW Centers	DIS V53 Release Notes
General	07 05 08	May-08	BMW Centers	DIS V54 Changes Based on Diagnosis Feedback (June 2008 Release)
		•		
	14 NU			
Programming/Coding Explainations	09 03 98	May-06	E60/E63/E90	Car & Key Memory (Updated date with additional E90 info Supercedes Nov 05)
Programming/Coding Explainations	B090398_Att5_CKM_E60	P/O 09 03 98	E60/E63	PDF of car and Key memory settings
Programming/Coding Explainations	09 05 01	March-06	E60/E63	CIP General Info (Supercedes Dec 05)
Programming/Coding Explainations	Att3_CBSCheck	P/O 09 05 01	E60/E63	Condition Based Service Plausibility Check
Programming/Coding Explainations	Att4_CBSCorrct	P/O 09 05 01	E60/E63	Condition Based Service Adjustments based on previous service
Programming/Coding Explainations	ProgCoding	P/O 09 05 01	E60/E63	Detailed Description of programming and coding using CIPs
Programming/Coding Explainations	09 07 02	March-03	E65	CIP 7.0
Programming/Coding Explainations	09 01 04	January-05	BMW Centers	Programming Manager
Programming/Coding Explainations	09 01 05	May-05	All	CIP 17.0 Release Notes
Programming/Coding Explainations	09 02 05	July-05	All	OBD Replacement Cables for GTI/DISplus Diagnostic Heads
Programming/Coding Explainations	09 03 05	January-07	E90	Personal Profile (Replaces 8/05)
Programming/Coding Explainations	09 04 05	July-05	All	CIP 18.0 release notes
Programming/Coding Explainations	09 05 05	July-05	E60 w/o NAV	After Programming, CIP shows MASK-H to be replaced
Programming/Coding Explainations	09 06 05	August-05	E60/E63	CIP Shows IHKA (Automatic heating & AC) to be Replaced
Programming/Coding Explainations	09 07 05	September-05	All	CIP 19.0 and 19.1 release notes
Programming/Coding Explainations	09 08 05	October-05	E64 Cabrio	
Programming/Coding Explainations Programming/Coding Explainations	09 09 05	November-05	BMW Centers	Service Action: Correction to Integration Level CIP: Report Recurring Irregularities
				CCC Fails to Program with CIP 19.x (Supercedes Dec 05, Feb 06, May 06, Aug 06)
Programming/Coding Explainations	09 11 05	October-06	E60/E63/E90	
Programming/Coding Explainations	09 01 06	February-06	E90	JBE Fails to Program (supercedes Jan 06)
Programming/Coding Explainations	09 02 06	January-06	E90	Replacement FZD Not Accepted by CIP/PROGMAN
Programming/Coding Explainations	09 03 06	January-06	All	Deciphering and Troubleshooting the Vehicle Order
Programming/Coding Explainations	09 05 06	January-06	E60/E63/E90	Release Notes Progman V20.0 and V20.0.1
Programming/Coding Explainations	09 06 06	February-06	E90	RAD2 Cannot be Programmed after Programming Abort (Supercedes Jan 06 - Online 20.02.00)
Programming/Coding Explaination	09 07 06	January-06	E90/x drives	DSC Cannot be Encoded
Programming/Coding Explainations	09 08 06	February-06	E90	DWA LED on Rearview Mirror Cannot be Activated
Programming/Coding Explainations	09 09 06	March-06	All	Release Notes Progman 21.0
Programming/Coding Explainations	09 10 06	May-06	All	Release Notes Progman V21.02 and V21.02.01
Programming/Coding Explainations	09 11 06	May-06	E60	Replacement SZL Not Accepted By Progman
Programming/Coding Explainations	09 13 06	June-06	All	Release Notes Progman V22.0 and V22.0.1
Programming/Coding Explainations	09 14 06	July-06	E60/E63/E90	Maintenance Interval Retrofit is Not Used in US Market Vehicles
Programming/Coding Explainations	09 15 06	July-06	E90	Personal Profile Settings for Alarm System Missing
Programming/Coding Explainations	09 16 06	August-06	E60/E63/E90	Release Notes Progman V22.1 and V22.1.1 and V22.1.2
Programming/Coding Explainations	09 17 06	December-06	ALL	Vehicle Order (VO) Cannot be Adapted Using CIP
Programming/Coding Explainations	09 20 06	October-06	E90	Daytime Running Lamps Switched On after Update with Progman V23
Programming/Coding Explainations	09 21 06	October-06	E90	Satellite Radio Inoperable after Programming with Program V23 - Need 23.01.03
Programming/Coding Explainations	09 22 06	October-06	E60/E63/E90	Coding Function for Headunit Available in Progman V23
Programming/Coding Explainations	09 01 07	January-07	E60/E63/E90	CCC: Programming or Coding Fails with Program V24
Programming/Coding Explainations	09 02 07	October-07	All w/CCC	CCC: Enabling Code (FSC) Required for Voice Recognition System(update to May 07
g. Ig. I I I I I I I I I I I I I		22.5501 01	11/000	5 2222 (C 22) Collection Collection Of Storm about to may of

<u>Category</u> Programming/Coding Explainations	SIBs (SI B## ## ##) B090207Attachment.	<u>Date</u> P/O 09 02 07	Application BMW Centers	Title B090207Parts Info V1 1
Programming/Coding Explainations	09 03 07	June-07	E92	FRM Fails Coding
Programming/Coding Explainations	09 04 07	August-07	ALL w/CCC	Programming Failure Due to CD or DVD in Drives
Programming/Coding Explainations	09 05 07	September-07	E90	CAS2 Programming with Special Measure not Possible
Programming/Coding Explainations	09 07 07	September-08	ALL	Progman Version vs. Vehicle Data Status (update to 7/08) 30.00.02 latest shown
	06 other model			
Engine System	11 08 98	June-06	All	BMW Engine Oils (Includes Annual Change Coverage) (Supercedes Oct 05)
Engine System	11 04 03	February-07	E60	Recurring Noise Complaints From Mechanical Alternator Belt Tensioners (Replaces 7/05)
Engine System	11 02 05	January-06	E60/E63	N62 - Rough Idle, Misfire faults after cold start (Supercedes May 05)
Engine System Engine System	11 03 05 11 05 05	June-05 December-06	E60/E63 E60	N62 and N62TU Valve Cover and Valve Cover Gasket Replacement N52 Engine Runs Poorly with Camshaft Sensor and VANOS Faults (Supercedes Novr 06)
Engine System	11 07 05	July-05	E60/E63	N62 and N62TU Water Pump Replacement - corrects installation procedure
Engine System	11 09 05	April-06	E60/E63	Non-Return Valve Parts Found In Engine Oil Filter During Engine Oil Service Supercedes Dec 05)
Engine System	11 10 05	February-06	E60 (M5)	Service Action: S85 Replace VANOS High Pressure Line (Supercedes Jan 06)
Engine System	11 01 06	March-06	M5/M6	S85 Engine Oil Level and Oil Service Information
Engine System	11 02 06	December-06	E60	NG6 Engines - Front and Rear Radial Crankshaft Seal Replacement
Engine System Engine System	11 03 06 11 04 06	June-06 June-06	All w/N62 Engine All	Voluntary Emissions Recall 06E-A02: N62 - Crankcase Ventilation Valves Replacement Engine, Transmission, or Clutch Related Complaints
Engine System	11 06 06	June-06	M54/M54TU	Head Bolt Threads Pulling Out of Block During Engine Reassembly
Engine System	11 07 06	October-06	All w/N62 Engine	N62 Engine - Rough Idle at Operating Temperature
Engine System	11 13 06	January-08	E90/E92 w N54	N54 Engine Compression and Cylinder Leakage Test Procedures (rpl 11/06)
Engine System	11 01 07	October-07	All with N62 (4.4I)	N62 Crankcase Ventilation System – Cold Climate Conditions (rpl 6/07)
Engine System	11 05 07	April-07	All S85 (V10)	Service Action: Replace Front Crankshaft Radial Seal
Engine System	11 09 07	July-07	All N52 Engine	Intermittent Hydraulic Valve Adjuster (HVA) "Ticking" or "Rattling" Noises
Engine System Engine System	11 12 07 11 13 07	October-07 November-07	N62/N62TU N54	N62 and N62TU Engine Replacement (after an engine has been replaced) N54 Rattle Noise from Turbocharger Area
Engine System	11 14 07	November-07	N54	N54 Turbocharger Waste Gate Control Noises and Operation
Engine System	11 02 08	February-08	N54	N54: Power Reduction - DME Fault 2A82 VANOS Inlet is Stored
Engine System	11 04 08	July-08	All	TeileClearing for Engine Components
Engine System	11 05 08	August-08	1, 3 Series	N51 Engine: Cylinder Head Bolt Torque Is not Available via TIS
Engine System	11 06 08	August-08	E46	Overheated Engine - Diagnostic Tips
5 · 5 · 10 ·	06 - Alpina B7			
Engine Electrical System Engine Electrical System	12 01 99 12 01 04	June-06 October-04	All N62 in E60	High Performance Platinum Spark Plug/Spark Plug Application Chart E60 with N62; DME Reprogramming
Engine Electrical System	12 03 04	September-04	M54 in E60	Voluntary Emissions Recall Campaign 04E-A02: Emission Readiness Codes Not Completely Setting
Engine Electrical System	12 04 04	July-04	E60/E63	Safety Recall Campaign 04V-344: DME Replacement on N62/N73 Engines
Engine Electrical System	12 05 04	October-05	E60/E63	Voluntary Emissions Recall 04E-A04: Reprogram DME for Oxygen Sensor Diagnostics on E53, E60,
Engine Electrical System	12 09 04	August-06	All	Special DME Programming - Shipping Procedure (Replaces 12/04)
Engine Electrical System Engine Electrical System	12 10 04 12 01 05	December-04 March-08	M54 in E60 N52 in E60	Intermittent Hesitation While Driving or Intermittent Crank, No Start Situation High Perf Iridium spark Plugs (rpl 06/06)
Engine Electrical System	12 03 05	September-05	N62 in E60/E63	CBS Oil Message
Engine Electrical System	12 04 05	July-07	N52 in E60	Check Engine light or engine overheats (Supercedes Mar 06)
Engine Electrical System	12 06 05	June-05	N52 in E60	DME FC CDA7 CAN Message
Engine Electrical System	12 08 05	July-05	E60	Oxygen Sensor
Engine Electrical System	12 11 05	January-06	N62 in E60/E63	Service Action: Reprogramming for Incorrect Oil Service (Supercedes August 05)
Engine Electrical System Engine Electrical System	12 15 05 12 16 05	March-08 September-05	N62 in E60/E63 E60	Map Thermostat faults (rpl 12/07) Mixture is too Lean, Fault codes 2882, 2883
Engine Electrical System	12 17 05	September-05	E60	Engine Power drops at 4000 RPM
Engine Electrical System	12 19 05	October-05	N52 in E60/E90	Service Action: Reprogram for OBD Diagnostic
Engine Electrical System	12 20 05	October-05	E60/E63	Loss of Power while decelerating & turning or coming to stop
Engine Electrical System	12 25 05	December-05	E90	CBS Oil formula (different but similar to E60/63)
Engine Electrical System Engine Electrical System	12 27 05 12 29 05	April-07 March-06	E60/E63 M5	N62TU (4.8L) Pinging and Surging (Supercedes Jul 06) S85 Engine Diagnosis Test Plan Updates (Supercedes Dec 05 - minor change)
Engine Electrical System Engine Electrical System	12 03 06	February-06	E60/M52	Loss of Power or Intermittent Crank, No Start Situation
Engine Electrical System	12 04 06	February-06	E60/M52	DMTL Diagnosis Test Plan Error
Engine Electrical System	12 06 06	April-07	E60/E90/N52	Voluntary Emissions Recall 06E-A01: N52 - Reprogramming Vehicle for OBD Diagnostic (Supercedes 5
Engine Electrical System	12 07 06	January-07	E60/E90/N52	Service Engine Soon Light Illuminated: FC 2EF4 Map Thermostat (Replaces 5/06)
Engine Electrical System	12 10 06	September-06	E60/E90/N52	Service Engine Soon Lamp Illuminated: FC 2C2D, 2C3D, 2C2E, 2C3E
Engine Electrical System Engine Electrical System	12 12 06 12 16 06	April-07 September-06	E60/E63/N62TU E90/E92 w N54	N62TU - Diagnosis for DME FC 2A90 (Supercedes Dec 06) E90. E92 with N54 - Diagnostic for DME FC 29F1/29F2
Engine Electrical System Engine Electrical System	12 18 06	November-06	Ms	Voluntary Emissions Recall 06E-A04: S85 - DME Reprogramming for OBD Monitoring
Engine Electrical System	12 19 06	October-06	E60/E63/E90	Check Gas Cap Warning with DME FC 2A17 – DMTL, System Error
Engine Electrical System	12 25 06	November-06	All	Fuel Quality Determination (Supercedes August 06)
Engine Electrical System	12 27 06	November-06	E60/N62	DME Fault Codes 278B and 278D
Engine Electrical System	12 28 06	October-06 November-06	E60 E60/M54	DME Fault Code 27CD DME Fault Codes 2896, 2877, 2766
Engine Electrical System Engine Electrical System	12 29 06 12 33 06	October-06	E60/M54 E60/E63	Various Complaints Caused by Defective Oil Level Sensor - Diagnostic Hints
Engine Electrical System	12 34 06	October-06	E60/M54	E60, M54 - Various Oxygen Sensor FC's Caused by Defective Transmission Harness
Engine Electrical System	12 38 06	October-06	E90	MSV70 - DME, FC 29DA Segment Adaptation
Engine Electrical System	12 40 06	October-06	E60	MS45.1 – Various O2 Sensor Faults Stored in DME
Engine Electrical System	12 42 06 13 43 06	November-06	E60	E60, MS45.1 – DME FC 28A2 and FC 2783
Engine Electrical System Engine Electrical System	12 43 06 12 46 06	October-06 November-06	E60/E63 E90/E92 w N54	N62 DME ME9.2.1 Engine Difficult to Restart at Operating Temperatures N54 – Slight Bucking is Felt During Acceleration With a Cold Engine
	.2 .3 00		200,202 11 1104	2g 22g to 1 on 20g 10000010001111111 0 0010 Engine

Category	SIBs (SI B## ## ##)	<u>Date</u>	Application	<u>Title</u>
Engine Electrical System	12 47 06	November-06	E60/E63	Break Out Box Overlay Identification
Engine Electrical System	12 49 06	April-07	E60/M54	DME MS45 - FC28B2, 28AA, 28AC; Internal RAM Faults (Rpl 11/06)
Engine Electrical System	12 50 06	November-06	E60/E63/E90	OBD II Fault Codes List in TIS
Engine Electrical System	12 51 06	December-06	E92	MSD80 N54 Engine Diagnostic Test Plans Inoperative
Engine Electrical System	12 54 06	December-06	E90/92	N54 CBS4 Oil Service Indicates 25,000 Miles
Engine Electrical System	12 55 06	January-08	E90/92	E90, E92 with N54 - Diagnosis for DME FC 29DC/2FBF (Replaces 1/07)
Engine Electrical System	12 58 06	January-07	E90	Service Action: Replace the Alternator
Engine Electrical System	12 05 07	January-08	E60/E90	Erroneous Low Oil Level Warning Message While Driving (rpl 120/07)
Engine Electrical System	12 06 07	September-07	E90/E92	Voluntary Emissions Recall 07E-A01: N54 - Reprogramming Vehicle (DME) for OBD Diagnostic
Engine Electrical System	12 07 07	June-07	E90/E92	N51 - Fault 2A43: Valvetronic, Thermal Overload Protection
Engine Electrical System	12 09 07	May-07	M5/M6	Service Engine Soon Light Illuminated: S85 - Various VANOS Related Faults Stored
Engine Electrical System	12 10 07	October-07	E60/E63/N62TU	Service Action: N62TU - Retrofit Engine Compartment Ground Cables - rpl 7/07 (now recall)
Engine Electrical System	12 11 07	July-07	E60/E63/N62TU	N62TU: EDK Throttle Faults - Diagnostic
Engine Electrical System	12 15 07	October-07	3 Series	N52K - Loss of Power
Engine Electrical System	12 16 07	October-07	3 Series	N51 - EAC Sensor Fault 2AD8 is Stored
Engine Electrical System	12 18 07	October-07	3/5 w N54	N54: Running Issues with Various Faults in DME
Engine Electrical System	12 22 07	November-07	All	TeileClearing (Enhanced Technical Support) for DME
Engine Electrical System	12 23 07	November-07	E70 (X5)	FC 2EF4 Characteristic Map Thermostat
Engine Electrical System	12 25 07	November-07	E70 (X5)	E70 N62TU: Pressure Sensor Fault 2D32
Engine Electrical System	12 28 07	December-07	3/5 w N54	N54 Engine Failsafe: FC 3100, FC 30FE and/or FC 30FF is stored in DME Fault Memory
Engine Electrical System	12 01 08	January-08	3/5 w N52	N52 EDK Throttle Jamming Faults 2D09, 2CED and 2CEC
Engine Electrical System	12 02 08	January-08	3/5 w N54	N54 - Diagnosis for DME Fuel Injector Faults
Engine Electrical System	12 03 08	January-08	X5 w N54	N52K - Diagnosis of DME FC 2E97
Engine Electrical System	12 05 08	February-08	X5 w N62TU	N62TU: Fault 2A17 - DMTL System Error is Stored
Engine Electrical System	12 09 08	February-08	E60/63/70	Driveability Complaints due to Cooling Fan Relay Failure
Engine Electrical System	12 10 08	April-08	All w N54	N54 – Aftermarket "Engine Performance Tuning" Kits
Engine Electrical System	12 12 08	March-08	3 Series/N52/N52K	DME FC 2A15 Minor Leak and 2A16 Superfine Leak in Evaporation System
Engine Electrical System	12 13 08	March-08	3/5 ser w/M54/N52	After Vehicle Repair, Service Engine Soon Lamp Cannot Be Switched Off
Engine Electrical System	12 14 08	May-08	New M3 /S65	Service Engine Soon Lamp Is Illuminated, EKP FC 2786, 2787, 2788 (rpl 3/08)
Engine Electrical System	12 16 08	June-08	M5/M6 V10	Voluntary Emissions Recall 08E-A02: M5 and M6 with S85 – OBD Communication
Engine Electrical System	12 17 08	June-08	E65/66	Service Action: E65 and E66 with N62, N62TU, or N73 – OBD Communication
Engine Electrical System	12 18 08	June-08	All w/N54	Service Action: N54 Oil Level Programming
Engine Electrical System	12 19 08	June-08	M5/M6 V10	S85 - Power Reduction with Idle Actuator Faults Stored
Engine Electrical System	12 20 08	June-08	All w/N54	N54 - Various Complaints Caused by Aftermarket "Tuning Kits"
Engine Electrical System	12 21 08	July-08	M5/M6	S85 - DME Fault 2742/2743 for O2 Sensor
Engine Electrical System	12 23 08	July-08	E65/66/B7	Service Action: E65 and E66 with N62, N62TU, or N73 - OBD Communication
Engine Electrical System	12 24 08	September-08	E65/66/B7	Service Action: E65 and E66 with N62TU or N73 – OBD Communication
Engine Electrical System	12 25 08	September-08	1/3/5 series & X6	Charge Air Pressure Control B1214_D16LDRN Test Plan Is Inoperative

no 04, 06, 07, 08 02, 03, 04, 12, 13, 20, 24, 26 other models, 01, 14, 19, 21, 27 NU

· ·	2, 00, 0 1, 12, 10, 20, 2 1, 20 00101 1100010, 0 1, 1 1, 1	, 2., 2		
Fuel Systems Fuel Systems	13 01 04 B130104Q&A	July-04 P/O 13 01 04	E60/E63 (V8) E60/E63 (V8)	Recall Campaign 04V- 303: Retaining Clip Retrofit for the Fuel Line Quick Release Coupling Q&A
Fuel Systems	13 01 06	September-06	All	Alcohol Fuel Blends in BMW Vehicles (replaces March 06)
Fuel Systems	13 02 06	September-06	All	TOP TIER Detergent Gasoline in BMW Vehicles (Replaces 03/06)
Fuel Systems	13 03 06	May-06	All	Fuel Pump Failure after Refueling with Ethanol Fuel Blend
Fuel Systems	13 04 06	August-06	All	Alcohol Detection Procedure
Fuel Systems	13 05 06	September-06	All	BMW Group Fuel System Cleaner Plus (Supercedes Aug 06)
Fuel Systems	13 06 06	November-06	E90/E92	High Precision Injection (HPI) Information and Service Procedures
Fuel Systems	13 00 00	November-06	ALL	Gasoline Quality & Detergent Additives - Customer Information Brochure
Fuel Systems	13 07 00	February-08	ALL/ex turbo	Fuel Injection and Induction System Cleaning (rpl 12/07)
Fuel Systems	13 07 07	September-08	E90/92/93/wN54	Service Action: Replace the High Pressure Pump
Fuel Systems	13 02 00	September-08	E90/92/93/wN54	Service Action: Replace the High-Pressure Pump (older vehicles)
ruei Systems	13 03 06	September-06	E90/92/93/WN54	Service Action: Replace the high-riessure rump (older vehicles)
Fuel Supply	16 02 05	March-05	E60/E63	Fuel Tank Difficult to Refuel
Fuel Supply	16 01 06	September-06	E90	Fuel Level Sensor Repair Procedure w/N54
Fuel Supply	16 03 06	October-06	E90	Vehicle is Difficult to Refuel
Fuel Supply	16 06 06	October-06	E60	Humming/Buzzing Noise from Center Dash Area When Accelerator is Depressed
Fuel Supply	16 08 06	February-07	E90	N51 PZEV - Erroneous Fuel Gauge Reading (Replaces 12/06)
Fuel Supply	16 01 07	August-07	All	Testing Evaporative Systems for Leaks
Fuel Supply	16 02 07	December-07	E70 (X5)	Service Action: Repair the Fuel Tank Level Sensor
Fuel Supply	16 01 08	September-08	All w/N54	DMTL Tank Leakage Test Module Provides Inaccurate Results
	- 02 other models			
Cooling Systems	17 01 07	October-07	ALL	BMW Long-Term Antifreeze/Coolant: Maintenance, Repairs and Replacement Requirements
Cooling Systems	17 01 08	July-08	E9x M3	Low Coolant Warning Lamp is Illuminated
Clutch	21 02 06	October-06	E60 (M5)	S85 - SMG Transmission Faults 4FA0, 4F80 and Clutch is Damaged
Clutch	07 for Z4	May-07	Z4	Service Action: Clutch Fork Lever Inspection
Drive Shaft	26 01 06	June-07	E65/E66	Noise from Driveshaft Area (Rpl 06/06)
Drive Shaft	26 01 08	July-08	3 Series Xi	Service Action: Replace Front Propeller Shaft Bolts (Build 12/07)

<u>Category</u>	SIBs (SI B## ## ##)	<u>Date</u>	<u>Application</u>	<u>Title</u>
Manual Transmission	23 01 05	November-05	E60/M5	E60 M5 - CAN Communication Fault FFFF
Manual Transmission	23 01 06	February-06	M Cars	SMG III: Fault Code 5101 Analyze Hydraulic Sensor (Supercedes Jan 06)
Manual Transmission	23 02 06	January-06	SMG Tranny	Towing Vehicles with SMG Transmissions
Manual Transmission	23 03 06	April-07	M Cars	Getrag SMG Transmission Repair & Replacement Information (SMG II and III) (Rpl 02/06)
Manual Transmission	23 04 06	April-06	E60/E63	ZF SMG FC 4F6F - Hydraulic Pump Failure (Supercedes Mar 06)
Manual Transmission	23 07 06	February-07	M Cars	M5, M6 with SMG III; FC 4F42/4F43 - Hydraulic Unit Faults (Replaces 12/06)
Manual Transmission	23 08 06		All SMG Cars	
Manual Transmission	23 09 06	January-07	All non M SMG	SMG - Service Functions Performed after Drivetrain Repairs
		January-07		ZF SMG - Replacement Parts Availability
Manual Transmission	23 01 07	August-07	S85 M5	Service Action: Replace SMG Hydraulic Unit Electric Motor on M5 Vehicles (rpl 7/07)
Manual Transmission	23 02 07	March-08	E60/E63	Voluntary Emissions Recall 07E-A02: SMG Reprogramming
Manual Transmission	23 03 07	December-07	ZF SMG	TeileClearing (Enhanced Technical Support) for ZF SMG Transmissions
Manual Transmission	23 01 08	May-08	Many	Vehicles equipped with Manual Transmissions manufactured by Getrag:
Manual Transmission	23 02 08	July-08	E46	E46, E85 with M54 and ZF SMG - OBD Communication
	- 06 other model			
Automatic Transmission	24 08 03	November-04	E60	EGS Fault 4F6A
Automatic Transmission	24 02 05	April-06	E60	Service Action: Replace Mechatronic Adapter (Supercedes May 05
Automatic Transmission	24 03 05	February-07	E60/E63	Harsh 2-1 Downshift (Replaces 6/05)
Automatic Transmission	24 06 05	November-05	E60/E63	Safety Recall Campaign 05V-504: Parking Lock Guide Plate
Automatic Transmission	B240605CustomerLetter	P/O 24 06 05	E60/E63	Recall Letter
Automatic Transmission	B240605Q&A.	P/O 24 06 05	E60/E63	Q&A
Automatic Transmission	24 06 06	October-06	E90	A Slight Bump is Felt Shortly after the Vehicle Comes to a Stop (Supercedes Aug 06)
Automatic Transmission	24 11 06	October-06	E92	E92; N54 with 6HP16 - Diagnosis for EGS FC 511B
Automatic Transmission	24 04 07	April-07	E90/E91/E92	ZF 6HP19TU in Failsafe Mode with Fault 4F8D Stored
Automatic Transmission	24 09 07	April-07	E90/E91/E92	The Service Engine Soon Light is on and EGS Fault CF1C Stored
Automatic Transmission	24 10 07	April-07	E60/3 Series	The Transmission is in "Failsafe" mode with EGS Fault CF33 Stored
Automatic Transmission	24 11 07	April-07	3 Series	GM6 - 6L46R Transmission Adaptations and Terminology (info only)
Automatic Transmission	24 13 07	June-07	All STEP Equipped	Various Complaints Due to Poor Connection at Transmission Connector
Automatic Transmission Automatic Transmission	24 13 07	September-07	E60	Drive Position "D" Cannot be Engaged
				0 0
Automatic Transmission	24 20 07	October-07	3 Xi	6L45R Transmission with AWD Leaks from the Selector Shaft Seal
Automatic Transmission	24 21 07	October-07	3 Series	Diagnosis - DME Fault CDB4: No Message (transmission data 3, 3B1)
Automatic Transmission	24 22 07	October-07	3 Series	6HP19TU (6HP21) - Fault 5087: One-Touch Hardware is Stored
Automatic Transmission	24 23 07	February-08	All STEP Equipped	6-Speed Automatic Transmissions Diagnosis and Troubleshooting Hints (rpl 12/07)
Automatic Transmission	24 01 08	February-08	E65/66	E65, E66 with 6HP26 - Diagnosis for EGS FC 4F81
Automatic Transmission	24 02 08	February-08	E60/63/70	Driveability Complaints due to Cooling Fan Relay Failure
Automatic Transmission	24 03 08	July-08	E9x/E60	E60, E9x with N54 and 6HP19TU - Jolt and Delay when Pulling Away (rpl 6/08)
Automatic Transmission	24 04 08	July-08	E70 (X5)	E70, X5 3.0i with N52K and 6HP19TU - Transmission Driveability Complaints
Automatic Transmission	24 05 08	August-08	E65/66	E65, E66 with N62TU - Various Driveability Complaints
	24 process info			
Gear Shift Mechanism	25 01 07	January-07	E70	Service Action: Gear Shift Knob Replacement
Gear Shift Mechanism	25 02 07	November-07	E60	Diagnostic for GWS Faults - Drive Position "D" Cannot be Engaged
Gear Shift Mechanism	25 03 07	November-07	E60/E63	Sport Transmission Paddle Shifters Inoperative - Diagnosis
Gear Shift Mechanism	25 01 08	June-08	M5/M6	M5, M6 with SMG III - Gear Selector Display Position Changes from N to R (3-7/07)
	14 - 18 other models			
Front Axle	31 02 04	August-04	All	Rattling Noise From Front or Rear Axle
Front Axle	31 02 06	June-06	E60/E63	Recall Campaign 06V-187 : Front Axle Control Arm and Tension Strut Fasteners
Front Axle	31 03 06	November-06	E90	Recall Campaign 06V-400: Check Tightening Torque of Front Axle Control Arms and Tie Rods
Front Axle	31 01 07	January-08	E70 (X5)	Knocking Noise from Front Suspension
Front Axle	31 01 08	July-08	E53 (X5)	E53 (X5) - Replacement of Front Outer CV Joint
	no 08 yet			
0			F00	D 0 1 A 1 5 L
Steering and Wheel Alignment	32 01 05	July-05	E60	Power Steering Assist Enhancement
Steering and Wheel Alignment	32 04 05	June-05	E60	Steering Column Comfort Exit Feature
Steering and Wheel Alignment	32 07 05	September-05	E60/E63	Active Front Steering, Noise Fault Code 613E
Steering and Wheel Alignment	32 13 05	October-05	E60/E63	Active Front Steering, Fault Code 6141
Steering and Wheel Alignment	32 14 05	October-05	E60/E63	Active Front Steering Sensitivity
Steering and Wheel Alignment	32 01 06	February-06	E90	Service Action: Install Clip for Power Steering Line
Steering and Wheel Alignment	32 04 06	February-06	E60/E63	AFS Programming
Steering and Wheel Alignment	32 05 06	March-06	E90	Steering Wheel Offset
Steering and Wheel Alignment	32 06 06	March-06	E60/E63	Steering Angle Sensor Adjustment
Steering and Wheel Alignment	32 07 06	April-06	E90/91	Steering Column Clicking Noise
Steering and Wheel Alignment	32 04 07	July-07	ALL	TeileClearing (Enhanced Technical Support) for Steering Systems
Steering and Wheel Alignment	32 07 07	January-08	E60/E70	Active Front Steering (AFS) Warning Lamp; Fault Code 6141 stored
Steering and Wheel Alignment	32 01 08	January-08	E70 (X5)	Active Steering Troubleshooting Procedures
3				

0-4	CID- (CI D## ## ##)	D-4-	A	Title
<u>Category</u>	SIBs (SI B## ## ##)	<u>Date</u>	<u>Application</u>	<u>Title</u>
Steering and Wheel Alignment	32 02 08	August-08	M5/M6	Repair Instructions for Power Steering Pump and Pressure Line
		no 05, 06		
Door Aylo	22.04.02	March 00	M Coro	Crinding Naise from the Differential during Slaw Cornering
Rear Axle	33 01 02	March-08	M Cars	Grinding Noise from the Differential during Slow Cornering
Rear Axle	33 01 06	April-06	E60 (M5)	Grating Noise from Differential During Slow Cornering
Rear Axle	33 02 06	September-06	E60/E63/E65	Recall Campaign 06V-277: Inspect Rear Shock Absorbers (Supercedes Aug 06)
Rear Axle	33 01 07	October-07	E60 - M5	E60 M5 Howling Noise from Rear Axle Area
Rear Axle	33 01 08	March-08	3 series M/S65	E90, E92, E93 M3 - "Clunk Noise" on Load Reversal
Rear Axle	33 02 08	April-08	E70 (X5)	Recall Campaign 08V-170: Replace Rear Stabilizer Bar (mfr March 08)
Rear Axle	33 03 08	April-08	All models	Differential Cover Sealer
		·		
Brakes	34 06 05	July-05	E90	DSC MK60E5 Fault Codes: 5DB6, 5DC6, 5E30, 5D8F
Brakes	34 02 06	March-06	E60/E63	Brake Squeals
Brakes	34 04 06	April-07	E60/E63/E90	DSC Warning - Various SZL FCs Stored (Supercedes Jun 06)-Changed to e90 only??
Brakes	34 05 06	September-06	E60/E63	Service Action: Replace SZL Optical Element (Made Svc Action)
Brakes	34 02 07	September-07	E70 (X5)	Recall Campaign 07V-391: Inspect the Brake Fluid Reservoir Cap
Brakes	34 03 07	September-07	E70 (X5)	DSC Warning Lamp Illuminated
Brakes	34 04 07	October-07	E60/E63	DSC/DXC Warning Lamp, Fault Code 5EBA (may - June 07 production)
Brakes	34 05 07	October-07		
			E70 (X5)	Replacement of the Parking Brake Module (EMF)
Brakes	34 06 07	November-07	E90/91/92/93	Additional Effort Required to Press Brake Pedal Prior to Engine Initial Start
Brakes	34 07 07	November-07	M5/M6	M5, M6 - DSC Disabling Function
Brakes	34 01 08	April-08	E70 (X5)	The Parking Brake Warning Is Illuminated and Fault Code 6032 Is Stored
Brakes	34 02 08	April-08		
			3 Series	Erroneous Brake Pad Replacement Message
Brakes	34 03 08	May-08	E65/66	Parking Brake Repair Instructions
Brakes	34 05 08	August-08	All	Brake Rotor Minimum Thickness (Insp Only Spec 2.4mm non-M)
Brakes	34 07 08	August-08	X5/X6	Parking Brake Warning Illuminated; Fault Code 600D and/or 600B Is Stored
2.4	0.0.00	ragaer ee	710/710	. arming France training mammatca, t and bodo 5002 and 5, 5002 to 500 to
	01 other model			
Wheels and Tires	36 01 04	August-05	BMW Center	Hunter GSP97BMW Wheel Balancer - Features and Operator Training
Wheels and Tires	36 02 05	July-05	E60	Noise and/or Vibration Caused by Irregular Tire Wear
Wheels and Tires	36 04 05	October-05	E60	Erroneous Flat Tire Monitor Warning
Wheels and Tires	36 05 05	June-05	All	Tire Pressure Monitoring Systems (TPMS)
Wheels and Tires	36 06 05	May-05	E60	Wheels - Different between X models and regular models
Wheels and Tires	36 04 06	April-06	E60	Nitrogen Inflated Tires
Wheels and Tires	36 02 07	September-07	3 Series	Service Action: Reprogram the Control Module for the Tire Pressure Monitoring System (RDC)
Wheels and Tires	36 03 07	September-07	All	Flat Tire Monitor System (FTM) Diagnosis
Miles and a serial Theory	20.04.00	4 4 00	AII	
wheels and lires	36 01 08	August-u8	All	Tire Pressure Warning Caused by Damaged Wheel Electronics
Wheels and Tires	36 01 08	August-08	All	Tire Pressure Warning Caused by Damaged Wheel Electronics
wheels and Tires	36 01 08	August-08	All	Tire Pressure Warning Caused by Damaged Wheel Electronics
wheels and Tires	36 01 08	August-08	All	Tire Pressure Warning Caused by Damaged Wheel Electronics
wneels and Tires	36 01 08	August-08	All	Tire Pressure Warning Caused by Damaged Wheel Electronics
Suspension	36 01 08 37 02 05	August-08 August-05	E60/E63	Tire Pressure Warning Caused by Damaged Wheel Electronics Anti-Roll Stabilization Noise
Suspension	37 02 05	August-05	E60/E63	Anti-Roll Stabilization Noise
Suspension Suspension	37 02 05 37 01 06	August-05 March-06	E60/E63 E61	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable
Suspension Suspension Suspension	37 02 05 37 01 06 37 01 07	August-05 March-06 November-07	E60/E63 E61 E70 (X5)	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension
Suspension Suspension Suspension Suspension	37 02 05 37 01 06 37 01 07 37 02 07	August-05 March-06 November-07 October-07	E60/E63 E61 E70 (X5) E70 (X5)	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored
Suspension Suspension Suspension	37 02 05 37 01 06 37 01 07	August-05 March-06 November-07	E60/E63 E61 E70 (X5)	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension
Suspension Suspension Suspension Suspension	37 02 05 37 01 06 37 01 07 37 02 07	August-05 March-06 November-07 October-07	E60/E63 E61 E70 (X5) E70 (X5)	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored
Suspension Suspension Suspension Suspension	37 02 05 37 01 06 37 01 07 37 02 07	August-05 March-06 November-07 October-07	E60/E63 E61 E70 (X5) E70 (X5)	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored
Suspension Suspension Suspension Suspension	37 02 05 37 01 06 37 01 07 37 02 07	August-05 March-06 November-07 October-07	E60/E63 E61 E70 (X5) E70 (X5)	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored
Suspension Suspension Suspension Suspension Suspension	37 02 05 37 01 06 37 01 07 37 02 07 37 03 07	August-05 March-06 November-07 October-07 January-08	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5)	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs
Suspension Suspension Suspension Suspension	37 02 05 37 01 06 37 01 07 37 02 07	August-05 March-06 November-07 October-07	E60/E63 E61 E70 (X5) E70 (X5)	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored
Suspension Suspension Suspension Suspension Suspension	37 02 05 37 01 06 37 01 07 37 02 07 37 03 07	August-05 March-06 November-07 October-07 January-08 May-05	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5)	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions
Suspension Suspension Suspension Suspension Suspension	37 02 05 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06	August-05 March-06 November-07 October-07 January-08 May-05 February-06	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5)	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow
Suspension Suspension Suspension Suspension Suspension Body Body Body	37 02 05 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E70(X5)	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area
Suspension Suspension Suspension Suspension Suspension	37 02 05 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06	August-05 March-06 November-07 October-07 January-08 May-05 February-06	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5)	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow
Suspension Suspension Suspension Suspension Suspension Body Body Body	37 02 05 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E70(X5)	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area
Suspension Suspension Suspension Suspension Suspension Body Body Body	37 02 05 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E70(X5)	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area
Suspension Suspension Suspension Suspension Suspension Body Body Body	37 02 05 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E70(X5)	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area
Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body	37 02 05 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E70(X5) E90/91	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar
Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Body	37 02 05 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E70(X5) E90/91	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07)
Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Body	37 02 05 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E70(X5) E90/91	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06)
Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Body	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05 51 04 05	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E70(X5) E90/91 E60/E63 E60 E60/E61 (xi, xiT)	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floor Mats (deliveries before May 16, 05)
Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Body	37 02 05 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E70(X5) E90/91	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06)
Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05 51 04 05 51 08 05	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-07 June-05 July-05	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E60/E63 E60/E61 (xi, xiT) E60/E63	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floor Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming
Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05 51 04 05 51 08 05 51 17 05	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-07 June-05 July-05 July-05	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E70(X5) E90/91 E60/E63 E60 E60/E61 (xi, xiT) E60/E63 E60	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floor Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position
Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05 51 04 05 51 08 05 51 17 05 51 30 05	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-07 June-05 July-05 July-05 October-05	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E70(X5) E90/91 E60/E63 E60 E60/E61 (xi, xiT) E60/E63 E60 E90	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floor Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position Cracking or Ticking Noise from Lower B-Pillar
Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05 51 04 05 51 08 05 51 17 05 51 30 05 51 30 05 51 31 05	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-07 June-05 July-05 October-05 March-06	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E60/E63 E60/E61 (xi, xiT) E60/E63 E60 E90 E90	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floor Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position Cracking or Ticking Noise from Lower B-Pillar Center Console Heats Up In Knee Contact Area (Supercedes Nov 05)
Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05 51 04 05 51 08 05 51 17 05 51 30 05	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-07 June-05 July-05 July-05 October-05	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E70(X5) E90/91 E60/E63 E60 E60/E61 (xi, xiT) E60/E63 E60 E90	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floor Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position Cracking or Ticking Noise from Lower B-Pillar
Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05 51 04 05 51 08 05 51 17 05 51 30 05 51 31 05 51 32 05	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-07 June-05 July-05 July-05 October-05 March-06 October-05	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E70(X5) E90/91 E60/E61 (xi, xiT) E60/E63 E60 E90 E90 E90	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floor Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position Cracking or Ticking Noise from Lower B-Pillar Center Console Heats Up In Knee Contact Area (Supercedes Nov 05) Clicking Noise from Upper B-pillar Trim
Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05 51 04 05 51 08 05 51 17 05 51 30 05 51 31 05 51 32 05 51 32 05 51 33 05	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-07 June-05 July-05 July-05 July-05 October-05 March-06 October-05 October-05	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E60 E60/E61 (xi, xiT) E60/E63 E90 E90 E90 E90	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floor Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position Cracking or Ticking Noise from Lower B-Pillar Center Console Heats Up In Knee Contact Area (Supercedes Nov 05) Clicking Noise from Upper B-pillar Trim Water Ingress from A/C Blower Housing
Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05 51 04 05 51 08 05 51 17 05 51 30 05 51 31 05 51 32 05 51 33 05 51 33 05 51 37 05	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-07 June-05 July-05 October-05 March-06 October-05 October-05 December-05	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E60/E63 E60/E61 (xi, xiT) E60/E63 E60 E90 E90 E90 E90 E90 E90 E90 E90 E90	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floor Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position Cracking or Ticking Noise from Lower B-Pillar Center Console Heats Up In Knee Contact Area (Supercedes Nov 05) Clicking Noise from Upper B-pillar Trim Water Ingress from A/C Blower Housing The cup holder jams when retracted
Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05 51 04 05 51 08 05 51 17 05 51 30 05 51 31 05 51 32 05 51 32 05 51 33 05 51 37 05 51 37 05 51 10 06	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-07 June-05 July-05 July-05 October-05 March-06 October-05 October-05 December-05 May-07	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E60/E63 E60 E60/E61 (xi, xiT) E60/E63 E60 E90 E90 E90 E90 E90 E90 E90 E90 E90 E60	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floor Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position Cracking or Ticking Noise from Lower B-Pillar Center Console Heats Up In Knee Contact Area (Supercedes Nov 05) Clicking Noise from Upper B-pillar Trim Water Ingress from A/C Blower Housing The cup holder jams when retracted Anti-trap is Activated when Raising the Front Window (rpl 2/06)
Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05 51 04 05 51 08 05 51 17 05 51 30 05 51 31 05 51 32 05 51 33 05 51 33 05 51 37 05	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-07 June-05 July-05 October-05 March-06 October-05 October-05 December-05	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E60/E63 E60/E61 (xi, xiT) E60/E63 E60 E90 E90 E90 E90 E90 E90 E90 E90 E90	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floor Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position Cracking or Ticking Noise from Lower B-Pillar Center Console Heats Up In Knee Contact Area (Supercedes Nov 05) Clicking Noise from Upper B-pillar Trim Water Ingress from A/C Blower Housing The cup holder jams when retracted
Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05 51 04 05 51 08 05 51 17 05 51 30 05 51 31 05 51 32 05 51 32 05 51 33 05 51 37 05 51 37 05 51 10 06	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-07 June-05 July-05 July-05 October-05 March-06 October-05 October-05 December-05 May-07	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E60/E63 E60 E60/E61 (xi, xiT) E60/E63 E60 E90 E90 E90 E90 E90 E90 E90 E90 E90 E60	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floor Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position Cracking or Ticking Noise from Lower B-Pillar Center Console Heats Up In Knee Contact Area (Supercedes Nov 05) Clicking Noise from Upper B-pillar Trim Water Ingress from A/C Blower Housing The cup holder jams when retracted Anti-trap is Activated when Raising the Front Window (rpl 2/06)
Suspension Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05 51 04 05 51 04 05 51 17 05 51 30 05 51 31 05 51 32 05 51 33 05 51 33 05 51 37 05 51 13 06 51 14 06 51 14 06 51 18 06	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-07 June-05 July-05 October-05 March-06 October-05 October-05 December-05 May-07 March-08 May-07	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E60/E63 E60/E61 (xi, xiT) E60/E63 E60 E90 E90 E90 E90 E90 E90 E90 E90 E90 E9	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floro Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position Cracking or Ticking Noise from Lower B-Pillar Center Console Heats Up In Knee Contact Area (Supercedes Nov 05) Clicking Noise from Upper B-pillar Trim Water Ingress from A/C Blower Housing The cup holder jams when retracted Anti-trap is Activated when Raising the Front Window (rpl 2/06) Outside Door Handles Hangling up in the Pulled Position (rpl 2/08) Interior Door Grab Handle Finish Peeling (rpl 8/06)
Suspension Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05 51 04 05 51 08 05 51 17 05 51 30 05 51 31 05 51 32 05 51 32 05 51 33 05 51 37 05 51 37 05 51 10 06 51 14 06 51 18 06 51 18 06	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-07 June-05 July-05 October-05 March-06 October-05 October-05 December-05 May-07 March-08 May-07 November-06	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E60/E63 E60 E60/E61 (xi, xiT) E60/E63 E60 E90 E90 E90 E90 E90 E90 E90 E90 E90 E9	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floor Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position Cracking or Ticking Noise from Lower B-Pillar Center Console Heats Up In Knee Contact Area (Supercedes Nov 05) Clicking Noise from Upper B-pillar Trim Water Ingress from A/C Blower Housing The cup holder jams when retracted Anti-trap is Activated when Raising the Front Window (rpl 2/06) Outside Door Handles Hanging up in the Pulled Position (rpl 2/08) Interior Door Grab Handle Finish Peeling (rpl 8/06) Luggage Compartment Roller Cover Malfunction
Suspension Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 O1 other model 51 13 04 51 02 05 51 04 05 51 08 05 51 17 05 51 30 05 51 31 05 51 31 05 51 32 05 51 32 05 51 33 05 51 37 05 51 10 06 51 14 06 51 18 06 51 14 06 51 12 06	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-07 June-05 July-05 July-05 October-05 March-06 October-05 December-05 December-05 May-07 March-08 May-07 November-06 January-07	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E60/E61 (xi, xiT) E60/E63 E60 E90 E90 E90 E90 E90 E90 E90 E90 E90 E9	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floor Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position Cracking or Ticking Noise from Lower B-Pillar Center Console Heats Up In Knee Contact Area (Supercedes Nov 05) Clicking Noise from Upper B-pillar Trim Water Ingress from A/C Blower Housing The cup holder jams when retracted Anti-trap is Activated when Raising the Front Window (rpl 2/06) Outside Door Handles Hanging up in the Pulled Position (rpl 2/08) Interior Door Grab Handle Finish Peeling (rpl 8/06) Luggage Compartment Roller Cover Malfunction Rattle Noise from B-Pillar Trim
Suspension Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05 51 04 05 51 08 05 51 17 05 51 30 05 51 31 05 51 32 05 51 32 05 51 33 05 51 37 05 51 37 05 51 10 06 51 14 06 51 18 06 51 18 06	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-07 June-05 July-05 October-05 March-06 October-05 October-05 December-05 May-07 March-08 May-07 November-06	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E60/E63 E60 E60/E61 (xi, xiT) E60/E63 E60 E90 E90 E90 E90 E90 E90 E90 E90 E90 E9	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floor Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position Cracking or Ticking Noise from Lower B-Pillar Center Console Heats Up In Knee Contact Area (Supercedes Nov 05) Clicking Noise from Upper B-pillar Trim Water Ingress from A/C Blower Housing The cup holder jams when retracted Anti-trap is Activated when Raising the Front Window (rpl 2/06) Outside Door Handles Hanging up in the Pulled Position (rpl 2/08) Interior Door Grab Handle Finish Peeling (rpl 8/06) Luggage Compartment Roller Cover Malfunction
Suspension Suspension Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05 51 04 05 51 04 05 51 17 05 51 30 05 51 31 05 51 32 05 51 33 05 51 33 05 51 37 05 51 10 06 51 14 06 51 14 06 51 18 06 51 27 06 51 06 07	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-07 June-05 July-05 October-05 March-06 October-05 October-05 December-05 May-07 March-08 May-07 November-06 January-07 March-07	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E60/E61 (xi, xiT) E60/E63 E60 E90 E90 E90 E90 E90 E90 E90 E90 E90 E9	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floro Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position Cracking or Ticking Noise from Lower B-Pillar Center Console Heats Up In Knee Contact Area (Supercedes Nov 05) Clicking Noise from Upper B-pillar Trim Water Ingress from A/C Blower Housing The cup holder jams when retracted Anti-trap is Activated when Raising the Front Window (rpl 2/06) Outside Door Handles Hanging up in the Pulled Position (rpl 2/08) Interior Door Grab Handle Finish Peeling (rpl 8/06) Luggage Compartment Roller Cover Malfunction Rattle Noise from B-Pillar Trim Service Action: Replace Underbody Panel
Suspension Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05 51 04 05 51 08 05 51 17 05 51 30 05 51 31 05 51 32 05 51 33 05 51 37 05 51 37 05 51 37 05 51 10 06 51 14 06 51 18 06 51 14 06 51 18 06 51 24 06 51 27 06 51 06 07 51 08 07	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-07 June-05 July-05 October-05 March-06 October-05 December-05 December-05 May-07 March-08 May-07 November-06 January-07 March-07 March-07	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E60/E63 E60 E60/E61 (xi, xiT) E60/E63 E60 E90 E90 E90 E90 E90 E90 E90 E90 E90 E9	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floor Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position Cracking or Ticking Noise from Lower B-Pillar Center Console Heats Up In Knee Contact Area (Supercedes Nov 05) Clicking Noise from Upper B-pillar Trim Water Ingress from A/C Blower Housing The cup holder jams when retracted Anti-trap is Activated when Raising the Front Window (rpl 2/06) Outside Door Handles Hanging up in the Pulled Position (rpl 2/08) Interior Door Grab Handle Finish Peeling (rpl 8/06) Luggage Compartment Roller Cover Malfunction Rattle Noise from B-Pillar Trim Service Action: Replace Underbody Panel Erroneous Trunk Lid Open Check Control Message
Suspension Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 O1 other model 51 13 04 51 02 05 51 04 05 51 08 05 51 17 05 51 30 05 51 31 05 51 32 05 51 33 05 51 37 05 51 30 05 51 31 05 51 31 05 51 32 05 51 31 05 51 32 05 51 31 05 51 32 05 51 32 05 51 31 05 51 32 05 51 33 05 51 32 05 51 33 05 51 32 05 51 33 05 51 33 05 51 32 05 51 33 05 51 33 05 51 33 05 51 31 05 51 32 05 51 33 05 51 33 05 51 31 05 51 32 05 51 33 05 51 31 05 51 32 05 51 33 05 51 33 05 51 31 05 51 32 05 51 33 05 51 33 05 51 33 05 51 33 05 51 34 06 51	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-05 July-05 July-05 October-05 March-06 October-05 December-05 May-07 March-08 May-07 November-06 January-07 March-07 March-07 April-07	E60/E63 E61 E70 (X5) E60/E63 E60/E63 E60/E61 (xi, xiT) E60/E63 E60 E90 E90 E90 E90 E90 E90 E90 E90 E90 E9	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floor Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position Cracking or Ticking Noise from Lower B-Pillar Center Console Heats Up In Knee Contact Area (Supercedes Nov 05) Clicking Noise from Upper B-pillar Trim Water Ingress from A/C Blower Housing The cup holder jams when retracted Anti-trap is Activated when Raising the Front Window (rpl 2/06) Outside Door Handles Hanging up in the Pulled Position (rpl 2/08) Interior Door Grab Handle Finish Peeling (rpl 8/06) Luggage Compartment Roller Cover Maffunction Rattle Noise from B-Pillar Trim Service Action: Replace Underbody Panel Erroneous Trunk Lid Open Check Control Message Rear Window will not Fully Defrost
Suspension Suspension Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05 51 04 05 51 04 05 51 17 05 51 30 05 51 31 05 51 32 05 51 33 05 51 33 05 51 37 05 51 10 06 51 14 06 51 14 06 51 14 06 51 14 06 51 12 07 51 08 07 51 10 07 51 10 07	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-07 June-05 July-05 October-05 March-06 October-05 October-05 December-05 May-07 March-08 May-07 November-06 January-07 March-07 May-07	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E60/E63 E60 E60/E61 (xi, xiT) E60/E63 E90	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floro Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position Cracking or Ticking Noise from Lower B-Pillar Center Console Heats Up In Knee Contact Area (Supercedes Nov 05) Clicking Noise from Upper B-pillar Trim Water Ingress from A/C Blower Housing The cup holder jams when retracted Anti-trap is Activated when Raising the Front Window (rpl 2/06) Outside Door Handles Hanging up in the Pulled Position (rpl 2/08) Interior Door Grab Handle Finish Peeling (rpl 8/06) Luggage Compartment Roller Cover Malfunction Rattle Noise from B-Pillar Trim Service Action: Replace Underbody Panel Erroneous Trunk Lid Open Check Control Message Rear Window will not Fully Defrost Service Action: Install Luggage Compartment Labels
Suspension Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 O1 other model 51 13 04 51 02 05 51 04 05 51 08 05 51 17 05 51 30 05 51 31 05 51 32 05 51 33 05 51 37 05 51 30 05 51 31 05 51 31 05 51 32 05 51 31 05 51 32 05 51 31 05 51 32 05 51 32 05 51 31 05 51 32 05 51 33 05 51 32 05 51 33 05 51 32 05 51 33 05 51 33 05 51 32 05 51 33 05 51 33 05 51 33 05 51 31 05 51 32 05 51 33 05 51 33 05 51 31 05 51 32 05 51 33 05 51 31 05 51 32 05 51 33 05 51 33 05 51 31 05 51 32 05 51 33 05 51 33 05 51 33 05 51 33 05 51 34 06 51	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-05 July-05 July-05 October-05 March-06 October-05 December-05 May-07 March-08 May-07 November-06 January-07 March-07 March-07 April-07	E60/E63 E61 E70 (X5) E60/E63 E60/E63 E60/E61 (xi, xiT) E60/E63 E60 E90 E90 E90 E90 E90 E90 E90 E90 E90 E9	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floor Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position Cracking or Ticking Noise from Lower B-Pillar Center Console Heats Up In Knee Contact Area (Supercedes Nov 05) Clicking Noise from Upper B-pillar Trim Water Ingress from A/C Blower Housing The cup holder jams when retracted Anti-trap is Activated when Raising the Front Window (rpl 2/06) Outside Door Handles Hanging up in the Pulled Position (rpl 2/08) Interior Door Grab Handle Finish Peeling (rpl 8/06) Luggage Compartment Roller Cover Maffunction Rattle Noise from B-Pillar Trim Service Action: Replace Underbody Panel Erroneous Trunk Lid Open Check Control Message Rear Window will not Fully Defrost
Suspension Suspension Suspension Suspension Suspension Suspension Suspension Suspension Body Body Body Body Body Body Body Bod	37 02 05 37 01 06 37 01 06 37 01 07 37 02 07 37 03 07 41 01 05 41 05 06 41 02 07 41 01 08 01 other model 51 13 04 51 02 05 51 04 05 51 04 05 51 17 05 51 30 05 51 31 05 51 32 05 51 33 05 51 33 05 51 37 05 51 10 06 51 14 06 51 14 06 51 14 06 51 14 06 51 12 07 51 08 07 51 10 07 51 10 07	August-05 March-06 November-07 October-07 January-08 May-05 February-06 October-07 April-08 August-07 February-07 June-05 July-05 October-05 March-06 October-05 October-05 December-05 May-07 March-08 May-07 November-06 January-07 March-07 May-07	E60/E63 E61 E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E70 (X5) E60/E63 E60/E63 E60/E63 E60 E60/E61 (xi, xiT) E60/E63 E90	Anti-Roll Stabilization Noise Chafed Ride Height Sensor Cable Knocking Noise from Front Suspension The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs Structural Aluminum Repair Precautions Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area Rear Door Brake Connection Pulls out of the B-pillar Rattling Noise from Center Display (Replaces 06/07) Squeaking Noise from Door Frame area While Driving (Replaces 12/06) Incorrect or Missing Floro Mats (deliveries before May 16, 05) Door Mirror Glass Discolored after Programming Replacement Windshield - VIN Window in Wrong Position Cracking or Ticking Noise from Lower B-Pillar Center Console Heats Up In Knee Contact Area (Supercedes Nov 05) Clicking Noise from Upper B-pillar Trim Water Ingress from A/C Blower Housing The cup holder jams when retracted Anti-trap is Activated when Raising the Front Window (rpl 2/06) Outside Door Handles Hanging up in the Pulled Position (rpl 2/08) Interior Door Grab Handle Finish Peeling (rpl 8/06) Luggage Compartment Roller Cover Malfunction Rattle Noise from B-Pillar Trim Service Action: Replace Underbody Panel Erroneous Trunk Lid Open Check Control Message Rear Window will not Fully Defrost Service Action: Install Luggage Compartment Labels

Title

Category	SIBS (SI B## ## ##)	Date	Application	<u>Inte</u>
Body Equipment	51 17 07	July-07	E93	Rear Window(s) Inoperative
Body Equipment	51 19 07	November-07	E90	Doors will not Unlock Using the Key Fob or Central Locking Button (rpl 09/07)
Body Equipment	51 22 07	September-07	E91	Creaking Noise from the C-Pillar Area
Body Equipment	51 24 07	November-07	E93	Water Leaks into the Sides of the Luggage Compartment
Body Equipment	51 25 07	November-07	3 series	Floor Mat Retainer in Wrong Location
Body Equipment	51 28 07	December-07	E93	Compass Changes Direction when Operating the RHT
		December-07	E61	
Body Equipment	51 29 07			Luggage Compartment Roller Cover Symptom Diagnosis
Body Equipment	51 30 07	December-07	E91	Noises from the Roller Cover Retainers
Body Equipment	51 31 07	December-07	E70 (X5)	Tailgate Soft-close Malfunction
Body Equipment	51 32 07	January-08	E70 (X5)	Rattle from the Upper Tailgate Trim
Body Equipment	51 35 07	January-08	E70 (X5)	Tailgate Latch Noisy when Closing
Body Equipment	51 02 08	February-08	3 series	Compass is Difficult to Read at High Temperatures
	51 03 08	February-08	E91	Luggage Compartment Roller Cover Symptom Diagnosis
Body Equipment				
Body Equipment	51 04 08	April-08	E93	RHT Rear Roof Shell Headliner Eliminated
Body Equipment	51 05 08	April-08	E60/63	Door Opening/Closing Symptom Diagnosis
Body Equipment	51 06 08	May-08	1 Series	Window Short-drop or Anti-trap Malfunctions
Body Equipment	51 07 08	May-08	E93	Rear Windows Inoperative After Junction Box Replacement
Body Equipment	51 08 08	May-08	E60/63	Power Window Drives: Symptom Diagnosis
Body Equipment				Instrument Panel Symptom Diagnosis
	51 09 08	May-08	1 Series	
Body Equipment	51 10 08	May-08	E60/63	Noises from the Front Doors - Symptom Diagnosis
Body Equipment	51 11 08	May-08	E63	Water Ingress at the Doors: Symptom Diagnosis
Body Equipment	51 12 08	May-08	1 Series	Rattle from the Armrest Hinge
Body Equipment	51 16 08	June-08	3 series	Hood Insulation Pad Discontinued
Body Equipment	51 18 08	June-08	3 series	Instrument Panel Symptom Diagnosis
			X3	
Body Equipment	51 20 08	July-08		Doors Will Not Unlock with the Remote or Central Locking Switch
Body Equipment	51 21 08	July-08	1 Series vert	Squeak from Rear Trim with the Convertible Top Open
Body Equipment	51 23 08	July-08	1 Series vert	Clicking Noise from the Bottom of the A-pillar
Body Equipment	51 25 08	September-08	1 Series	Buzzing Noise from the Center Vent Area
		-		
Seats	52 02 04	April-05	E60/E63	Recall Campaign 04V-575: Modification of the Front Seat Heater Circuit
Seats	52 05 07	August-07	E93	Lumbar Support Inoperative
Seats	52 01 08	February-08	E60/E61	Active Backrest Width Adjustment Inoperative
Seats	52 02 08	January-08	Z4	Knocking Noise from the Seat Frame
Seats	52 03 08	March-08	X5	Lateral Seat Movement and/or Noises
Seats	52 04 08	June-08	E93	Backrest Seat Cover Material Loose
Seats	52 05 08	June-08	E92	Seat Frame Design Change
Seats	52 06 08	August-08	1/3 series	Raised Area on the Seat Bottom
	01, 02, 04-07 all X5			
Special Roofs	54 03 05	July-05	E64 (Cabrio)	Convertible Top will not Lower
Special Roofs	54 13 06	May-06	È60	SHD Coding Error - Progman V21.1
Special Roofs	54 17 06	November-06	E64 (Cabrio)	Convertible Top Does Not Completely Open or Close
	54 01 07		E93	
Special Roofs		July-07		Service Action: Replace Roof Shell Trim Strips (rpl 4/07)
Special Roofs	54 02 07	April-07	E93	RHT Opens but Trunk Lid will not Close
Special Roofs	54 03 07	April-07	E93	Convenience Open/Close Function
Special Roofs	54 06 07	July-07	E93	Roof Shell 1 Slams Down on the Cowl when Closing the RHT (rpl 5/07)
Special Roofs	54 08 07	May-07	E93	RHT Statuses Reversed in DIS/GT1
Special Roofs	54 09 07	June-07	E93	RHT Status Request Supplement
Special Roofs	54 10 07	August-07	E93	RHT Stops Opening in the Stacked/Extended Position
Special Roofs	54 11 07	September-07	E93	Headliner is Loose in the C-pillar Area
Special Roofs	54 12 07	September-07	E93	Rattle from the Front Latch of the RHT
Special Roofs	54 15 07	November-07	E93	RHT Symptom Diagnosis Update
Special Roofs	54 16 07	November-07	E93	Headliner Loose Near A-pillar
Special Roofs	54 17 07	January-08	E93	Headliner Fabric is Creased and/or Stretched
Special Roofs	54 01 08	January-08	E61/91	Wind Noise from the Panoramic Sunroof
Special Roofs	54 02 08	January-08	E60	Water Leak from Sunroof
Special Roofs	54 03 08	February-08	E93	RHT Seal Replacement Update
Special Roofs	54 04 08	June-08	E93	Wind Buffeting/Pressure Noise at Highway Speeds
Special Roofs	54 05 08	March-08	E83 (X3)	Rattle from Panoramic Roof when Fully Open
Special Roofs	54 06 08	May-08	(E70) X5	Clicking Noise From Sunroof
Special Roofs	54 07 08	June-08	E88 (1 Series)	Convertible Top Material Loose at Rear Bow
				·
Special Roofs	54 08 08	August-08	(E70) X5	The Sunroof's Rear Glass Panel Does Not Close from the Vent Position
Special Roofs	54 09 08	August-08	E93	Cleaning Excess Butyl from RHT Roof Shells
Special Roofs	54 11 08	August-08	All w/Pan Roof	TeileClearing for Panoramic Roof
	18, 19 other model			
	- ,			
Conoral Floatrical Systems	61.07.00	Docomber 06	AII	Battery Maintenance Requirements (Replaces 10/06)
General Electrical Systems	61 07 88	December-06	All	
	61 08 00	June-07	All	Closed-Circuit Current Measurement (Replaces 1/07 - new cars)
General Electrical Systems	04.45.00	February-06	E60/E63	MOST Bus Diagnosis (Supercedes July 04 with new diagnostics & models)
General Electrical Systems General Electrical Systems	61 15 02		E60/E63	MOST Bus Diagnosis Description
		P/O 61 15 02	E0U/E03	
General Electrical Systems General Electrical Systems	B611502F_Description.			
General Electrical Systems General Electrical Systems General Electrical Systems	B611502F_Description. B611502ChartsA&B.	P/O 61 15 02	E60/E63	MOST Bus Diagnosis Troubleshooting Chart
General Electrical Systems General Electrical Systems General Electrical Systems General Electrical Systems	B611502F_Description. B611502ChartsA&B. 61 03 03	P/O 61 15 02 January-06	E60/E63 E60/E63	MOST Bus Diagnosis Troubleshooting Chart CAN/Byteflight Bus Diagnostics (Supercedes June 05 - Adds E61 & E91)
General Electrical Systems General Electrical Systems General Electrical Systems	B611502F_Description. B611502ChartsA&B.	P/O 61 15 02	E60/E63	MOST Bus Diagnosis Troubleshooting Chart

Application

Category

SIBs (SI B## ## ##)

Date

Category	SIBs (SI B## ## ##)	<u>Date</u>	Application	<u>Title</u>
General Electrical Systems	61 01 04	June-05	E65	CIP 17.01 - MY02-05 various complaints
General Electrical Systems	61 01 04	September-06	E65	Various Complaints Caused by Software Errors (21.02.01) (Supercedes Mar 06 / CIP 20.00)
General Electrical Systems	61 01 05	December-05	E60/E63	Special Survey for CAS related problems (Supercedes Apr 05 - Survey completed)
General Electrical Systems	61 03 05	October-07	E90	CIP 27.00.00 - Software errors corrected with PROGMAN (Rpl 25.01.00 4/07)
General Electrical Systems	61 06 05	September-05	E60	High Drain Battery Message in CIP (N52 Engine)
General Electrical Systems	61 07 05	January-06	E60/E63	PDC Light Flashing after SZM Replacement (Supercedes info in August 05)
General Electrical Systems	61 08 05	August-05	E90	Roof Functions Center Causes Various System Malfunctions
General Electrical Systems	61 09 05	August-05	E90	Remote Key Sticks In/Falls Out of CAS Holder
General Electrical Systems	61 10 05	August-05	E90	Various Electrical Problems
General Electrical Systems General Electrical Systems	61 11 05 61 12 05	October-05 November-05	E60 E60/E63	Battery Safety Terminal Dead Battery by MPM
General Electrical Systems	61 13 05	May-08	E60/E63	Dead Battery - Perform Energy Diagnosis (update to 10/07 - added models)
General Electrical Systems	61 01 06	February-06	E90	Trunk Opens without Request
General Electrical Systems	61 02 06	February-06	E60/E63/E90	Key Falls Out of, or Gets Stuck in Key Holder (Supercedes 2/06 adding models)
General Electrical Systems	61 04 06	February-06	ALL	Exiting a Vehicle that is Double-Locked from the Outside
General Electrical Systems	61 05 06	September-07	E65	Various Customer Complaints Corrected With Progman
General Electrical Systems	61 06 06	May-06	E90	Junction Box Pin Assignment Change
General Electrical Systems	61 07 06	August-06	E60/E63/E90	No Crank, No Start, CAS FC A111
General Electrical Systems	61 10 06	October-06	E63	Windows Convenience Open When Door is Opened
General Electrical Systems	61 13 06	October-06	E60	Various Electrical Problems Caused by Water Ingress
General Electrical Systems	61 14 06	October-06	E60/E63	One-Touch Close Inoperative after Door Module Replacement
General Electrical Systems	61 15 06	October-06	E64	Rear Windows Close First, or Anti-trap Activates During Convenience Closing
General Electrical Systems	61 20 06	October-06	E60	Rear Windows Move in Small Increments
General Electrical Systems	61 22 06	October-06 October-06	E60 E60	iDrive Controller Malfunction (Low Version)
General Electrical Systems General Electrical Systems	61 23 06 61 24 06	October-06	E60	Battery Charger Causes Faults to be Set Starts only once following EWS calibration
General Electrical Systems	61 26 06	September-06	E90	Central Electronics Failure, K-CAN bus Fault Codes Stored
General Electrical Systems	61 27 06	October-06	E92	Replacement CAS3 - Calibration Error Message
General Electrical Systems	61 28 06	May-07	E92	Red ELV Warning in Instrument Cluster (Replaces 1/07)
General Electrical Systems	61 29 06	April-08	E60/E63/E90	CAS / ELV Diagnostics (rpl 10/07)
General Electrical Systems	61 31 06	September-07	X5	Software Errors Corrected with Progman (update to 5/07) PROGMAN 27.01.00
General Electrical Systems	61 32 06	December-06	E90/91/92	Sunroof Moves in Small Steps or Interior Lights not Working
General Electrical Systems	61 33 06	December-06	E60/E63/E90	Battery Warning Displayed when Deleting Transport Mode
General Electrical Systems	61 34 06	August-07	E90/91/92	Engine Fails to Start after CAS Replacement (update to 9/06)
General Electrical Systems	61 04 07	May-07	E60/E63	SZL Functions Lock Up after Deleting Transport Mode
General Electrical Systems	61 08 07	August-07	E60/E63	Electric Steering Lock Inoperative
General Electrical Systems	61 09 07	August-07	E60/E65/E90	OBD Socket Housing Cover Missing
General Electrical Systems	61 12 07	November-07	E90	No Crank after CAS3 Replacement
General Electrical Systems	61 13 07	November-07 December-07	E70 (X5)	Electronic Malfunction CC Message Caused by Shorted Wiring
General Electrical Systems General Electrical Systems	61 14 07 61 01 08	January-08	E60/E63 E60/E63/E90/E70	Battery Discharged KGM FC 93AB MPM Relay Sticking CC Message "Increased battery discharge while stationary"
General Electrical Systems	61 02 08	February-08	3 series	Gong Warning Without Visual Check Control Message
General Electrical Systems	61 03 08	February-08	E93	Doors Will Not Lock Using Comfort Access Handles
General Electrical Systems	61 05 08	May-08	Service Center	TeileClearing for General Electrical Systems
General Electrical Systems	61 05 08	May-08	E90/91/92	Windshield Wiper Parks out of Position
General Electrical Systems	61 06 08	May-08	X5/X6	Sliding Sunroof, Interior Lights, and Rain Sensor Are Inoperative
General Electrical Systems	61 07 08	June-08	E60	Rear Window Functional Problems
General Electrical Systems	61 09 08	August-08	1, 3, X5, X6	Controller Fault Code A2CB Internal Control Module Fault
General Electrical Systems	61 10 08	August-08	3 Series w/DCT	CAS3 Fault Code A0B1
General Electrical Systems	61 11 08	August-08	E60/61	Steering Wheel or Seat Adjustment Inoperative
General Electrical Systems	61 12 08	August-08	1 & 3 Series	Sliding Sunroof, Interior Lights, and Rain Sensor Are Inoperative
	01, 02, 03 , 05, 06, 07, 10, 11 X5 or other	models		
Instruments	62 01 06	May-07	E60/E63	Instrument Cluster Needles Vibrate (Replaces 1/07)
Instruments	62 02 06	May-06	E60/E63	Engine Oil Level Menu Option is Displayed After Reprogramming
Instruments	62 04 06	October-06	E60/E63	Instrument Cluster: Failure of Displays/Functions
Instruments	62 01 07	January-07	E90/92	Warning Chime Inoperative for Check Control and/or Directionals
Instruments	62 02 07	January-07	E60/E63/E92	No Communication or Diagnosis Possible With Instrument Cluster
Instruments	62 03 07	May-07	E90/92	On-Board Computer Functions Cannot Be Displayed (rpl 1/07)
Instruments	62 06 07	March-07	BMW Centers	Check Control Messages (With PDF list)
Instruments Instruments	62 07 07 62 01 08	May-08 May-08	E70 (X5)/E71 (X6) 1 Series	TeileClearing (Enhanced Technical Support) for Instrument Cluster Cruise Control Display in Instrument Cluster Increments Incorrectly
Instruments	62 01 08 62 02 08	August-08	M3 w/DCT	Instrument Cluster Center Displays Go Blank
Instruments	62 04 08	September-08	E6x	Instrument Cluster Mileage Display Switches to Kilometers when Key Is Switched
monuments	02 04 00	ocptember oo	Lox	matument officer mileage propriay officines to fallometers when hely to officine
	04 07 note to dealer 05 - 09 other models			
Lighto	62.02.04	July 04	E60	Poplace Lamp Module
Lights Lights	63 02 04 63 02 05	July-04 June-05	E60	Replace Lamp Module Brake Force Display (BFD) Inoperative
Lights	63 03 05	July-05	E60	Eyebrow Lights are Inoperative after Programming
Lights	63 05 05	September-05	E64 Cabrio	Third Brake Light Cracked
Lights	63 06 05	November-05	E60	Service Action: Check the Adaptive Headlights for Proper Operation
Lights	63 01 06	May-06	Z4	Front Lighting Configuration
Lights	63 05 06	October-06	E60/E63	Automatic Headlamps: Lights Do Not Switch Off

				Compiled and called by cobladat
Category	SIBs (SI B## ## ##)	Date	Application	<u>Title</u>
Lights	63 06 06	October-06	E60	LED Flashing On Headlight Switch, No Faults Stored
Lights	63 08 06	October-06	E60	Lights Flash Briefly When Vehicle Wakes Up; Battery May Become Discharged
		October-06		
Lights	63 09 06		E60	Brake Lighting Pulsates Intermittently
Lights	63 12 06	October-06	E63	Adaptive Headlamp Does Not Turn
Lights	63 13 06	October-06	E60/E63	Automatic Headlamp System Does Not Switch Off the Lights
Lights	63 15 06	October-06	E60	Headlamp Leak (Replaces 12/04)
Lights	63 16 06	November-06	E60	3rd Brake Light Comes Loose From Rear Window
Lights	63 17 06	January-07	E60/63/90	Eyebrow Lights are Inoperative after Programming (Replaces 12/06)
Lights	63 02 07	January-07	E90/91/92	Bulb Out Symbol Displayed in BC
Lights	63 03 07	February-07	E90/91/92	Daytime Running Lights are Inoperative
Lights	63 04 07	March-07	E60/E63	Fault Code 9CAD in LM
Lights	63 06 07	April-07	E92/93	Cornering lights failure Displayed in Check Control
Lights	63 13 07	August-07	E90/91/92	Headlight Vibrations
Lights	63 15 07	October-07	E70 (X5)	Interior Light Switch Illumination
Lights	63 16 07	December-07	E60/E63	Option Code 08S4 - Variable Light Decoding
Lights	63 01 08	March-08	E63/E64	Side Marker Lamp not Working in Conjunction with Welcome Light
Lights	63 02 08	March-08	E92/93	Rear Bulb Failure
Lights	63 03 08	March-08	3 Series	Flashlight Deleted as a Running Change
Lights	63 04 08	June-08	1/3/5/6/7/X series	Headlamp Moisture: Fault Diagnostics
Lights	63 05 08	May-08	E60	CC Message Missing/Incorrect when Front Parking Light Faulty
Lights	63 06 08	July-08	X3	Bulb-Out Warning, FC 2F or 3E
Lights	63 07 08	August-08	E60/E63	Adaptive Headlights Intermittently Inoperative (SW fix coming in Oct)
Lights	63 08 08	August-08	X5 (E70)	Contact Between Inner and Outer Rear Lamps
Lights	63 09 08	August-08	Х3	Interior Lamps "Soft ON/OFF" Inoperative
	08 09 for X5 (E63 and E70) 07 NU			
Heating and Air Conditioning	64 08 91	October-06	All	Musty Odors
Heating and Air Conditioning	64 02 05	August-05	E64 (Cabrio)	Poor Temperature Regulation from Center Vents
Heating and Air Conditioning	64 03 05	June-08	E60/E63	Air Conditionaing Delayed Startup (Supercedes 4/07 w/new info)
Heating and Air Conditioning	64 04 05	August-07	E60/E63	Air Conditioning Stops Cooling after Long Drive (Replaces 12/06)
Heating and Air Conditioning	64 21 05	May-08	All	Troubleshooting Air Conditioning Compressor Noise (Supercedes Dec 06)
Heating and Air Conditioning	64 01 06	January-06	E60	Blower Motor Stays On with Key Off
Heating and Air Conditioning	64 02 06	June-06	E60	Water Droplets are Blown from Center Vents with A/C On (Supercedes Jan 06)
Heating and Air Conditioning	64 04 06	May-07	E90	Air Conditioning Does not Cool (Replaces 1/07)
Heating and Air Conditioning	64 06 06	May-06	E90	Front Defroster Performance Poor at Mid-Blower Speeds
Heating and Air Conditioning	64 07 06	May-07	E90	Air Conditioning System does not Cool (Refrigerant Charge Good) (rpl 6/06)
Heating and Air Conditioning	64 09 06	October-06	E90	Air Conditioning System Blows Warm Air After Long Drive (Replaces 8/06)
Heating and Air Conditioning	64 10 06	July-06	E60/61	Water Droplets Blown from Right Side Center Vents with A/C On
Heating and Air Conditioning	64 14 06	November-07	E60/61	A/C Compressor Noise "Droning, Howling or Ticking" at Low Engine Speed (update to 10/06)
Heating and Air Conditioning	64 03 07	October-07	E92	Banging Noise from Air Conditioner Compressor (update to 3/07)
Heating and Air Conditioning	64 04 07	May-08	All	Heating and Air Conditioning Symptom Diagnosis (update to 1/08)
Heating and Air Conditioning	64 06 07	May-08	E60/E63	Air Conditioning Compressor Does Not Switch On
Heating and Air Conditioning	64 08 07	August-07	All	Important Information about Heating and Air Conditioning
Heating and Air Conditioning	64 10 07	January-08	E60/E63	Air Conditioning Delayed Startup
Heating and Air Conditioning	64 12 07	June-08	3 Series	White Flakes/Powder Coming from the Air Conditioning Vents
Heating and Air Conditioning	64 13 07	February-08	3 Series	CID or IHKA Total Failure Because F61 Blown
Heating and Air Conditioning	64 14 07	November-07	E70 (X5)	Water Leak on Carpet During Air Conditioning Usage
Heating and Air Conditioning	64 02 08	June-08	1 & 3 Series	Whistling from the Heating/Air Conditioning Unit at Speeds over 50 MPH
Heating and Air Conditioning	64 03 08	August-08	All	TeileClearing for Air Conditioning Systems
Heating and Air Conditioning	64 04 08	September-08	E70 (X5)	Different Delivery Temperature from Each Side of the Rear Compartment Blower
	07 09 for (X5)			
Audio, Navigation, Monitors, Alarms, SR	65 06 04	July-04	E60/E63	Consumption Set to mpg UK instead of mpg US
Audio, Navigation, Monitors, Alarms, SR	65 10 04	January-05	E60/E63	Audio Stays On
Audio, Navigation, Monitors, Alarms, SR	65 01 05	June-05	E90	Radio Seek/Scan Inoperative
Audio, Navigation, Monitors, Alarms, SR	65 02 05	April-06	E60/E63/E90	SIRIUS Satellite Radio - General Info (Supercedes May 05 - Added E90)
Audio, Navigation, Monitors, Alarms, SR	65 06 05	July-05	E60/E63	CID Fault Analysis Guide
			E90	
Audio, Navigation, Monitors, Alarms, SR	65 07 05	April-06		MOST Bus is Inoperative or Central Information Display has Reduced Brightness (Jul 05)
Audio, Navigation, Monitors, Alarms, SR	65 08 05	October-05	E90	Temperature Display in RAD2 Shows Dashes
Audio, Navigation, Monitors, Alarms, SR	65 09 05	February-06	E60/E63/E90	No Audio Sound in any Mode (Supercedes Aug 05 with new info)
Audio, Navigation, Monitors, Alarms, SR	65 10 05	November-07	E60/E63/E90	CCC: Loss of all Audio (update to 8/06)
Audio, Navigation, Monitors, Alarms, SR	65 16 05	September-05	E60/E63/E90	RDS Function Causes Confusing Station Names when in "All stations" Screen
Audio, Navigation, Monitors, Alarms, SR	65 18 05	January-06	E60/E63/E90	MP3 Compatibility Overview (Supercedes October 2006)
Audio, Navigation, Monitors, Alarms, SR	B651805MP3_Compatibility_Chart	P/O 65 18 05	E60/E63/E90	MP3 Compatibility Chart
Audio, Navigation, Monitors, Alarms, SR	65 19 05	October-05	E60	Weather Band Available on Multi Audio System Controller
Audio, Navigation, Monitors, Alarms, SR	65 20 05	January-06	E90	RAD2 - CD Mode Malfunctions (In-Dash CD skips or does not play - Business Radio)
Audio, Navigation, Monitors, Alarms, SR		March-07	E63/E64	SIRIUS Satellite Radio Cuts Out in Certain Geographic Areas (May 06 -)
	65 21 05			
Audio, Navigation, Monitors, Alarms, SR	65 22 05	November-05	E60	' Favorites' Function is Selectable in the Entertainment Menu
Audio, Navigation, Monitors, Alarms, SR	65 23 05	November-05	E60	Disclaimer Screen Disappears Automatically after 10 Seconds
Audio, Navigation, Monitors, Alarms, SR	65 24 05	October-05	E60/E63/E90	Static Between Words on AM Radio
Audio, Navigation, Monitors, Alarms, SR	65 25 05	August-07	E60/E63	HD-Radio™- Functionality and Diagnosis (Supercedes Mar 07)
Audio, Navigation, Monitors, Alarms, SR		March-06	E60/E63/E90	Audio Switches off Briefly when Listening to FM Stations (Supercedes Jan 06 w/new info)
Audio, Navigation, Monitors, Alarms, SR	65 26 05			
Audio, Navigation, Monitors, Alarms, SK		November-05	E60/E63/E90	CID Screen Image Not Displayed Correctly Since CCC Replacement
	65 27 05	November-05	E60/E63/E90	CID Screen Image Not Displayed Correctly Since CCC Replacement
Audio, Navigation, Monitors, Alarms, SR	65 27 05 65 28 05	November-05 March-06	E60/E63/E90 E60/E63/E90	CID Screen Image Not Displayed Correctly Since CCC Replacement CCC: Radio Station Preset List Intermittently Empty (Supercedes Nov 05)
	65 27 05	November-05	E60/E63/E90	CID Screen Image Not Displayed Correctly Since CCC Replacement

<u>Category</u> Audio, Navigation, Monitors, Alarms, SR	SIBs (SI B## ## ##) 65 32 05	<u>Date</u> March-07	Application E60/E63/E90	Title CCC: CD/CDC Track Counter Advances After Mute Selected(Replaces 1/07)
Audio, Navigation, Monitors, Alarms, SR	65 02 06	March-06	E60/E63/E90	CCC: Loss of Audio in All Modes (Supercedes Feb 06)
Audio, Navigation, Monitors, Alarms, SR	65 04 06	March-06	E60/E63/E90	KL-R Stays On After Ignition Off – Comfort Access Only
Audio, Navigation, Monitors, Alarms, SR	65 05 06	April-06	E60/E63/E90	CCC: CD Drive Errors
Audio, Navigation, Monitors, Alarms, SR	65 06 06	November-07	E60/E63/E90	Various Problems with CCC Following Replacement (update to 4/06)
Audio, Navigation, Monitors, Alarms, SR	65 08 06	September-06	E60/E63/E90	CCC with Top HiFi Loses Surround Sound after Navigation Announcement (Supercedes May 06)
Audio, Navigation, Monitors, Alarms, SR	65 10 06	May-06	E60/E63/E90	New Audio-Test-CD for Diagnosing a Faulty CD/Audio-DVD Drive or Media
Audio, Navigation, Monitors, Alarms,	65 12 06	July-08	E60/E63/E90	Popping/Crackling Noise from Audio System (rpl 12/06)
Audio, Navigation, Monitors, Alarms, SR	65 16 06	September-06	E60/E63	CCC: Acoustic Warning Gong Sounds at Times, No CC Message
Audio, Navigation, Monitors, Alarms, SR	65 18 06	October-06	E63/E64	DWA (Theft Deterant System) Causes Excessive Closed Circuit Current Draw
Audio, Navigation, Monitors, Alarms,	65 25 06	August-08	ALL w / CCC	Enhanced Technical Support for Audio System (Replaces 6/07)
Audio, Navigation, Monitors, Alarms, SR	65 26 06	October-06	E60/E63/E90	CCC Disclaimer Screen Disappears Automatically after 10 Seconds
Audio, Navigation, Monitors, Alarms, SR	65 27 06	October-06	E60/E63/E90	CCC Does Not Play All MP3 Formats
Audio, Navigation, Monitors, Alarms, SR	65 28 06	October-06	E60/E63/E90	CCC Radio Station RDS Information Missing After Programming
Audio, Navigation, Monitors, Alarms, SR	65 29 06	April-07	E60/E63/E90	CCC Next Entertainment Source Not Selectable Via MFL (rpl 10/06)
Audio, Navigation, Monitors, Alarms, SR	65 33 06	December-06	E60/E63/E90	CD Changer is Inoperative; Magazine is Jammed or Broken
Audio, Navigation, Monitors, Alarms, SR	65 35 06	June-07	E60	Poor Radio Reception in FM Mode (rpl 12/06)
Audio, Navigation, Monitors, Alarms, SR	65 36 06	August-07	E60	Poor Radio Reception in AM Mode (rpl 6/07)
Audio, Navigation, Monitors, Alarms, SR	65 37 06	December-06	E60	RDS Function
Audio, Navigation, Monitors, Alarms, SR	65 43 06	May-07	E60/E63/E90	CCC: High Frequency Noises from the DVD drive (rpl 12/06)
Audio, Navigation, Monitors, Alarms, SR	65 44 06	December-06	E60/E63/E90	CCC: AUX-IN Loud Hissing if no Device Connected
Audio, Navigation, Monitors, Alarms, SR	65 45 06	December-06	E60/E63/E90	CCC: Poor Radio Reception after Software Update
Audio, Navigation, Monitors, Alarms, SR	65 46 06	May-07	E60/E63/E90	CCC: Radio Continues to Play after Ignition off (rpl 12/06)
Audio, Navigation, Monitors, Alarms, SR	65 48 06	December-06	E60/E63/E90	SIRIUS Satellite Radio Is No Longer Accessible
Audio, Navigation, Monitors, Alarms, SR	65 01 07	March-07	E60/E63/E90	CID Changes Introduced March 2007
Addio, Navigation, Monitors, Atlantis, Ore	65 01 07_CCC_Display_Changes	March-07	E60/E63/E90	M-ASK also available
Audio, Navigation, Monitors, Alarms, SR	65 03 07	April-07	E60/E63/E90	CCC: Slow Response from System when using Controller (Rpl Jan 07)
Audio, Navigation, Monitors, Alarms, SR	65 04 07	January-07	E90/91	SDARS Sirius Radio is Inoperative After Programming
Audio, Navigation, Monitors, Alarms, SR	65 06 07	March-07	All CCC equipped	CCC Symptom Troubleshooting
Audio, Navigation, Monitors, Alarms,	65 07 07	March-08	E60/E63/E90/E92	SDARS SIRIUS Radio is Intermittently Inoperative
Audio, Navigation, Monitors, Alarms,	65 08 07	May-08	E60/E63/E90/E92	USB Audio Interface
Audio, Navigation, Monitors, Alarms, SR	65 15 07	May-07	E90/91	Airbag Warning Lamp Illuminated, FC 93C1/93C3
Audio, Navigation, Monitors, Alarms, SR	65 18 07	January-08	E64 Cabrio	Radio or Speakers Inoperative (rpl 6/06)
Audio, Navigation, Monitors, Alarms,	65 19 07	May-07	E63/E64	Recall Campaign 07V-178: Replace the Seat Occupancy Detection Mat
Audio, Navigation, Monitors, Alarms, SR	65 21 07	January-08	E93	Whistling Noise From the Radio in AM Mode Only
Audio, Navigation, Monitors, Alarms, SR	65 22 07	August-07	E60/E63/E90/E92	CCC CD Text not Updated When CD is Swapped
Audio, Navigation, Monitors, Alarms, SR	65 23 07	August-07	E60/E63/E90/E92	CCC Navigation Displays Incorrect Vehicle Position
Audio, Navigation, Monitors, Alarms, SR	65 24 07	August-07	E60/E63/E90/E92	CCC Navigation Map DVD not Detected
Audio, Navigation, Monitors, Alarms, SR	65 25 07	November-07	E60	Recode or Replace OC3 Seat Mat
Audio, Navigation, Monitors, Alarms,	65 26 07	June-08	E60/E63/E90/E92	CCC: Volume Differences between CD\AUX and FM after Programming
Audio, Navigation, Monitors, Alarms, SR	65 27 07	December-07	X5 (E70)	Airbag Warning Lamp Illuminated - FC 93D2
Audio, Navigation, Monitors, Alarms, SR	65 28 07	September-07	E60/E63/E90/E92	CCC: Radio Does Not Resume With Previously Selected Station
Audio, Navigation, Monitors, Alarms, SR	65 30 07	October-07	E90/91/92/93/E70	iPod Mode is Switching to FM Mode
Audio, Navigation, Monitors, Alarms, SR	65 31 07	September-07	E60/E70	CHAMP: Intermittently No Audio Output in FM Mode Only After Restart
Audio, Navigation, Monitors, Alarms, SR	65 32 07	December-07	X5 (E70)	Rear Seat Entertainment System (RSE) is Not Working Correctly
Audio, Navigation, Monitors, Alarms,	65 33 07	August-08	X5 (E70)	Airbag Warning Illuminated, FC 93D2
Audio, Navigation, Monitors, Alarms, SR	65 34 07	November-07	E90/91/92/93	Service Action: Program the MULF2-High Control Module
Audio, Navigation, Monitors, Alarms, SR	65 35 07	December-07	X5 (E70)	No Audio Output After Turning the Ignition On
Audio, Navigation, Monitors, Alarms, SR	65 36 07	January-08	E60/E63	Radio Turns Off After 8 Minutes and Time and Date Display is Cleared (rpl 12/07)
Audio, Navigation, Monitors, Alarms, SR	65 37 07	November-07	E93	No AM Reception During Convertible Top Operation
Audio, Navigation, Monitors, Alarms, SR	65 39 07	December-07		CCC Navigation Not Working -September 24, 2007 to October 29, 2007
Audio, Navigation, Monitors, Alarms,	65 41 07	July-08		CCC Loss of Audio and CID Blanks Out (rpl 01/08
Audio, Navigation, Monitors, Alarms, SR	65 42 07 65 01 08	January-08	All w/Alarm All w/SAT RAD	Alarm Triggers Unexpectedly - Troubleshooting
Audio, Navigation, Monitors, Alarms, SR		May-08	All w/6FL (USB)	SIRIUS Radio Stations Missing in "All Channels" List
Audio, Navigation, Monitors, Alarms, S Audio, Navigation, Monitors, Alarms, SR	65 02 08 65 03 08	August-08 March-08	3 & 5 Series	iPod Classic Doesn't Get Charged through USB Connection Interference with Radio Reception on all Bands (FM, AM, HD Radio)
Audio, Navigation, Monitors, Alarms, SR Audio, Navigation, Monitors, Alarms, SR	65 04 08	April-08	All w/SAT RAD	Call SIRIUS Is Displayed
Audio, Navigation, Monitors, Alarms, SR	65 05 08	April-08	7 Series	SIRIUS Radio Station List Is Not Displayed in the RSE Monitor
Audio, Navigation, Monitors, Alarms, SR Audio, Navigation, Monitors, Alarms, SR	65 05 08 65 06 08	April-08	1 & 3 series	RAD2: The Audio Volume is Briefly Muted or Reduced
Audio, Navigation, Monitors, Alarms, SR Audio, Navigation, Monitors, Alarms, SR	65 07 08	April-08	3 series	USB Device Is Not Detected
Audio, Navigation, Monitors, Alarms, SR	65 08 08	May-08	3 series	Fault Code "E190" stored in the RAD2 GW
Audio, Navigation, Monitors, Alarms, SR	65 10 08	May-08	1 & 3 Series	RAD2: Intermittently No Audio after Check Control Message
Audio, Navigation, Monitors, Alarms, SR	65 11 08	May-08	All w/6FL	iPod Classic is Discharged after an Extended Period of Inactivity
Audio, Navigation, Monitors, Alarms, SR	65 12 08	June-08	E60	SRS Warning Lamp Illuminated, but No Fault Codes Stored
, rangaton, montoro, radino, ore	00 .2 00	04.10 00	200	The state of the s

01, 11, 14, 20 other model, 05, 09, 10, 12, 13, 29, 38, 40 NU,

Distance Systems, Cruise Control, Remo	- 01 other model		E65	
Distance Systems, Cruise Control, Remo	66 01 04	March-08	X3	315MHz Remote Control Range Is Inadequate or Inoperative
Distance Systems, Cruise Control, Remo	66 03 05	November-05	E60/E63	PDC and Gong Volume Cannot be Adjusted
Distance Systems, Cruise Control, Remo	66 01 06	February-06	E90	PDC Button not Installed (Supercedes Feb 06 with added info)
Distance Systems, Cruise Control, Remo	66 04 06	March-07	E60/E63	Night Vision Malfunctions and Parts Replacement (update to 11/06)
Distance Systems, Cruise Control, Remo	66 05 06	September-06	E61	Vehicle Does Not Start
Distance Systems, Cruise Control, Remo	66 07 06	December-06	All	Remote Control Key Not Working
Distance Systems, Cruise Control, Remo	66 02 07	March-07	All	Comfort Access: Replacement ID Transmitter Initialization
Distance Systems, Cruise Control, Remo	66 04 07	September-07	E60/E63	Unexpected Lane Departure Warning
Distance Systems, Cruise Control, Remo	66 06 07	October-07	ALL	Universal Garage Door Opener Cannot be Programmed

Category Distance Systems, Cruise Control, Remo	SIBs (SI B## ## ##) 66 01 08 02 for e65	<u>Date</u> February-08	Application E91	PDC Gong volume low
Distance Systems, Cruise Control, Remc Distance Systems, Cruise Control, Remc Distance Systems, Cruise Control, Remc	66 03 08 66 05 08	March-08 May-08	X5 (E70) 1 Series	Seal Must Be Replaced when Rear View Camera Is Removed PDC and Warning Gong Volume too Low
	03, 06 for other model 02 other model			
Vehicle Tools Vehicle Tools	71 01 07 71 01 08	September-07 March-08	W/Sunroof 3/5/6/Z series	Sunroof Emergency Operation Tool Eliminated Combination Wrench Eliminated from the Vehicle Tool Kit
Safety Restraint Systems Safety Restraint Systems Safety Restraint Systems Safety Restraint Systems Safety Restraint Systems	72 05 04 72 02 05 72 03 05 72 09 05 72 02 06	June-04 August-06 June-05 November-05 June-06	E60/E63 E60/E65/E90 E64 (Cabrio) E64 (Cabrio) ALL	Various "Self-Test" Faults Stored in "Byteflight" Modules Passenger Airbag Status Lamp Goes ON/OFF During Driving (Replaces 1/06) Check Control Message "Rollover Protection Fault" Service Action: Reprogram Control Modules for Backrest Lock Microswitch Airbag Warning Lamp for OC3 Seat Mat Fault (Supercedes Mar 06 w/new parts info)
Safety Restraint Systems	72 03 06 72 04 06 72 05 06 72 08 06	January-06 January-06 February-06 April-06	E64 (Cabrio) E90 E60 E90	Airbag Warning Lamp Illuminated for Backrest Microswitch Rear Belt Tensioners Deploy in Accident Airbag Warning Illuminated, FC 9B2D in SFZ OC3 Occupancy Status does not Change
Safety Restraint Systems	72 09 06 72 10 06 72 18 06 72 19 06	August-06 November-06 October-06 October-06	E90 E90 E60 E63	Airbag Warning Lamp, FC93EB (Update to Apr -06) Airbag Warning Lamp Illuminates - No Fault Codes (Replaces Apr 06) Various Telegram Errors in Satellites Various Fault Memory Entries in the SBE
Safety Restraint Systems	72 20 06 72 24 06 72 25 06 72 26 06	October-06 October-06 October-06 October-06	E60 E60 E60 E60	SBSL/SBSR FC 9845/98C5, implausible crash severity Rear Side Airbags Come Activated FC 96CA: Passenger Thorax Airbag Resistance too Great SGM FC 9413 "Signal Lamp Airbag Deactivation"
Safety Restraint Systems	72 28 06 72 29 06 72 01 07 72 03 07	December-06 December-06 January-07 August-07	E92 E60/E63/E65 E90/E91 E92	Seathelt Assistant *Nand* Portion Breaks Off DIS Test Plan Error While Performing SIM/SGM Self Test Assistant *Nand* Portion Breaks Off DIS Test Plan Error While Performing SIM/SGM Self Test Assistant Planch Protection (updates 3/07) Seat Belt Assistant Pinch Protection (updates 3/07)
Safety Restraint Systems Safety Restraint Systems Safety Restraint Systems Safety Restraint Systems	72 04 07 72 05 07 72 01 08	May-07 April-07 May-08	E63/64 E92 E92	Recall Campaign 07V-178: Replace the Seat Occupancy Detection Mat Seat Belt Assistant Malfunction Passenger Seat Belt Assistant Extends Unexpectedly
	-07 other model			
Communication Systems Communication Systems Communication Systems	84 14 01 84 01 03 B840103E60Telephone	November-06 December-05 P/O 84 01 03	E60/E63 E60/E63 E60/E63	Telephone Installation on New Vehicles Replaces Mar 05) CPT9000 Telephone (Supercedes Aug 05 w/new info) E60/E63 TCU Wiring Diagram
Communication Systems Communication Systems Communication Systems	84 15 03 B841503Diagnosis 84 214 04	March-08 P/O 85 15 03 September-05	E60/E63 E60/E63 E60/E63 E60/E63	BMW Assist Initialization (now usimg GSM Rpl 11/06) Troubleshooting Guide (Flowchart) Linked Sequence calls Fail on Bluetooth (REPLACED BY 84 18 05)
Communication Systems Communication Systems Communication Systems Communication Systems	84 02 04 84 03 04 84 10 04 B841004Installer	May-05 July-04 July-04 P/O 84 10 04	E60 E60 E60	Navigation Map DVD for Vehicles with CCC MFL Button Dials "911", or Last Number Dialed CCC Navigation Retrofit Kit Installation Instructions
Communication Systems Communication Systems Communication Systems Communication Systems	B841004SalesBulletin 84 12 04 84 12 04 Attachment 84 13 04	P/O 84 10 04 September-07 September-07 November-07	E60 E60/E63 E60/E63 E60/E63	Product Planning MY 04 5 Series Diagnosis and Repair of the CCC (updates 2/06) DVD Screws attachment BMW Assist with Integrated Bluetooth (Rpl Mar 07)
Communication Systems Communication Systems Communication Systems Communication Systems	B841304BluetoothDiagnosis B841304BluetoothUserManuallBus. B841304BluetoothUserManualE60E63 84 14 04	P/O 84 13 04 P/O 84 13 04 P/O 84 13 04 October-04	E60/E63 E60/E63 E60/E63 E60/E63	Diagnostic Instructions for Bluetooth Telephone Systems Bluetooth Users Manual for Business Phone Bluetooth Users Manual for CPT9000 and Bluetooth Service Action: Activate SVS (Voice Recognition System)
Communication Systems Communication Systems Communication Systems Communication Systems	B841404Q&A 84 01 05 84 04 05 84 07 05	P/O 84 14 04 July-05 January-07 June-05	E60/E63 E60/E63 E60/E63	FAQ Service Action: Reactivate TCUs for specified Production models that were accidently deactivated Nav system missing or incorrect data (Replaces April 05) Motorola v710 Handset Phonebook does not download
Communication Systems Communication Systems Communication Systems Communication Systems	84 08 05 84 09 05 B800905POICategories B800905POI ICONS	April-07 June-05 P/O 84 09 05 P/O 84 09 05	E60 /E90 E60/E63 E60/E63 E60/E63	CID switches between BMW banner and blank screen (Rpl 3/06 - adds E90 & new procedure) CCC NAV places of interest (POIs) PDF of categories and sub categories PDF of ICON symbols
Communication Systems Communication Systems Communication Systems	84 10 05 84 11 05 84 12 05	May-06 June-05 April-06	E60/E63/E90 E60/E63 E60/E63	Nav Displays incorrect Vehicle Position (Supercedes Mar 06) - Replaced with 65 23 07 CCC CD/DVD disc does not eject DVD Drive makes clicking noise (Supercedes Aug 05 w/E90)
Communication Systems Communication Systems Communication Systems Communication Systems	84 13 05 84 14 05 84 14 05 Attachment 84 18 05	May-07 August-08 September-07 September-05	E60/E63/E90 AII AII E60/E63	Bluetooth Phone call may still be displayed as active after the call has ended (Rpl 3/07 - adds E90) Retrofitting a Telematics Control Unit (TCU) with Bluetooth® Technology (update to 9/07) Special Inst for E6x Linked Sequence calls Fail on Bluetooth and CPT9000 Handsets
Communication Systems Communication Systems Communication Systems Communication Systems	84 19 05 84 24 05 84 25 05 84 02 06	September-05 August-06 January-06 January-06	E90 E60/E63/E90 E90 All	Teleservice does not place call for CBS due CCC Voice Input System Incorrectly States Speed Limit in "km" (Supercedes Nov 05) Software error in the Telematics Control Unit (TCU). (Supercedes Dec 05) Hands free Bluetooth® Phone Call May be Lost if a Call Waiting Call is Received

Category	SIBs (SI B## ## ##)	<u>Date</u>	<u>Application</u>	Title
Communication Systems	84 03 06	March-07	All	Enhanced Support for CCC Car Communication Computer (Supercedes Dec 06)
Communication Systems	84 04 06	July-06	All	Service Action: Reactivation of Telematics Control Unit (TCU) (Replace Mar 06)
Communication Systems	84 05 06	March-07	All	Diagnosis of Bluetooth® Handset Related Complaints (Rpl Mar 06)
Communication Systems	84 06 06	March-06	All	Information Displayed in the BMW Assist Menu is Incorrect or Unknown
Communication Systems	84 08 06	March-06	All	CCC Navigation is Inoperative at Low Ambient Temperatures
Communication Systems	84 09 06	October-07	All	Bluetooth® Inoperative, TCU FC# A379 or 79 (update to 04/07)
Communication Systems	84 10 06	August-07	E60/E63/E90	BMW Assist or Bluetooth® Inoperative, TCU FC# A379 (rpl 4/06)
Communication Systems	84 14 06	May-07	E60/E63/E90	Service Action: Reactivation of Telematics Control Unit (TCU) - (superceded Dec 06)
Communication Systems	84 15 06	May-06	E60/E63/E90	CCC Navigation Address Book Shows Duplicate Entries after Programming
Communication Systems	84 18 06	June-06	E60/E63/E90	Low Bluetooth Signal is Displayed in the Handset or the Bluetooth® Connection is Lost
Communication Systems	84 20 06	September-06	E60/E63/E90	CCC Navigation Stuck on "Accept" Screen(Superedes Jun 06)
Communication Systems	84 23 06	May-07	E60/E63/E90	Service Action: Telematics Control Unit (TCU) – MOST-bus Vehicles Supercedes Dec 06)
Communication Systems	84 25 06	June-08	E60/E63/E90/E65	NAD Check, Recovery or Deactivation Procedure (MOST-Bus vehicles) Supercedes Dec 06
Communication Systems	84 26 06	July-08	E60/E63/E90/E65	Cannot Enable BMW Assist Services (Supercedes Aug 06)
Communication Systems	84 27 06	July-08	E60/E63/E90/E65	BMW Assist Inactive Warning Message Displayed (Supercedes Aug 06)
Communication Systems	84 48 06	October-06	E60/E63	CPT9000 (V60s) Telephone Switches to Silent Mode when Connected to Vehicle
Communication Systems	84 49 06	October-07	E60/E63	Vehicle Dials BMW Assist on its Own (update to 10/06)
Communication Systems	84 50 06	October-06	E60/E63	CPT9000 Handset Phone does not Load into Vehicles
Communication Systems	84 51 06	October-06	E60/E63	The BMW Assist "Embedded" Phone Rings Erroneously in the Vehicle
Communication Systems	84 58 06	November-06	E60/E63/E90/E92	Real Time Traffic Information w/PDF attachment (Updated in Nov 06)
Communication Systems	84 59 06	October-06	E90/E92	CCC Telephone Address Book Not in Alphabetical Order
Communication Systems	84 61 06	March-07	E60/E63/E90/E92	CCC Navigation System Pop-up Arrow Display Missing During Route Guidance (rpl 10/06)
Communication Systems	84 62 06	July-08	E60/E63/E90/E92	Progman Displays 'The TEL Control Module is Malfunctioning' on the Final Report
Communication Systems	84 01 07	January-07	E60/E63/E90/E92	CCC SVS: Letter and Number Inputs by Voice are Misinterpreted
Communication Systems	84 02 07	March-07	E60/E63/E90/E92	Service Action: Activation of Telematics Control Unit (TCU)
Communication Systems	84 04 07	March-07	E60/E63/E90/E92	Bluetooth® Handsets No Longer Pairs to the Vehicle
Communication Systems	84 05 07	August-07		Checking NAD Signal Strength for BMW Assist
Communication Systems	84 06 07	March-07	E90	Call Cannot be Answered if the Voice Recognition System (SVS) is Active
Communication Systems	84 07 07	July-08	E60/E63/E90	NAD was Found to be Faulty when Performing SI B84 22 05 (Reactivation of BMW Assist Services)
Communication Systems	84 09 07	July-07	E60/E63/E90	Echo on Landline Side of Phone Call
Communication Systems	84 11 07	April-08	E60/E90	Service Action: Replace the Hands-Free Charging Electronics (MULF2-High) rpl 7/07
Communication Systems	84 12 07	July-07	E60/E63/E90/E92	Voice Only Call, No Data Transmitted When Placing a BMW Assist Call
Communication Systems	84 13 07	July-07	E60/E63/E90/E92	BMW Assist Location (GPS) Unknown or Inaccurate, When Placing a BMW Assist Call
Communication Systems	84 16 07	September-07	E60/E63/E90/E92	Erroneous SOS Inactive Warning Message (rpl 7/07)
Communication Systems	84 17 07	July-08	E60/E63/E90/E92	SOS Inactive Warning Message, No Communication with TCU (rpl 09/07)
Communication Systems	84 18 07	August-07	E60/E63/E90/E92	Enable Services Status Bar Does NOT Progress
Communication Systems	84 19 07	October-07	E60/E63/E90/E92	One Way Audio when Using a Bluetooth Enabled Handset
Communication Systems	84 20 07	November-07	All w/TCU	Upgrading BMW Assist to Support New Bluetooth Handsets
Communication Systems	84 21 07	November-07	All w/TCU	Diagnosis When an Unapproved Handset is Paired to a Vehicle
Communication Systems	84 02 08	March-08	All w/TCU	Service Action: Initialize BMW Assist Services (SC VPC on 3/3/08)
Communication Systems	84 03 08	May-08	X3	Echo and Poor Voice Quality on the Landline Side of a Call
Communication Systems	84 04 08	June-08	E60	Service Action: Update BMW Assist Services
Communication Systems	84 05 08	September-08	E60/E90/E83	Service Action: Reactivation of Telematics Control Unit (TCU)
Communication Systems	84 06 08	September-08	3 Series	CIC: Unable to Select an Address via the Contact Book
Communication Systems	84 07 08	September-08	1/3/5/6 series	Echo and Reverberation on the Landline during a Hands-free Call

01, 03, 10, other models or minor

Rev 18 published 22 Sep 08

NOTE: Text in Maroon represents new data or updated since previous edition (SIB_List_rev_17, published 2 July 2008)

Red = Safety recall notice

Bold = Service Action or Recall campaigns

Another Service Bulletin resource ---> Checkout periodically to see if they keep current
This link seems to have been closed to non-subscribers sometime in January 2007

Most Recent

No Longer available free http://www.alldata.com/tsb/BMW/index-post.html