

COMPILED AND EDITED BY COBRADAV - COURTESY OF KoTR @ bimmerdrivers.com

| Category | SIBs (SI B## ## #) | Date | Application | Title |
|--------------------------------------|---|-----------------|---------------------|--|
| Maintenance and General Hints | 00 04 02 | March-08 | All | BMW Group Technical Hotline (rpl 1/08) |
| Maintenance and General Hints | 00 06 03 | November-03 | All | General info on TIS Website |
| Maintenance and General Hints | 00 01 05 | June-06 | All | New Vehicle Preparation and Maintenance Requirements (Supercedes Jan 06) |
| Maintenance and General Hints | B000105ATT_VehChk | P/O 00 01 05 | 525/530 | Quality Certification Form |
| Maintenance and General Hints | 00 02 06 | March-07 | All | New Vehicle Preparation and Maintenance Requirements (MY07) (Rpl 11/06) |
| Maintenance and General Hints | 00 01 07 | May-08 | ALL | New Vehicle Preparation and Maintenance Requirements (rpl 3/8 adds M3 DCT and 1 series) |
| Maintenance and General Hints | 00 03 07 | August-07 | ALL | PuMA Enhancements for TeileClearing Process |
| Maintenance and General Hints | 00 04 07 | March-08 | X3, X5 | New Vehicle Preparation and Maintenance Requirements (rpl 12/07 adds X6) |
| Maintenance and General Hints | 00 08 07 | October-07 | All | Construction Group Changes |
| Maintenance and General Hints | 00 01 08 | March-08 | BMW Centers | BMW Center Technical Support Overview |
| Maintenance and General Hints | 00 02 08 | March-08 | E82/E88 | E82, E88 (1 Series) Quality Control Information |
| Maintenance and General Hints | 00 03 08 | April-08 | E71 (X6) | E71 (X6) Quality Control Information |
| Maintenance and General Hints | 00 04 08 | April-09 | ALL | New Vehicle Preparation and Maintenance Requirements (add new Z4) |
| Maintenance and General Hints | 00 05 08 | January-09 | ALL | New Vehicle Preparation and Maintenance Requirements |
| Maintenance and General Hints | 00 06 08 | September-08 | ALL | Information Tags |
| Maintenance and General Hints | 00 07 08 | October-08 | 3 series | E90, E91 (3 Series) LCI Quality Control Information |
| Maintenance and General Hints | 00 08 08 | December-08 | 335d & X5d | E90, E70 Diesel Quality Control Information |
| Maintenance and General Hints | 00 01 09 | March-09 | 5, 6 Series | New Vehicle Preparation and Maintenance Requirements |
| Maintenance and General Hints | 00 02 09 | February-09 | 7 series | F01, F02 Quality Control Information |
| Maintenance and General Hints | 00 04 09 | May-09 | Z4 (e89) | E89 Quality Control Information |
| Maintenance and General Hints | 00 05 09 | June-09 | All | CBS Service Maintenance Substitute Checklists |
| | 09 na | | | |
| Warranty | 01 02 03 | September-03 | BMW Centers | BMW Maintenance Program 4 Years - 50,000 Miles |
| Warranty | 01 07 03 | January-07 | BMW Centers | BMW Center Administered Customer Assistance Program (CACAP) |
| Warranty | 01 02 04 | November-06 | BMW Centers | BMW Tire Center Target Satisfaction Program |
| Warranty | 01 06 05 | March-05 | BMW Centers | BMW Maintenance Program 2005 Laminated Reference Chart and Mouse Pad |
| Warranty | B010605Attachment. | P/O 01 06 05 | BMW Centers | Chart of Warranty Codes/Services |
| Warranty | 01 07 05 | March-05 | BMW Centers | Warranty Claims Processing – "Overnight Payments" |
| Warranty | 01 10 05 | August-05 | BMW Centers | TCU ESN Registration via DCSnet |
| Warranty | B011005Attachment. | P/O 01 10 05 | BMW Centers | FAQ's for TCU Claims |
| Warranty | 01 01 06 | January-08 | BMW Centers | BMW Warranty Policy and Procedures Manual – Updates from 01/01/05 through 12/21/07) |
| Warranty | B010106Attachment | P/O 01 01 06 | BMW Centers | BMW Warranty Policy and Procedures Manual – Updates from 01/01/05 through 12/21/05 rev notes |
| Warranty | 01 02 06 | February-06 | BMW Centers | BMW Electronic Archiving System (EAS) Evaluation and Certification |
| Warranty | B010206EAS_Flowchart. | February-06 | BMW Centers | EAS Flowchart |
| Warranty | 01 03 06 | February-07 | BMW Centers | Warranty Claims for Software Update Programming (Progman) (Replace NOV 06) |
| Warranty | 01 04 06 | April-06 | BMW Centers | Reasons for Vehicle Update Programming Reminder Magnet |
| Warranty | 01 09 06 | February-07 | BMW Centers | Defect Code for Programming Prior to Accessory Retrofit (Supercedes 12/06) |
| Warranty | 01 03 07 | June-07 | BMW Centers | New Pricing Plan and Program Enhancements - Maintenance Program Upgrade |
| Warranty | 01 02 08 | February-08 | BMW Centers | BMW Performance Line of Accessories |
| Warranty | 01 03 08 | May-08 | BMW Centers | OEM Tire Manufacturer Warranty Coverage CD-ROM |
| Warranty | 01 05 08 | July-08 | BMW Centers | Certified Pre-Owned (CPO) Reconditioning Changes |
| Warranty | 01 06 08 | December-08 | BMW Centers | Warranties Knowledge Portal (WKP) |
| Warranty | 01 07 08 | December-08 | BMW Centers | Labor Rate Calculation on all Reimbursed Labor as of 1/1/09 |
| After Sales Business Development | 02 01 05 | October-05 | All | BMW Assist changes for September 2005 |
| After Sales Business Development | B020105KeyBenefitChart | P/O 02 01 05 | All | BMW Assist - Key Benefits |
| After Sales Business Development | 02 01 06 | February-06 | All | Updated DCSnet Vehicle History Inquiry Information on BMW Assist™ (Supercedes Jan 06) |
| After Sales Business Development | 02 02 06 | November-06 | All | BMW Assist™ Service Extension Incentive Program (Supercedes 02/06) |
| After Sales Business Development | 02 01 07 | February-07 | All | Mobile Assistance Program |
| Tools and Equipment | 04 02 05 | January-05 | E60/E63 | Zero-Coded Cover |
| Tools and Equipment | 04 04 05 | January-05 | E60 | Antenna Knife |
| Tools and Equipment | 04 07 05 | April-05 | N52 Engine | N52 Special Tools |
| Tools and Equipment | 04 08 05 | February-05 | E60/E63 | Aluminum Body Tools |
| Tools and Equipment | 04 13 05 | March-05 | E61 | Tailgate Support |
| Tools and Equipment | 04 14 05 | April-05 | E60/E63 | CD Eject Tool |
| Tools and Equipment | 04 15 05 | May-05 | E90 | DME Test Cable |
| Tools and Equipment | 04 29 05 | November-05 | E60/E63 | AC Sprayer Wand |
| Tools and Equipment | 04 02 06 | January-06 | M - S85 engine | Backlash Gauge |
| Tools and Equipment | 04 04 07 | April-07 | Turbocharged | Turbocharger Diagnostic Tool |
| Tools and Equipment | 04 07 07 | December-07 | All | Fuel Injection and Induction System Cleaning |
| Tools and Equipment | 04 01 08 | January-08 | S65/M3 | New Special Tools |
| | thru - 2106 no value | | | |
| | 0107-0307/0507-0607/ & 0807-2807 no value | | | |
| Information Systems | 05 01 05 | September-05 | All | Teleservice Changing a Customer's Preferred Home Dealer |
| | end | | | |
| General | 07 02 96 | June-07 | BMW Centers | CD42: Updated DISplus & GT1 Software (update to Mar 07) |
| General | 07 03 02 | June-04 | BMW Centers | Optical Testing & Programming System - OPSS |
| General | 07 05 02 | June-05 | BMW Centers | Online Update |
| General | 07 02 04 | November-04 | BMW Centers | Optical Programming System - OPS |
| General | 07 01 05 | December-05 | BMW Centers | Software Service Station r2 (SSSr2) |
| General | 07 01 06 | August-06 | BMW Centers | Next Generation Workshop Technology – iBase Server Readiness Project |
| General | 07 03 06 | October-06 | BMW Centers | Next Generation Workshop Technology 3G |
| General | 07 04 06 | January-07 | BMW Centers | Use Agreement for 3G Workshop Technology |
| General | 07 01 07 | March-07 | BMW Centers | DIS V49 Corrections Based on Diagnosis Feedback |
| General | B070107_Feedback PDF | March-07 | BMW Centers | B070107Diagnosis_Feedback_Corrected_DIS_V49. |
| General | 07 03 07 | June-07 | BMW Centers | DIS V50 Corrections Based on Diagnosis Feedback |
| General | B070307_Feedback PDF | | | |
| General | 07 04 07 | August-07 | BMW Centers | DIS V51 Corrections Based on Diagnosis Feedback (Update to June 07) |
| General | 07 05 07 | June-07 | BMW Centers | DIS V50 Release Notes |
| General | 07 06 07 | August-07 | BMW Centers | Diagnosis Process |
| General | 07 08 07 | August-07 | BMW Centers | DIS V51 Release Notes |
| General | 07 10 07 | October-07 | BMW Centers | Importance of Using the Most Current Diagnostic / Programming Software |
| General | 07 11 07 | November-07 | BMW Centers | DIS V52 Corrections Based on Diagnosis Feedback (December 2007 Release) |
| General | 07 13 07 | December-07 | BMW Centers | DIS V52 Release Notes |
| General | 07 15 07 | January-08 | E60/E63/E90/E92/E70 | Diagnosis via D-CAN Not Possible |
| General | 07 01 08 | March-08 | BMW Centers | DIS V53 Changes Based on Diagnosis Feedback (March 2008 Release) |
| General | 07 02 08 | March-08 | BMW Centers | DIS V53 Release Notes |
| General | 07 05 08 | May-08 | BMW Centers | DIS V54 Changes Based on Diagnosis Feedback (June 2008 Release) |
| General | 07 06 08 | August-08 | BMW Centers | Diagnosis Feedback with ISTA |
| General | 07 07 08 | August-08 | BMW Centers | ISTA Technical Data 2.8.0 Changes Based on Diagnosis Feedback |
| General | 07 08 08 | September-08 | BMW Centers | DIS V55 Release Notes |
| General | 07 09 08 | October-08 | BMW Centers | New ISTA/P Software |
| General | 07 10 08 | November-09 | BMW Centers | ISTA Does Not Automatically ID the Vehicle |
| General | 07 11 08 | December-09 | BMW Centers | DIS V56 Release Notes |
| General | 07 01 09 | April-09 | BMW Centers | DIS V57 Release Notes |

| Category | SIBs (SI B## ## #) | Date | Application | Title |
|--|-----------------------------|---------------------|-----------------------------|---|
| General | 07 02 09 | July-09 | BMW Centers | Activating ISTA in Offline Mode when ISIS Is Not Available |
| Programming/Coding Explanations | 09 03 98 | May-06 | E60/E63/E90 | Car & Key Memory (Updated date with additional E90 info Supercedes Nov 05) |
| Programming/Coding Explanations | B090398_Att5_CKM_E60 | P/O 09 03 98 | E60/E63 | PDF of car and Key memory settings |
| Programming/Coding Explanations | 09 05 01 | March-06 | E60/E63 | CIP General Info (Supercedes Dec 05) |
| Programming/Coding Explanations | Att3_CBSCheck | P/O 09 05 01 | E60/E63 | Condition Based Service Plausibility Check |
| Programming/Coding Explanations | Att4_CBSCorrct | P/O 09 05 01 | E60/E63 | Condition Based Service Adjustments based on previous service |
| Programming/Coding Explanations | ProgCoding | P/O 09 05 01 | E60/E63 | Detailed Description of programming and coding using CIPs |
| Programming/Coding Explanations | 09 07 02 | March-03 | E65 | CIP 7.0 |
| Programming/Coding Explanations | 09 01 04 | January-05 | BMW Centers | Programming Manager |
| Programming/Coding Explanations | 09 01 05 | May-05 | All | CIP 17.0 Release Notes |
| Programming/Coding Explanations | 09 02 05 | July-05 | All | OBD Replacement Cables for GTI/DISplus Diagnostic Heads |
| Programming/Coding Explanations | 09 03 05 | January-07 | E90 | Personal Profile (Replaces 8/05) |
| Programming/Coding Explanations | 09 04 05 | July-05 | All | CIP 18.0 release notes |
| Programming/Coding Explanations | 09 05 05 | July-05 | E60 w/o NAV | After Programming, CIP shows MASK-H to be replaced |
| Programming/Coding Explanations | 09 06 05 | August-05 | E60/E63 | CIP Shows IHKA (Automatic heating & AC) to be Replaced |
| Programming/Coding Explanations | 09 07 05 | September-05 | All | CIP 19.0 and 19.1 release notes |
| Programming/Coding Explanations | 09 08 05 | October-05 | E64 Cabrio | Service Action: Correction to Integration Level |
| Programming/Coding Explanations | 09 09 05 | November-05 | BMW Centers | CIP: Report Recurring Irregularities |
| Programming/Coding Explanations | 09 11 05 | October-06 | E60/E63/E90 | CCC Fails to Program with CIP 19.x (Supercedes Dec 05, Feb 06, May 06, Aug 06) |
| Programming/Coding Explanations | 09 01 06 | February-06 | E90 | JBE Fails to Program (supercedes Jan 06) |
| Programming/Coding Explanations | 09 02 06 | January-06 | E90 | Replacement FZD Not Accepted by CIP/PROGMAN |
| Programming/Coding Explanations | 09 03 06 | January-06 | All | Deciphering and Troubleshooting the Vehicle Order |
| Programming/Coding Explanations | 09 05 06 | January-06 | E60/E63/E90 | Release Notes Progran V20.0 and V20.0.1 |
| Programming/Coding Explanations | 09 06 06 | February-06 | E90 | RAD2 Cannot be Programmed after Programming Abort (Supercedes Jan 06 - Online 20.02.00) |
| Programming/Coding Explanations | 09 07 06 | January-06 | E90/x drives | DSC Cannot be Encoded |
| Programming/Coding Explanations | 09 08 06 | February-06 | E90 | DWA LED on Rearview Mirror Cannot be Activated |
| Programming/Coding Explanations | 09 09 06 | March-06 | All | Release Notes Progran 21.0 |
| Programming/Coding Explanations | 09 10 06 | May-06 | All | Release Notes Progran V21.02 and V21.02.01 |
| Programming/Coding Explanations | 09 11 06 | May-06 | E60 | Replacement SZL Not Accepted By Progran |
| Programming/Coding Explanations | 09 13 06 | June-06 | All | Release Notes Progran V22.0 and V22.0.1 |
| Programming/Coding Explanations | 09 14 06 | July-06 | E60/E63/E90 | Maintenance Interval Retrofit is Not Used in US Market Vehicles |
| Programming/Coding Explanations | 09 15 06 | July-06 | E90 | Personal Profile Settings for Alarm System Missing |
| Programming/Coding Explanations | 09 16 06 | August-06 | E60/E63/E90 | Release Notes Progran V22.1 and V22.1.1 and V22.1.2 |
| Programming/Coding Explanations | 09 17 06 | December-06 | ALL | Vehicle Order (VO) Cannot be Adapted Using CIP |
| Programming/Coding Explanations | 09 20 06 | October-06 | E90 | Daytime Running Lamps Switched On after Update with Progran V23 |
| Programming/Coding Explanations | 09 21 06 | October-06 | E90 | Satellite Radio Inoperable after Programming with Progran V23 - Need 23.01.03 |
| Programming/Coding Explanations | 09 22 06 | October-06 | E60/E63/E90 | Coding Function for Headunit Available in Progran V23 |
| Programming/Coding Explanations | 09 01 07 | January-07 | E60/E63/E90 | CCC: Programming or Coding Fails with Progran V24 |
| Programming/Coding Explanations | 09 02 07 | October-07 | All w/CCC | CCC: Enabling Code (FSC) Required for Voice Recognition System(update to May 07 |
| Programming/Coding Explanations | B090207Attachment. | P/O 09 02 07 | BMW Centers | B090207Parts_Info_V1_1 |
| Programming/Coding Explanations | 09 03 07 | June-07 | E92 | FRM Fails Coding |
| Programming/Coding Explanations | 09 04 07 | August-07 | ALL w/CCC | Programming Failure Due to CD or DVD in Drives |
| Programming/Coding Explanations | 09 05 07 | September-07 | E90 | CAS2 Programming with Special Measure not Possible |
| Programming/Coding Explanations | 09 07 07 | May-09 | ALL | Progran Version vs. Vehicle Data Status (update to 1/09) 2.33.02 latest shown |
| Programming/Coding Explanations | 09 01 09 | April-09 | F01/02 | Programming Fails for the IHKA, FKA, or CON |
| Programming/Coding Explanations | 09 02 09 | August-09 | 1/3 Series | RAD2 Programming with ISTA/P 2.34.2 - No MOST Communication |
| 06 other model | | | | |
| Engine System | 11 08 98 | June-06 | All | BMW Engine Oils (Includes Annual Change Coverage) (Supercedes Oct 05) |
| Engine System | 11 04 03 | February-07 | E60 | Recurring Noise Complaints From Mechanical Alternator Belt Tensioners (Replaces 7/05) |
| Engine System | 11 02 05 | January-06 | E60/E63 | N62 - Rough Idle, Misfire faults after cold start (Supercedes May 05) |
| Engine System | 11 03 05 | June-05 | E60/E63 | N62 and N62TU Valve Cover and Valve Cover Gasket Replacement |
| Engine System | 11 05 05 | December-06 | E60 | N52 Engine Runs Poorly with Camshaft Sensor and VANOS Faults (Supercedes Novr 06) |
| Engine System | 11 07 05 | July-05 | E60/E63 | N62 and N62TU Water Pump Replacement - corrects installation procedure |
| Engine System | 11 09 05 | April-06 | E60/E63 | Non-Return Valve Parts Found In Engine Oil Filter During Engine Oil Service Supercedes Dec 05) |
| Engine System | 11 10 05 | February-06 | E60 (M5) | Service Action: S85 Replace VANOS High Pressure Line (Supercedes Jan 06) |
| Engine System | 11 01 06 | March-06 | M5/M6 | S85 Engine Oil Level and Oil Service Information |
| Engine System | Replaced by 11 06 09 | December-06 | E60 | NG6 Engines - Front and Rear Radial Crankshaft Seal Replacement |
| Engine System | 11 03 06 | June-06 | All w/N62 Engine | Voluntary Emissions Recall 06E-A02: N62 - Crankcase Ventilation Valves Replacement |
| Engine System | 11 04 06 | June-06 | All | Engine, Transmission, or Clutch Related Complaints |
| Engine System | 11 06 06 | June-06 | M54/M54TU | Head Bolt Threads Pulling Out of Block During Engine Reassembly |
| Engine System | 11 07 06 | October-06 | All w/N62 Engine | N62 Engine - Rough Idle at Operating Temperature |
| Engine System | 11 13 06 | January-08 | E90/E92 w N54 | N54 Engine Compression and Cylinder Leakage Test Procedures (rpl 11/06) |
| Engine System | 11 01 07 | October-07 | All with N62 (4.4) | N62 Crankcase Ventilation System - Cold Climate Conditions (rpl 6/07) |
| Engine System | 11 05 07 | April-07 | All S85 (V10) | Service Action: Replace Front Crankshaft Radial Seal |
| Engine System | 11 09 07 | July-07 | All N52 Engine | Intermittent Hydraulic Valve Adjuster (HVA) "Ticking" or "Rattling" Noises |
| Engine System | 11 12 07 | October-07 | N62/N62TU | N62 and N62TU Engine Replacement (after an engine has been replaced) |
| Engine System | 11 13 07 | May-08 | N54 | N54 Rattle Noise from Turbocharger Area |
| Engine System | 11 14 07 | November-07 | N54 | N54 Turbocharger Waste Gate Control Noises and Operation |
| Engine System | 11 01 08 | April-08 | E60/E70/E83/3 series | Service Action: Replace the Chain Tensioning Rail Bearing Bolt |
| Engine System | 11 02 08 | February-08 | N54 | N54: Power Reduction - DME Fault 2A82 VANOS Inlet is Stored |
| Engine System | 11 03 08 | November-08 | All engines | Crankcase Ventilation System Specification |
| Engine System | 11 04 08 | July-08 | All | TeileClearing for Engine Components |
| Engine System | 11 05 08 | August-08 | 1, 3 Series | N51 Engine: Cylinder Head Bolt Torque Is not Available via TIS |
| Engine System | 11 07 08 | August-08 | E46 | Overheated Engine - Diagnostic Tips |
| Engine System | 11 09 08 | October-08 | 1 & 3 Series w/N54 | Alternator Drive Belt Broken |
| Engine System | 11 10 08 | October-08 | S62 (E39 M5 & Z8) | S62 VANOS Assembly Mode Test Plan |
| Engine System | 11 01 09 | March-09 | All | CPO Inspection Guidelines - Engine Inspection on Vehicles with Extended ("Overdue") Oil Service Intervals |
| Engine System | 11 03 09 | March-09 | M3 w/S65 | Engine Oil Residue Found Near Oil Filler Cap |
| Engine System | 11 04 09 | April-09 | 3 & X5 w/diesel | Soot Deposits Found Around Turbocharger Waste Gate Shaft Pivot |
| Engine System | 11 06 09 | July-09 | All w/N52, N54 | NG6 Crankshaft Seal and Bed Plate Sealer |
| Engine System | 11 07 09 | August-09 | M3 w/S65 | Service Action: M3 S65 - Thermostat Housing Inspection |
| 06 - Alpina B7 | | | | |
| Engine Electrical System | 12 01 99 | June-06 | All | High Performance Platinum Spark Plug/Spark Plug Application Chart |
| Engine Electrical System | 12 01 04 | October-04 | N62 in E60 | E60 with N62; DME Reprogramming |
| Engine Electrical System | 12 03 04 | September-04 | M54 in E60 | Voluntary Emissions Recall Campaign 04E-A02: Emission Readiness Codes Not Completely Setting |
| Engine Electrical System | 12 04 04 | July-04 | E60/E63 | Safety Recall Campaign 04V-344: DME Replacement on N62/N73 Engines |
| Engine Electrical System | 12 05 04 | October-05 | E60/E63 | Voluntary Emissions Recall 04E-A04: Reprogram DME for Oxygen Sensor Diagnostics on E53, E60, |
| Engine Electrical System | 12 09 04 | August-06 | All | Special DME Programming - Shipping Procedure (Replaces 12/04) |
| Engine Electrical System | 12 10 04 | December-04 | M54 in E60 | Intermittent Hesitation While Driving or Intermittent Crank, No Start Situation |
| Engine Electrical System | 12 01 05 | March-08 | N52 in E60 | High Perf Iridium spark Plugs (rpl 06/06) |
| Engine Electrical System | 12 03 05 | September-05 | N62 in E60/E63 | CBS Oil Message |
| Engine Electrical System | 12 04 05 | July-07 | N52 in E60 | Check Engine light or engine overheats (Supercedes Mar 06) |
| Engine Electrical System | 12 06 05 | June-05 | N52 in E60 | DME FC CDA7 CAN Message |
| Engine Electrical System | 12 08 05 | July-05 | E60 | Oxygen Sensor |
| Engine Electrical System | 12 11 05 | January-06 | N62 in E60/E63 | Service Action: Reprogramming for Incorrect Oil Service (Supercedes August 05) |
| Engine Electrical System | 12 15 05 | March-08 | N62 in E60/E63 | Map Thermostat faults (rpl 12/07) |
| Engine Electrical System | 12 16 05 | September-05 | E60 | Mixture is too Lean, Fault codes 2882, 2883 |
| Engine Electrical System | 12 17 05 | September-05 | E60 | Engine Power drops at 4000 RPM |

| Category | SIBs (SI B## ## ##) | Date | Application | Title |
|---------------------------------|---------------------|---------------------|----------------------------|---|
| Engine Electrical System | 12 19 05 | October-05 | N52 in E60/E90 | Service Action: Reprogram for OBD Diagnostic |
| Engine Electrical System | 12 20 05 | October-05 | E60/E63 | Loss of Power while decelerating & turning or coming to stop |
| Engine Electrical System | 12 25 05 | December-05 | E90 | CBS Oil formula (different but similar to E60/63) |
| Engine Electrical System | 12 27 05 | April-07 | E60/E63 | N62TU (4.8L) Pinging and Surging (Supersedes Jul 06) |
| Engine Electrical System | 12 29 05 | March-06 | M5 | S85 Engine Diagnosis Test Plan Updates (Supersedes Dec 05 - minor change) |
| Engine Electrical System | 12 03 06 | February-06 | E60/M52 | Loss of Power or Intermittent Crank, No Start Situation |
| Engine Electrical System | 12 04 06 | February-06 | E60/M52 | DMTL Diagnosis Test Plan Error |
| Engine Electrical System | 12 06 06 | April-07 | E60/E90/N52 | Voluntary Emissions Recall 06E-A01: N52 - Reprogramming Vehicle for OBD Diagnostic (Supersedes 5/06) |
| Engine Electrical System | 12 07 06 | January-07 | E60/E90/N52 | Service Engine Soon Light Illuminated: FC 2EF4 Map Thermostat (Replaces 5/06) |
| Engine Electrical System | 12 10 06 | September-06 | E60/E90/N52 | Service Engine Soon Lamp Illuminated: FC 2C2D, 2C3D, 2C2E, 2C3E |
| Engine Electrical System | 12 12 06 | April-07 | E60/E63/N62TU | N62TU - Diagnosis for DME FC 2A90 (Supersedes Dec 06) |
| Engine Electrical System | 12 16 06 | September-06 | E90/E92 w N54 | E90, E92 with N54 - Diagnostic for DME FC 29F1/29F2 |
| Engine Electrical System | 12 18 06 | November-06 | Ms | Voluntary Emissions Recall 06E-A04: S85 - DME Reprogramming for OBD Monitoring |
| Engine Electrical System | 12 19 06 | October-06 | E60/E63/E90 | Check Gas Cap Warning with DME FC 2A17 - DMTL, System Error |
| Engine Electrical System | 12 25 06 | November-06 | All | Fuel Quality Determination (Supersedes August 06) |
| Engine Electrical System | 12 27 06 | November-06 | E60/N62 | DME Fault Codes 278B and 278D |
| Engine Electrical System | 12 28 06 | October-06 | E60 | DME Fault Code 27CD |
| Engine Electrical System | 12 29 06 | November-06 | E60/M54 | DME Fault Codes 2896, 2877, 2766 |
| Engine Electrical System | 12 33 06 | October-06 | E60/E63 | Various Complaints Caused by Defective Oil Level Sensor - Diagnostic Hints |
| Engine Electrical System | 12 34 06 | October-06 | E60/M54 | E60, M54 - Various Oxygen Sensor FC's Caused by Defective Transmission Harness |
| Engine Electrical System | 12 38 06 | October-06 | E90 | MSV70 - DME, FC 29DA Segment Adaptation |
| Engine Electrical System | 12 40 06 | October-06 | E60 | MS45.1 - Various O2 Sensor Faults Stored in DME |
| Engine Electrical System | 12 42 06 | November-06 | E60 | E60, MS45.1 - DME FC 28A2 and FC 2783 |
| Engine Electrical System | 12 43 06 | October-06 | E60/E63 | N62 DME ME9.2.1 Engine Difficult to Restart at Operating Temperatures |
| Engine Electrical System | 12 46 06 | November-06 | E90/E92 w N54 | N54 - Slight Bucking is Felt During Acceleration With a Cold Engine |
| Engine Electrical System | 12 47 06 | November-06 | E60/E63 | Break Out Box Overlay Identification |
| Engine Electrical System | 12 49 06 | April-07 | E60/M54 | DME MS45 - FC28B2, 28AA, 28AC; Internal RAM Faults (Rpl 11/06) |
| Engine Electrical System | 12 50 06 | November-06 | E60/E63/E90 | OBD II Fault Codes List in TIS |
| Engine Electrical System | 12 51 06 | December-06 | E92 | MSD80 N54 Engine Diagnostic Test Plans Inoperative |
| Engine Electrical System | 12 54 06 | December-06 | E90/92 | N54 CBS4 Oil Service Indicates 25,000 Miles |
| Engine Electrical System | 12 55 06 | January-08 | E90/92 | E90, E92 with N54 - Diagnosis for DME FC 29DC/2FBF (Replaces 1/07) |
| Engine Electrical System | 12 58 06 | January-07 | E90 | Service Action: Replace the Alternator |
| Engine Electrical System | 12 05 07 | January-08 | E60/E90 | Erroneous Low Oil Level Warning Message While Driving (rpl 12/07) |
| Engine Electrical System | 12 06 07 | September-07 | E90/E92 | Voluntary Emissions Recall 07E-A01: N54 - Reprogramming Vehicle (DME) for OBD Diagnostic |
| Engine Electrical System | 12 07 07 | June-07 | E90/E92 | N51 - Fault 2A43: Valvetronic, Thermal Overload Protection |
| Engine Electrical System | 12 09 07 | May-07 | M5/M6 | Service Engine Soon Light Illuminated: S85 - Various VANOS Related Faults Stored |
| Engine Electrical System | 12 10 07 | October-07 | E60/E63/N62TU | Service Action: N62TU - Retrofit Engine Compartment Ground Cables - rpl 7/07 (now recall) |
| Engine Electrical System | 12 11 07 | July-07 | E60/E63/N62TU | N62TU: EDK Throttle Faults - Diagnostic |
| Engine Electrical System | 12 15 07 | October-07 | 3 Series | N52K - Loss of Power |
| Engine Electrical System | 12 16 07 | October-07 | 3 Series | N51 - EAC Sensor Fault 2AD8 is Stored |
| Engine Electrical System | 12 18 07 | October-07 | 3/5 w N54 | N54: Running Issues with Various Faults in DME |
| Engine Electrical System | 12 22 07 | November-07 | All | TeileClearing (Enhanced Technical Support) for DME |
| Engine Electrical System | 12 23 07 | November-07 | E70 (X5) | FC 2EF4 Characteristic Map Thermostat |
| Engine Electrical System | 12 25 07 | November-07 | E70 (X5) | E70 N62TU: Pressure Sensor Fault 2D32 |
| Engine Electrical System | 12 28 07 | December-07 | 3/5 w N54 | N54 Engine Failsafe: FC 3100, FC 30FE and/or FC 30FF is stored in DME Fault Memory |
| Engine Electrical System | 12 01 08 | January-08 | 3/5 w N52 | N52 EDK Throttle Jamming Faults 2D09, 2CED and 2CEC |
| Engine Electrical System | 12 02 08 | January-08 | 3/5 w N54 | N54 - Diagnosis for DME Fuel Injector Faults |
| Engine Electrical System | 12 03 08 | January-08 | X5 w N54 | N52K - Diagnosis of DME FC 2E97 |
| Engine Electrical System | 12 05 08 | February-08 | X5 w N62TU | N62TU: Fault 2A17 - DMTL System Error is Stored |
| Engine Electrical System | 12 06 08 | July-08 | 1/3 series, X5 | CBS4 Oil Service Forecast Displays Due in 25,000 miles |
| Engine Electrical System | 12 09 08 | February-08 | E60/63/70 | Driveability Complaints due to Cooling Fan Relay Failure |
| Engine Electrical System | 12 10 08 | April-08 | All w N54 | N54 - Aftermarket "Engine Performance Tuning" Kits |
| Engine Electrical System | 12 12 08 | March-08 | 3 Series/N52/N52K | DME FC 2A15 Minor Leak and 2A16 Superfine Leak in Evaporation System |
| Engine Electrical System | 12 13 08 | March-08 | 3/5 ser w/M54/N52 | After Vehicle Repair, Service Engine Soon Lamp Cannot Be Switched Off |
| Engine Electrical System | 12 14 08 | May-08 | New M3 /S65 | Service Engine Soon Lamp Is Illuminated, EKP FC 2786, 2787, 2788 (rpl 3/08) |
| Engine Electrical System | 12 15 08 | August-08 | E65/66 | E65, E66 with N62TU - Various Driveability Complaints |
| Engine Electrical System | 12 16 08 | June-08 | M5/M6 V10 | Voluntary Emissions Recall 08E-A02: M5 and M6 with S85 - OBD Communication |
| Engine Electrical System | 12 17 08 | June-08 | E65/66 | Service Action: E65 and E66 with N62, N62TU, or N73 - OBD Communication |
| Engine Electrical System | 12 18 08 | June-08 | All w/N54 | Service Action: N54 Oil Level Programming |
| Engine Electrical System | 12 19 08 | June-08 | M5/M6 V10 | S85 - Power Reduction with Idle Actuator Faults Stored |
| Engine Electrical System | 12 20 08 | June-08 | All w/N54 | N54 - Various Complaints Caused by Aftermarket "Tuning Kits" |
| Engine Electrical System | 12 21 08 | July-08 | M5/M6 | S85 - DME Fault 2742/2743 for O2 Sensor |
| Engine Electrical System | 12 23 08 | July-08 | E65/66/B7 | Service Action: E65 and E66 with N62, N62TU, or N73 - OBD Communication |
| Engine Electrical System | 12 24 08 | September-08 | E65/66/B7 | Service Action: E65 and E66 with N62TU or N73 - OBD Communication |
| Engine Electrical System | 12 25 08 | September-08 | 1/3/5 series & X6 | Charge Air Pressure Control B1214_D16LDRN Test Plan Is Inoperative |
| Engine Electrical System | 12 26 08 | October-08 | All w/N54 & N63 engine | Injector Removal, Installation, and Replacement Procedures |
| Engine Electrical System | 12 27 08 | October-08 | All w/N54 & N63 engine | Ignition Coil Faults |
| Engine Electrical System | 12 28 08 | December-08 | S65 / S85 | S65 / S85 Rough Running During the Catalyst Heating Phase |
| Engine Electrical System | 12 01 09 | February-09 | 1, 3, 5/X5 | Service Engine Soon Lamp or Check Gas Cap Warning Illuminated |
| Engine Electrical System | 12 02 09 | February-09 | 1, 3, 5, 6/X5, X3 | Service Engine Soon or Check Gas Cap Warning Is Illuminated: Tank Leakage |
| Engine Electrical System | 12 03 09 | March-09 | X5 (E70) | The Engine Oil Level Is Displayed as Overfilled |
| Engine Electrical System | 12 04 09 | February-09 | M3 w/S65 | M3 S65 - Diagnosis for DME Fault Code 2AFD |
| Engine Electrical System | 12 05 09 | April-09 | 5 Series | N54 E60, E61 - Misfire Faults Are Stored due to DME Software Errors |
| Engine Electrical System | 12 06 09 | April-09 | 1, 3 series | N54 E9x, E82, E88 - Misfire Faults Are Stored due to a DME Software Error |
| Engine Electrical System | 12 07 09 | April-09 | 1, 3 series | N51 - Service Engine Soon Lamp Is On with Fault Code 2A38 Stored |
| Engine Electrical System | 12 09 09 | May-09 | 3 & X5 w/diesel | M57Y - The Service Engine Soon Lamp (MIL) Is On with Fault Codes 46CE, 4D11, or 4D12 Stored |
| Engine Electrical System | 12 10 09 | February-09 | 3 & X5 w/diesel | E90, E70 M57Y Diesel - Diagnosis for DDE FC 4521/4530 |
| Engine Electrical System | 12 11 09 | April-09 | F01/02 w/N63 | Service Action: Program Control Units (DME) |
| Engine Electrical System | 12 12 09 | April-09 | X6 w/N63 | Service Action: Program Control Units (DME) |
| Engine Electrical System | 12 13 09 | March-09 | M3 w/S65 | M3 S65 - Various Oxygen Sensor Faults Stored in DME Memory |
| Engine Electrical System | 12 14 09 | June-09 | M57Y Eng | M57Y Diesel; Service Engine Soon Lamp Illuminated - No Faults Stored |
| Engine Electrical System | 12 17 09 | May-09 | X5/X6 | Water Is Leaking into the Electronics Box |
| Engine Electrical System | 12 18 09 | May-09 | X5 | Service Action: Program Control Units (DME - DMTL Diagnosis) |
| Engine Electrical System | 12 21 09 | June-09 | F01/02 w/N63 | Loss of Power, Extended Engine Cranking, or Engine Cranks But Does Not Start |

no 04, 06, 07, 08

02, 03, 04, 12, 13, 20, 24, 26 other models, 01, 14, 19, 21, 27 NU

| | | | | |
|---------------------|-----------------|---------------------|-----------------------|---|
| Fuel Systems | 13 01 04 | July-04 | E60/E63 (V8) | Recall Campaign 04V- 303: Retaining Clip Retrofit for the Fuel Line Quick Release Coupling |
| Fuel Systems | B130104Q&A | P/O 13 01 04 | E60/E63 (V8) | Q&A |
| Fuel Systems | 13 01 06 | September-06 | All | Alcohol Fuel Blends in BMW Vehicles (replaces March 06) |
| Fuel Systems | 13 02 06 | September-06 | All | TOP TIER Detergent Gasoline in BMW Vehicles (Replaces 03/06) |
| Fuel Systems | 13 03 06 | May-06 | All | Fuel Pump Failure after Refueling with Ethanol Fuel Blend |
| Fuel Systems | 13 04 06 | August-06 | All | Alcohol Detection Procedure |
| Fuel Systems | 13 05 06 | September-06 | All | BMW Group Fuel System Cleaner Plus (Supersedes Aug 06) |
| Fuel Systems | 13 06 06 | November-06 | E90/E92 | High Precision Injection (HPI) Information and Service Procedures |
| Fuel Systems | 13 07 06 | November-06 | ALL | Gasoline Quality & Detergent Additives - Customer Information Brochure |
| Fuel Systems | 13 01 07 | March-09 | ALL/ex turbo | Fuel Injection and Induction System Cleaning (rpl 12/07) |
| Fuel Systems | 13 02 08 | September-08 | E90/92/93/wN54 | Service Action: Replace the High Pressure Pump |
| Fuel Systems | 13 03 08 | September-08 | E90/92/93/wN54 | Service Action: Replace the High-Pressure Pump (older vehicles) |
| Fuel Systems | 13 05 08 | February-09 | E90/92/93 M3 | Rough Idle, Rough Running, Misfiring and Loss of Power (rpl 12/08) |
| Fuel Systems | 13 02 09 | March-09 | X5d | E70 M57Y Diesel - Diagnosis for Low Pressure Fuel Supply Faults |
| Fuel Systems | 13 04 09 | March-09 | All w/N54 | N54 - Cold Start Rough Running with Misfire Fault |
| Fuel Systems | 13 05 09 | April-09 | All w/N54 | N54 - Diagnosis for FC 2AAF |
| Fuel Systems | 13 06 09 | June-09 | All port inj | Fuel Injection and Induction System Cleaning - Customer Information Brochure |

| Category | SIBs (SI B## ## ##) | Date | Application | Title |
|--|-----------------------|--------------------|--------------------|--|
| Fuel Systems | 13 07 09 | June-09 | All w/N54 | N54 - Diagnosis for "Long Crank" Complaint |
| Fuel Supply | 16 02 05 | March-05 | E60/E63 | Fuel Tank Difficult to Refuel |
| Fuel Supply | 16 01 06 | September-06 | E90 | Fuel Level Sensor Repair Procedure w/N54 |
| Fuel Supply | 16 03 06 | October-06 | E90 | Vehicle is Difficult to Refuel |
| Fuel Supply | 16 06 06 | October-06 | E60 | Humming/Buzzing Noise from Center Dash Area When Accelerator is Depressed |
| Fuel Supply | 16 08 06 | February-07 | E90 | N51 PZEV - Erroneous Fuel Gauge Reading (Replaces 12/06) |
| Fuel Supply | 16 01 07 | August-07 | All | Testing Evaporative Systems for Leaks |
| Fuel Supply | 16 02 07 | December-07 | E70 (X5) | Service Action: Repair the Fuel Tank Level Sensor |
| Fuel Supply | 16 01 08 | September-08 | All w/N54 | DMTL Tank Leakage Test Module Provides Inaccurate Results |
| Fuel Supply | 16 03 08 | January-09 | E90/X5 w/d | Diesel Misfueling Protection Bypass Adapter |
| Fuel Supply | 16 01 09 | May-09 | X3/3 w/d | DEF Extraction and Refill |
| - 02 other models | | | | |
| Cooling Systems | 17 01 07 | October-07 | ALL | BMW Long-Term Antifreeze/Coolant: Maintenance, Repairs and Replacement Requirements |
| Cooling Systems | 17 01 08 | July-08 | E9x M3 | Low Coolant Warning Lamp is Illuminated |
| Cooling Systems | 17 01 09 | June-09 | X5 (E70) | Service Action: E70 N52K Coolant Hose Seal Plug Retrofit |
| Cooling Systems | 17 02 09 | July-09 | E70/E90 w/d | Oil Leak from Turbocharger Charge Air Hose |
| Cooling Systems | 17 03 09 | July-09 | E70/E90 w/d | N63 Turbocharger Auxiliary Water Pump Faults |
| Clutch | 21 02 06 | October-06 | E60 (M5) | S85 - SMG Transmission Faults 4FA0, 4F80 and Clutch is Damaged |
| Clutch | 07 for Z4 | May-07 | Z4 | Service Action: Clutch Fork Lever Inspection |
| Drive Shaft | 26 01 06 | June-07 | E65/E66 | Noise from Driveshaft Area (Rpl 06/06) |
| Drive Shaft | 26 01 08 | July-08 | 3 Series Xi | Service Action: Replace Front Propeller Shaft Bolts (Build 12/07) |
| Manual Transmission | 23 01 05 | November-05 | E60/M5 | E60 M5 - CAN Communication Fault FFFF |
| Manual Transmission | 23 01 06 | February-06 | M Cars | SMG III: Fault Code 5101 Analyze Hydraulic Sensor (Supercedes Jan 06) |
| Manual Transmission | 23 02 06 | January-06 | SMG tranny | Towing Vehicles with SMG Transmissions |
| Manual Transmission | 23 03 06 | April-07 | M Cars | Getrag SMG Transmission Repair & Replacement Information (SMG II and III) (Rpl 02/06) |
| Manual Transmission | 23 04 06 | April-06 | E60/E63 | ZF SMG FC 4F6F - Hydraulic Pump Failure (Supercedes Mar 06) |
| Manual Transmission | 23 07 06 | February-07 | M Cars | M5, M6 with SMG III; FC 4F42/4F43 - Hydraulic Unit Faults (Replaces 12/06) |
| Manual Transmission | 23 08 06 | January-07 | All SMG Cars | SMG - Service Functions Performed after Drivetrain Repairs |
| Manual Transmission | 23 09 06 | January-07 | All non M SMG | ZF SMG - Replacement Parts Availability |
| Manual Transmission | 23 01 07 | August-07 | S85 M5 | Service Action: Replace SMG Hydraulic Unit Electric Motor on M5 Vehicles (rpl 7/07) |
| Manual Transmission | 23 02 07 | March-08 | E60/E63 | Voluntary Emissions Recall 07E-A02: SMG Reprogramming |
| Manual Transmission | 23 03 07 | December-07 | ZF SMG | TeileClearing (Enhanced Technical Support) for ZF SMG Transmissions |
| Manual Transmission | 23 01 08 | May-08 | Many | Vehicles equipped with Manual Transmissions manufactured by Getrag: |
| Manual Transmission | 23 02 08 | July-08 | E46 | E46, E85 with M54 and ZF SMG - OBD Communication |
| Manual Transmission | 23 03 08 | December-08 | M5/M6 | M5, M6 with SMG III; FC 4F82/4F83/4F84/4F85 - Gear Blocking Faults (rpl 10/08) |
| Manual Transmission | 23 01 09 | May-09 | 1/3 series | Gears Difficult to Select in 6-Speed Manual Transmission - Diagnostic Hints |
| - 06 other model | | | | |
| Automatic Transmission | 24 08 03 | November-04 | E60 | EGS Fault 4F6A |
| Automatic Transmission | 24 02 05 | April-06 | E60 | Service Action: Replace Mechatronic Adapter (Supercedes May 05) |
| Automatic Transmission | 24 03 05 | February-07 | E60/E63 | Harsh 2-1 Downshift (Replaces 6/05) |
| Automatic Transmission | 24 06 05 | November-05 | E60/E63 | Safety Recall Campaign 05V-504: Parking Lock Guide Plate |
| Automatic Transmission | B240605CustomerLetter | P/O 24 06 05 | E60/E63 | Recall Letter |
| Automatic Transmission | B240605Q&A. | P/O 24 06 05 | E60/E63 | Q&A |
| Automatic Transmission | 24 06 06 | October-06 | E90 | A Slight Bump is Felt Shortly after the Vehicle Comes to a Stop (Supercedes Aug 06) |
| Automatic Transmission | 24 11 06 | October-06 | E92 | E92; N54 with 6HP16 - Diagnosis for EGS FC 511B |
| Automatic Transmission | 24 04 07 | April-07 | E90/E91/E92 | ZF 6HP19TU in Failsafe Mode with Fault 4F8D Stored |
| Automatic Transmission | 24 09 07 | April-07 | E90/E91/E92 | The Service Engine Soon Light is on and EGS Fault CF1C Stored |
| Automatic Transmission | 24 10 07 | May-08 | E60/3 Series | The Transmission is in "Failsafe" mode with EGS Fault CF33 Stored - rpl 4/07 |
| Automatic Transmission | 24 11 07 | April-07 | 3 Series | GM6 - 6L46R Transmission Adaptations and Terminology (info only) |
| Automatic Transmission | 24 13 07 | June-07 | All STEP Equipped | Various Complaints Due to Poor Connection at Transmission Connector |
| Automatic Transmission | 24 19 07 | December-08 | E60 | Drive Position "D" Cannot be Engaged - rpl 6/08 |
| Automatic Transmission | 24 20 07 | October-07 | 3 Xi | 6L45R Transmission with AWD Leaks from the Selector Shaft Seal |
| Automatic Transmission | 24 21 07 | January-09 | 3 Series | Diagnosis - DME Fault CDB4: No Message (transmission data 3, 3B1) |
| Automatic Transmission | 24 22 07 | October-07 | 3 Series | 6HP19TU (6HP21) - Fault 5087: One-Touch Hardware is Stored |
| Automatic Transmission | 24 23 07 | February-08 | All STEP Equipped | 6-Speed Automatic Transmissions Diagnosis and Troubleshooting Hints (rpl 12/07) |
| Automatic Transmission | 24 01 08 | December-08 | E65/66 | E65, E66 with 6HP26 - Diagnosis for EGS FC 4F81 - rpl 2/08 |
| Automatic Transmission | 24 02 08 | September-08 | E60/63/70 | Drivability Complaints due to Cooling Fan Relay Failure - rpl 2/08 |
| Automatic Transmission | 24 03 08 | June-09 | E9x/E60 | E60, E9x with N54 and 6HP19TU - Jolt and Delay when Pulling Away (rpl 1/09) |
| Automatic Transmission | 24 04 08 | September-08 | E70 (X5) | E70, X5 3.0i with N52K and 6HP19TU - Transmission Drivability Complaints - rpl 7/08 |
| Automatic Transmission | 24 05 08 | August-08 | E65/66 | E65, E66 with N62TU - Various Drivability Complaints |
| Automatic Transmission | 24 06 08 | October-08 | E65/66 | E70, X5 4.8i with N62TU and 6HP26TU - Various Drivability Complaints |
| Automatic Transmission | 24 08 08 | December-08 | E60/61/X5(E70) | E6x with 6HP19TU - Transmission Clunks after Engine Start - rpl 10/08 |
| Automatic Transmission | 24 09 08 | October-08 | E60/61 & X5 | GWS - Transmission Jumps Back to Neutral |
| Automatic Transmission | 24 01 09 | May-09 | X5 | E70 with ZF 6HP26TU - Delayed Up-shift in Hill Program |
| Automatic Transmission | 24 03 09 | April-09 | E60/E63 | 550i and 650i with N62TU and 6HP26 - Various Drivability Complaints |
| 24 process info | | | | |
| Gear Shift Mechanism | 25 01 07 | January-07 | E70 | Service Action: Gear Shift Knob Replacement |
| Gear Shift Mechanism | 25 02 07 | November-07 | E60 | Diagnostic for GWS Faults - Drive Position "D" Cannot be Engaged |
| Gear Shift Mechanism | 25 03 07 | November-07 | E60/E63 | Sport Transmission Paddle Shifters Inoperative - Diagnosis |
| Gear Shift Mechanism | 25 01 08 | June-08 | M5/M6 | M5, M6 with SMG III - Gear Selector Display Position Changes from N to R (3-7/07) |
| Gear Shift Mechanism | 25 01 09 | February-09 | E6x | E6x GWS: Gears D or R Cannot Be Selected |
| Gear Shift Mechanism | 25 02 09 | April-09 | X5/X6 | E70, E71 GWS - Gears Intermittently Cannot Be Engaged |
| 14 - 18 other models | | | | |
| Double-clutch Transmission with Dri | 28 01 08 | June-09 | M3 | M Double-clutch Transmission with Drivelogic Fluid Requirements (rpl 5/08) |
| Double-clutch Transmission with Dri | 28 02 08 | May-09 | M3 | TeileClearing for M DCT Drivelogic (double-clutch) Transmission (rpl 7/08) |
| Double-clutch Transmission with Drivel | 28 03 08 | July-08 | M3 | M Double-Clutch Transmission with Drivelogic - Transmission Filling and Fluid Level Checking Procedure |
| Double-clutch Transmission with Drivel | 28 04 08 | November-08 | M3 | M Double-Clutch Transmission with Drivelogic - Transmission Replacement Procedure |
| Double-clutch Transmission with Drivel | 28 05 08 | October-08 | M3 | M3 with DCT with Drivelogic - Gearbox Emergency Program with FC 5060 |
| Double-clutch Transmission with Drivel | 28 06 08 | November-08 | M3 | Recall Campaign 08V-595: M3 with M DCT - Reprogramming for Incorrect DCT Clutch Operation |
| Double-clutch Transmission with Dri | 28 07 08 | June-09 | M3 | M3 with M DCT - Complaint of Delayed Throttle Response |
| Double-clutch Transmission with Drivel | 28 01 09 | March-09 | M3 | M3 with M DCT - Gearbox Warning Lamp with FC 5A87, 5A81 or 5A5B |
| Front Axle | 31 02 04 | August-04 | All | Rattling Noise From Front or Rear Axle |

| Category | SIBs (SI B##-##-##) | Date | Application | Title |
|------------------------------|---------------------|--------------|--------------------|--|
| Front Axle | 31 02 06 | June-06 | E60/E63 | Recall Campaign 06V-187 : Front Axle Control Arm and Tension Strut Fasteners |
| Front Axle | 31 03 06 | November-06 | E90 | Recall Campaign 06V-400: Check Tightening Torque of Front Axle Control Arms and Tie Rods |
| Front Axle | 31 01 07 | January-08 | E70 (X5) | Knocking Noise from Front Suspension |
| Front Axle | 31 01 08 | November-08 | E53 (X5) | E53 (X5) - Replacement of Front Outer CV Joint (rpl 10/08) |
| Front Axle | 31 01 09 | February-09 | 1, 3 ser not M3 | Creaking or Groaning Noise During Compression and/or Rebound of Front Axle |
| Front Axle | 31 02 09 | June-09 | E46/x | E46 All-wheel Drive - Replacement of Front Outer CV Joint |
| Steering and Wheel Alignment | 32 01 05 | July-05 | E60 | Power Steering Assist Enhancement |
| Steering and Wheel Alignment | 32 04 05 | June-05 | E60 | Steering Column Comfort Exit Feature |
| Steering and Wheel Alignment | 32 07 05 | September-05 | E60/E63 | Active Front Steering, Noise Fault Code 613E |
| Steering and Wheel Alignment | 32 13 05 | October-05 | E60/E63 | Active Front Steering, Fault Code 6141 |
| Steering and Wheel Alignment | 32 14 05 | October-05 | E60/E63 | Active Front Steering Sensitivity |
| Steering and Wheel Alignment | 32 01 06 | February-06 | E90 | Service Action: Install Clip for Power Steering Line |
| Steering and Wheel Alignment | 32 04 06 | February-06 | E60/E63 | AFS Programming |
| Steering and Wheel Alignment | 32 05 06 | March-06 | E90 | Steering Wheel Offset |
| Steering and Wheel Alignment | 32 06 06 | March-06 | E60/E63 | Steering Angle Sensor Adjustment |
| Steering and Wheel Alignment | 32 07 06 | April-06 | E90/91 | Steering Column Clicking Noise |
| Steering and Wheel Alignment | 32 04 07 | May-08 | ALL | TeileClearing (Enhanced Technical Support) for Steering Systems |
| Steering and Wheel Alignment | 32 07 07 | January-08 | E60/E70 | Active Front Steering (AFS) Warning Lamp; Fault Code 6141 stored |
| Steering and Wheel Alignment | 32 01 08 | January-08 | E70 (X5) | Active Steering Troubleshooting Procedures |
| Steering and Wheel Alignment | 32 02 08 | August-08 | M5/M6 | Repair Instructions for Power Steering Pump and Pressure Line |
| Steering and Wheel Alignment | 32 04 08 | January-09 | 1,3,5,6 & X5 | Active Steering (AL) Warning Lamp Illuminated, Fault Code 6149 Stored |
| Steering and Wheel Alignment | 32 06 08 | October-08 | X5/X6 | Clicking Noise during Steering Column Adjustment |
| Steering and Wheel Alignment | 32 07 08 | March-09 | E46/53/60/61/83 | Squeaking Noise from the Steering Gear |
| Steering and Wheel Alignment | 32 08 08 | November-08 | X5/X6 | Steering Column Position Is Lost with Easy Entry |
| Steering and Wheel Alignment | 32 10 08 | August-08 | All | Wheel Alignment Data |
| Steering and Wheel Alignment | 31 01 09 | May-09 | 3 series | Heated Steering Wheel Malfunction (rpl March/09) |
| | | no 05, 06 | | |
| Rear Axle | 33 01 02 | March-08 | M Cars | Grinding Noise from the Differential during Slow Cornering |
| Rear Axle | 33 01 06 | April-06 | E60 (M5) | Grating Noise from Differential During Slow Cornering |
| Rear Axle | 33 02 06 | September-06 | E60/E63/E65 | Recall Campaign 06V-277: Inspect Rear Shock Absorbers (Supercedes Aug 06) |
| Rear Axle | 33 01 07 | October-07 | E60 - M5 | E60 M5 Howling Noise from Rear Axle Area |
| Rear Axle | 33 01 08 | March-08 | 3 series M/S65 | E90, E92, E93 M3 - "Clunk Noise" on Load Reversal |
| Rear Axle | 33 02 08 | April-08 | E70 (X5) | Recall Campaign 08V-170: Replace Rear Stabilizer Bar (mfr March 08) |
| Rear Axle | 33 03 08 | April-08 | All models | Differential Cover Sealer |
| Rear Axle | 33 04 08 | October-08 | 1,3,5,6,7 ser & Z4 | Clicking or Cracking Noise from Rear Differential |
| Rear Axle | 33 05 08 | August-08 | X5, X6 | Cracking or Banging Noise from Rear Axle |
| Rear Axle | 33 07 08 | December-08 | E36/46/Z4/9x/82 | Rear Spring Repair Procedures |
| Rear Axle | 33 08 08 | December-08 | X6 | Oil Ageing |
| Rear Axle | 33 09 08 | December-08 | X6 | No Communication with ICM After Programming |
| Rear Axle | 33 01 09 | May-09 | X6 | Differential Output Flange Loose (QMVH) |
| Rear Axle | 33 02 09 | May-09 | X6 | Rattle from Rear Suspension |
| Brakes | 34 06 05 | July-05 | E90 | DSC MK60E5 Fault Codes: 5DB6, 5DC6, 5E30, 5D8F |
| Brakes | 34 02 06 | March-06 | E60/E63 | Brake Squeals |
| Brakes | 34 04 06 | April-07 | E60/E63/E90 | DSC Warning - Various SZL FCs Stored (Supercedes Jun 06)-Changed to e90 only?? |
| Brakes | 34 05 06 | September-06 | E60/E63 | Service Action: Replace SZL Optical Element (Made Svc Action) |
| Brakes | 34 02 07 | September-07 | E70 (X5) | Recall Campaign 07V-391: Inspect the Brake Fluid Reservoir Cap |
| Brakes | 34 03 07 | September-07 | E70 (X5) | DSC Warning Lamp Illuminated |
| Brakes | 34 04 07 | October-07 | E60/E63 | DSC/DXC Warning Lamp, Fault Code 5EBA (may - June 07 production) |
| Brakes | 34 05 07 | October-07 | E70 (X5) | Replacement of the Parking Brake Module (EMF) |
| Brakes | 34 06 07 | November-07 | E90/91/92/93 | Additional Effort Required to Press Brake Pedal Prior to Engine Initial Start |
| Brakes | 34 07 07 | November-07 | M5/M6 | M5, M6 - DSC Disabling Function |
| Brakes | 34 01 08 | April-08 | E70 (X5) | The Parking Brake Warning Is Illuminated and Fault Code 6032 Is Stored |
| Brakes | 34 02 08 | April-08 | 3 Series | Erroneous Brake Pad Replacement Message |
| Brakes | 34 03 08 | May-08 | E65/66 | Parking Brake Repair Instructions |
| Brakes | 34 05 08 | August-08 | All | Brake Rotor Minimum Thickness (Insp Only Spec 2.4mm non-M) |
| Brakes | 34 07 08 | August-08 | X5/X6 | Parking Brake Warning Illuminated; Fault Code 600D and/or 600B Is Stored |
| Brakes | 34 08 08 | October-08 | X5/X6 | Brake Squeal from Pad Wear Sensor (rpl 8/08) |
| Brakes | 34 09 08 | October-08 | E60/E63 | Brake Squeak from Pad Wear Sensor |
| Brakes | 34 10 08 | November-08 | E9x & M3 | Rattle Noise from Front Wheel Area |
| Brakes | 34 11 08 | December-08 | 1, 3 series & Z4 | TeileClearing for Dynamic Stability Control (DSC) |
| Brakes | 34 12 08 | April-09 | X6 | TeileClearing for Integrated Chassis Management (ICM) |
| Wheels and Tires | 36 01 04 | August-05 | BMW Center | Hunter GSP97BMW Wheel Balancer - Features and Operator Training |
| Wheels and Tires | 36 02 05 | July-05 | E60 | Noise and/or Vibration Caused by Irregular Tire Wear |
| Wheels and Tires | 36 04 05 | October-05 | E60 | Erroneous Flat Tire Monitor Warning |
| Wheels and Tires | 36 05 05 | June-05 | All | Tire Pressure Monitoring Systems (TPMS) |
| Wheels and Tires | 36 06 05 | May-05 | E60 | Wheels - Different between X models and regular models |
| Wheels and Tires | 36 04 06 | April-06 | E60 | Nitrogen Inflated Tires |
| Wheels and Tires | 36 02 07 | September-07 | 3 Series | Service Action: Reprogram the Control Module for the Tire Pressure Monitoring System (RDC) |
| Wheels and Tires | 36 03 07 | September-07 | All | Flat Tire Monitor System (FTM) Diagnosis |
| Wheels and Tires | 36 01 08 | August-08 | All | Tire Pressure Warning Caused by Damaged Wheel Electronics |
| Wheels and Tires | 36 02 09 | June-09 | 5 series | Retrofit Spare Tire and Jack Kit |
| Suspension | 37 02 05 | August-05 | E60/E63 | Anti-Roll Stabilization Noise |
| Suspension | 37 01 06 | March-06 | E61 | Chafed Ride Height Sensor Cable |
| Suspension | 37 01 07 | November-07 | E70 (X5) | Knocking Noise from Front Suspension |
| Suspension | 37 02 07 | October-07 | E70 (X5) | The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored |
| Suspension | 37 03 07 | January-08 | E70 (X5) | Dynamic Drive (ARS) Front Sway Bar Repairs |
| Suspension | 37 01 09 | April-09 | E61 | Self-leveling Suspension Faults |
| Suspension | 37 02 09 | May-09 | X6 | Rattle from Rear Axle |
| Body | 41 01 05 | May-05 | E60/E63 | Structural Aluminum Repair Precautions |
| Body | 41 05 06 | February-06 | E60/E63 | Trunk Lid Opens Too Fast/Slow |
| Body | 41 02 07 | October-07 | E70(X5) | Water Leak from the Upper Tailgate Area |
| Body | 41 01 08 | April-08 | E90/91 | Rear Door Brake Connection Pulls out of the B-pillar |
| Body | 41 02 08 | March-09 | X5, X6 | Service Action: Remove Excessive Underbody Coating |
| Body | 41 01 09 | June-09 | E46 | Rear Axle Support Inspection |
| Body | 41 02 09 | June-09 | E46 | Rear Axle Carrier (Sub-frame) Support Proposed Class Action Settlement |

| Category | SIBs (SI B## ## ##) | Date | Application | Title |
|-----------------------------|---------------------|---------------------|----------------------|---|
| Body Equipment | 51 13 04 | August-07 | E60/E63 | Rattling Noise from Center Display (Replaces 06/07) |
| Body Equipment | 51 02 05 | February-07 | E60 | Squeaking Noise from Door Frame area While Driving (Replaces 12/06) |
| Body Equipment | 51 04 05 | June-05 | E60/E61 (xi, xiT) | Incorrect or Missing Floor Mats (deliveries before May 16, 05) |
| Body Equipment | 51 08 05 | July-05 | E60/E63 | Door Mirror Glass Discolored after Programming |
| Body Equipment | 51 17 05 | July-05 | E60 | Replacement Windshield - VIN Window in Wrong Position |
| Body Equipment | 51 30 05 | October-05 | E90 | Cracking or Ticking Noise from Lower B-Pillar |
| Body Equipment | 51 31 05 | March-06 | E90 | Center Console Heats Up In Knee Contact Area (Supercedes Nov 05) |
| Body Equipment | 51 32 05 | October-05 | E90 | Clicking Noise from Upper B-pillar Trim |
| Body Equipment | 51 33 05 | October-05 | E90 | Water Ingress from A/C Blower Housing |
| Body Equipment | 51 37 05 | December-05 | E90 | The cup holder jams when retracted |
| Body Equipment | 51 10 06 | May-07 | E60 | Anti-trap is Activated when Raising the Front Window (rpl 2/06) |
| Body Equipment | 51 14 06 | March-08 | 3 series/X5 | Outside Door Handles Hanging up in the Pulled Position (rpl 2/08) |
| Body Equipment | 51 18 06 | May-07 | E9x series | Interior Door Grab Handle Finish Peeling (rpl 8/06) |
| Body Equipment | 51 24 06 | November-06 | E61 | Luggage Compartment Roller Cover Malfunction |
| Body Equipment | 51 27 06 | January-07 | E92 | Rattle Noise from B-Pillar Trim |
| Body Equipment | 51 06 07 | March-07 | E60 - M5 | Service Action: Replace Underbody Panel |
| Body Equipment | 51 08 07 | March-07 | E90/E91/E92 | Erroneous Trunk Lid Open Check Control Message |
| Body Equipment | 51 10 07 | April-07 | E90/E92/E93 | Rear Window will not Fully Defrost |
| Body Equipment | 51 12 07 | May-07 | E93 | Service Action: Install Luggage Compartment Labels |
| Body Equipment | 51 14 07 | June-07 | E93 | Center Console Lock Inoperative |
| Body Equipment | 51 16 07 | July-07 | E93 | Rear Roundel Emblem Comes Loose |
| Body Equipment | 51 17 07 | July-07 | E93 | Rear Window(s) Inoperative |
| Body Equipment | 51 19 07 | November-07 | E90 | Doors will not Unlock Using the Key Fob or Central Locking Button (rpl 09/07) |
| Body Equipment | 51 22 07 | September-07 | E91 | Creaking Noise from the C-Pillar Area |
| Body Equipment | 51 24 07 | November-07 | E93 | Water Leaks into the Sides of the Luggage Compartment |
| Body Equipment | 51 25 07 | November-07 | 3 series | Floor Mat Retainer in Wrong Location |
| Body Equipment | 51 28 07 | December-07 | E93 | Compass Changes Direction when Operating the RHT |
| Body Equipment | 51 29 07 | December-07 | E61 | Luggage Compartment Roller Cover Symptom Diagnosis |
| Body Equipment | 51 30 07 | December-07 | E91 | Noises from the Roller Cover Retainers |
| Body Equipment | 51 31 07 | December-07 | E70 (X5) | Tailgate Soft-close Malfunction |
| Body Equipment | 51 32 07 | January-08 | E70 (X5) | Rattle from the Upper Tailgate Trim |
| Body Equipment | 51 35 07 | January-08 | E70 (X5) | Tailgate Latch Noisy when Closing |
| Body Equipment | 51 02 08 | February-08 | 3 series | Compass is Difficult to Read at High Temperatures |
| Body Equipment | 51 03 08 | February-08 | E91 | Luggage Compartment Roller Cover Symptom Diagnosis |
| Body Equipment | 51 04 08 | April-08 | E93 | RHT Rear Roof Shell Headliner Eliminated |
| Body Equipment | 51 05 08 | April-08 | E60/63 | Door Opening/Closing Symptom Diagnosis |
| Body Equipment | 51 06 08 | March-09 | 1 Series | Window Short-drop or Anti-trap Malfunctions |
| Body Equipment | 51 07 08 | May-08 | E93 | Rear Windows Inoperative After Junction Box Replacement |
| Body Equipment | 51 08 08 | May-08 | E60/63 | Power Window Drives: Symptom Diagnosis |
| Body Equipment | 51 09 08 | May-08 | 1 Series | Instrument Panel Symptom Diagnosis |
| Body Equipment | 51 10 08 | May-08 | E60/63 | Noises from the Front Doors - Symptom Diagnosis |
| Body Equipment | 51 11 08 | May-08 | E63 | Water Ingress at the Doors: Symptom Diagnosis |
| Body Equipment | 51 12 08 | May-08 | 1 Series | Rattle from the Armrest Hinge |
| Body Equipment | 51 16 08 | June-08 | 3 series | Hood Insulation Pad Discontinued |
| Body Equipment | 51 17 08 | August-08 | X5/X6 | Grating Noise from the Instrument Panel |
| Body Equipment | 51 18 08 | June-08 | 3 series | Instrument Panel Symptom Diagnosis |
| Body Equipment | 51 19 08 | July-08 | 3 series | Passenger Side Floor Mat Curling |
| Body Equipment | 51 20 08 | July-08 | X3 | Doors Will Not Unlock with the Remote or Central Locking Switch |
| Body Equipment | 51 21 08 | July-08 | 1 Series vert | Squeak from Rear Trim with the Convertible Top Open |
| Body Equipment | 51 23 08 | July-08 | 1 Series vert | Clicking Noise from the Bottom of the A-pillar |
| Body Equipment | 51 24 08 | September-08 | M3 | Washer Fluids Leaking out of the Right Side M Vent |
| Body Equipment | 51 25 08 | September-08 | 1 Series | Buzzing Noise from the Center Vent Area |
| Body Equipment | 51 26 08 | September-08 | E64 | Service Action: Modifying the Rear Water Drain Hoses |
| Body Equipment | 51 27 08 | October-08 | E60/61 | The Front and Rear Doors Do Not Unlock at the Same Time |
| Body Equipment | 51 28 08 | September-08 | 3 series | Door Mirrors Do Not Fold When Using "Convenient Closure" |
| Body Equipment | 51 29 08 | November-08 | E64 | Water Leak into the Trunk Area |
| Body Equipment | 51 30 08 | November-08 | X5, X6 | Water Leak in the Front Right Footwell Area |
| Body Equipment | 51 34 08 | November-08 | 1 series | Wind Noise from the B-pillar at High Speeds |
| Body Equipment | 51 35 08 | January-09 | All | Cracked or Damaged Windshields |
| Body Equipment | 51 36 08 | February-09 | All | Outside Mirror Moves when Unlocking the Vehicle |
| Body Equipment | 51 01 09 | January-09 | X6 | Rear Bumper Cover Sticks Out Below the Tail Lamp |
| Body Equipment | 51 02 09 | January-09 | 1 Series | Buzzing Noise from the Door Panel Pocket |
| Body Equipment | 51 04 09 | February-09 | X5/X6 | Gas Strut for Spare Wheel Cover Deleted |
| Body Equipment | 51 05 09 | February-09 | E90/91 | Buzzing Noise from the Door Speaker Area |
| Body Equipment | 51 06 09 | February-09 | 5 Series | Squeaking Noise from the Top of the B-pillar |
| Body Equipment | 51 07 09 | March-09 | 1 Series | Creaking Noise from the Center Armrest |
| Body Equipment | 51 08 09 | March-09 | X5/X6 | Ashtray Does Not Pop Out When the Release is Pressed |
| Body Equipment | 51 09 09 | April-09 | X5/X6 | Rattle from the Luggage Compartment |
| Body Equipment | 51 11 09 | April-09 | F01/02 | Wind Noise from the A-pillar Area |
| Body Equipment | 51 13 09 | July-09 | F01/02 | Rattling Noises from Around the Glove Box |
| Body Equipment | 51 14 09 | March-09 | F01/02 | Automatic Trunk Lid Does Not Close Properly |
| Body Equipment | 51 16 09 | April-09 | 3 series | Rattle Noise from the Radio Area |
| Body Equipment | 51 17 09 | April-09 | 3 series | Replacing Front Cup Holders - part numbers |
| Body Equipment | 51 18 09 | May-09 | 1 series | Noises from the Glove Box Area |
| Body Equipment | 51 19 09 | May-09 | 1 series | Water Leaking into the Luggage Compartment |
| Body Equipment | 51 20 09 | June-09 | 3/5 touring | Tailgate Does Not Open Fully in Cold Temperatures |
| Body Equipment | 51 21 09 | June-09 | 1 series | Rattle Noise from the Center Vent on the Instrument Panel |
| Body Equipment | 51 22 09 | June-09 | Z4 (E89) | Creaking Noise from the Glove Box |
| Body Equipment | 51 23 09 | July-09 | F01/02 | Service Action: Replace the Front Door Handle Bowden Cables |
| Body Equipment | 51 24 09 | July-09 | 3 series | Smoker's Package, Option Code 441 |
| Body Equipment | 51 25 09 | July-09 | X5/X6 | Rattle Noise from the Front Door |
| Body Equipment | 51 27 09 | July-09 | F01/02 | The DVD Changer Cover Doesn't Open Fully |
| Body Equipment | 51 28 09 | July-09 | F01/02 | Roof Rack Cannot Be Installed |
| Seats | 52 02 04 | April-05 | E60/E63 | Recall Campaign 04V-575: Modification of the Front Seat Heater Circuit |
| Seats | 52 05 07 | August-07 | E93 | Lumbar Support Inoperative |
| Seats | 52 01 08 | February-08 | E60/E61 | Active Backrest Width Adjustment Inoperative |
| Seats | 52 02 08 | January-08 | Z4 | Knocking Noise from the Seat Frame |
| Seats | 52 03 08 | March-08 | X5 | Lateral Seat Movement and/or Noises |
| Seats | 52 04 08 | June-08 | E93 | Backrest Seat Cover Material Loose |
| Seats | 52 05 08 | June-08 | E92 | Seat Frame Design Change |
| Seats | 52 06 08 | August-08 | 1/3 series | Raised Area on the Seat Bottom |
| Seats | 52 07 08 | November-08 | E90/91 | Stiffness in the Fore and Aft Adjustment of the Seat |
| Seats | 52 09 08 | April-09 | X5, X6 | Seat Heater Does Not Feel Hot Enough (rpl 11/08) |
| Seats | 52 01 09 | June-09 | E64 | Seat Adjustment when Unlocking (rpl 1/09) |
| Seats | 52 02 09 | March-09 | E70/71 (X5/6) | Thigh Support Cover Loose |
| Seats | 52 05 09 | June-09 | E70/71 (X5/6) | Rattle from the Front Seat Head Restraints |
| Seats | 52 06 09 | July-09 | X5/X6 | Squeaking Noise from the Passenger Seat |
| Seats | 52 07 09 | July-09 | X5/X6 | Noise from the Active Head Restraint Connecting Cable |
| Seats | 52 08 09 | July-09 | X5/X6 | Noises From the Forward/Back Seat Adjuster Drive Shaft |
| Seats | 52 09 09 | August-09 | X5/X6 | Seat Backrest Panel Creaks |
| 01, 02, 04-07 all X5 | | | | |
| Special Roofs | 54 03 05 | July-05 | E64 (Cabrio) | Convertible Top will not Lower |

| Category | SIBs (SI B### ## ##) | Date | Application | Title |
|----------------------|----------------------|--------------------|------------------------|--|
| Special Roofs | 54 13 06 | May-06 | E60 | SHD Coding Error - Progran V21.1 |
| Special Roofs | 54 17 06 | November-06 | E64 (Cabrio) | Convertible Top Does Not Completely Open or Close |
| Special Roofs | 54 01 07 | July-07 | E93 | Service Action: Replace Roof Shell Trim Strips (rpl 4/07) |
| Special Roofs | 54 02 07 | April-07 | E93 | RHT Opens but Trunk Lid will not Close |
| Special Roofs | 54 03 07 | April-07 | E93 | Convenience Open/Close Function |
| Special Roofs | 54 06 07 | March-08 | E93 | Roof Shell 1 Slams Down on the Cowl when Closing the RHT (rpl 5/07) |
| Special Roofs | 54 08 07 | May-07 | E93 | RHT Statuses Reversed in DIS/GT1 |
| Special Roofs | 54 09 07 | June-07 | E93 | RHT Status Request Supplement |
| Special Roofs | 54 10 07 | August-07 | E93 | RHT Stops Opening in the Stacked/Extended Position |
| Special Roofs | 54 11 07 | September-07 | E93 | Headliner is Loose in the C-pillar Area |
| Special Roofs | 54 12 07 | September-07 | E93 | Rattle from the Front Latch of the RHT |
| Special Roofs | 54 15 07 | April-08 | E93 | RHT Symptom Diagnosis Update (rpl 11/07) |
| Special Roofs | 54 16 07 | November-07 | E93 | Headliner Loose Near A-pillar |
| Special Roofs | 54 17 07 | January-08 | E93 | Headliner Fabric is Creased and/or Stretched |
| Special Roofs | 54 01 08 | January-08 | E61/91 | Wind Noise from the Panoramic Sunroof |
| Special Roofs | 54 02 08 | January-08 | E60 | Water Leak from Sunroof |
| Special Roofs | 54 03 08 | February-08 | E93 | RHT Seal Replacement Update |
| Special Roofs | 54 04 08 | August-09 | E93 | Wind Buffeting/Pressure Noise at Highway Speeds (rpl 10/08) |
| Special Roofs | 54 05 08 | March-08 | E83 (X3) | Rattle from Panoramic Roof when Fully Open |
| Special Roofs | 54 06 08 | May-08 | (E70) X5 | Clicking Noise From Sunroof |
| Special Roofs | 54 07 08 | September-08 | E88 (1 Series) | Convertible Top Material Loose at Rear Bow (rpl 6/08) |
| Special Roofs | 54 08 08 | March-09 | (E70) X5 | The Sunroof's Rear Glass Panel Does Not Close from the Vent Position (rpl 8/08) |
| Special Roofs | 54 09 08 | August-08 | E93 | Cleaning Excess Butyl from RHT Roof Shells |
| Special Roofs | 54 11 08 | April-09 | All w/Pan Roof | TeileClearing for Panoramic Roof (rpl 10/08) |
| Special Roofs | 54 12 08 | August-09 | (E70) X5 | Water Leak from the Front of the Sunroof (rpl 11/08) |
| Special Roofs | 54 01 09 | February-09 | E88 (1 Series) | Service Action: Repair of the Convertible Top |
| Special Roofs | 54 03 09 | May-09 | 1,3,6 Verts | Soft Top Switch Function and Window Operation (rpl 3/09) |
| Special Roofs | 54 04 09 | May-09 | 5, 7, X5/X6 | Wind Noise or Water Leak from the Sunroof |
| Special Roofs | 54 05 09 | June-09 | 1 Series | Soft Top Does Not Close Fully |
| Special Roofs | 54 06 09 | July-09 | 1 Series | Soft Top Hydraulic System Inoperative |
| Special Roofs | 54 07 09 | July-09 | X & Touring | Squeaking Noise from the Sliding Headliner |

18 , 19 other model

| | | | | |
|-----------------------------------|-----------------------|---------------------|-------------------------|--|
| General Electrical Systems | 61 07 88 | December-06 | All | Battery Maintenance Requirements (Replaces 10/06) |
| General Electrical Systems | 61 08 00 | June-07 | All | Closed-Circuit Current Measurement (Replaces 1/07 - new cars) |
| General Electrical Systems | 61 15 02 | February-06 | E60/E63 | MOST Bus Diagnosis (Supercedes July 04 with new diagnostics & models) |
| General Electrical Systems | B611502F_Description. | P/O 61 15 02 | E60/E63 | MOST Bus Diagnosis Description |
| General Electrical Systems | B611502Charts&B.B. | P/O 61 15 02 | E60/E63 | MOST Bus Diagnosis Troubleshooting Chart |
| General Electrical Systems | 61 03 03 | January-06 | E60/E63 | CAN/Byteflight Bus Diagnostics (Supercedes June 05 - Adds E61 & E91) |
| General Electrical Systems | 61 13 02 | December-05 | E65 | CIP 16.0 - 2002 MY Electrical complaints (Supercedes April 05 w/new info) |
| General Electrical Systems | 61 14 03 | September-07 | E60/E63 | CIP Updates (CIP 27.00.00) - (Supercedes Apr 07 - 25.01.00) |
| General Electrical Systems | 61 01 04 | June-05 | E65 | CIP 17.01 - MY02-05 various complaints |
| General Electrical Systems | 61 01 04 | September-06 | E65 | Various Complaints Caused by Software Errors (21.02.01) (Supercedes Mar 06 / CIP 20.00) |
| General Electrical Systems | 61 01 05 | December-05 | E60/E63 | Special Survey for CAS related problems (Supercedes Apr 05 - Survey completed) |
| General Electrical Systems | 61 03 05 | October-07 | E90 | CIP 27.00.00 - Software errors corrected with PROGMAN (Rpl 25.01.00 4/07) |
| General Electrical Systems | 61 06 05 | September-05 | E60 | High Drain Battery Message in CIP (N52 Engine) |
| General Electrical Systems | 61 07 05 | January-06 | E60/E63 | PDC Light Flashing after SZM Replacement (Supercedes info in August 05) |
| General Electrical Systems | 61 08 05 | August-05 | E90 | Roof Functions Center Causes Various System Malfunctions |
| General Electrical Systems | 61 09 05 | August-05 | E90 | Remote Key Sticks In/Falls Out of CAS Holder |
| General Electrical Systems | 61 10 05 | August-05 | E90 | Various Electrical Problems |
| General Electrical Systems | 61 11 05 | October-05 | E60 | Battery Safety Terminal |
| General Electrical Systems | 61 12 05 | November-05 | E60/E63 | Dead Battery by MPM |
| General Electrical Systems | 61 13 05 | May-08 | E60/E63 | Dead Battery - Perform Energy Diagnosis (update to 10/07 - added models) |
| General Electrical Systems | 61 01 06 | February-06 | E90 | Trunk Opens without Request |
| General Electrical Systems | 61 02 06 | February-06 | E60/E63/E90 | Key Falls Out of, or Gets Stuck in Key Holder (Supercedes 2/06 adding models) |
| General Electrical Systems | 61 04 06 | February-06 | ALL | Exiting a Vehicle that is Double-Locked from the Outside |
| General Electrical Systems | 61 05 06 | September-07 | E65 | Various Customer Complaints Corrected With Progran |
| General Electrical Systems | 61 06 06 | May-06 | E90 | Junction Box Pin Assignment Change |
| General Electrical Systems | 61 07 06 | August-06 | E60/E63/E90 | No Crank, No Start, CAS FC A111 |
| General Electrical Systems | 61 10 06 | October-06 | E63 | Windows Convenience Open When Door is Opened |
| General Electrical Systems | 61 13 06 | October-06 | E60 | Various Electrical Problems Caused by Water Ingress |
| General Electrical Systems | 61 14 06 | October-06 | E60/E63 | One-Touch Close Inoperative after Door Module Replacement |
| General Electrical Systems | 61 15 06 | October-06 | E64 | Rear Windows Close First, or Anti-trap Activates During Convenience Closing |
| General Electrical Systems | 61 20 06 | October-06 | E60 | Rear Windows Move in Small Increments |
| General Electrical Systems | 61 22 06 | October-06 | E60 | iDrive Controller Malfunction (Low Version) |
| General Electrical Systems | 61 23 06 | October-06 | E60 | Battery Charger Causes Faults to be Set |
| General Electrical Systems | 61 24 06 | October-06 | E60 | Starts only once following EWS calibration |
| General Electrical Systems | 61 26 06 | September-06 | E90 | Central Electronics Failure, K-CAN bus Fault Codes Stored |
| General Electrical Systems | 61 27 06 | October-06 | E92 | Replacement CAS3 - Calibration Error Message |
| General Electrical Systems | 61 28 06 | May-07 | E92 | Red ELV Warning in Instrument Cluster (Replaces 1/07) |
| General Electrical Systems | 61 29 06 | April-08 | E60/E63/E90 | CAS / ELV Diagnostics (rpl 10/07) |
| General Electrical Systems | 61 31 06 | September-07 | X5 | Software Errors Corrected with Progran (update to 5/07) PROGMAN 27.01.00 |
| General Electrical Systems | 61 32 06 | December-06 | E90/91/92 | Sunroof Moves in Small Steps or Interior Lights not Working |
| General Electrical Systems | 61 33 06 | December-06 | E60/E63/E90 | Battery Warning Displayed when Deleting Transport Mode |
| General Electrical Systems | 61 34 06 | August-07 | E90/91/92 | Engine Fails to Start after CAS Replacement (update to 9/06) |
| General Electrical Systems | 61 04 07 | May-07 | E60/E63 | SZL Functions Lock Up after Deleting Transport Mode |
| General Electrical Systems | 61 08 07 | August-07 | E60/E63 | Electric Steering Lock Inoperative |
| General Electrical Systems | 61 09 07 | August-07 | E60/E65/E90 | OBID Socket Housing Cover Missing |
| General Electrical Systems | 61 12 07 | November-07 | E90 | No Crank after CAS3 Replacement |
| General Electrical Systems | 61 13 07 | November-07 | E70 (X5) | Electronic Malfunction CC Message Caused by Shorted Wiring |
| General Electrical Systems | 61 14 07 | December-07 | E60/E63 | Battery Discharged KGM FC 93AB MPM Relay Sticking |
| General Electrical Systems | 61 01 08 | January-08 | E60/E63/E90/E70 | CC Message "Increased battery discharge while stationary" |
| General Electrical Systems | 61 02 08 | February-08 | 3 series | Gong Warning Without Visual Check Control Message |
| General Electrical Systems | 61 03 08 | February-08 | E93 | Doors Will Not Lock Using Comfort Access Handles |
| General Electrical Systems | 61 05 08 | May-08 | Service Center | TeileClearing for General Electrical Systems |
| General Electrical Systems | 61 05 08 | May-08 | E90/91/92 | Windshield Wiper Parks out of Position |
| General Electrical Systems | 61 06 08 | May-08 | X5/X6 | Sliding Sunroof, Interior Lights, and Rain Sensor Are Inoperative |
| General Electrical Systems | 61 07 08 | June-08 | E60 | Rear Window Functional Problems |
| General Electrical Systems | 61 09 08 | August-08 | 1, 3, X5, X6 | Controller Fault Code A2CB Internal Control Module Fault |
| General Electrical Systems | 61 10 08 | August-08 | 3 Series w/DCT | CAS3 Fault Code A0B1 |
| General Electrical Systems | 61 11 08 | August-08 | E60/61 | Steering Wheel or Seat Adjustment Inoperative |
| General Electrical Systems | 61 12 08 | April-09 | 1 & 3 Series | Sliding Sunroof, Interior Lights, and Rain Sensor Are Inoperative |
| General Electrical Systems | 61 14 08 | September-08 | E60 | Intermittently, the Rear Doors Do Not Lock |
| General Electrical Systems | 61 16 08 | November-08 | 3er w CIC & N51 | N51 PZEV - JBE Repeat Failures Due to Shorted Fuel Sender Harness |
| General Electrical Systems | 61 17 08 | November-08 | E83 (X3) | Service Action: Reprogram General Module |
| General Electrical Systems | 61 18 08 | December-08 | BMW Centers | Battery Maintenance Requirements |
| General Electrical Systems | 61 01 09 | March-09 | All | Windshield Washer Malfunction |
| General Electrical Systems | 61 02 09 | March-09 | 7 Series (F01) | Engine Does Not Start |
| General Electrical Systems | 61 03 09 | May-09 | 7 Series (F01) | ZGM Fault Code 801C20 (Hex) or 8395808 (Dec) |
| General Electrical Systems | 61 05 09 | April-09 | 1,3,5,6,7,X5/6 | CC Message "Vehicle Battery! Increased Battery Discharge" After Vehicle Is Stationary |
| General Electrical Systems | 61 06 09 | April-09 | F01/02 | Service Action: Program Control Units (Central Gateway Module) |
| General Electrical Systems | 61 07 09 | April-09 | 5, 6, E46, E53 | One-touch Windows Inoperative After General Module Replacement |
| General Electrical Systems | 61 08 09 | May-09 | 1 series | Rattle Noise from the Washer Fluid Reservoir |
| General Electrical Systems | 61 09 09 | May-09 | X6 | Service Action: Check and Replace Battery |
| General Electrical Systems | 61 10 09 | May-09 | F01/02 | Erroneous FC 801C05 (Hex), 8395781 (Dec) in ZGM |

| Category | SIBs (SI B## ## ##) | Date | Application | Title |
|----------------------------|---------------------|---------|-------------|---|
| General Electrical Systems | 61 11 09 | June-09 | All | Battery Charging and Testing Procedure |
| General Electrical Systems | 61 12 09 | June-09 | F01/02 | System Analysis: signal fault Diagnostics - Important Information |
| General Electrical Systems | 61 13 09 | July-09 | 1 series | Missing "Year One of the 1" Start/Stop Ring |

01, 02, 03 , 05, 06, 07, 10, 11 X5 or other models

| | | | | |
|-------------|----------|--------------|-------------------|--|
| Instruments | 62 01 06 | May-07 | E60/E63 | Instrument Cluster Needles Vibrate (Replaces 1/07) |
| Instruments | 62 02 06 | May-06 | E60/E63 | Engine Oil Level Menu Option is Displayed After Reprogramming |
| Instruments | 62 04 06 | October-06 | E60/E63 | Instrument Cluster: Failure of Displays/Functions |
| Instruments | 62 01 07 | January-07 | E90/92 | Warning Chime Inoperative for Check Control and/or Directionals |
| Instruments | 62 02 07 | January-07 | E60/E63/E92 | No Communication or Diagnosis Possible With Instrument Cluster |
| Instruments | 62 03 07 | May-07 | E90/92 | On-Board Computer Functions Cannot Be Displayed (rpl 1/07) |
| Instruments | 62 06 07 | March-07 | BMW Centers | Check Control Messages (With PDF list) |
| Instruments | 62 07 07 | May-08 | E70 (X5)/E71 (X6) | TeileClearing (Enhanced Technical Support) for Instrument Cluster |
| Instruments | 62 01 08 | May-08 | 1 Series | Cruise Control Display in Instrument Cluster Increments Incorrectly |
| Instruments | 62 02 08 | August-08 | M3 w/DCT | Instrument Cluster Center Displays Go Blank |
| Instruments | 62 04 08 | September-08 | E6x | Instrument Cluster Mileage Display Switches to Kilometers when Key Is Switched |
| Instruments | 62 01 09 | April-09 | E6x | All Instrument Dials Inoperative and Display in Instrument Cluster Is Bright |
| Instruments | 62 02 09 | May-09 | M3 w/DCT | Shift Lights on M3 Instrument Cluster Cannot Be Permanently Activated |
| Instruments | 62 03 09 | July-09 | All | Outside Temperature Display Is Incorrect |

04 07 note to dealer
05 - 09 other models

| | | | | |
|--------|----------|--------------|--------------------|---|
| Lights | 63 02 04 | July-04 | E60 | Replace Lamp Module |
| Lights | 63 02 05 | June-05 | E60 | Brake Force Display (BFD) Inoperative |
| Lights | 63 03 05 | July-05 | E60 | Eyebrow Lights are Inoperative after Programming |
| Lights | 63 05 05 | September-05 | E64 Cabrio | Third Brake Light Cracked |
| Lights | 63 06 05 | November-05 | E60 | Service Action: Check the Adaptive Headlights for Proper Operation |
| Lights | 63 01 06 | May-06 | Z4 | Front Lighting Configuration |
| Lights | 63 05 06 | October-06 | E60/E63 | Automatic Headlamps: Lights Do Not Switch Off |
| Lights | 63 06 06 | October-06 | E60 | LED Flashing On Headlight Switch, No Faults Stored |
| Lights | 63 08 06 | October-06 | E60 | Lights Flash Briefly When Vehicle Wakes Up; Battery May Become Discharged |
| Lights | 63 09 06 | October-06 | E60 | Brake Lighting Pulsates Intermittently |
| Lights | 63 12 06 | October-06 | E63 | Adaptive Headlamp Does Not Turn |
| Lights | 63 13 06 | October-06 | E60/E63 | Automatic Headlamp System Does Not Switch Off the Lights |
| Lights | 63 15 06 | October-06 | E60 | Headlamp Leak (Replaces 12/04) |
| Lights | 63 16 06 | November-06 | E60 | 3rd Brake Light Comes Loose From Rear Window |
| Lights | 63 17 06 | January-07 | E60/63/90 | Eyebrow Lights are Inoperative after Programming (Replaces 12/06) |
| Lights | 63 02 07 | January-07 | E90/91/92 | Bulb Out Symbol Displayed in BC |
| Lights | 63 03 07 | February-07 | E90/91/92 | Daytime Running Lights are Inoperative |
| Lights | 63 04 07 | March-07 | E60/E63 | Fault Code 9CAD in LM |
| Lights | 63 05 07 | April-07 | X5 (E70) | Rear Turn Signal is Inoperative |
| Lights | 63 06 07 | April-07 | E92/93 | Cornering lights failure Displayed in Check Control |
| Lights | 63 09 07 | June-07 | X5 (E70) | Taillight Partially Inoperative |
| Lights | 63 10 07 | October-07 | E92/93 | Headlight Vibrates when Vehicle is in Motion |
| Lights | 63 13 07 | August-07 | E90/91/92 | Headlight Vibrations |
| Lights | 63 15 07 | October-07 | E70 (X5) | Interior Light Switch Illumination |
| Lights | 63 16 07 | December-07 | E60/E63 | Option Code 08S4 - Variable Light Decoding |
| Lights | 63 01 08 | March-08 | E63/E64 | Side Marker Lamp not Working in Conjunction with Welcome Light |
| Lights | 63 02 08 | March-08 | E92/93 | Rear Bulb Failure |
| Lights | 63 03 08 | March-08 | 3 Series | Flashlight Deleted as a Running Change |
| Lights | 63 04 08 | June-08 | 1/3/5/6/7/X series | Headlamp Moisture: Fault Diagnostics |
| Lights | 63 05 08 | May-08 | E60 | CC Message Missing/Incorrect when Front Parking Light Faulty |
| Lights | 63 06 08 | July-08 | X3 | Bulb-Out Warning, FC 2F or 3E |
| Lights | 63 07 08 | August-08 | E60/E63 | Adaptive Headlights Intermittently Inoperative (SW fix coming in Oct) |
| Lights | 63 08 08 | August-08 | X5 (E70) | Contact Between Inner and Outer Rear Lamps |
| Lights | 63 09 08 | August-08 | X3 | Interior Lamps "Soft ON/OFF" Inoperative |
| Lights | 63 10 08 | November-08 | 1 series, X3 | Cracked Third Brake Light (rpl 9/08) |
| Lights | 63 11 08 | November-08 | All w/MOST | Automatic Headlamps: Adjust Sensitivity |
| Lights | 63 12 08 | January-09 | E60/E63 | Changes to Panel Illumination (58G) |
| Lights | 63 03 09 | March-09 | 7 Series (F01) | High-beam Assistant (FLA): Erratic Operation |
| Lights | 63 04 09 | March-09 | 7 Series (F01) | Headlamp Flashes Several Times, Then Switches Off |
| Lights | 63 06 09 | May-09 | 3 Series | Front LED Turn Signal Not Working or Malfunctioning |
| Lights | 63 07 09 | July-09 | 5, 6, 7 series | Lights Do Not Switch Off Automatically after replacing light module |

08 09 for X5 (E63 and E70) 07 NU

| | | | | |
|------------------------------|----------|--------------|--------------|--|
| Heating and Air Conditioning | 64 08 91 | October-06 | All | Musty Odors |
| Heating and Air Conditioning | 64 02 05 | August-05 | E64 (Cabrio) | Poor Temperature Regulation from Center Vents |
| Heating and Air Conditioning | 64 03 05 | June-08 | E60/E63 | Air Conditioning Delayed Startup (Supersedes 4/07 w/new info) |
| Heating and Air Conditioning | 64 04 05 | August-07 | E60/E63 | Air Conditioning Stops Cooling after Long Drive (Replaces 12/06) |
| Heating and Air Conditioning | 64 21 05 | May-08 | All | Troubleshooting Air Conditioning Compressor Noise (Supersedes Dec 06) |
| Heating and Air Conditioning | 64 01 06 | January-06 | E60 | Blower Motor Stays On with Key Off |
| Heating and Air Conditioning | 64 02 06 | June-06 | E60 | Water Droplets are Blown from Center Vents with A/C On (Supersedes Jan 06) |
| Heating and Air Conditioning | 64 04 06 | May-07 | E90 | Air Conditioning Does not Cool (Replaces 1/07) |
| Heating and Air Conditioning | 64 06 06 | May-06 | E90 | Front Defroster Performance Poor at Mid-Blower Speeds |
| Heating and Air Conditioning | 64 07 06 | May-07 | E90 | Air Conditioning System does not Cool (Refrigerant Charge Good) (rpl 6/06) |
| Heating and Air Conditioning | 64 09 06 | October-06 | E90 | Air Conditioning System Blows Warm Air After Long Drive (Replaces 8/06) |
| Heating and Air Conditioning | 64 10 06 | July-06 | E60/61 | Water Droplets Blown from Right Side Center Vents with A/C On |
| Heating and Air Conditioning | 64 14 06 | November-07 | E60/61 | A/C Compressor Noise "Droning, Howling or Ticking" at Low Engine Speed (update to 10/06) |
| Heating and Air Conditioning | 64 03 07 | October-07 | E92 | Banging Noise from Air Conditioner Compressor (update to 3/07) |
| Heating and Air Conditioning | 64 04 07 | May-08 | All | Heating and Air Conditioning Symptom Diagnosis (update to 1/08) |
| Heating and Air Conditioning | 64 06 07 | May-08 | E60/E63 | Air Conditioning Compressor Does Not Switch On |
| Heating and Air Conditioning | 64 08 07 | August-07 | All | Important Information about Heating and Air Conditioning |
| Heating and Air Conditioning | 64 10 07 | January-08 | E60/E63 | Air Conditioning Delayed Startup |
| Heating and Air Conditioning | 64 12 07 | June-08 | 3 Series | White Flakes/Powder Coming from the Air Conditioning Vents |
| Heating and Air Conditioning | 64 13 07 | February-08 | 3 Series | CID or IHKA Total Failure Because F61 Blown |
| Heating and Air Conditioning | 64 14 07 | November-07 | E70 (X5) | Water Leak on Carpet During Air Conditioning Usage |
| Heating and Air Conditioning | 64 02 08 | June-08 | 1 & 3 Series | Whistling from the Heating/Air Conditioning Unit at Speeds over 50 MPH |
| Heating and Air Conditioning | 64 03 08 | August-08 | All | TeileClearing for Air Conditioning Systems |
| Heating and Air Conditioning | 64 04 08 | September-08 | E70 (X5) | Different Delivery Temperature from Each Side of the Rear Compartment Blower |
| Heating and Air Conditioning | 64 05 08 | October-08 | All | Damage to the Air Conditioning Control Panel |
| Heating and Air Conditioning | 64 06 08 | October-08 | E71 (X6) | Cold Air Is Leaking from Center Console Area |
| Heating and Air Conditioning | 64 01 09 | March-09 | E70 (X5) | Whirring Noise from the Auxiliary Water Pump |
| Heating and Air Conditioning | 64 02 09 | May-09 | F01/02 | Rear Air Conditioning is Automatically Reactivated After Sleep Cycle |
| Heating and Air Conditioning | 64 03 09 | June-09 | F01/02 | Heating and Air Conditioning Conversions Available in ISTA/P |

07 09 for (X5)

| | | | | |
|---|----------|------------|---------|---|
| Audio, Navigation, Monitors, Alarms, SI | 65 06 04 | July-04 | E60/E63 | Consumption Set to mpg UK instead of mpg US |
| Audio, Navigation, Monitors, Alarms, SI | 65 10 04 | January-05 | E60/E63 | Audio Stays On |
| Audio, Navigation, Monitors, Alarms, SI | 65 01 05 | June-05 | E90 | Radio Seek/Scan Inoperative |

| Category | SIBs (SIB##-###-###) | Date | Application | Title |
|---|--------------------------------|--------------------|----------------------------|--|
| Audio, Navigation, Monitors, Alarms, SI | 65 02 05 | April-06 | E60/E63/E90 | SIRIUS Satellite Radio - General Info (Supersedes May 05 - Added E90) |
| Audio, Navigation, Monitors, Alarms, SI | 65 06 05 | July-05 | E60/E63 | CID Fault Analysis Guide |
| Audio, Navigation, Monitors, Alarms, SI | 65 07 05 | April-06 | E90 | MOST Bus is Inoperative or Central Information Display has Reduced Brightness (Jul 05) |
| Audio, Navigation, Monitors, Alarms, SI | 65 08 05 | October-05 | E90 | Temperature Display in RAD2 Shows Dashes |
| Audio, Navigation, Monitors, Alarms, SI | 65 09 05 | February-06 | E60/E63/E90 | No Audio Sound in any Mode (Supersedes Aug 05 with new info) |
| Audio, Navigation, Monitors, Alarms, SI | 65 10 05 | November-07 | E60/E63/E90 | CCC: Loss of all Audio (update to 8/06) |
| Audio, Navigation, Monitors, Alarms, SI | 65 16 05 | September-05 | E60/E63/E90 | RDS Function Causes Confusing Station Names when in "All stations" Screen |
| Audio, Navigation, Monitors, Alarms, SI | 65 18 05 | January-06 | E60/E63/E90 | MP3 Compatibility Overview (Supersedes October 2006) |
| Audio, Navigation, Monitors, Alarms, SI | B651805MP3_Compatibility_Chart | P/O 65 18 05 | E60/E63/E90 | MP3 Compatibility Chart |
| Audio, Navigation, Monitors, Alarms, SI | 65 19 05 | October-05 | E60 | Weather Band Available on Multi Audio System Controller |
| Audio, Navigation, Monitors, Alarms, SI | 65 20 05 | January-06 | E90 | RAD2 - CD Mode Malfunctions (In-Dash CD skips or does not play - Business Radio) |
| Audio, Navigation, Monitors, Alarms, SI | 65 21 05 | March-07 | E63/E64 | SIRIUS Satellite Radio Cuts Out in Certain Geographic Areas (May 06 -) |
| Audio, Navigation, Monitors, Alarms, SI | 65 22 05 | November-05 | E60 | 'Favorites' Function is Selectable in the Entertainment Menu |
| Audio, Navigation, Monitors, Alarms, SI | 65 23 05 | November-05 | E60 | Disclaimer Screen Disappears Automatically after 10 Seconds |
| Audio, Navigation, Monitors, Alarms, SI | 65 24 05 | October-05 | E60/E63/E90 | Static Between Words on AM Radio |
| Audio, Navigation, Monitors, Alarms, SI | 65 25 05 | August-07 | E60/E63 | HD-Radio™ - Functionality and Diagnosis (Supersedes Mar 07) |
| Audio, Navigation, Monitors, Alarms, SI | 65 26 05 | March-06 | E60/E63/E90 | Audio Switches off Briefly when Listening to FM Stations (Supersedes Jan 06 w/new info) |
| Audio, Navigation, Monitors, Alarms, SI | 65 27 05 | November-05 | E60/E63/E90 | CID Screen Image Not Displayed Correctly Since CCC Replacement |
| Audio, Navigation, Monitors, Alarms, SI | 65 28 05 | March-06 | E60/E63/E90 | CCC: Radio Station Preset List Intermittently Empty (Supersedes Nov 05) |
| Audio, Navigation, Monitors, Alarms, SI | 65 30 05 | March-06 | E60/E63/E90 | CCC: MP3 CD Playback Not Available (Supersedes Jan 06 -minor changes) |
| Audio, Navigation, Monitors, Alarms, SI | 65 32 05 | March-07 | E60/E63/E90 | CCC: CD/CDC Track Counter Advances After Mute Selected(Replaces 1/07) |
| Audio, Navigation, Monitors, Alarms, SI | 65 02 06 | March-06 | E60/E63/E90 | CCC: Loss of Audio in All Modes (Supersedes Feb 06) |
| Audio, Navigation, Monitors, Alarms, SI | 65 04 06 | March-06 | E60/E63/E90 | KL-R Stays On After Ignition Off – Comfort Access Only |
| Audio, Navigation, Monitors, Alarms, SI | 65 05 06 | April-06 | E60/E63/E90 | CCC: CD Drive Errors |
| Audio, Navigation, Monitors, Alarms, SI | 65 06 06 | November-07 | E60/E63/E90 | Various Problems with CCC Following Replacement (update to 4/06) |
| Audio, Navigation, Monitors, Alarms, SI | 65 08 06 | September-06 | E60/E63/E90 | CCC with Top HiFi Loses Surround Sound after Navigation Announcement (Supersedes May 06) |
| Audio, Navigation, Monitors, Alarms, SI | 65 10 06 | May-06 | E60/E63/E90 | New Audio-Test-CD for Diagnosing a Faulty CD/Audio-DVD Drive or Media |
| Audio, Navigation, Monitors, Alarms, SI | 65 12 06 | July-08 | E60/E63/E90 | Popping/Cracking Noise from Audio System (rpl 12/06) |
| Audio, Navigation, Monitors, Alarms, SI | 65 16 06 | September-06 | E60/E63 | CCC: Acoustic Warning Gong Sounds at Times, No CC Message |
| Audio, Navigation, Monitors, Alarms, SI | 65 18 06 | October-06 | E63/E64 | DWA (Theft Deterant System) Causes Excessive Closed Circuit Current Draw |
| Audio, Navigation, Monitors, Alarms, SI | 65 25 06 | August-08 | ALL w / CCC | Enhanced Technical Support for Audio System (Replaces 6/07) |
| Audio, Navigation, Monitors, Alarms, SI | 65 26 06 | October-06 | E60/E63/E90 | CCC Disclaimer Screen Disappears Automatically after 10 Seconds |
| Audio, Navigation, Monitors, Alarms, SI | 65 27 06 | October-06 | E60/E63/E90 | CCC Does Not Play All MP3 Formats |
| Audio, Navigation, Monitors, Alarms, SI | 65 28 06 | October-06 | E60/E63/E90 | CCC Radio Station RDS Information Missing After Programming |
| Audio, Navigation, Monitors, Alarms, SI | 65 29 06 | April-07 | E60/E63/E90 | CCC Next Entertainment Source Not Selectable Via MFL (rpl 10/06) |
| Audio, Navigation, Monitors, Alarms, SI | 65 33 06 | December-06 | E60/E63/E90 | CD Changer is Inoperative; Magazine is Jammed or Broken |
| Audio, Navigation, Monitors, Alarms, SI | 65 35 06 | June-07 | E60 | Poor Radio Reception in FM Mode (rpl 12/06) |
| Audio, Navigation, Monitors, Alarms, SI | 65 36 06 | August-07 | E60 | Poor Radio Reception in AM Mode (rpl 6/07) |
| Audio, Navigation, Monitors, Alarms, SI | 65 37 06 | December-06 | E60 | RDS Function |
| Audio, Navigation, Monitors, Alarms, SI | 65 43 06 | May-07 | E60/E63/E90 | CCC: High Frequency Noises from the DVD drive (rpl 12/06) |
| Audio, Navigation, Monitors, Alarms, SI | 65 44 06 | December-06 | E60/E63/E90 | CCC: AUX-IN Loud Hissing if no Device Connected |
| Audio, Navigation, Monitors, Alarms, SI | 65 45 06 | December-06 | E60/E63/E90 | CCC: Poor Radio Reception after Software Update |
| Audio, Navigation, Monitors, Alarms, SI | 65 46 06 | May-07 | E60/E63/E90 | CCC: Radio Continues to Play after Ignition off (rpl 12/06) |
| Audio, Navigation, Monitors, Alarms, SI | 65 48 06 | December-06 | E60/E63/E90 | SIRIUS Satellite Radio Is No Longer Accessible |
| Audio, Navigation, Monitors, Alarms, SI | 65 01 07 | March-07 | E60/E63/E90 | CID Changes Introduced March 2007 |
| Audio, Navigation, Monitors, Alarms, SI | 65 03 07 | March-07 | E60/E63/E90 | M-ASK also available |
| Audio, Navigation, Monitors, Alarms, SI | 65 04 07 | April-07 | E60/E63/E90 | CCC: Slow Response from System when using Controller (Rpl Jan 07) |
| Audio, Navigation, Monitors, Alarms, SI | 65 06 07 | January-07 | E90/91 | SDARS Sirius Radio is Inoperative After Programming |
| Audio, Navigation, Monitors, Alarms, SI | 65 07 07 | March-07 | All CCC equipped | CCC Symptom Troubleshooting |
| Audio, Navigation, Monitors, Alarms, SI | 65 08 07 | March-08 | E60/E63/E90/E92 | SDARS SIRIUS Radio is Intermittently Inoperative |
| Audio, Navigation, Monitors, Alarms, SI | 65 08 07 | May-08 | E60/E63/E90/E92 | USB Audio Interface |
| Audio, Navigation, Monitors, Alarms, SI | 65 15 07 | May-07 | E90/91 | Airbag Warning Lamp Illuminated, FC 93C1/93C3 |
| Audio, Navigation, Monitors, Alarms, SI | 65 18 07 | January-08 | E64 Cabrio | Radio or Speakers Inoperative (rpl 6/06) |
| Audio, Navigation, Monitors, Alarms. | 65 19 07 | May-07 | E63/E64 | Recall Campaign 07V-178: Replace the Seat Occupancy Detection Mat |
| Audio, Navigation, Monitors, Alarms, SI | 65 21 07 | January-08 | E93 | Whistling Noise From the Radio in AM Mode Only |
| Audio, Navigation, Monitors, Alarms, SI | 65 22 07 | August-07 | E60/E63/E90/E92 | CCC CD Text not Updated When CD is Swapped |
| Audio, Navigation, Monitors, Alarms, SI | 65 23 07 | August-07 | E60/E63/E90/E92 | CCC Navigation Displays Incorrect Vehicle Position |
| Audio, Navigation, Monitors, Alarms, SI | 65 24 07 | August-07 | E60/E63/E90/E92 | CCC Navigation Map DVD not Detected |
| Audio, Navigation, Monitors, Alarms, SI | 65 25 07 | November-07 | E60 | Recode or Replace OC3 Seat Mat |
| Audio, Navigation, Monitors, Alarms, SI | 65 26 07 | June-08 | E60/E63/E90/E92 | CCC: Volume Differences between CD/AUX and FM after Programming |
| Audio, Navigation, Monitors, Alarms, SI | 65 27 07 | December-07 | X5 (E70) | Airbag Warning Lamp Illuminated - FC 93D2 |
| Audio, Navigation, Monitors, Alarms, SI | 65 28 07 | September-07 | E60/E63/E90/E92 | CCC: Radio Does Not Resume With Previously Selected Station |
| Audio, Navigation, Monitors, Alarms, SI | 65 30 07 | October-07 | E90/91/92/93/E70 | iPod Mode is Switching to FM Mode |
| Audio, Navigation, Monitors, Alarms, SI | 65 31 07 | September-07 | E60/E70 | CHAMP: Intermittently No Audio Output in FM Mode Only After Restart |
| Audio, Navigation, Monitors, Alarms, SI | 65 32 07 | December-07 | X5 (E70) | Rear Seat Entertainment System (RSE) is Not Working Correctly |
| Audio, Navigation, Monitors, Alarms, SI | 65 33 07 | August-08 | X5 (E70) | Airbag Warning Illuminated, FC 93D2 |
| Audio, Navigation, Monitors, Alarms, SI | 65 34 07 | November-07 | E90/91/92/93 | Service Action: Program the MULF2-High Control Module |
| Audio, Navigation, Monitors, Alarms, SI | 65 35 07 | December-07 | X5 (E70) | No Audio Output After Turning the Ignition On |
| Audio, Navigation, Monitors, Alarms, SI | 65 36 07 | January-08 | E60/E63 | Radio Turns Off After 8 Minutes and Time and Date Display is Cleared (rpl 12/07) |
| Audio, Navigation, Monitors, Alarms, SI | 65 37 07 | November-07 | E93 | No AM Reception During Convertible Top Operation |
| Audio, Navigation, Monitors, Alarms, SI | 65 39 07 | December-07 | E60/E63/E90/E92/E70 | CCC Navigation Not Working -September 24, 2007 to October 29, 2007 |
| Audio, Navigation, Monitors, Alarms. | 65 41 07 | June-09 | E60/E63/E90/E92/E70 | CCC Loss of Audio and CID Blanks Out (rpl 07/08) |
| Audio, Navigation, Monitors, Alarms, SI | 65 42 07 | January-08 | All w/Alarm | Alarm Triggers Unexpectedly - Troubleshooting |
| Audio, Navigation, Monitors, Alarms, SI | 65 01 08 | May-08 | All w/SAT RAD | SIRIUS Radio Stations Missing in "All Channels" List |
| Audio, Navigation, Monitors, Alarms, SI | 65 02 08 | August-08 | All w/6FL (USB) | iPod Classic Doesn't Get Charged through USB Connection |
| Audio, Navigation, Monitors, Alarms, SI | 65 03 08 | March-08 | 3 & 5 Series | Interference with Radio Reception on all Bands (FM, AM, HD Radio) |
| Audio, Navigation, Monitors, Alarms, SI | 65 04 08 | April-08 | All w/SAT RAD | Call SIRIUS Is Displayed |
| Audio, Navigation, Monitors, Alarms, SI | 65 05 08 | April-08 | 7 Series | SIRIUS Radio Station List Is Not Displayed in the RSE Monitor |
| Audio, Navigation, Monitors, Alarms. | 65 06 08 | February-09 | 1 & 3 series | RAD2: The Audio Volume is Briefly Muted or Reduced (4/08) |
| Audio, Navigation, Monitors, Alarms, SI | 65 07 08 | April-08 | 3 series | USB Device Is Not Detected |
| Audio, Navigation, Monitors, Alarms, SI | 65 08 08 | May-08 | 3 series | Fault Code "E190" stored in the RAD2_GW |
| Audio, Navigation, Monitors, Alarms. | 65 09 08 | March-09 | X6/X5 (E70) | Anti-theft Alarm System Triggers a False Alarm rpl 11/08) |
| Audio, Navigation, Monitors, Alarms, SI | 65 10 08 | May-08 | 1 & 3 Series | RAD2: Intermittently No Audio after Check Control Message |
| Audio, Navigation, Monitors, Alarms, SI | 65 11 08 | May-08 | All w/6FL | iPod Classic is Discharged after an Extended Period of Inactivity |
| Audio, Navigation, Monitors, Alarms, SI | 65 12 08 | June-08 | E60 | SRS Warning Lamp Illuminated, but No Fault Codes Stored |
| Audio, Navigation, Monitors, Alarms, SI | 65 14 08 | October-08 | X5 (E70) | Controller Scrolling Function Not Responsive |
| Audio, Navigation, Monitors, Alarms. | 65 15 08 | June-09 | 1 Series | Volume of Warning Gong too Quiet (9/08) |
| Audio, Navigation, Monitors, Alarms, SI | 65 16 08 | September-08 | E83 (X3) | Airbag Warning Lamp Illuminated, FC A1 |
| Audio, Navigation, Monitors, Alarms, SI | 65 17 08 | December-08 | E60/63 | CD Changer Is Inoperative; Magazine Is Jammed |
| Audio, Navigation, Monitors, Alarms, SI | 65 18 08 | September-08 | MY09 1 & 3 series | TeileClearing for Car Information Computer (CIC) |
| Audio, Navigation, Monitors, Alarms. | 65 19 08 | July-09 | E60/E90/E83 (X3) | Recall Campaign 08V-384: Modify Seat Occupancy Detection Mat (6/09) |
| Audio, Navigation, Monitors, Alarms, SI | 65 20 08 | November-08 | 1 & 3 Series | Interference Noises and/or Reception Varies in Certain Areas |
| Audio, Navigation, Monitors, Alarms, SI | 65 21 08 | November-08 | E93 | Airbag Warning Illuminated, FC 9402 |
| Audio, Navigation, Monitors, Alarms, SI | 65 22 08 | November-08 | 1 series | Loss of Navigation GPS Position |
| Audio, Navigation, Monitors, Alarms, SI | 65 24 08 | December-08 | M3/M5 | Audio System Is Intermittently Inoperative |
| Audio, Navigation, Monitors, Alarms, SI | 65 27 08 | February-09 | 1,3,5,6 ser X5,X6 | Entertainment and Communication Systems are Inoperative |
| Audio, Navigation, Monitors, Alarms, SI | 65 01 09 | January-09 | 1,3,6 ser | Incorrect Message in the USB Audio Interface Diagnosis |
| Audio, Navigation, Monitors, Alarms, SI | 65 02 09 | January-09 | 1 Series | Audio Interference Noises in All Modes When Vehicle Is in Motion |
| Audio, Navigation, Monitors, Alarms, SI | 65 03 09 | March-09 | 7 Series (F01) | Side View Camera Has Blurred Image |
| Audio, Navigation, Monitors, Alarms. | 65 05 09 | July-09 | All w/CIC | Navigation System Road Map (rpl 3/09) |
| Audio, Navigation, Monitors, Alarms, SI | 65 06 09 | February-09 | 5, X5, X6 LSI | CID Is Blank, No Audio, CHAMP Resets and Is Then Inoperative |
| Audio, Navigation, Monitors, Alarms, SI | 65 08 09 | March-09 | X5, X6 | Ultrasonic Passenger Compartment Motion Detector Triggers False Alarm |
| Audio, Navigation, Monitors, Alarms. | 65 10 09 | May-09 | 1,3,7 series | Vehicle Position Is Missing or Incorrect On the Navigation Map |
| Audio, Navigation, Monitors, Alarms. | 65 11 09 | May-09 | 1,3,7 series | Satellite Radio: Channel List May Be Empty or Channels Are Missing |
| Audio, Navigation, Monitors, Alarms. | 65 12 09 | June-09 | 1, 3 series | RAD2: Audio Is Intermittently Inoperative (rpl 4/09) |
| Audio, Navigation, Monitors, Alarms. | 65 13 09 | March-09 | X5, X6 | Incorrect Test Plan for CID FC A48B Power Supply |
| Audio, Navigation, Monitors, Alarms. | 65 14 09 | April-09 | 3 series | Active Head Restraint Cannot Be Locked Back into Position |

| Category | SIBs (SI B## ## ##) | Date | Application | Title |
|--------------------------------------|---------------------|---------|-------------|--|
| Audio, Navigation, Monitors, Alarms. | 65 15 09 | June-09 | X5, X6 | DWA Siren Too Quiet When Locking and Unlocking (rpl 4/09) |
| Audio, Navigation, Monitors, Alarms. | 65 16 09 | June-09 | 1, 3 series | RAD2: Audio and/or Radio Display Is Intermittently Inoperative |
| Audio, Navigation, Monitors, Alarms. | 65 18 09 | May-09 | E60/61 | Service Action: HD® Radio Activation |
| Audio, Navigation, Monitors, Alarms. | 65 19 09 | June-09 | E65/66 | ISTA/P Prompts to Replace CDC |
| Audio, Navigation, Monitors, Alarms. | 65 20 09 | June-09 | X5 | Airbag Warning Lamp Illuminated, FC 93C6 |
| Audio, Navigation, Monitors, Alarms. | 65 21 09 | June-09 | All w/CIC | Artist and Song Title are Not Displayed |
| Audio, Navigation, Monitors, Alarms. | 65 23 09 | July-09 | 1, 3 series | RAD2: Audio Volume Fluctuates |

01, 11, 14, 20 other model, 05, 09, 10, 12, 13, 29, 38, 40 NU,

| | | | | |
|--|------------------|--------------|------------|--|
| Distance Systems, Cruise Control, Rerr | - 01 other model | | E65 | |
| Distance Systems, Cruise Control, Rerr | 66 01 04 | March-08 | X3 | 315MHz Remote Control Range Is Inadequate or Inoperative |
| Distance Systems, Cruise Control, Rerr | 66 03 05 | November-05 | E60/E63 | PDC and Gong Volume Cannot be Adjusted |
| Distance Systems, Cruise Control, Rerr | 66 01 06 | February-06 | E90 | PDC Button not Installed (Supersedes Feb 06 with added info) |
| Distance Systems, Cruise Control, Rerr | 66 04 06 | March-07 | E60/E63 | Night Vision Malfunctions and Parts Replacement (update to 11/06) |
| Distance Systems, Cruise Control, Rerr | 66 05 06 | September-06 | E61 | Vehicle Does Not Start |
| Distance Systems, Cruise Control, Rerr | 66 07 06 | December-06 | All | Remote Control Key Not Working |
| Distance Systems, Cruise Control, Rerr | 66 02 07 | March-07 | All | Comfort Access: Replacement ID Transmitter Initialization |
| Distance Systems, Cruise Control, Rerr | 66 04 07 | September-07 | E60/E63 | Unexpected Lane Departure Warning |
| Distance Systems, Cruise Control, Rerr | 66 06 07 | October-07 | ALL | Universal Garage Door Opener Cannot be Programmed |
| Distance Systems, Cruise Control, Rerr | 66 01 08 | February-08 | E91 | PDC Gong volume low |
| Distance Systems, Cruise Control, Rerr | 02 for e65 | | | |
| Distance Systems, Cruise Control, Rerr | 66 03 08 | March-08 | X5 (E70) | Seal Must Be Replaced when Rear View Camera Is Removed |
| Distance Systems, Cruise Control, Rerr | 66 05 08 | May-08 | 1 Series | PDC and Warning Gong Volume too Low |
| Distance Systems, Cruise Control, Rerr | 66 06 08 | October-08 | E61 | Remote Control Malfunction or Radio Reception Problem |
| Distance Systems, Cruise Control, Rerr | 66 07 08 | January-09 | E63/E64 M6 | PDC Malfunction |
| Distance Systems, Cruise Control, Rerr | 66 01 09 | March-09 | 3 Series | PDC Ultrasonic Sensor(s) Become Discolored |
| Distance Systems, Cruise Control, R | 66 02 09 | April-09 | F01/02 | Windows or Sunroof Do Not Open with Remote Control |
| Distance Systems, Cruise Control, R | 66 04 09 | April-09 | F01/02 | Night Vision: Pedestrian Recognition Is Intermittently Inoperative |
| Distance Systems, Cruise Control, R | 66 05 09 | April-09 | F01/02 | Night Vision System Is Intermittently Inoperative |
| Distance Systems, Cruise Control, R | 66 06 09 | April-09 | F01/02 | Side View Camera Has Blurred Image |
| Distance Systems, Cruise Control, R | 66 07 09 | April-09 | F01/02 | Erroneous Fault Code Entries in the TRSVC Module |
| Distance Systems, Cruise Control, R | 66 09 09 | June-09 | X5 (E70) | Failure of Remote Control Locking |

03, 06 for other model 02 other model

| | | | | |
|---------------|----------|--------------|----------------|---|
| Vehicle Tools | 71 01 07 | September-07 | W/Sunroof | Sunroof Emergency Operation Tool Eliminated |
| Vehicle Tools | 71 01 08 | March-08 | 3/5/6/Z series | Combination Wrench Eliminated from the Vehicle Tool Kit |

| | | | | |
|---------------------------------|-----------------|--------------------|---------------------|---|
| Safety Restraint Systems | 72 05 04 | June-04 | E60/E63 | Various "Self-Test" Faults Stored in "Byteflight" Modules |
| Safety Restraint Systems | 72 02 05 | August-06 | E60/E65/E90 | Passenger Airbag Status Lamp Goes ON/OFF During Driving (Replaces 1/06) |
| Safety Restraint Systems | 72 03 05 | June-05 | E64 (Cabrio) | Check Control Message "Rollover Protection Fault" |
| Safety Restraint Systems | 72 09 05 | November-05 | E64 (Cabrio) | Service Action: Reprogram Control Modules for Backrest Lock Microswitch |
| Safety Restraint Systems | 72 02 06 | June-06 | ALL | Airbag Warning Lamp for OC3 Seat Mat Fault (Supersedes Mar 06 w/new parts info) |
| Safety Restraint Systems | 72 03 06 | January-06 | E64 (Cabrio) | Airbag Warning Lamp Illuminated for Backrest Microswitch |
| Safety Restraint Systems | 72 04 06 | January-06 | E90 | Rear Belt Tensioners Deploy in Accident |
| Safety Restraint Systems | 72 05 06 | February-06 | E60 | Airbag Warning Illuminated, FC 9B2D in SFZ |
| Safety Restraint Systems | 72 08 06 | April-06 | E90 | OC3 Occupancy Status does not Change |
| Safety Restraint Systems | 72 09 06 | August-06 | E90 | Airbag Warning Lamp, FC93EB (Update to Apr -06) |
| Safety Restraint Systems | 72 10 06 | November-06 | E90 | Airbag Warning Lamp Illuminates - No Fault Codes (Replaces Apr 06) |
| Safety Restraint Systems | 72 18 06 | October-06 | E60 | Various Telegram Errors in Satellites |
| Safety Restraint Systems | 72 19 06 | October-06 | E63 | Various Fault Memory Entries in the SBE |
| Safety Restraint Systems | 72 20 06 | October-06 | E60 | SBSL/SBSR FC 9845/98C5, implausible crash severity |
| Safety Restraint Systems | 72 24 06 | October-06 | E60 | Rear Side Airbags Come Activated |
| Safety Restraint Systems | 72 25 06 | October-06 | E60 | FC 96CA: Passenger Thorax Airbag Resistance too Great |
| Safety Restraint Systems | 72 26 06 | October-06 | E60 | SGM FC 9413 "Signal Lamp Airbag Deactivation" |
| Safety Restraint Systems | 72 28 06 | December-06 | E92 | Seatbelt Assistant "hand" Portion Breaks Off |
| Safety Restraint Systems | 72 29 06 | December-06 | E60/E63/E65 | DIS Test Plan Error While Performing SIM/SGM Self Test |
| Safety Restraint Systems | 72 01 07 | January-07 | E90/E91 | Airbag Warning Lamp Illuminated, FC 93C1/93C3 |
| Safety Restraint Systems | 72 03 07 | August-07 | E92 | Seat Belt Assistant Pinch Protection (updates 3/07) |
| Safety Restraint Systems | 72 04 07 | May-07 | E63/64 | Recall Campaign 07V-178: Replace the Seat Occupancy Detection Mat |
| Safety Restraint Systems | 72 05 07 | April-07 | E92 | Seat Belt Assistant Malfunction |
| Safety Restraint Systems | 72 01 08 | May-08 | E92 | Passenger Seat Belt Assistant Extends Unexpectedly |
| Safety Restraint Systems | 72 01 09 | March-09 | F01/02 | Front Seat Belt Electric Motor Driven Reel Activates Unexpectedly |
| Safety Restraint Systems | 72 02 09 | Z4 | E89 | Service Action: Belt Tensioner Harnesses |

-07 other model

| | | | | |
|------------------------------|----------------------------------|-------------------|----------------|---|
| Communication Systems | 84 14 01 | November-06 | E60/E63 | Telephone Installation on New Vehicles Replaces Mar 05) |
| Communication Systems | 84 01 03 | December-05 | E60/E63 | CPT9000 Telephone (Supersedes Aug 05 w/new info) |
| Communication Systems | B840103E60Telephone | P/O 84 01 03 | E60/E63 | E60/E63 TCU Wiring Diagram |
| Communication Systems | 84 15 03 | March-08 | E60/E63 | BMW Assist Initialization (now using GSM Rpl 11/06) |
| Communication Systems | B841503Diagnosis | P/O 85 15 03 | E60/E63 | Troubleshooting Guide (Flowchart) |
| Communication Systems | 84 21 04 | September-05 | E60/E63 | Linked Sequence calls Fail on Bluetooth (REPLACED BY 84 18 05) |
| Communication Systems | 84 02 04 | May-05 | E60/E63 | Navigation Map DVD for Vehicles with CCC |
| Communication Systems | 84 03 04 | July-04 | E60 | MFL Button Dials "911", or Last Number Dialed |
| Communication Systems | 84 10 04 | July-04 | E60 | CCC Navigation Retrofit Kit |
| Communication Systems | B841004Installer | P/O 84 10 04 | E60 | Installation Instructions |
| Communication Systems | B841004SalesBulletin | P/O 84 10 04 | E60 | Product Planning MY 04 5 Series |
| Communication Systems | 84 12 04 | September-07 | E60/E63 | Diagnosis and Repair of the CCC (updates 2/06) |
| Communication Systems | 84 12 04 Attachment | September-07 | E60/E63 | DVD Screws attachment |
| Communication Systems | 84 13 04 | November-07 | E60/E63 | BMW Assist with Integrated Bluetooth (Rpl Mar 07) |
| Communication Systems | B841304BluetoothDiagnosis | P/O 84 13 04 | E60/E63 | Diagnostic Instructions for Bluetooth Telephone Systems |
| Communication Systems | B841304BluetoothUserManualBus. | P/O 84 13 04 | E60/E63 | Bluetooth Users Manual for Business Phone |
| Communication Systems | B841304BluetoothUserManualE60E63 | P/O 84 13 04 | E60/E63 | Bluetooth Users Manual for CPT9000 and Bluetooth |
| Communication Systems | 84 14 04 | October-04 | E60/E63 | Service Action: Activate SVS (Voice Recognition System) |
| Communication Systems | B841404Q&A | P/O 84 14 04 | E60/E63 | FAQ |
| Communication Systems | 84 01 05 | July-05 | E60/E63 | Service Action: Reactivate TCUs for specified Production models that were accidentally deactivated |
| Communication Systems | 84 04 05 | January-07 | E60/E63 | Nav system missing or incorrect data (Replaces April 05) |
| Communication Systems | 84 07 05 | June-05 | E60/E63 | Motorola v710 Handset Phonebook does not download |
| Communication Systems | 84 08 05 | April-07 | E60 /E90 | CID switches between BMW banner and blank screen (Rpl 3/06 - adds E90 & new procedure) |
| Communication Systems | 84 09 05 | June-05 | E60/E63 | CCC NAV places of interest (POIs) |
| Communication Systems | B800905POICategories | P/O 84 09 05 | E60/E63 | PDF of categories and sub categories |
| Communication Systems | B800905POI_ICONS | P/O 84 09 05 | E60/E63 | PDF of ICON symbols |
| Communication Systems | 84 10 05 | May-06 | E60/E63/E90 | Nav Displays incorrect Vehicle Position (Supersedes Mar 06) - Replaced with 65 23 07 |
| Communication Systems | 84 11 05 | June-05 | E60/E63 | CCC CD/DVD disc does not eject |
| Communication Systems | 84 12 05 | April-06 | E60/E63 | DVD Drive makes clicking noise (Supersedes Aug 05 w/E90) |
| Communication Systems | 84 13 05 | May-07 | E60/E63/E90 | Bluetooth Phone call may still be displayed as active after the call has ended (Rpl 3/07 - adds E90) |
| Communication Systems | 84 14 05 | August-08 | All | Retrofitting a Telematics Control Unit (TCU) with Bluetooth® Technology (update to 9/07) |
| Communication Systems | 84 14 05 Attachment | September-07 | All | Special Inst for E6x |
| Communication Systems | 84 18 05 | September-05 | E60/E63 | Linked Sequence calls Fail on Bluetooth and CPT9000 Handsets |
| Communication Systems | 84 19 05 | September-05 | E90 | Teleservice does not place call for CBS due |
| Communication Systems | 84 24 05 | August-06 | E60/E63/E90 | CCC Voice Input System Incorrectly States Speed Limit in "km" (Supersedes Nov 05) |

| Category | SIBs (SIB## ## ##) | Date | Application | Title |
|------------------------------|--------------------|---------------------|-----------------------------|---|
| Communication Systems | 84 25 05 | January-06 | E90 | Software error in the Telematics Control Unit (TCU). (Supersedes Dec 05) |
| Communication Systems | 84 02 06 | January-06 | All | Hands free Bluetooth® Phone Call May be Lost if a Call Waiting Call is Received |
| Communication Systems | 84 03 06 | March-07 | All | Enhanced Support for CCC Car Communication Computer (Supersedes Dec 06) |
| Communication Systems | 84 04 06 | July-06 | All | Service Action: Reactivation of Telematics Control Unit (TCU) (Replace Mar 06) |
| Communication Systems | 84 05 06 | March-07 | All | Diagnosis of Bluetooth® Handset Related Complaints (Rpl Mar 06) |
| Communication Systems | 84 06 06 | March-06 | All | Information Displayed in the BMW Assist Menu is Incorrect or Unknown |
| Communication Systems | 84 08 06 | March-06 | All | CCC Navigation is Inoperative at Low Ambient Temperatures |
| Communication Systems | 84 09 06 | October-07 | All | Bluetooth® Inoperative, TCU FC# A379 or 79 (update to 04/07) |
| Communication Systems | 84 10 06 | August-07 | E60/E63/E90 | BMW Assist or Bluetooth® Inoperative, TCU FC# A379 (rpl 4/06) |
| Communication Systems | 84 14 06 | May-07 | E60/E63/E90 | Service Action: Reactivation of Telematics Control Unit (TCU) - (superceded Dec 06) |
| Communication Systems | 84 15 06 | May-06 | E60/E63/E90 | CCC Navigation Address Book Shows Duplicate Entries after Programming |
| Communication Systems | 84 18 06 | June-06 | E60/E63/E90 | Low Bluetooth Signal is Displayed in the Handset or the Bluetooth® Connection is Lost |
| Communication Systems | 84 20 06 | September-06 | E60/E63/E90 | CCC Navigation Stuck on "Accept" Screen(Supersedes Jun 06) |
| Communication Systems | 84 23 06 | May-07 | E60/E63/E90 | Service Action: Telematics Control Unit (TCU) – MOST-bus Vehicles Supersedes Dec 06) |
| Communication Systems | 84 25 06 | January-09 | E60/E63/E90/E65 | NAD Check, Recovery or Deactivation Procedure (MOST-Bus vehicles) (rpl 6/08) |
| Communication Systems | 84 26 06 | July-08 | E60/E63/E90/E65 | Cannot Enable BMW Assist Services (Supersedes Aug 06) |
| Communication Systems | 84 27 06 | July-08 | E60/E63/E90/E65 | BMW Assist Inactive Warning Message Displayed (Supersedes Aug 06) |
| Communication Systems | 84 48 06 | October-06 | E60/E63 | CPT9000 (V60s) Telephone Switches to Silent Mode when Connected to Vehicle |
| Communication Systems | 84 49 06 | October-07 | E60/E63 | Vehicle Dials BMW Assist on its Own (update to 10/06) |
| Communication Systems | 84 50 06 | October-06 | E60/E63 | CPT9000 Handset Phone does not Load into Vehicles |
| Communication Systems | 84 51 06 | October-06 | E60/E63 | The BMW Assist "Embedded" Phone Rings Erroneously in the Vehicle |
| Communication Systems | 84 58 06 | November-06 | E60/E63/E90/E92 | Real Time Traffic Information w/PDF attachment (Updated in Nov 06) |
| Communication Systems | 84 59 06 | June-09 | 3 Series | CCC Telephone Address Book Not in Alphabetical Order (rpl 10/06) |
| Communication Systems | 84 61 06 | March-07 | E60/E63/E90/E92 | CCC Navigation System Pop-up Arrow Display Missing During Route Guidance (rpl 10/06) |
| Communication Systems | 84 62 06 | July-08 | E60/E63/E90/E92 | Program Displays "The TEL Control Module is Malfunctioning" on the Final Report |
| Communication Systems | 84 01 07 | January-07 | E60/E63/E90/E92 | CCC SVS: Letter and Number Inputs by Voice are Misinterpreted |
| Communication Systems | 84 02 07 | March-07 | E60/E63/E90/E92 | Service Action: Activation of Telematics Control Unit (TCU) |
| Communication Systems | 84 04 07 | March-07 | E60/E63/E90/E92 | Bluetooth® Handsets No Longer Pairs to the Vehicle |
| Communication Systems | 84 05 07 | August-07 | E60/E63/E70/E90/E92 | Checking NAD Signal Strength for BMW Assist |
| Communication Systems | 84 06 07 | March-07 | E90 | Call Cannot be Answered if the Voice Recognition System (SVS) is Active |
| Communication Systems | 84 07 07 | July-08 | E60/E63/E90 | NAD was Found to be Faulty when Performing SI B84 22 05 (Reactivation of BMW Assist Services) |
| Communication Systems | 84 08 07 | June-09 | E60/E63/X5/Z4 | Service Action: Activation of Telematics Control Unit (TCU) (rpl 8/07) |
| Communication Systems | 84 09 07 | July-07 | E60/E63/E90 | Echo on Landline Side of Phone Call |
| Communication Systems | 84 11 07 | April-08 | E60/E90 | Service Action: Replace the Hands-Free Charging Electronics (MULF2-High) rpl 7/07 |
| Communication Systems | 84 12 07 | July-07 | E60/E63/E90/E92 | Voice Only Call, No Data Transmitted When Placing a BMW Assist Call |
| Communication Systems | 84 13 07 | July-07 | E60/E63/E90/E92 | BMW Assist Location (GPS) Unknown or Inaccurate, When Placing a BMW Assist Call |
| Communication Systems | 84 16 07 | September-07 | E60/E63/E90/E92 | Erroneous SOS Inactive Warning Message (rpl 7/07) |
| Communication Systems | 84 17 07 | July-08 | E60/E63/E90/E92 | SOS Inactive Warning Message, No Communication with TCU (rpl 09/07) |
| Communication Systems | 84 18 07 | June-09 | E60/E63/E90/E92 | Enable Services Status Bar Does NOT Progress (rpl 8/07) |
| Communication Systems | 84 19 07 | October-07 | E60/E63/E90/E92 | One Way Audio when Using a Bluetooth Enabled Handset |
| Communication Systems | 84 20 07 | October-08 | All w/TCU | Upgrading BMW Assist to Support New Bluetooth Handsets (rpl 11/07) |
| Communication Systems | 84 21 07 | November-07 | All w/TCU | Diagnosis When an Unapproved Handset is Paired to a Vehicle |
| Communication Systems | 84 01 08 | June-08 | 3/5/6/7/X series | Pairing between the iPhone and the Vehicle Fails |
| Communication Systems | 84 02 08 | March-08 | All w/TCU | Service Action: Initialize BMW Assist Services (SC VPC on 3/3/08) |
| Communication Systems | 84 03 08 | November-08 | X3 | Echo and Poor Voice Quality on the Landline Side of a Call (rpl 05/08) |
| Communication Systems | 84 04 08 | June-08 | E60 | Service Action: Update BMW Assist Services |
| Communication Systems | 84 05 08 | September-08 | E60/E90/E83 | Service Action: Reactivation of Telematics Control Unit (TCU) |
| Communication Systems | 84 06 08 | September-08 | 3 Series | CIC: Unable to Select an Address via the Contact Book |
| Communication Systems | 84 07 08 | September-08 | 1/3/5/6 series | Echo and Reverberation on the Landline during a Hands-free Call |
| Communication Systems | 84 08 08 | September-08 | 1/3/5/6/X series | BMW Assist Menu Item |
| Communication Systems | 84 09 08 | October-08 | 1/3 series | Service Due CC Message Appears Before Handover Inspection |
| Communication Systems | 84 11 08 | January-09 | All | BMW Assist Inoperative in Certain Areas (rpl 10/08) |
| Communication Systems | 84 12 08 | June-09 | All | TCU Symptom Diagnosis (rpl 11/08) |
| Communication Systems | 84 13 08 | December-08 | Z4 | Poor Voice Quality on the Receiving End When Placing a Telephone Call |
| Communication Systems | 84 02 09 | February-09 | All | Telephone - Incomplete Contact List Available in Vehicle |
| Communication Systems | 84 03 09 | February-09 | All | Telephone Contacts Cannot Be Deleted from the CIC |
| Communication Systems | 84 04 09 | June-09 | All | The Landside Person Finds the Caller Speaking from an iPhone 3G Hard to Understand (rpl 3/9) |
| Communication Systems | 84 06 09 | May-09 | All | Telephone: Humming or Pulsing Noise Coming from the Vehicle Loudspeakers |
| Communication Systems | 84 08 09 | May-09 | 1, 3, 5, 6, 7 series | Telephone: Poor Voice Quality at Landside End |
| Communication Systems | 84 09 09 | June-09 | 1, 3, 5, 6, 7, X5/6 | BMW Assist Services - Vehicle Position Incorrect |
| Communication Systems | 84 10 09 | June-09 | All | BMW Assist " MyInfo" Troubleshooting Tips |

01, 03, 10, other models or minor

Rev 21 published

NOTE: Text in Maroon represents new data or updated since previous edition (SIB_List_rev_20, published 7 June 2009)

Red = Safety recall notice

Bold = Service Action or Recall campaigns

Another Service Bulletin resource ---> Checkout periodically to see if they keep current

This link seems to have been closed to non-subscribers sometime in January 2007

No Longer available from: <http://www.alldata.com/tsb/BMW/index-post.html>