COMPILED AND EDITED BY COBRADAV - COURTESY OF KoTR @ bimmerdrivers.com						
Category	SIBs (SI B## ## ##)	<u>Date</u>	<u>Application</u>	<u>Title</u>		
Maintenance and General Hints	00 04 02	March-08	All	BMW Group Technical Hotlline (rpl 1/08)		
Maintenance and General Hints Maintenance and General Hints	00 06 03 00 01 05	November-03 June-06	AII AII	General info on TIS Website New Vehicle Preparation and Maintenance Requirements (Supercedes Jan 06)		
Maintenance and General Hints	B000105ATT_VehChk	P/O 00 01 05	525/530	Quality Certification Form		
Maintenance and General Hints	00 02 06	March-07	All	New Vehicle Preparation and Maintenance Requirements (MY07) (Rpl 11/06)		
Maintenance and General Hints	00 01 07	May-08	ALL	New Vehicle Preparation and Maintenance Requirements (rpl 3/8 adds M3 DCT and 1 series)		
Maintenance and General Hints	00 03 07	August-07	ALL	PuMA Enhancements for TeileClearing Process		
Maintenance and General Hints Maintenance and General Hints	00 04 07 00 08 07	March-08 October-07	X3, X5 All	New Vehicle Preparation and Maintenance Requirements (rpl 12/07 adds X6) Construction Group Changes		
Maintenance and General Hints	00 08 07	March-08	BMW Centers	BMW Center Technical Support Overview		
Maintenance and General Hints	00 02 08	March-08	E82/E88	E82, E88 (1 Series) Quality Control Information		
Maintenance and General Hints	00 03 08	April-08	E71 (X6)	E71 (X6) Quality Control Information		
Maintenance and General Hints	00 04 08	February-09	ALL	New Vehicle Preparation and Maintenance Requirements		
Maintenance and General Hints Maintenance and General Hints	00 05 08 00 06 08	January-09	ALL	New Vehicle Preparation and Maintenance Requirements		
Maintenance and General Hints	00 06 08	September-08 October-08	ALL 3 series	Information Tags E90, E91 (3 Series) LCI Quality Control Information		
Maintenance and General Hints	00 08 08	December-08	335d & X5d	E90, E70 Diesel Quality Control Information		
Maintenance and General Hints	00 01 09	March-09	5, 6 Series	New Vehicle Preparation and Maintenance Requirements		
Maintenance and General Hints	00 02 09	February-09	7 series	F01, F02 Quality Control Information		
	09 na					
Warranty	01 02 03	September-03	BMW Centers	BMW Maintenance Program 4 Years - 50,000 Miles		
Warranty	01 07 03	January-07	BMW Centers	BMW Center Administered Customer Assistance Program (CACAP)		
Warranty	01 02 04	November-06	BMW Centers	BMW Tire Center Target Satisfaction Program		
Warranty Warranty	01 06 05 B010605Attachment.	March-05 P/O 01 06 05	BMW Centers BMW Centers	BMW Maintenance Program 2005 Laminated Reference Chart and Mouse Pad Chart of Warranty Codes/Services		
Warranty	01 07 05	March-05	BMW Centers	Warranty Claims Processing – "Overnight Payments"		
Warranty	01 10 05	August-05	BMW Centers	TCU ESN Registration via DCSnet		
Warranty	B011005Attachment.	P/O 01 10 05	BMW Centers	FAQ's for TCU Claims		
Warranty	01 01 06	January-08	BMW Centers	BMW Warranty Policy and Procedures Manual – Updates from 01/01/05 through 12/21/07)		
Warranty	B010106Attachment	P/O 01 01 06	BMW Centers	BMW Warranty Policy and Procedures Manual – Updates from 01/01/05 through 12/21/05 rev notes		
Warranty Warranty	01 02 06 B010206EAS Flowchart.	February-06 February-06	BMW Centers BMW Centers	BMW Electronic Archiving System (EAS) Evaluation and Certification EAS Flowchart		
Warranty	01 03 06	February-07	BMW Centers	Warranty Claims for Software Update Programming (Progman) (Replace NOV 06)		
Warranty	01 04 06	April-06	BMW Centers	Reasons for Vehicle Update Programming Reminder Magnet		
Warranty	01 09 06	February-07	BMW Centers	Defect Code for Programming Prior to Accessory Retrofit (Supercedes 12/06)		
Warranty	01 03 07	June-07	BMW Centers	New Pricing Plan and Program Enhancements - Maintenance Program Upgrade		
Warranty	01 02 08	February-08	BMW Centers	BMW Performance Line of Accessories		
Warranty Warranty	01 03 08 01 05 08	May-08 July-08	BMW Centers BMW Centers	OEM Tire Manufacturer Warranty Coverage CD-ROM Certified Pre-Owned (CPO) Reconditioning Changes		
Warranty	01 06 08	December-08	BMW Centers	Warranties Knowledge Portal (WKP)		
Warranty	01 07 08	December-08	BMW Centers	Labor Rate Calculation on all Reimbursed Labor as of 1/1/09		
After Sales Business Development	02 01 05	October-05	All	BMW Assist changes for September 2005		
After Sales Business Development After Sales Business Development	B020105KeyBenefitChart 02 01 06	P/O 02 01 05 February-06	All	BMW Assist - Key Benefits Updated DCSnet Vehicle History Inquiry Information on BMW Assist™ (Supercedes Jan 06)		
After Sales Business Development	02 07 00	November-06	All	BMW Assist™ Service Extension Incentive Program (Supercedes 02/06)		
After Sales Business Development	02 01 07	February-07	All	Mobile Assistance Program		
		,				
Tools and Equipment	04 02 05	January-05	E60/E63	Zero-Coded Cover		
Tools and Equipment	04 04 05	January-05	E60	Antenna Knife		
Tools and Equipment	04 07 05	April-05	N52 Engine	N52 Special Tools		
Tools and Equipment Tools and Equipment	04 08 05 04 13 05	February-05 March-05	E60/E63 E61	Aluminum Body Tools Tailgate Support		
Tools and Equipment	04 14 05	April-05	E60/E63	CD Eject Tool		
Tools and Equipment	04 15 05	May-05	E90	DME Test Cable		
Tools and Equipment	04 29 05	November-05	E60/E63	AC Sprayer Wand		
Tools and Equipment	04 02 06	January-06	M - S85 engine	Backlash Gauge		
Tools and Equipment Tools and Equipment	04 04 07 04 07 07	April-07 December-07	Turbocharged All	Turbocharger Diagnostic Tool Fuel Injection and Induction System Cleaning		
Tools and Equipment	04 01 08	January-08	S65/M3	New Special Tools		
	thru - 2106 no value					
01	07-0307/0507-0607/ & 0807-2807 no valu	е				
Information Systems	05 01 05	September-05	All	Teleservice Changing a Customer's Preferred Home Dealer		
	end					
Service Roundtable	06 01 06	September-06	ALL	Service Roundtable – September 2006 Show		
Service Roundtable	06 02 06	October-06	ALL	Service Roundtable – October 2006 Show		
Service Roundtable Service Roundtable	06 03 06 06 04 06	November-06 December-06	ALL ALL	Service Roundtable – November 2006 Show Service Roundtable – December 2006 Show		
Service Roundtable	06 01 07	January-07	ALL	Service Roundtable – December 2000 Show		
Service Roundtable	06 02 07	February-07	ALL	Service Roundtable – February 2007 Show		
Service Roundtable	06 03 07	March-07	ALL	Service Roundtable – March 2007 Show		
Service Roundtable	06 04 07	April-07	ALL	Service Roundtable – April 2007 Show		
Service Roundtable	06 05 07	May-07	ALL	Service Roundtable – May2007 Show		
Service Roundtable Service Roundtable	06 06 07 06 07 07	June-07 July-07	ALL ALL	Service Roundtable – June 2007 Show Service Roundtable – July 2007 Show		
Service Roundtable	06 08 07	August-07	ALL	Service Roundtable – 3dly 2007 Show		
Service Roundtable	06 09 07	September-07	ALL	Service Roundtable – September 2007 Show		
Service Roundtable	06 10 07	October-07	ALL	Service Roundtable – October 2007 Show		
Service Roundtable	06 11 07	November-07	ALL	Service Roundtable: November 2007 Show		
Service Roundtable	06 12 07	December-07	ALL	Service Roundtable: December 2007 Show		
Service Roundtable Service Roundtable	06 01 08 06 02 08	January-08 February-08	ALL ALL	Service Roundtable: January 2008 Show Service Roundtable: February 2008 Show		
Service Roundtable Service Roundtable	06 02 08 06 03 08	March-08	ALL	Service Roundtable: February 2008 Show Service Roundtable: March 2008 Show		
Service Roundtable	06 04 08	April-08	ALL	Service Roundtable: March 2008 Show		
Service Roundtable	06 05 08	May-08	ALL	Service Roundtable: May 2008 Show		
Service Roundtable	06 08 08	June-08	ALL	Service Roundtable: June 2008 Show		
Service Roundtable Service Roundtable	06 07 08 06 09 08	July-08 September-08	ALL ALL	Service Roundtable: July 2008 Show		
Service Roundtable Service Roundtable	06 09 08 06 10 08	October-08	ALL ALL	Service Roundtable: September 2008 Show Service Roundtable: October 2008 Show		
Service Roundtable	06 11 08	November-08	ALL	Service Roundtable: November 2008 Show		
Service Roundtable	06 12 08	December-08	ALL	Service Roundtable: December 2008 Show		
Service Roundtable	06 01 09	January-09	ALL	Service Roundtable: January 2009 Show		
Service Roundtable	06 01 09	February-09 March-09	ALL	Service Roundtable: February 2009 Show		
Service Roundtable	06 01 09	Wat CII-U9	ALL	Service Roundtable: March 2009 Show		

Category	SIBs (SI B## ## ##)	<u>Date</u>	Application	Title
	07 02 96			
General General	07 02 96 07 03 02	June-07 June-04	BMW Centers BMW Centers	CD42: Updated DISplus & GT1 Software (update to Mar 07) Optical Testing & Programming System - OPPS
General	07 05 02	June-05	BMW Centers	Online Update
General	07 02 04 07 01 05	November-04	BMW Centers	Optical Programming System - OPS
General General	07 01 05	December-05 August-06	BMW Centers BMW Centers	Software Service Station r2 (SSSr2) Next Generation Workshop Technology – iBase Server Readiness Project
General	07 03 06	October-06	BMW Centers	Next Generation Workshop Technology 3G
General General	07 04 06 07 01 07	January-07 March-07	BMW Centers BMW Centers	Use Agreement for 3G Workshop Technology
General	B070107_Feedback PDF	March-07	BMW Centers	DIS V49 Corrections Based on Diagnosis Feedback B070107Diagnosis_Feedback_Corrected_DIS_V49.
General	07 03 07	June-07	BMW Centers	DIS V50 Corrections Based on Diagnosis Feedback
General General	B070307_Feedback PDF 07 04 07	August-07	BMW Centers	DIS V51 Corrections Based on Diagnosis Feedback (Update to June 07)
General	07 05 07	June-07	BMW Centers	DIS V50 Release Notes
General	07 06 07	August-07	BMW Centers	Diagnosis Process
General General	07 08 07 07 10 07	August-07 October-07	BMW Centers BMW Centers	DIS V51 Release Notes Importance of Using the Most Current Diagnostic / Programming Software
General	07 11 07	November-07	BMW Centers	DIS V52 Corrections Based on Diagnosis Feedback (December 2007 Release)
General	07 13 07	December-07	BMW Centers	DIS V52 Release Notes
General General	07 15 07 07 01 08	January-08 March-08	E60/E63/E90/E92/E70 BMW Centers	Diagnosis via D-CAN Not Possible DIS V53 Changes Based on Diagnosis Feedback (March 2008 Release)
General	07 02 08	March-08	BMW Centers	DIS V53 Release Notes
General	07 05 08	May-08	BMW Centers	DIS V54 Changes Based on Diagnosis Feedback (June 2008 Release)
General General	07 06 08 07 07 08	August-08 August-08	BMW Centers BMW Centers	Diagnosis Feedback with ISTA ISTA Technical Data 2.8.0 Changes Based on Diagnosis Feedback
General	07 08 08	September-08	BMW Centers	DIS V55 Release Notes
General	07 09 08	October-08	BMW Centers	New ISTA/P Software
General General	07 10 08 07 11 08	November-09 December-09	BMW Centers BMW Centers	ISTA Does Not Automatically ID the Vehicle DIS V56 Release Notes
Programming/Coding Explainations	09 03 98	May-06	E60/E63/E90	Car & Key Memory (Updated date with additional E90 info Supercedes Nov 05)
Programming/Coding Explainations	B090398_Att5_CKM_E60 09 05 01	P/O 09 03 98 March-06	E60/E63 E60/E63	PDF of car and Key memory settings CIP General Info (Supercedes Dec 05)
Programming/Coding Explainations Programming/Coding Explainations	Att3_CBSCheck	P/O 09 05 01	E60/E63	Condition Based Service Plausibility Check
Programming/Coding Explainations	Att4_CBSCorrct	P/O 09 05 01	E60/E63	Condition Based Service Adjustments based on previous service
Programming/Coding Explainations	ProgCoding	P/O 09 05 01	E60/E63	Detailed Description of programming and coding using CIPs
Programming/Coding Explainations Programming/Coding Explainations	09 07 02 09 01 04	March-03 January-05	E65 BMW Centers	CIP 7.0 Programming Manager
Programming/Coding Explainations	09 01 05	May-05	All	CIP 17.0 Release Notes
Programming/Coding Explainations	09 02 05	July-05	All E90	OBD Replacement Cables for GTI/DISplus Diagnostic Heads
Programming/Coding Explainations Programming/Coding Explainations	09 03 05 09 04 05	January-07 July-05	All	Personal Profile (Replaces 8/05) CIP 18.0 release notes
Programming/Coding Explainations	09 05 05	July-05	E60 w/o NAV	After Programming, CIP shows MASK-H to be replaced
Programming/Coding Explainations Programming/Coding Explainations	09 06 05 09 07 05	August-05 September-05	E60/E63 All	CIP Shows IHKA (Automatic heating & AC) to be Replaced CIP 19.0 and 19.1 release notes
Programming/Coding Explainations Programming/Coding Explainations	09 08 05	October-05	E64 Cabrio	Service Action: Correction to Integration Level
Programming/Coding Explainations	09 09 05	November-05	BMW Centers	CIP: Report Recurring Irregularities
Programming/Coding Explainations Programming/Coding Explainations	09 11 05 09 01 06	October-06 February-06	E60/E63/E90 E90	CCC Fails to Program with CIP 19.x (Supercedes Dec 05, Feb 06, May 06, Aug 06) JBE Fails to Program (supercedes Jan 06)
Programming/Coding Explainations	09 02 06	January-06	E90	Replacement FZD Not Accepted by CIP/PROGMAN
Programming/Coding Explainations	09 03 06	January-06	All	Deciphering and Troubleshooting the Vehicle Order
Programming/Coding Explainations Programming/Coding Explainations	09 05 06 09 06 06	January-06 February-06	E60/E63/E90 E90	Release Notes Program V20.0 and V20.0.1 RAD2 Cannot be Programmed after Programming Abort (Supercedes Jan 06 - Online 20.02.00)
Programming/Coding Explainations	09 07 06	January-06	E90/x drives	DSC Cannot be Encoded
Programming/Coding Explainations	09 08 06	February-06	E90	DWA LED on Rearview Mirror Cannot be Activated
Programming/Coding Explainations Programming/Coding Explainations	09 09 06 09 10 06	March-06 May-06	All All	Release Notes Progman 21.0 Release Notes Progman V21.02 and V21.02.01
Programming/Coding Explainations	09 11 06	May-06	E60	Replacement SZL Not Accepted By Progman
Programming/Coding Explainations	09 13 06 09 14 06	June-06	All	Release Notes Progman V22.0 and V22.0.1 Maintenance Interval Retrofit is Not Used in US Market Vehicles
Programming/Coding Explainations Programming/Coding Explainations	09 14 06	July-06 July-06	E60/E63/E90 E90	Personal Profile Settings for Alarm System Missing
Programming/Coding Explainations	09 16 06	August-06	E60/E63/E90	Release Notes Progman V22.1 and V22.1.1 and V22.1.2
Programming/Coding Explainations	09 17 06	December-06	ALL E90	Vehicle Order (VO) Cannot be Adapted Using CIP
Programming/Coding Explainations Programming/Coding Explainations	09 20 06 09 21 06	October-06 October-06	E90	Daytime Running Lamps Switched On after Update with Progman V23 Satellite Radio Inoperable after Programming with Progman V23 - Need 23.01.03
Programming/Coding Explainations	09 22 06	October-06	E60/E63/E90	Coding Function for Headunit Available in Progman V23
Programming/Coding Explainations Programming/Coding Explainations	09 01 07 09 02 07	January-07 October-07	E60/E63/E90 All w/CCC	CCC: Programming or Coding Fails with Progman V24 CCC: Enabling Code (FSC) Required for Voice Recognition System(update to May 07
Programming/Coding Explainations	B090207Attachment.	P/O 09 02 07	BMW Centers	B090207Parts_Info_V1_1
Programming/Coding Explainations	09 03 07	June-07	E92	FRM Fails Coding
Programming/Coding Explainations Programming/Coding Explainations	09 04 07 09 05 07	August-07 September-07	ALL w/CCC E90	Programming Failure Due to CD or DVD in Drives CAS2 Programming with Special Measure not Possible
Programming/Coding Explainations	09 07 07	April-09	ALL	Program Version vs. Vehicle Data Status (update to 1/09) 2.33.02 latest shown
	06 other model			
Engine System	11 08 98	June-06	All	BMW Engine Oils (Includes Annual Change Coverage) (Supercedes Oct 05)
Engine System Engine System	11 04 03	February-07	E60	Recurring Noise Complaints From Mechanical Alternator Belt Tensioners (Replaces 7/05)
Engine System	11 02 05	January-06	E60/E63	N62 - Rough Idle, Misfire faults after cold start (Supercedes May 05)
Engine System Engine System	11 03 05 11 05 05	June-05 December-06	E60/E63 E60	N62 and N62TU Valve Cover and Valve Cover Gasket Replacement N52 Engine Runs Poorly with Camshaft Sensor and VANOS Faults (Supercedes Novr 06)
Engine System	11 07 05	July-05	E60/E63	N62 and N62TU Water Pump Replacement - corrects installation procedure
Engine System	11 09 05	April-06	E60/E63	Non-Return Valve Parts Found In Engine Oil Filter During Engine Oil Service Supercedes Dec 05)
Engine System Engine System	11 10 05 11 01 06	February-06 March-06	E60 (M5) M5/M6	Service Action: S85 Replace VANOS High Pressure Line (Supercedes Jan 06) S85 Engine Oil Level and Oil Service Information
Engine System	11 02 06	December-06	E60	NG6 Engines - Front and Rear Radial Crankshaft Seal Replacement
Engine System	11 03 06	June-06	All w/N62 Engine	Voluntary Emissions Recall 06E-A02: N62 - Crankcase Ventilation Valves Replacement
Engine System Engine System	11 04 06 11 06 06	June-06 June-06	All M54/M54TU	Engine, Transmission, or Clutch Related Complaints Head Bolt Threads Pulling Out of Block During Engine Reassembly
Engine System	11 07 06	October-06	All w/N62 Engine	N62 Engine - Rough Idle at Operating Temperature
Engine System	11 13 06	January-08	E90/E92 w N54	N54 Engine Compression and Cylinder Leakage Test Procedures (rpl 11/06)
Engine System Engine System	11 01 07 11 05 07	October-07 April-07	All with N62 (4.4I) All S85 (V10)	N62 Crankcase Ventilation System – Cold Climate Conditions (rpl 6/07) Service Action: Replace Front Crankshaft Radial Seal
Engine System	11 09 07	July-07	All N52 Engine	Intermittent Hydraulic Valve Adjuster (HVA) "Ticking" or "Rattling" Noises
Engine System	11 12 07 11 13 07	October-07	N62/N62TU	N62 and N62TU Engine Replacement (after an engine has been replaced)
Engine System Engine System	11 13 07 11 14 07	May-08 November-07	N54 N54	N54 Rattle Noise from Turbocharger Area N54 Turbocharger Waste Gate Control Noises and Operation
Engine System	11 01 08	April-08	E60/E70/E83/3 series	Service Action: Replace the Chain Tensioning Rail Bearing Bolt
Engine System	11 02 08	February-08	N54	N54: Power Reduction - DME Fault 2A82 VANOS Inlet is Stored
Engine System Engine System	11 03 08 11 04 08	November-08 July-08	All engines All	Crankcase Ventilation System Specification TeileClearing for Engine Components
Engine System	11 05 08	August-08	1, 3 Series	N51 Engine: Cylinder Head Bolt Torque Is not Available via TIS
Engine System Engine System	11 07 08 11 09 08	August-08 October-08	E46 1 & 3 Series w/N54	Overheated Engine - Diagnostic Tips Alternator Drive Belt Broken
Engine System Engine System	11 10 08	October-08	S62 (E39 M5 & Z8)	S62 VANOS Assembly Mode Test Plan
Engine System	11 01 09	March-09	All	CPO Inspection Guidelines - Engine Inspection on Vehicles with Extended ("Overdue") Oil Service Intervals

<u>Category</u> Engine System	SIBs (SI B## ## ##) 11 03 09	<u>Date</u> March-09	Application M3 w/S65	Title Engine Oil Residue Found Near Oil Filler Cap
	06 - Alpina B7			
Engine Electrical System	12 01 99	June-06	All	High Performance Platinum Spark Plug/Spark Plug Application Chart
Engine Electrical System Engine Electrical System	12 01 04 12 03 04	October-04 September-04	N62 in E60 M54 in E60	E60 with N62; DME Reprogramming Voluntary Emissions Recall Campaign 04E-A02: Emission Readiness Codes Not Completely Setting
Engine Electrical System	12 04 04	July-04	E60/E63	Safety Recall Campaign 04V-344: DME Replacement on N62/N73 Engines
Engine Electrical System Engine Electrical System	12 05 04 12 09 04	October-05 August-06	E60/E63 All	Voluntary Emissions Recall 04E-A04: Reprogram DME for Oxygen Sensor Diagnostics on E53, E60, Special DME Programming - Shipping Procedure (Replaces 12/04)
Engine Electrical System	12 10 04	December-04	M54 in E60	Intermittent Hesitation While Driving or Intermittent Crank, No Start Situation
Engine Electrical System Engine Electrical System	12 01 05 12 03 05	March-08 September-05	N52 in E60 N62 in E60/E63	High Perf Iridium spark Plugs (rpl 06/06) CBS Oil Message
Engine Electrical System	12 04 05	July-07	N52 in E60	Check Engine light or engine overheats (Supercedes Mar 06)
Engine Electrical System Engine Electrical System	12 06 05 12 08 05	June-05 July-05	N52 in E60 E60	DME FC CDA7 CAN Message Oxygen Sensor
Engine Electrical System	12 11 05	January-06	N62 in E60/E63	Service Action: Reprogramming for Incorrect Oil Service (Supercedes August 05)
Engine Electrical System Engine Electrical System	12 15 05 12 16 05	March-08 September-05	N62 in E60/E63 E60	Map Thermostat faults (rpl 12/07) Mixture is too Lean, Fault codes 2882, 2883
Engine Electrical System	12 17 05	September-05	E60	Engine Power drops at 4000 RPM
Engine Electrical System Engine Electrical System	12 19 05 12 20 05	October-05 October-05	N52 in E60/E90 E60/E63	Service Action: Reprogram for OBD Diagnostic Loss of Power while decelerating & turning or coming to stop
Engine Electrical System	12 25 05	December-05	E90	CBS Oil formula (different but similar to E60/63)
Engine Electrical System Engine Electrical System	12 27 05 12 29 05	April-07 March-06	E60/E63 M5	N62TU (4.8L) Pinging and Surging (Supercedes Jul 06) S85 Engine Diagnosis Test Plan Updates (Supercedes Dec 05 - minor change)
Engine Electrical System	12 03 06	February-06	E60/M52	Loss of Power or Intermittent Crank, No Start Situation
Engine Electrical System Engine Electrical System	12 04 06 12 06 06	February-06 April-07	E60/M52 E60/E90/N52	DMTL Diagnosis Test Plan Error Voluntary Emissions Recall 06E-A01: N52 - Reprogramming Vehicle for OBD Diagnostic (Supercedes 5/06)
Engine Electrical System	12 07 06	January-07	E60/E90/N52	Service Engine Soon Light Illuminated: FC 2EF4 Map Thermostat (Replaces 5/06)
Engine Electrical System Engine Electrical System	12 10 06 12 12 06	September-06 April-07	E60/E90/N52 E60/E63/N62TU	Service Engine Soon Lamp Illuminated: FC 2C2D, 2C3D, 2C2E, 2C3E N62TU - Diagnosis for DME FC 2A90 (Supercedes Dec 06)
Engine Electrical System	12 16 06	September-06	E90/E92 w N54	E90, E92 with N54 - Diagnostic for DME FC 29F1/29F2
Engine Electrical System	12 18 06	November-06	Ms	Voluntary Emissions Recall 06E-A04: S85 - DME Reprogramming for OBD Monitoring
Engine Electrical System Engine Electrical System	12 19 06 12 25 06	October-06 November-06	E60/E63/E90 All	Check Gas Cap Warning with DME FC 2A17 – DMTL, System Error Fuel Quality Determination (Supercedes August 06)
Engine Electrical System	12 27 06	November-06	E60/N62	DME Fault Codes 278B and 278D
Engine Electrical System Engine Electrical System	12 28 06 12 29 06	October-06 November-06	E60 E60/M54	DME Fault Code 27CD DME Fault Codes 2896, 2877, 2766
Engine Electrical System	12 33 06	October-06	E60/E63	Various Complaints Caused by Defective Oil Level Sensor - Diagnostic Hints
Engine Electrical System Engine Electrical System	12 34 06 12 38 06	October-06 October-06	E60/M54 E90	E60, M54 - Various Oxygen Sensor FC's Caused by Defective Transmission Harness MSV70 - DME, FC 29DA Segment Adaptation
Engine Electrical System	12 40 06	October-06	E60	MS45.1 – Various O2 Sensor Faults Stored in DME
Engine Electrical System Engine Electrical System	12 42 06 12 43 06	November-06 October-06	E60 E60/E63	E60, MS45.1 – DME FC 28A2 and FC 2783 N62 DME ME9.2.1 Engine Difficult to Restart at Operating Temperatures
Engine Electrical System	12 46 06	November-06	E90/E92 w N54	N54 – Slight Bucking is Felt During Acceleration With a Cold Engine
Engine Electrical System Engine Electrical System	12 47 06 12 49 06	November-06 April-07	E60/E63 E60/M54	Break Out Box Overlay Identification DME MS45 - FC28B2, 28AA, 28AC; Internal RAM Faults (Rpl 11/06)
Engine Electrical System	12 50 06	November-06	E60/E63/E90	OBD II Fault Codes List in TIS
Engine Electrical System Engine Electrical System	12 51 06 12 54 06	December-06 December-06	E92 E90/92	MSD80 N54 Engine Diagnostic Test Plans Inoperative N54 CBS4 Oil Service Indicates 25,000 Miles
Engine Electrical System	12 55 06	January-08	E90/92	E90, E92 with N54 - Diagnosis for DME FC 29DC/2FBF (Replaces 1/07)
Engine Electrical System	12 58 06 12 05 07	January-07	E90 E60/E90	Service Action: Replace the Alternator Erroneous Low Oil Level Warning Message While Driving (rpl 120/07)
Engine Electrical System Engine Electrical System	12 03 07 12 06 07	January-08 September-07	E90/E92	Voluntary Emissions Recall 07E-A01: N54 - Reprogramming Vehicle (DME) for OBD Diagnostic
Engine Electrical System Engine Electrical System	12 07 07	June-07	E90/E92	N51 - Fault 2A43: Valvetronic, Thermal Overload Protection
Engine Electrical System	12 09 07 12 10 07	May-07 October-07	M5/M6 E60/E63/N62TU	Service Engine Soon Light Illuminated: S85 - Various VANOS Related Faults Stored Service Action: N62TU - Retrofit Engine Compartment Ground Cables - rpl 7/07 (now recall)
Engine Electrical System	12 11 07	July-07	E60/E63/N62TU	N62TU: EDK Throttle Faults - Diagnostic
Engine Electrical System Engine Electrical System	12 15 07 12 16 07	October-07 October-07	3 Series 3 Series	N52K - Loss of Power N51 - EAC Sensor Fault 2AD8 is Stored
Engine Electrical System	12 18 07	October-07	3/5 w N54	N54: Running Issues with Various Faults in DME
Engine Electrical System Engine Electrical System	12 22 07 12 23 07	November-07 November-07	AII E70 (X5)	TeileClearing (Enhanced Technical Support) for DME FC 2EF4 Characteristic Map Thermostat
Engine Electrical System	12 25 07	November-07	E70 (X5)	E70 N62TU: Pressure Sensor Fault 2D32
Engine Electrical System Engine Electrical System	12 28 07 12 01 08	December-07 January-08	3/5 w N54 3/5 w N52	N54 Engine Failsafe: FC 3100, FC 30FE and/or FC 30FF is stored in DME Fault Memory N52 EDK Throttle Jamming Faults 2D09, 2CED and 2CEC
Engine Electrical System	12 02 08	January-08	3/5 w N54	N54 - Diagnosis for DME Fuel Injector Faults
Engine Electrical System Engine Electrical System	12 03 08 12 05 08	January-08 February-08	X5 w N54 X5 w N62TU	N52K - Diagnosis of DME FC 2E97 N62TU: Fault 2A17 - DMTL System Error is Stored
Engine Electrical System	12 06 08	July-08	1/3 series, X5	CBS4 Oil Service Forecast Displays Due in 25,000 miles
Engine Electrical System Engine Electrical System	12 09 08 12 10 08	February-08 April-08	E60/63/70 All w N54	Driveability Complaints due to Cooling Fan Relay Failure N54 – Aftermarket "Engine Performance Tuning" Kits
Engine Electrical System	12 12 08	March-08	3 Series/N52/N52K	DME FC 2A15 Minor Leak and 2A16 Superfine Leak in Evaporation System
Engine Electrical System Engine Electrical System	12 13 08 12 14 08	March-08 May-08	3/5 ser w/M54/N52 New M3 /S65	After Vehicle Repair, Service Engine Soon Lamp Cannot Be Switched Off Service Engine Soon Lamp Is Illuminated, EKP FC 2786, 2787, 2788 (rpl 3/08)
Engine Electrical System	12 15 08	August-08	E65/66	E65, E66 with N62TU - Various Driveability Complaints
Engine Electrical System Engine Electrical System	12 16 08 12 17 08	June-08 June-08	M5/M6 V10 E65/66	Voluntary Emissions Recall 08E-A02: M5 and M6 with S85 – OBD Communication Service Action: E65 and E66 with N62, N62TU, or N73 – OBD Communication
Engine Electrical System	12 18 08	June-08	All w/N54	Service Action: N54 Oil Level Programming
Engine Electrical System Engine Electrical System	12 19 08 12 20 08	June-08 June-08	M5/M6 V10 All w/N54	S85 - Power Reduction with Idle Actuator Faults Stored N54 - Various Complaints Caused by Aftermarket "Tuning Kits"
Engine Electrical System	12 21 08	July-08	M5/M6	S85 - DME Fault 2742/2743 for O2 Sensor
Engine Electrical System Engine Electrical System	12 23 08 12 24 08	July-08 September-08	E65/66/B7 E65/66/B7	Service Action: E65 and E66 with N62, N62TU, or N73 – OBD Communication Service Action: E65 and E66 with N62TU or N73 – OBD Communication
Engine Electrical System	12 25 08	September-08	1/3/5 series & X6	Charge Air Pressure Control B1214_D16LDRN Test Plan Is Inoperative
Engine Electrical System Engine Electrical System	12 26 08 12 27 08	October-08 October-08	All w/N54 & N63 engir All w/N54 & N63 engir	n Injector Removal, Installation, and Replacement Procedures
Engine Electrical System	12 28 08	December-08	S65 / S85	S65 / S85 Rough Running During the Catalyst Heating Phase
Engine Electrical System Engine Electrical System	12 01 09 12 02 09	February-09 February-09	1,3,5/X5 1,3,5,6/X5,X3	Service Engine Soon Lamp or Check Gas Cap Warning Illuminated Service Engine Soon or Check Gas Cap Warning Is Illuminated: Tank Leakage
Engine Electrical System Engine Electrical System	12 02 09	March-09	1,3,5,6/X5,X3 X5 (E70)	The Engine Oil Level Is Displayed as Overfilled
Engine Electrical System	12 04 09 12 05 09	February-09	M3 w/S65	M3 S65 - Diagnosis for DME Fault Code 2AFD
Engine Electrical System Engine Electrical System	12 05 09 12 06 09	March-09 March-09	5 Series 1, 3 series	N54 E60, E61- Misfire Faults Are Stored due to DME Software Errors N54 E9x, E82, E88 - Misfire Faults Are Stored due to a DME Software Error
			•	
	no 04, 06, 07, 08			
	02, 03, 04, 12, 13, 20, 24, 26 other models, 01, 14, 19	21, 27 NU		
Fuel Systems	13.01.04	luly-04	E60/E63 (V8)	Pecall Campaign MV- 303: Petaining Clin Petrofit for the Fuel Line Quick Pelease Counling

Fuel Systems	13 01 04	July-04	E60/E63 (V8)	Recall Campaign 04V- 303: Retaining Clip Retrofit for the Fuel Line Quick Release Coupling
Fuel Systems	B130104Q&A	P/O 13 01 04	E60/E63 (V8)	Q&A
Fuel Systems	13 01 06	September-06	All	Alcohol Fuel Blends in BMW Vehicles (replaces March 06)
Fuel Systems	13 02 06	September-06	All	TOP TIER Detergent Gasoline in BMW Vehicles (Replaces 03/06)
Fuel Systems	13 03 06	May-06	All	Fuel Pump Failure after Refueling with Ethanol Fuel Blend
Fuel Systems	13 04 06	August-06	All	Alcohol Detection Procedure
Fuel Systems	13 05 06	September-06	All	BMW Group Fuel System Cleaner Plus (Supercedes Aug 06)

			Complied and edited	by cobraday
Category	SIBs (SI B## ## ##)	<u>Date</u>	Application	Title
Fuel Systems	13 06 06	November-06	E90/E92	High Precision Injection (HPI) Information and Service Procedures
Fuel Systems	13 07 06	November-06	ALL	Gasoline Quality & Detergent Additives - Customer Information Brochure
Fuel Systems	13 01 07	February-08	ALL/ex turbo	Fuel Injection and Induction System Cleaning (rpl 12/07)
Fuel Systems	13 02 08	September-08	E90/92/93/wN54	Service Action: Replace the High Pressure Pump
Fuel Systems	13 03 08	September-08	E90/92/93/wN54	Service Action: Replace the High-Pressure Pump (older vehicles)
Fuel Systems	13 05 08	February-09	E90/92/93 M3	Rough Idle, Rough Running, Misfiring and Loss of Power (rpl 12/08)
Fuel Systems	13 02 09	March-09	X5d	E70 M57Y Diesel - Diagnosis for Low Pressure Fuel Supply Faults
Fuel Systems	13 04 09	March-09	All w/N54	N54 - Cold Start Rough Running with Misfire Fault
r dei dystems	10 04 03	maron os	All W/104	1604 Cold Clark Rough Kuming With Mishire Fullik
Fuel Supply	16 02 05	March-05	E60/E63	Fuel Tank Difficult to Refuel
Fuel Supply	16 01 06	September-06	E90	Fuel Level Sensor Repair Procedure w/N54
Fuel Supply	16 03 06	October-06	E90	Vehicle is Difficult to Refuel
Fuel Supply	16 06 06	October-06	E60	Humming/Buzzing Noise from Center Dash Area When Accelerator is Depressed
Fuel Supply	16 08 06	February-07	E90	N51 PZEV - Erroneous Fuel Gauge Reading (Replaces 12/06)
Fuel Supply	16 01 07	August-07	All	Testing Evaporative Systems for Leaks
Fuel Supply	16 02 07	December-07	E70 (X5)	Service Action: Repair the Fuel Tank Level Sensor
Fuel Supply	16 01 08	September-08	All w/N54	DMTL Tank Leakage Test Module Provides Inaccurate Results
Fuel Supply	16 03 08	January-09	E90/X5 w/d	Diesel Misfueling Protection Bypass Adapter
	- 02 other models			
Cooling Systems	17 01 07	October-07	ALL	BMW Long-Term Antifreeze/Coolant: Maintenance, Repairs and Replacement Requirements
	17 01 07	July-08	E9x M3	
Cooling Systems	17 01 08	July-06	Eax M2	Low Coolant Warning Lamp is Illuminated
Clutch	21 02 06	October-06	E60 (M5)	S85 - SMG Transmission Faults 4FA0, 4F80 and Clutch is Damaged
Clutch	07 for Z4	May-07	Z4	Service Action: Clutch Fork Lever Inspection
		.,		
Drive Shaft	26 01 06	June-07	E65/E66	Noise from Driveshaft Area (Rpl 06/06)
Drive Shaft	26 01 08	July-08	3 Series Xi	Service Action: Replace Front Propeller Shaft Bolts (Build 12/07)
		-		
Manual Transmission	23 01 05	November-05	E60/M5	E60 M5 - CAN Communication Fault FFFF
Manual Transmission	23 01 06	February-06	M Cars	SMG III: Fault Code 5101 Analyze Hydraulic Sensor (Supercedes Jan 06)
Manual Transmission	23 02 06	January-06	SMG Tranny	Towing Vehicles with SMG Transmissions
Manual Transmission	23 03 06	April-07	M Cars	Getrag SMG Transmission Repair & Replacement Information (SMG II and III) (Rpl 02/06)
Manual Transmission	23 04 06	April-06	E60/E63	ZF SMG FC 4F6F - Hydraulic Pump Failure (Supercedes Mar 06)
Manual Transmission	23 07 06	February-07	M Cars	M5, M6 with SMG III; FC 4F42/4F43 - Hydraulic Unit Faults (Replaces 12/06)
Manual Transmission	23 08 06	January-07	All SMG Cars	SMG - Service Functions Performed after Drivetrain Repairs
Manual Transmission	23 09 06	January-07	All non M SMG	ZF SMG - Replacement Parts Availability
Manual Transmission	23 01 07	August-07	S85 M5	Service Action: Replace SMG Hydraulic Unit Electric Motor on M5 Vehicles (rpl 7/07)
Manual Transmission	23 02 07	March-08	E60/E63	Voluntary Emissions Recall 07E-A02: SMG Reprogramming
Manual Transmission	23 03 07	December-07	ZF SMG	TeileClearing (Enhanced Technical Support) for ZF SMG Transmissions
Manual Transmission	23 01 08	May-08	Many	Vehicles equipped with Manual Transmissions manufactured by Getrag:
Manual Transmission	23 02 08	July-08	E46	E46, E85 with M54 and ZF SMG - OBD Communication
Manual Transmission	23 03 08	December-08	M5/M6	M5, M6 with SMG III; FC 4F82/4F83/4F84/4F85 - Gear Blocking Faults (rpl 10/08)
	- 06 other model			
Automatic Transmission	24 08 03	November-04	E60	EGS Fault 4F6A
Automatic Transmission	24 02 05	April-06	E60	Service Action: Replace Mechatronic Adapter (Supercedes May 05
Automatic Transmission	24 03 05	February-07	E60/E63	Harsh 2-1 Downshift (Replaces 6/05)
Automatic Transmission	24 06 05	November-05	E60/E63	Safety Recall Campaign 05V-504: Parking Lock Guide Plate
Automatic Transmission	B240605CustomerLetter	P/O 24 06 05	E60/E63	Recall Letter
Automatic Transmission	B240605Q&A.	P/O 24 06 05	E60/E63	Q&A
Automatic Transmission Automatic Transmission	24 06 06 24 11 06	October-06	E90 E92	A Slight Bump is Felt Shortly after the Vehicle Comes to a Stop (Supercedes Aug 06)
Automatic Transmission	24 04 07	October-06 April-07	E90/E91/E92	E92; N54 with 6HP16 - Diagnosis for EGS FC 511B ZF 6HP19TU in Failsafe Mode with Fault 4F8D Stored
* * * * * * * * * * * * * * * * * * *	0.4.00.00			The Service Engine Soon Light is on and EGS Fault CF1C Stored
Automatic Transmission Automatic Transmission	24 09 07 24 10 07	April-07 May-08	E90/E91/E92 E60/3 Series	The Transmission is in "Failsafe" mode with EGS Fault CF1C Stored - rpl 4/07
Automatic Transmission	24 10 07	April-07	3 Series	GM6 - 6L46R Transmission Adaptations and Terminology (info only)
Automatic Transmission	24 11 07	June-07	All STEP Equipped	Various Complaints Due to Poor Connection at Transmission Connector
Automatic Transmission	24 19 07	December-08	E60	Drive Position "D" Cannot be Engaged - rpl 6/08
Automatic Transmission	24 20 07	October-07	3 Xi	6L45R Transmission with AWD Leaks from the Selector Shaft Seal
Automatic Transmission	24 21 07	January-09	3 Series	Diagnosis - DME Fault CDB4: No Message (transmission data 3, 3B1)
Automatic Transmission	24 22 07	October-07	3 Series	6HP19TU (6HP21) - Fault 5087: One-Touch Hardware is Stored
Automatic Transmission	24 23 07	February-08	All STEP Equipped	6-Speed Automatic Transmissions Diagnosis and Troubleshooting Hints (rpl 12/07)
Automatic Transmission	24 01 08	December-08	E65/66	E65, E66 with 6HP26 - Diagnosis for EGS FC 4F81 - rpl 2/08
Automatic Transmission	24 02 08	September-08	E60/63/70	Driveability Complaints due to Cooling Fan Relay Failure - rpl 2/08
Automatic Transmission	24 03 08	January-09	E9x/E60	E60, E9x with N54 and 6HP19TU - Jolt and Delay when Pulling Away (rpl 6/08)
Automatic Transmission	24 04 08	September-08	E70 (X5)	E70, X5 3.0i with N52K and 6HP19TU - Transmission Driveability Complaints - rpl 7/08
Automatic Transmission	24 05 08	August-08	E65/66	E65, E66 with N62TU - Various Driveability Complaints
Automatic Transmission	24 06 08	October-08	E65/66	E70, X5 4.8i with N62TU and 6HP26TU - Various Driveability Complaints
Automatic Transmission	24 08 08	December-08	E60/61/X5(E70)	E6x with 6HP19TU - Transmission Clunks after Engine Start - rpl 10/08
Automatic Transmission	24 09 08	October-08	E60/61 & X5	GWS - Transmission Jumps Back to Neutral
	24 process info			
Coor Chitt Montania	25.24.27	I	F70	Comitee Action, Coor Chiff Knoh Doules-
Gear Shift Mechanism	25 01 07	January-07	E70	Service Action: Gear Shift Knob Replacement
Gear Shift Mechanism	25 02 07 25 03 07	November-07	E60	Diagnostic for GWS Faults - Drive Position "D" Cannot be Engaged
Gear Shift Mechanism	25 03 07 35 01 08	November-07	E60/E63	Sport Transmission Paddle Shifters Inoperative - Diagnosis
Gear Shift Mechanism	25 01 08 25 01 09	June-08	M5/M6	M5, M6 with SMG III - Gear Selector Display Position Changes from N to R (3-7/07)
Gear Shift Mechanism	25 01 09	February-09	E6x	E6x GWS: Gears D or R Cannot Be Selected
	14 - 18 other models			
Double-clutch Transmission with Dri	28 01 08	May-08	M3	M Double-clutch Transmission with Drivelogic Fluid Requirements
Double-clutch Transmission with Dri	28 02 08	May-08	M3	TeileClearing for M DCT Drivelogic (double-clutch) Transmission
Double-clutch Transmission with Dri	28 03 08	July-08	M3	M Double-Clutch Transmission with Drivelogic - Transmission Filling and Fluid Level Checking Procedure
Double-clutch Transmission with Dri	28 04 08	November-08	M3	M Double-Clutch Transmission with Drivelogic Transmission Replacement Procedure
Double-clutch Transmission with Dri	28 05 08	October-08	M3	M3 with DCT with Drivelogic – Gearbox Emergency Program with FC 5060
Double-clutch Transmission with Dri	28 06 08	November-08	M3	Recall Campaign 08V-595: M3 with M DCT – Reprogramming for Incorrect DCT Clutch Operation
Double-clutch Transmission with Dri	28 07 08	January-09	M3	M3 with M DCT - Complaint of Delayed Throttle Response
Double-clutch Transmission with Dri	28 01 09	March-09	M3	M3 with M DCT – Gearbox Warning Lamp with FC 5A87, 5A81 or 5A5B
				· · · · · · · · · · · · · · · · · · ·
Front Axle	31 02 04	August-04	All	Rattling Noise From Front or Rear Axle
Front Axle	31 02 06	June-06	E60/E63	Recall Campaign 06V-187 : Front Axle Control Arm and Tension Strut Fasteners

Category	SIBs (SI B## ## ##)	<u>Date</u>	Application	Title
Front Axle	31 03 06	November-06	E90	Recall Campaign 06V-400: Check Tightening Torque of Front Axle Control Arms and Tie Rods
Front Axle	31 01 07	January-08	E70 (X5)	Knocking Noise from Front Suspension
Front Axle Front Axle	31 01 08 31 01 09	November-08 February-09	E53 (X5) 1, 3 ser not M3	E53 (X5) - Replacement of Front Outer CV Joint (rpl 10/08) Creaking or Groaning Noise During Compression and/or Rebound of Front Axle
	0.0.00	. 02. 44. 7 00	1,000.1101.110	ordaning or ordaning rollo burning compression and or resource or rollo
	no 08 yet			
Steering and Wheel Alignment	32 01 05	July-05	E60	Power Steering Assist Enhancement
Steering and Wheel Alignment	32 04 05	June-05	E60	Steering Column Comfort Exit Feature
Steering and Wheel Alignment	32 07 05	September-05 October-05	E60/E63	Active Front Steering, Noise Fault Code 613E
Steering and Wheel Alignment Steering and Wheel Alignment	32 13 05 32 14 05	October-05	E60/E63 E60/E63	Active Front Steering, Fault Code 6141 Active Front Steering Sensitivity
Steering and Wheel Alignment	32 01 06	February-06	E90	Service Action: Install Clip for Power Steering Line
Steering and Wheel Alignment Steering and Wheel Alignment	32 04 06 32 05 06	February-06 March-06	E60/E63 E90	AFS Programming Steering Wheel Offset
Steering and Wheel Alignment	32 06 06	March-06	E60/E63	Steering Angle Sensor Adjustment
Steering and Wheel Alignment	32 07 06	April-06	E90/91	Steering Column Clicking Noise
Steering and Wheel Alignment	32 04 07	May-08	ALL F60/F70	TeileClearing (Enhanced Technical Support) for Steering Systems Active Front Steering (AFS) Warning Lamp; Fault Code 6141 stored
Steering and Wheel Alignment Steering and Wheel Alignment	32 07 07 32 01 08	January-08 January-08	E60/E70 E70 (X5)	Active Steering (AFS) Warning Lamp, Fault Code 6141 stored Active Steering Troubleshooting Procedures
Steering and Wheel Alignment	32 02 08	August-08	M5/M6	Repair Instructions for Power Steering Pump and Pressure Line
Steering and Wheel Alignment	32 04 08	January-09	1,3,5,6 & X5	Active Steering (AL) Warning Lamp Illuminated, Fault Code 6149 Stored
Steering and Wheel Alignment Steering and Wheel Alignment	32 06 08 32 07 08	October-08 March-09	X5/X6 E46/53/60/61/83	Clicking Noise during Steering Column Adjustment Squeaking Noise from the Steering Gear
Steering and Wheel Alignment	32 08 08	November-08	X5/X6	Steering Column Position Is Lost with Easy Entry
Steering and Wheel Alignment	32 10 08	August-08	All	Wheel Alignment Data
Steering and Wheel Alignment	31 01 09	March-09	3 series	Heated Steering Wheel Malfunction
		no 05, 06		
Rear Axle	33 01 02	March-08	M Cars	Grinding Noise from the Differential during Slow Cornering
Rear Axle	33 01 06	April-06	E60 (M5)	Grating Noise from Differential During Slow Cornering
Rear Axle	33 02 06	September-06	E60/E63/E65	Recall Campaign 06V-277: Inspect Rear Shock Absorbers (Supercedes Aug 06)
Rear Axle Rear Axle	33 01 07 33 01 08	October-07 March-08	E60 - M5 3 series M/S65	E60 M5 Howling Noise from Rear Axle Area E90, E92, E93 M3 - "Clunk Noise" on Load Reversal
Rear Axle	33 02 08	April-08	E70 (X5)	Recall Campaign 08V-170: Replace Rear Stabilizer Bar (mfr March 08)
Rear Axle	33 03 08	April-08	All models	Differential Cover Sealer
Rear Axle Rear Axle	33 04 08 33 05 08	October-08 August-08	1,3,5,6,7 ser & Z4 X5, X6	Clicking or Cracking Noise from Rear Differential Cracking or Banging Noise from Rear Axle
Rear Axle	33 07 08	December-08	E36/46/Z4/9x/82	Rear Spring Repair Procedures
Rear Axle	33 08 08	December-08	X6	Oil Ageing
Rear Axle	33 09 08	December-08	Х6	No Communication with ICM After Programming
Brakes	34 06 05	July-05	E90	DSC MK60E5 Fault Codes: 5DB6, 5DC6, 5E30, 5D8F
Brakes	34 02 06	March-06	E60/E63	Brake Squeals
Brakes Brakes	34 04 06 34 05 06	April-07 September-06	E60/E63/E90 E60/E63	DSC Warning - Various SZL FCs Stored (Supercedes Jun 06)-Changed to e90 only?? Service Action: Replace SZL Optical Element (Made Svc Action)
Brakes	34 02 07	September-07	E70 (X5)	Recall Campaign 07V-391: Inspect the Brake Fluid Reservoir Cap
Brakes	34 03 07	September-07	E70 (X5)	DSC Warning Lamp Illuminated
Brakes Brakes	34 04 07 34 05 07	October-07 October-07	E60/E63 E70 (X5)	DSC/DXC Warning Lamp, Fault Code 5EBA (may - June 07 production) Replacement of the Parking Brake Module (EMF)
Brakes	34 06 07	November-07	E90/91/92/93	Additional Effort Required to Press Brake Pedal Prior to Engine Initial Start
Brakes	34 07 07	November-07	M5/M6	M5, M6 - DSC Disabling Function
Brakes Brakes	34 01 08 34 02 08	April-08 April-08	E70 (X5) 3 Series	The Parking Brake Warning Is Illuminated and Fault Code 6032 Is Stored Erroneous Brake Pad Replacement Message
Brakes	34 03 08	May-08	E65/66	Parking Brake Repair Instructions
Brakes	34 05 08	August-08	All	Brake Rotor Minimum Thickness (Insp Only Spec 2.4mm non-M)
Brakes	34 07 08	August-08	X5/X6	Parking Brake Warning Illuminated; Fault Code 600D and/or 600B Is Stored
Brakes Brakes	34 08 08 34 09 08	October-08 October-08	X5/X6 E60/E63	Brake Squeal from Pad Wear Sensor (rpl 8/08) Brake Squeak from Pad Wear Sensor
Brakes	34 10 08	November-08	E9x & M3	Rattle Noise from Front Wheel Area
Brakes Brakes	34 11 08 34 12 08	December-08 December-08	1, 3 series & Z4 X6	TeileClearing for Dynamic Stability Control (DSC) TeileClearing for Integrated Chassis Management (ICM)
Dianes	34 12 00	Describer 66	A.	Circocaling to Integrated Glassis management (Com)
Wheels and Tires	36 01 04	August-05	BMW Center	Hunter GSP97BMW Wheel Balancer - Features and Operator Training
Wheels and Tires Wheels and Tires	36 02 05	July-05	E60	Noise and/or Vibration Caused by Irregular Tire Wear
Wheels and Tires	36 04 05	October-05	E60	Erroneous Flat Tire Monitor Warning
Wheels and Tires Wheels and Tires	36 05 05 36 06 05	June-05 May-05	All E60	Tire Pressure Monitoring Systems (TPMS) Wheels - Different between X models and regular models
Wheels and Tires	36 04 06	April-06	E60	Nitrogen Inflated Tires
Wheels and Tires	36 02 07	September-07	3 Series	Service Action: Reprogram the Control Module for the Tire Pressure Monitoring System (RDC)
Wheels and Tires Wheels and Tires	36 03 07 36 01 08	September-07 August-08	All All	Flat Tire Monitor System (FTM) Diagnosis Tire Pressure Warning Caused by Damaged Wheel Electronics
		. 3		
Suspension	37 02 05	August-05	E60/E63	Anti-Roll Stabilization Noise
Suspension	37 01 06	March-06	E61	Chafed Ride Height Sensor Cable
Suspension	37 01 07	November-07	E70 (X5)	Knocking Noise from Front Suspension
Suspension Suspension	37 02 07 37 03 07	October-07 January-08	E70 (X5) E70 (X5)	The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored Dynamic Drive (ARS) Front Sway Bar Repairs
Suspension	37 01 09	April-09	E61	Self-leveling Suspension Faults
			_	
Body Body	41 01 05 41 05 06	May-05	E60/E63	Structural Aluminum Repair Precautions
Body Body	41 05 06 41 02 07	February-06 October-07	E60/E63 E70(X5)	Trunk Lid Opens Too Fast/Slow Water Leak from the Upper Tailgate Area
Body	41 01 08	April-08	E90/91	Rear Door Brake Connection Pulls out of the B-pillar
Body	41 02 08	March-09	X5, X6	Service Action: Remove Excessive Underbody Coating
	01 other model			
Rody Equipment	51 13 04	August-07	E60/E63	Rattling Noise from Center Display (Replaces 06/07)
Body Equipment Body Equipment	51 13 04 51 02 05	February-07	E60/E63	Squeaking Noise from Door Frame area While Driving (Replaces 12/06)
Body Equipment	51 04 05	June-05	E60/E61 (xi, xiT)	Incorrect or Missing Floor Mats (deliveries before May 16, 05)
Body Equipment	51 08 05 51 17 05	July-05	E60/E63	Door Mirror Glass Discolored after Programming
Body Equipment Body Equipment	51 17 05 51 30 05	July-05 October-05	E60 E90	Replacement Windshield - VIN Window in Wrong Position Cracking or Ticking Noise from Lower B-Pillar
Body Equipment	51 31 05	March-06	E90	Center Console Heats Up In Knee Contact Area (Supercedes Nov 05)
Body Equipment	51 32 05	October-05	E90	Clicking Noise from Upper B-pillar Trim

			Complied and edited	d by cobradav
Category	SIBs (SI B## ## ##)	<u>Date</u>	<u>Application</u>	<u>Title</u>
Body Equipment	51 33 05	October-05	E90	Water Ingress from A/C Blower Housing
Body Equipment Body Equipment	51 37 05 51 10 06	December-05	E90	The cup holder jams when retracted
	51 10 06 51 14 06	May-07 March-08	E60 3 series/X5	Anti-trap is Activated when Raising the Front Window (rpl 2/06) Outside Door Handles Hanging up in the Pulled Position (rpl 2/08)
Body Equipment Body Equipment	51 18 06	May-07	E9x series	Interior Door Grab Handle Finish Peeling (rpl 8/06)
Body Equipment	51 24 06	November-06	E61	Luggage Compartment Roller Cover Malfunction
Body Equipment	51 27 06	January-07	E92	Rattle Noise from B-Pillar Trim
Body Equipment	51 06 07	March-07	E60 - M5	Service Action: Replace Underbody Panel
Body Equipment	51 08 07	March-07	E90/E91/E92	Erroneous Trunk Lid Open Check Control Message
Body Equipment	51 10 07	April-07	E90/E92/E93	Rear Window will not Fully Defrost
Body Equipment	51 12 07	May-07	E93	Service Action: Install Luggage Compartment Labels
Body Equipment	51 14 07	June-07	E93	Center Console Lock Inoperative
Body Equipment	51 16 07 51 17 07	July-07	E93 E93	Rear Roundel Emblem Comes Loose Rear Window(s) Inoperative
Body Equipment Body Equipment	51 19 07	July-07 November-07	E90	Doors will not Unlock Using the Key Fob or Central Locking Button (rpl 09/07)
Body Equipment	51 22 07	September-07	E91	Creaking Noise from the C-Pillar Area
Body Equipment	51 24 07	November-07	E93	Water Leaks into the Sides of the Luggage Compartment
Body Equipment	51 25 07	November-07	3 series	Floor Mat Retainer in Wrong Location
Body Equipment	51 28 07	December-07	E93	Compass Changes Direction when Operating the RHT
Body Equipment	51 29 07	December-07	E61	Luggage Compartment Roller Cover Symptom Diagnosis
Body Equipment	51 30 07	December-07	E91	Noises from the Roller Cover Retainers
Body Equipment Body Equipment	51 31 07 51 32 07	December-07 January-08	E70 (X5) E70 (X5)	Tailgate Soft-close Malfunction Rattle from the Upper Tailgate Trim
Body Equipment	51 35 07	January-08	E70 (X5)	Tailgate Latch Noisy when Closing
Body Equipment	51 02 08	February-08	3 series	Compass is Difficult to Read at High Temperatures
Body Equipment	51 03 08	February-08	E91	Luggage Compartment Roller Cover Symptom Diagnosis
Body Equipment	51 04 08	April-08	E93	RHT Rear Roof Shell Headliner Eliminated
Body Equipment	51 05 08	April-08	E60/63	Door Opening/Closing Symptom Diagnosis
Body Equipment	51 06 08	May-08	1 Series	Window Short-drop or Anti-trap Malfunctions
Body Equipment	51 07 08	May-08	E93	Rear Windows Inoperative After Junction Box Replacement
Body Equipment	51 08 08 51 09 08	May-08	E60/63	Power Window Drives: Symptom Diagnosis
Body Equipment Body Equipment	51 09 08	May-08 May-08	1 Series E60/63	Instrument Panel Symptom Diagnosis Noises from the Front Doors - Symptom Diagnosis
Body Equipment	51 10 08	May-08	E63	Water Ingress at the Doors: Symptom Diagnosis
Body Equipment	51 12 08	May-08	1 Series	Rattle from the Armrest Hinge
Body Equipment	51 16 08	June-08	3 series	Hood Insulation Pad Discontinued
Body Equipment	51 17 08	August-08	X5/X6	Grating Noise from the Instrument Panel
Body Equipment	51 18 08	June-08	3 series	Instrument Panel Symptom Diagnosis
Body Equipment	51 19 08	July-08	3 series	Passenger Side Floor Mat Curling
Body Equipment	51 20 08	July-08	X3	Doors Will Not Unlock with the Remote or Central Locking Switch
Body Equipment	51 21 08 51 23 08	July-08 July-08	1 Series vert 1 Series vert	Squeak from Rear Trim with the Convertible Top Open
Body Equipment Body Equipment	51 24 08	September-08	M3	Clicking Noise from the Bottom of the A-pillar Washer Fluids Leaking out of the Right Side M Vent
Body Equipment	51 25 08	September-08	1 Series	Buzzing Noise from the Center Vent Area
Body Equipment	51 26 08	September-08	E64	Service Action: Modifying the Rear Water Drain Hoses
Body Equipment	51 27 08	October-08	E60/61	The Front and Rear Doors Do Not Unlock at the Same Time
Body Equipment	51 28 08	September-08	3 series	Door Mirrors Do Not Fold When Using "Convenient Closure"
Body Equipment	51 29 08	November-08	E64	Water Leak into the Trunk Area
Body Equipment	51 30 08 51 34 08	November-08	X5, X6	Water Leak in the Front Right Footwell Area
Body Equipment Body Equipment	51 34 08 51 35 08	November-08 January-09	1 series All	Wind Noise from the B-pillar at High Speeds Cracked or Damaged Windshields
Body Equipment	51 36 08	February-09	All	Outside Mirror Moves when Unlocking the Vehicle
Body Equipment	51 01 09	January-09	X6	Rear Bumper Cover Sticks Out Below the Tail Lamp
Body Equipment	51 02 09	January-09	1 Series	Buzzing Noise from the Door Panel Pocket
Body Equipment	51 04 09	February-09	X5/X6	Gas Strut for Spare Wheel Cover Deleted
Body Equipment	51 05 09	February-09	E90/91	Buzzing Noise from the Door Speaker Area
Body Equipment	51 06 09	February-09	5 Series	Squeaking Noise from the Top of the B-pillar
Body Equipment	51 07 09 51 08 09	March-09 March-09	1 Series X5/X6	Creaking Noise from the Center Armrest Ashtray Does Not Pop Out When the Release is Pressed
Body Equipment	31 00 09	Waren-09	A3/A0	Ashiray Does Not rop out when the Release is Fresseu
Seats	52 02 04	April-05	E60/E63	Recall Campaign 04V-575: Modification of the Front Seat Heater Circuit
Seats	52 05 07	August-07	E93	Lumbar Support Inoperative
Seats	52 01 08	February-08	E60/E61	Active Backrest Width Adjustment Inoperative
Seats	52 02 08	January-08	Z4	Knocking Noise from the Seat Frame
Seats	52 03 08	March-08	X5	Lateral Seat Movement and/or Noises
Seats	52 04 08 53 05 08	June-08	E93 E92	Backrest Seat Cover Material Loose
Seats Seats	52 05 08 52 06 08	June-08 August-08	1/3 series	Seat Frame Design Change Raised Area on the Seat Bottom
Seats	52 07 08	November-08	E90/91	Stiffness in the Fore and Aft Adjustment of the Seat
Seats	52 09 08	November-08	X5, X6	Seat Heater Does Not Feel Hot Enough
Seats	52 01 09	January-09	E64	Seat Adjustment when Unlocking
Seats	52 02 09	March-09	E70/71 (X5/6)	Thigh Support Cover Loose
	01, 02, 04-07 all X5			
Special Poofe	54 03 05	luk OF	E64 (Cabrio)	Convertible Top will not Lower
Special Roofs Special Roofs	54 03 05 54 13 06	July-05 May-06	E64 (Cabrio) E60	Convertible Top will not Lower SHD Coding Error - Progman V21.1
Special Roofs	54 13 06 54 17 06	November-06	E64 (Cabrio)	Convertible Top Does Not Completely Open or Close
Special Roofs	54 01 07	July-07	E93	Service Action: Replace Roof Shell Trim Strips (rpl 4/07)
Special Roofs	54 02 07	April-07	E93	RHT Opens but Trunk Lid will not Close
Special Roofs	54 03 07	April-07	E93	Convenience Open/Close Function
Special Roofs	54 06 07	March-08	E93	Roof Shell 1 Slams Down on the Cowl when Closing the RHT (rpl 5/07)
Special Roofs	54 08 07 54 00 07	May-07	E93	RHT Statuses Reversed in DIS/GT1
Special Roofs Special Roofs	54 09 07 54 10 07	June-07 August-07	E93 E93	RHT Status Request Supplement RHT Stops Opening in the Stacked/Extended Position
Special Roofs Special Roofs	54 10 07 54 11 07	September-07	E93	Headliner is Loose in the C-pillar Area
Special Roofs	54 12 07	September-07	E93	Rattle from the Front Latch of the RHT
Special Roofs	54 15 07	April-08	E93	RHT Symptom Diagnosis Update (rpl 11/07)
Special Roofs	54 16 07	November-07	E93	Headliner Loose Near A-pillar
Special Roofs	54 17 07	January-08	E93	Headliner Fabric is Creased and/or Stretched
Special Roofs	54 01 08	January-08	E61/91	Wind Noise from the Panoramic Sunroof
Special Roofs	54 02 08 54 03 08	January-08	E60	Water Leak from Sunroof
Special Roofs	54 03 08 54 04 08	February-08 June-08	E93 E93	RHT Seal Replacement Update Wind Buffeting/Pressure Noise at Highway Speeds
Special Roofs Special Roofs	54 04 08 54 05 08	March-08	E83 (X3)	Wind Buffeting/Pressure Noise at Highway Speeds Rattle from Panoramic Roof when Fully Open
Special Roofs	54 06 08	May-08	(E70) X5	Clicking Noise From Sunroof
Special Roofs	54 07 08	September-08	E88 (1 Series)	Convertible Top Material Loose at Rear Bow (rpl 6/08)
Special Roofs	54 08 08	August-08	(E70) X5	The Sunroof's Rear Glass Panel Does Not Close from the Vent Position
Special Roofs	54 09 08	August-08	E93	Cleaning Excess Butyl from RHT Roof Shells
Special Roofs	54 11 08 54 12 08	October-08	All w/Pan Roof	TeileClearing for Panoramic Roof
Special Roofs Special Roofs	54 12 08 54 01 09	November-08 February-09	(E70) X5 E88 (1 Series)	Water Leak from the Front of the Sunroof Service Action: Repair of the Convertible Top
Special Roofs	54 07 09	March-09	1,3,6 Verts	Soft Top Switch Function and Window Operation
•				- Contract

Category	SIBs (SI B## ## ##)	<u>Date</u>	Application	Title
 -			<u> </u>	
General Electrical Systems General Electrical Systems	61 07 88 61 08 00	December-06 June-07	AII AII	Battery Maintenance Requirements (Replaces 10/06) Closed-Circuit Current Measurement (Replaces 1/07 - new cars)
General Electrical Systems	61 15 02	February-06	E60/E63	MOST Bus Diagnosis (Supercedes July 04 with new diagnostics & models)
General Electrical Systems General Electrical Systems	B611502F_Description. B611502ChartsA&B.	P/O 61 15 02 P/O 61 15 02	E60/E63 E60/E63	MOST Bus Diagnosis Description MOST Bus Diagnosis Troubleshooting Chart
General Electrical Systems	61 03 03	January-06	E60/E63	CAN/Byteflight Bus Diagnostics (Supercedes June 05 - Adds E61 & E91)
General Electrical Systems General Electrical Systems	61 13 02 61 14 03	December-05 September-07	E65 E60/E63	CIP 16.0 - 2002 MY Electrical complaints (Supercedes April 05 w/new info) CIP Updates (CIP 27.00.00) - (Supercedes Apr 07 - 25.01.00)
General Electrical Systems	61 01 04	June-05	E65	CIP 17.01 - MY02-05 various complaints
General Electrical Systems	61 01 04	September-06	E65	Various Complaints Caused by Software Errors (21.02.01) (Supercedes Mar 06 / CIP 20.00)
General Electrical Systems General Electrical Systems	61 01 05 61 03 05	December-05 October-07	E60/E63 E90	Special Survey for CAS related problems (Supercedes Apr 05 - Survey completed) CIP 27.00.00 - Software errors corrected with PROGMAN (Rpl 25.01.00 4/07)
General Electrical Systems	61 06 05	September-05	E60	High Drain Battery Message in CIP (N52 Engine)
General Electrical Systems General Electrical Systems	61 07 05 61 08 05	January-06 August-05	E60/E63 E90	PDC Light Flashing after SZM Replacement (Supercedes info in August 05) Roof Functions Center Causes Various System Malfunctions
General Electrical Systems	61 09 05	August-05	E90	Remote Key Sticks In/Falls Out of CAS Holder
General Electrical Systems General Electrical Systems	61 10 05 61 11 05	August-05 October-05	E90 E60	Various Electrical Problems Battery Safety Terminal
General Electrical Systems	61 12 05	November-05	E60/E63	Dead Battery by MPM
General Electrical Systems	61 13 05	May-08	E60/E63	Dead Battery - Perform Energy Diagnosis (update to 10/07 - added models)
General Electrical Systems General Electrical Systems	61 01 06 61 02 06	February-06 February-06	E90 E60/E63/E90	Trunk Opens without Request Key Falls Out of, or Gets Stuck in Key Holder (Supercedes 2/06 adding models)
General Electrical Systems	61 04 06	February-06	ALL	Exiting a Vehicle that is Double-Locked from the Outside
General Electrical Systems General Electrical Systems	61 05 06 61 06 06	September-07 May-06	E65 E90	Various Customer Complaints Corrected With Progman Junction Box Pin Assignment Change
General Electrical Systems	61 07 06	August-06	E60/E63/E90	No Crank, No Start, CAS FC A111
General Electrical Systems General Electrical Systems	61 10 06 61 13 06	October-06 October-06	E63 E60	Windows Convenience Open When Door is Opened Various Electrical Problems Caused by Water Ingress
General Electrical Systems	61 14 06	October-06	E60/E63	One-Touch Close Inoperative after Door Module Replacement
General Electrical Systems	61 15 06	October-06	E64	Rear Windows Close First, or Anti-trap Activates During Convenience Closing
General Electrical Systems General Electrical Systems	61 20 06 61 22 06	October-06 October-06	E60 E60	Rear Windows Move in Small Increments iDrive Controller Malfunction (Low Version)
General Electrical Systems	61 23 06	October-06	E60	Battery Charger Causes Faults to be Set
General Electrical Systems General Electrical Systems	61 24 06 61 26 06	October-06 September-06	E60 E90	Starts only once following EWS calibration Central Electronics Failure, K-CAN bus Fault Codes Stored
General Electrical Systems	61 27 06	October-06	E92	Replacement CAS3 - Calibration Error Message
General Electrical Systems	61 28 06	May-07	E92	Red ELV Warning in Instrument Cluster (Replaces 1/07)
General Electrical Systems General Electrical Systems	61 29 06 61 31 06	April-08 September-07	E60/E63/E90 X5	CAS / ELV Diagnostics (rpl 10/07) Software Errors Corrected with Progman (update to 5/07) PROGMAN 27.01.00
General Electrical Systems	61 32 06	December-06	E90/91/92	Sunroof Moves in Small Steps or Interior Lights not Working
General Electrical Systems General Electrical Systems	61 33 06 61 34 06	December-06 August-07	E60/E63/E90 E90/91/92	Battery Warning Displayed when Deleting Transport Mode Engine Fails to Start after CAS Replacement (update to 9/06)
General Electrical Systems	61 04 07	May-07	E60/E63	SZL Functions Lock Up after Deleting Transport Mode
General Electrical Systems	61 08 07	August-07	E60/E63	Electric Steering Lock Inoperative
General Electrical Systems General Electrical Systems	61 09 07 61 12 07	August-07 November-07	E60/E65/E90 E90	OBD Socket Housing Cover Missing No Crank after CAS3 Replacement
General Electrical Systems	61 13 07	November-07	E70 (X5)	Electronic Malfunction CC Message Caused by Shorted Wiring
General Electrical Systems General Electrical Systems	61 14 07 61 01 08	December-07 January-08	E60/E63 E60/E63/E90/E70	Battery Discharged KGM FC 93AB MPM Relay Sticking CC Message "Increased battery discharge while stationary"
General Electrical Systems	61 02 08	February-08	3 series	Gong Warning Without Visual Check Control Message
General Electrical Systems	61 03 08	February-08	E93	Doors Will Not Lock Using Comfort Access Handles
General Electrical Systems General Electrical Systems	61 05 08 61 05 08	May-08 May-08	Service Center E90/91/92	TeileClearing for General Electrical Systems Windshield Wiper Parks out of Position
General Electrical Systems	61 06 08	May-08	X5/X6	Sliding Sunroof, Interior Lights, and Rain Sensor Are Inoperative
General Electrical Systems General Electrical Systems	61 07 08 61 09 08	June-08 August-08	E60 1, 3, X5, X6	Rear Window Functional Problems Controller Fault Code A2CB Internal Control Module Fault
General Electrical Systems	61 10 08	August-08	3 Series w/DCT	CAS3 Fault Code A0B1
General Electrical Systems	61 11 08	August-08	E60/61	Steering Wheel or Seat Adjustment Inoperative
General Electrical Systems General Electrical Systems	61 12 08 61 14 08	August-08 September-08	1 & 3 Series E60	Sliding Sunroof, Interior Lights, and Rain Sensor Are Inoperative Intermittently, the Rear Doors Do Not Lock
General Electrical Systems	61 16 08	November-08	3er w CIC & N51	N51 PZEV - JBE Repeat Failures Due to Shorted Fuel Sender Harness
General Electrical Systems General Electrical Systems	61 17 08 61 18 08	November-08 December-08	E83 (X3) BMW Centers	Service Action: Reprogram General Module Battery Maintenance Requirements
General Electrical Systems	61 01 09	March-09	All	Windshield Washer Malfunction
General Electrical Systems	61 02 09	March-09	7 Series (F01)	Engine Does Not Start
	01, 02, 03 , 05, 06, 07, 10, 11 X5 or other r	models		
Instruments	62 01 06	May-07	E60/E63	Instrument Cluster Needles Vibrate (Replaces 1/07)
Instruments	62 02 06	May-06	E60/E63	Engine Oil Level Menu Option is Displayed After Reprogramming
Instruments Instruments	62 04 06 62 01 07	October-06 January-07	E60/E63 E90/92	Instrument Cluster: Failure of Displays/Functions Warning Chime Inoperative for Check Control and/or Directionals
Instruments	62 02 07	January-07	E60/E63/E92	No Communication or Diagnosis Possible With Instrument Cluster
Instruments Instruments	62 03 07 62 06 07	May-07 March-07	E90/92 BMW Centers	On-Board Computer Functions Cannot Be Displayed (rpl 1/07) Check Control Messages (With PDF list)
Instruments	62 07 07	May-08	E70 (X5)/E71 (X6)	TeileClearing (Enhanced Technical Support) for Instrument Cluster
Instruments	62 01 08	May-08	1 Series	Cruise Control Display in Instrument Cluster Increments Incorrectly
Instruments Instruments	62 02 08 62 04 08	August-08 September-08	M3 w/DCT E6x	Instrument Cluster Center Displays Go Blank Instrument Cluster Mileage Display Switches to Kilometers when Key Is Switched
Instruments	62 01 09	April-09	E6x	All Instrument Dials Inoperative and Display in Instrument Cluster Is Bright
	04 07 note to dealer 05 - 09 other models			
Lighto		hub : 0.4	F00	Panlace Laws Madula
Lights Lights	63 02 04 63 02 05	July-04 June-05	E60 E60	Replace Lamp Module Brake Force Display (BFD) Inoperative
Lights	63 03 05	July-05	E60	Eyebrow Lights are Inoperative after Programming
Lights Lights	63 05 05 63 06 05	September-05 November-05	E64 Cabrio E60	Third Brake Light Cracked Service Action: Check the Adaptive Headlights for Proper Operation
Lights	63 01 06	May-06	Z4	Front Lighting Configuration
Lights	63 05 06	October-06	E60/E63	Automatic Headlamps: Lights Do Not Switch Off
Lights Lights	63 06 06 63 08 06	October-06 October-06	E60 E60	LED Flashing On Headlight Switch, No Faults Stored Lights Flash Briefly When Vehicle Wakes Up; Battery May Become Discharged
Lights	63 09 06	October-06	E60	Brake Lighting Pulsates Intermittently
Lights Lights	63 12 06 63 13 06	October-06 October-06	E63 E60/E63	Adaptive Headlamp Does Not Turn Automatic Headlamp System Does Not Switch Off the Lights
Lights	63 15 06	October-06	E60	Headlamp Leak (Replaces 12/04)
Lights	63 16 06 63 17 06	November-06	E60	3rd Brake Light Comes Loose From Rear Window
Lights Lights	63 17 06 63 02 07	January-07 January-07	E60/63/90 E90/91/92	Eyebrow Lights are Inoperative after Programming (Replaces 12/06) Bulb Out Symbol Displayed in BC
Lights	63 03 07	February-07	E90/91/92	Daytime Running Lights are Inoperative
Lights Lights	63 04 07 63 06 07	March-07 April-07	E60/E63 E92/93	Fault Code 9CAD in LM Cornering lights failure Displayed in Check Control
Lights	63 13 07	August-07	E90/91/92	Headlight Vibrations
Lights	63 15 07	October-07	E70 (X5)	Interior Light Switch Illumination

Category	SIBs (SI B## ## ##)	<u>Date</u>	Application	<u>Title</u>
Lights	63 16 07	December-07	E60/E63	Option Code 08S4 - Variable Light Decoding
Lights Lights	63 01 08 63 02 08	March-08 March-08	E63/E64 E92/93	Side Marker Lamp not Working in Conjunction with Welcome Light Rear Bulb Failure
Lights	63 03 08	March-08	3 Series	Flashlight Deleted as a Running Change
Lights	63 04 08	June-08	1/3/5/6/7/X series	Headlamp Moisture: Fault Diagnostics
Lights Lights	63 05 08 63 06 08	May-08 July-08	E60 X3	CC Message Missing/Incorrect when Front Parking Light Faulty Bulb-Out Warning, FC 2F or 3E
Lights	63 07 08	August-08	E60/E63	Adaptive Headlights Intermittently Inoperative (SW fix coming in Oct)
Lights	63 08 08	August-08	X5 (E70)	Contact Between Inner and Outer Rear Lamps
Lights	63 09 08	August-08	X3	Interior Lamps "Soft ON/OFF" Inoperative
Lights Lights	63 10 08 63 11 08	November-08 November-08	1 series, X3 All w/MOST	Cracked Third Brake Light (rpl 9/08) Automatic Headlamps: Adjust Sensitivity
Lights	63 11 08	January-09	E60/E63	Changes to Panel Illumination (58G)
Lights	63 03 09 63 04 09	March-09 March-09	7 Series (F01)	High-beam Assistant (FLA): Erratic Operation
Lights	63 04 09	warch-09	7 Series (F01)	Headlamp Flashes Several Times, Then Switches Off
	08 09 for X5 (E63 and E70) 07 NU			
Heating and Air Conditioning	64 08 91	October-06	All	Musty Odors
Heating and Air Conditioning	64 02 05	August-05	E64 (Cabrio)	Poor Temperature Regulation from Center Vents
Heating and Air Conditioning Heating and Air Conditioning	64 03 05 64 04 05	June-08 August-07	E60/E63 E60/E63	Air Conditionaing Delayed Startup (Supercedes 4/07 w/new info) Air Conditioning Stops Cooling after Long Drive (Replaces 12/06)
Heating and Air Conditioning	64 21 05	May-08	All	Troubleshooting Air Conditioning Compressor Noise (Supercedes Dec 06)
Heating and Air Conditioning	64 01 06	January-06	E60	Blower Motor Stays On with Key Off
Heating and Air Conditioning	64 02 06 64 04 06	June-06 May-07	E60 E90	Water Droplets are Blown from Center Vents with A/C On (Supercedes Jan 06)
Heating and Air Conditioning Heating and Air Conditioning	64 06 06	May-06	E90	Air Conditioning Does not Cool (Replaces 1/07) Front Defroster Performance Poor at Mid-Blower Speeds
Heating and Air Conditioning	64 07 06	May-07	E90	Air Conditioning System does not Cool (Refrigerant Charge Good) (rpl 6/06)
Heating and Air Conditioning	64 09 06 64 10 06	October-06	E90	Air Conditioning System Blows Warm Air After Long Drive (Replaces 8/06) Water Droplets Blown from Right Side Center Vents with A/C On
Heating and Air Conditioning Heating and Air Conditioning	64 10 06 64 14 06	July-06 November-07	E60/61 E60/61	A/C Compressor Noise "Droning, Howling or Ticking" at Low Engine Speed (update to 10/06)
Heating and Air Conditioning	64 03 07	October-07	E92	Banging Noise from Air Conditioner Compressor (update to 3/07)
Heating and Air Conditioning	64 04 07	May-08	All	Heating and Air Conditioning Symptom Diagnosis (update to 1/08)
Heating and Air Conditioning Heating and Air Conditioning	64 06 07 64 08 07	May-08 August-07	E60/E63 All	Air Conditioning Compressor Does Not Switch On Important Information about Heating and Air Conditioning
Heating and Air Conditioning	64 10 07	January-08	E60/E63	Air Conditioning Delayed Startup
Heating and Air Conditioning	64 12 07	June-08	3 Series	White Flakes/Powder Coming from the Air Conditioning Vents
Heating and Air Conditioning Heating and Air Conditioning	64 13 07 64 14 07	February-08 November-07	3 Series E70 (X5)	CID or IHKA Total Failure Because F61 Blown Water Leak on Carpet During Air Conditioning Usage
Heating and Air Conditioning	64 02 08	June-08	1 & 3 Series	Whistling from the Heating/Air Conditioning Unit at Speeds over 50 MPH
Heating and Air Conditioning	64 03 08	August-08	All	TeileClearing for Air Conditioning Systems
Heating and Air Conditioning Heating and Air Conditioning	64 04 08 64 05 08	September-08 October-08	E70 (X5) All	Different Delivery Temperature from Each Side of the Rear Compartment Blower Damage to the Air Conditioning Control Panel
Heating and Air Conditioning	64 06 08	October-08	E71 (X6)	Cold Air Is Leaking from Center Console Area
Heating and Air Conditioning	64 01 09	March-09	E70 (X5)	Whirring Noise from the Auxiliary Water Pump
	07 09 for (X5)			
Audio, Navigation, Monitors, Alarms, SI Audio, Navigation, Monitors, Alarms, SI	65 06 04 65 10 04	July-04 January-05	E60/E63 E60/E63	Consumption Set to mpg UK instead of mpg US Audio Stays On
Audio, Navigation, Monitors, Alarms, Si Audio, Navigation, Monitors, Alarms, Si	65 01 05	June-05	E90	Radio Seek/Scan Inoperative
Audio, Navigation, Monitors, Alarms, SI	65 02 05	April-06	E60/E63/E90	SIRIUS Satellite Radio - General Info (Supercedes May 05 - Added E90)
Audio, Navigation, Monitors, Alarms, SI Audio, Navigation, Monitors, Alarms, SI	65 06 05 65 07 05	July-05 April-06	E60/E63 E90	CID Fault Analysis Guide MOST Bus is Inoperative or Central Information Display has Reduced Brightness (Jul 05)
Audio, Navigation, Monitors, Alarms, Sf Audio, Navigation, Monitors, Alarms, Sf	65 08 05	October-05	E90	Temperature Display in RAD2 Shows Dashes
Audio, Navigation, Monitors, Alarms, SI	65 09 05	February-06	E60/E63/E90	No Audio Sound in any Mode (Supercedes Aug 05 with new info)
Audio, Navigation, Monitors, Alarms, SI	65 10 05 65 16 05	November-07	E60/E63/E90 E60/E63/E90	CCC: Loss of all Audio (update to 8/06) RDS Function Causes Confusing Station Names when in "All stations" Screen
Audio, Navigation, Monitors, Alarms, SI Audio, Navigation, Monitors, Alarms, SI	65 18 05	September-05 January-06	E60/E63/E90	MP3 Compatibility Overview (Supercedes October 2006)
Audio, Navigation, Monitors, Alarms, SI	B651805MP3_Compatibility_Chart	P/O 65 18 05	E60/E63/E90	MP3 Compatibility Chart
Audio, Navigation, Monitors, Alarms, SI Audio, Navigation, Monitors, Alarms, SI	65 19 05	October-05 January-06	E60	Weather Band Available on Multi Audio System Controller
Audio, Navigation, Monitors, Alarms, Si Audio, Navigation, Monitors, Alarms, Si	65 20 05 65 21 05	March-07	E90 E63/E64	RAD2 - CD Mode Malfunctions (In-Dash CD skips or does not play - Business Radio) SIRIUS Satellite Radio Cuts Out in Certain Geographic Areas (May 06 -)
Audio, Navigation, Monitors, Alarms, SI	65 22 05	November-05	E60	'Favorites' Function is Selectable in the Entertainment Menu
Audio, Navigation, Monitors, Alarms, SI	65 23 05	November-05	E60	Disclaimer Screen Disappears Automatically after 10 Seconds
Audio, Navigation, Monitors, Alarms, SI Audio, Navigation, Monitors, Alarms, SI	65 24 05 65 25 05	October-05 August-07	E60/E63/E90 E60/E63	Static Between Words on AM Radio HD-Radio [™] - Functionality and Diagnosis (Supercedes Mar 07)
Audio, Navigation, Monitors, Alarms, SI	65 26 05	March-06	E60/E63/E90	Audio Switches off Briefly when Listening to FM Stations (Supercedes Jan 06 w/new info)
Audio, Navigation, Monitors, Alarms, SI	65 27 05	November-05	E60/E63/E90	CID Screen Image Not Displayed Correctly Since CCC Replacement
Audio, Navigation, Monitors, Alarms, SI Audio, Navigation, Monitors, Alarms, SI	65 28 05 65 30 05	March-06 March-06	E60/E63/E90 E60/E63/E90	CCC: Radio Station Preset List Intermittently Empty (Supercedes Nov 05) CCC: MP3 CD Playback Not Available (Supercedes Jan 06- minor changes)
Audio, Navigation, Monitors, Alarms, SI	65 32 05	March-07	E60/E63/E90	CCC: CD/CDC Track Counter Advances After Mute Selected (Replaces 1/07)
Audio, Navigation, Monitors, Alarms, SI	65 02 06	March-06	E60/E63/E90	CCC: Loss of Audio in All Modes (Supercedes Feb 06)
Audio, Navigation, Monitors, Alarms, SI Audio, Navigation, Monitors, Alarms, SI	65 04 06 65 05 06	March-06 April-06	E60/E63/E90 E60/E63/E90	KL-R Stays On After Ignition Off – Comfort Access Only CCC: CD Drive Errors
Audio, Navigation, Monitors, Alarms, SI	65 06 06	November-07	E60/E63/E90	Various Problems with CCC Following Replacement (update to 4/06)
Audio, Navigation, Monitors, Alarms, St	65 08 06 65 10 06	September-06	E60/E63/E90	CCC with Top HiFi Loses Surround Sound after Navigation Announcement (Supercedes May 06) New Audio-Test-CD for Diagnosing a Faulty CD/Audio-DVD Drive or Media
Audio, Navigation, Monitors, Alarms, SI Audio, Navigation, Monitors, Alarms, SI	65 10 06 65 12 06	May-06 July-08	E60/E63/E90 E60/E63/E90	New Audio-Test-CD for Diagnosing a Faulty CD/Audio-DVD Drive or Media Popping/Crackling Noise from Audio System (rpl 12/06)
Audio, Navigation, Monitors, Alarms, SI	65 16 06	September-06	E60/E63	CCC: Acoustic Warning Gong Sounds at Times, No CC Message
Audio, Navigation, Monitors, Alarms, SI	65 18 06 65 25 06	October-06 August-08	E63/E64 ALL w / CCC	DWA (Theft Deterant System) Causes Excessive Closed Circuit Current Draw Enhanced Technical Support for Audio System (Replaces 6/07)
Audio, Navigation, Monitors, Alarms, SI Audio, Navigation, Monitors, Alarms, SI	65 25 06 65 26 06	October-06	E60/E63/E90	CCC Disclaimer Screen Disappears Automatically after 10 Seconds
Audio, Navigation, Monitors, Alarms, SI	65 27 06	October-06	E60/E63/E90	CCC Does Not Play All MP3 Formats
Audio, Navigation, Monitors, Alarms, SI	65 28 06	October-06	E60/E63/E90	CCC Radio Station RDS Information Missing After Programming
Audio, Navigation, Monitors, Alarms, SI Audio, Navigation, Monitors, Alarms, SI	65 29 06 65 33 06	April-07 December-06	E60/E63/E90 E60/E63/E90	CCC Next Entertainment Source Not Selectable Via MFL (rpl 10/06) CD Changer is Inoperative; Magazine is Jammed or Broken
Audio, Navigation, Monitors, Alarms, Sf	65 35 06	June-07	E60	Poor Radio Reception in FM Mode (rpl 12/06)
Audio, Navigation, Monitors, Alarms, St	65 36 06 65 37 06	August-07	E60 E60	Poor Radio Reception in AM Mode (rpl 6/07) RDS Function
Audio, Navigation, Monitors, Alarms, SI Audio, Navigation, Monitors, Alarms, SI	65 37 06 65 43 06	December-06 May-07	E60/E63/E90	CCC: High Frequency Noises from the DVD drive (rpl 12/06)
Audio, Navigation, Monitors, Alarms, SI	65 44 06	December-06	E60/E63/E90	CCC: AUX-IN Loud Hissing if no Device Connected
Audio, Navigation, Monitors, Alarms, SI	65 45 06 65 46 06	December-06	E60/E63/E90	CCC: Poor Radio Reception after Software Update
Audio, Navigation, Monitors, Alarms, SI Audio, Navigation, Monitors, Alarms, SI	65 46 06 65 48 06	May-07 December-06	E60/E63/E90 E60/E63/E90	CCC: Radio Continues to Play after Ignition off (rpl 12/06) SIRIUS Satellite Radio Is No Longer Accessible
Audio, Navigation, Monitors, Alarms, SI	65 01 07	March-07	E60/E63/E90	CID Changes Introduced March 2007
-	65 01 07_CCC_Display_Changes	March-07	E60/E63/E90	M-ASK also available
Audio, Navigation, Monitors, Alarms, SI Audio, Navigation, Monitors, Alarms, SI	65 03 07 65 04 07	April-07 January-07	E60/E63/E90 E90/91	CCC: Slow Response from System when using Controller (Rpl Jan 07) SDARS Sirius Radio is Inoperative After Programming
Audio, Navigation, Monitors, Alarms, St Audio, Navigation, Monitors, Alarms, St	65 06 07	March-07	All CCC equipped	CCC Symptom Troubleshooting
Audio, Navigation, Monitors, Alarms, SI	65 07 07	March-08	E60/E63/E90/E92	SDARS SIRIUS Radio is Intermittently Inoperative
Audio, Navigation, Monitors, Alarms, SI Audio, Navigation, Monitors, Alarms, SI	65 08 07 65 15 07	May-08 May-07	E60/E63/E90/E92 E90/91	USB Audio Interface Airbag Warning Lamp Illuminated, FC 93C1/93C3
Audio, Navigation, Monitors, Alarms, St Audio, Navigation, Monitors, Alarms, St	65 18 07	January-08	E64 Cabrio	Radio or Speakers Inoperative (rpl 6/06)
Audio, Navigation, Monitors, Alarms	65 19 07	May-07	E63/E64	Recall Campaign 07V-178: Replace the Seat Occupancy Detection Mat
Audio, Navigation, Monitors, Alarms, SI Audio, Navigation, Monitors, Alarms, SI	65 21 07 65 22 07	January-08 August-07	E93 E60/E63/E90/E92	Whistling Noise From the Radio in AM Mode Only CCC CD Text not Updated When CD is Swapped
	00 <u>22</u> 01	, agust 01	200,200,200,202	222 22 . Six not operated thron our in orangeou

			Complied and edited i	by cobradav
Category	SIBs (SI B## ## ##)	<u>Date</u>	Application	<u>Title</u>
Audio, Navigation, Monitors, Alarms, SI	65 23 07	August-07	E60/E63/E90/E92	CCC Navigation Displays Incorrect Vehicle Position
Audio, Navigation, Monitors, Alarms, SI	65 24 07	August-07	E60/E63/E90/E92	CCC Navigation Map DVD not Detected
Audio, Navigation, Monitors, Alarms, SI	65 25 07	November-07	E60	Recode or Replace OC3 Seat Mat
Audio, Navigation, Monitors, Alarms, SI	65 26 07	June-08	E60/E63/E90/E92	CCC: Volume Differences between CD\AUX and FM after Programming
Audio, Navigation, Monitors, Alarms, SI	65 27 07	December-07	X5 (E70)	Airbag Warning Lamp Illuminated - FC 93D2
Audio, Navigation, Monitors, Alarms, SI	65 28 07	September-07	E60/E63/E90/E92	CCC: Radio Does Not Resume With Previously Selected Station
Audio, Navigation, Monitors, Alarms, SI	65 30 07	October-07	E90/91/92/93/E70	iPod Mode is Switching to FM Mode
Audio, Navigation, Monitors, Alarms, SI	65 31 07	September-07	E60/E70	CHAMP: Intermittently No Audio Output in FM Mode Only After Restart
Audio, Navigation, Monitors, Alarms, SI	65 32 07	December-07	X5 (E70)	Rear Seat Entertainment System (RSE) is Not Working Correctly
Audio, Navigation, Monitors, Alarms, SI	65 33 07	August-08	X5 (E70)	Airbag Warning Illuminated, FC 93D2
Audio, Navigation, Monitors, Alarms, SI	65 34 07	November-07	E90/91/92/93	Service Action: Program the MULF2-High Control Module
Audio, Navigation, Monitors, Alarms, SI	65 35 07	December-07	X5 (E70)	No Audio Output After Turning the Ignition On
Audio, Navigation, Monitors, Alarms, SI	65 36 07	January-08	E60/E63	Radio Turns Off After 8 Minutes and Time and Date Display is Cleared (rpl 12/07)
Audio, Navigation, Monitors, Alarms, Sf	65 37 07	November-07	E93	No AM Reception During Convertible Top Operation
Audio, Navigation, Monitors, Alarms, Sf	65 39 07	December-07		CCC Navigation Not Working -September 24, 2007 to October 29, 2007
Audio, Navigation, Monitors, Alarms, SI	65 41 07	July-08		CCC Loss of Audio and CID Blanks Out (rpl 01/08
Audio, Navigation, Monitors, Alarms, SI	65 42 07	January-08	All w/Alarm	Alarm Triggers Unexpectedly - Troubleshooting
Audio, Navigation, Monitors, Alarms, SI	65 01 08	May-08	All w/SAT RAD	SIRIUS Radio Stations Missing in "All Channels" List
Audio, Navigation, Monitors, Alarms, SI	65 02 08	August-08	All w/6FL (USB)	iPod Classic Doesn't Get Charged through USB Connection
Audio, Navigation, Monitors, Alarms, SI	65 03 08	March-08	3 & 5 Series	Interference with Radio Reception on all Bands (FM, AM, HD Radio)
Audio, Navigation, Monitors, Alarms, SI	65 04 08	April-08	All w/SAT RAD	Call SIRIUS Is Displayed
Audio, Navigation, Monitors, Alarms, SI	65 05 08	April-08	7 Series	SIRIUS Radio Station List Is Not Displayed in the RSE Monitor
Audio, Navigation, Monitors, Alarms, SI	65 06 08 65 07 08	April-08	1 & 3 series	RAD2: The Audio Volume is Briefly Muted or Reduced
Audio, Navigation, Monitors, Alarms, SI	65 07 08 65 08 08	April-08 May-08	3 series 3 series	USB Device Is Not Detected Fault Code "E190" stored in the RAD2_GW
Audio, Navigation, Monitors, Alarms, Sf Audio, Navigation, Monitors, Alarms	65 09 08	November-08	X6/X5 (E70)	Anti-theft Alarm System Triggers a False Alarm
Audio, Navigation, Monitors, Alarms, SI	65 10 08	May-08	1 & 3 Series	RAD2: Intermittently No Audio after Check Control Message
Audio, Navigation, Monitors, Alarms, SI	65 11 08	May-08	All w/6FL	iPod Classic is Discharged after an Extended Period of Inactivity
Audio, Navigation, Monitors, Alarms, SI	65 12 08	June-08	E60	SRS Warning Lamp Illuminated, but No Fault Codes Stored
Audio, Navigation, Monitors, Alarms,	65 14 08	October-08	X5 (E70)	Controller Scrolling Function Not Responsive
Audio, Navigation, Monitors, Alarms	65 15 08	September-08	1 Series	Volume of Warning Gong too Quiet
Audio, Navigation, Monitors, Alarms,	65 16 08	September-08	E83 (X3)	Airbag Warning Lamp Illuminated, FC A1
Audio, Navigation, Monitors, Alarms,	65 17 08	December-08	E60/63	CD Changer Is Inoperative; Magazine Is Jammed
Audio, Navigation, Monitors, Alarms,	65 18 08	September-08		TeileClearing for Car Information Computer (CIC)
Audio, Navigation, Monitors, Alarms,	65 19 08	October-08	E83 (X3)	Recall Campaign 08V-384: Modify Seat Occupancy Detection Mat
Audio, Navigation, Monitors, Alarms	65 20 08	October-08	1 & 3 Series	Interference Noises and/or Reception Varies in Certain Areas
Audio, Navigation, Monitors, Alarms	65 21 08	November-08	E93	Airbag Warning Illuminated, FC 9402
Audio, Navigation, Monitors, Alarms	65 22 08	November-08	1 series	Loss of Navigation GPS Position
Audio, Navigation, Monitors, Alarms	65 24 08	December-08	M3/M5	Audio System Is Intermittently Inoperative
Audio, Navigation, Monitors, Alarms,	65 27 08	January-09	1,3,5,6 ser X5,X6	Entertainment and Communication Systems are Inoperative
Audio, Navigation, Monitors, Alarms	65 01 09	January-09	1,3,6 ser	Incorrect Message in the USB Audio Interface Diagnosis
Audio, Navigation, Monitors, Alarms,	65 02 09	January-09	1 Series	Audio Interference Noises in All Modes When Vehicle Is in Motion
Audio, Navigation, Monitors, Alarms,	65 03 09	March-09	7 Series (F01)	Side View Camera Has Blurred Image
Audio, Navigation, Monitors, Alarms,	65 05 09	March-09	All w/CIC	Navigation System Road Map
Audio, Navigation, Monitors, Alarms,	65 06 09	February-09	5, X5, X6 LSI	CID Is Blank, No Audio, CHAMP Resets and Is Then Inoperative
Audio, Navigation, Monitors, Alarms,	65 08 09	March-09	X5, X6	Ultrasonic Passenger Compartment Motion Detector Triggers False Alarm
01, 11, 14,	20 other model, 05, 09, 10, 12, 13, 29, 38	3, 40 NU,		
Distance Systems, Cruise Control, Ren	- 01 other model		E65	
Distance Systems, Cruise Control, Ren	66 01 04	March-08	X3	315MHz Remote Control Range Is Inadequate or Inoperative
Distance Systems, Cruise Control, Ren	66 03 05	November-05	E60/E63	PDC and Gong Volume Cannot be Adjusted
Distance Systems, Cruise Control, Ren	66 01 06	February-06	E90	PDC Button not Installed (Supercedes Feb 06 with added info)
Distance Systems, Cruise Control, Ren	66 04 06	March-07	E60/E63	Night Vision Malfunctions and Parts Replacement (update to 11/06)
Distance Systems, Cruise Control, Ren	66 05 06	September-06	E61	Vehicle Does Not Start
Distance Systems, Cruise Control, Ren	66 07 06	December-06	All	Remote Control Key Not Working
Distance Systems, Cruise Control, Ren	66 02 07	March-07	All	Comfort Access: Replacement ID Transmitter Initialization
Distance Systems, Cruise Control, Ren	66 04 07	September-07	E60/E63	Unexpected Lane Departure Warning
Distance Systems, Cruise Control, Ren	66 06 07	October-07	ALL	Universal Garage Door Opener Cannot be Programmed
Distance Systems, Cruise Control, Ren	66 01 08	February-08	E91	PDC Gong volume low
Distance Systems, Cruise Control, Ren Distance Systems, Cruise Control, Ren	02 for e65 66 03 08	March-08	X5 (E70)	Seal Must Be Replaced when Rear View Camera Is Removed
Distance Systems, Cruise Control, Ren	66 05 08	May-08	1 Series	PDC and Warning Gong Volume too Low
Distance Systems, Cruise Control, R	66 06 08	October-08	E61	Remote Control Malfunction or Radio Reception Problem
Distance Systems, Cruise Control, R	66 07 08	January-09	E63/E64 M6	PDC Malfunction
Distance Systems, Cruise Control, R	66 01 09	March-09	3 Series	PDC Ultrasonic Sensor(s) Become Discolored
Diotailos Oyotomo, Graios Comaci, it	33 31 33	maron oo	0 0000	1 20 011 200110 0011001(0) 2000110 210001010
	03, 06 for other model 02 other model			
Vehicle Tools	71 01 07	September-07	W/Sunroof	Sunroof Emergency Operation Tool Eliminated
Vehicle Tools	71 01 08	March-08	3/5/6/Z series	Combination Wrench Eliminated from the Vehicle Tool Kit
Safety Restraint Systems	72 05 04	June-04	E60/E63	Various "Self-Test" Faults Stored in "Byteflight" Modules
Safety Restraint Systems	72 02 05 72 02 05	August-06	E60/E65/E90	Passenger Airbag Status Lamp Goes ON/OFF During Driving (Replaces 1/06)
Safety Restraint Systems Safety Restraint Systems	72 03 05	June-05	E64 (Cabrio) E64 (Cabrio)	Check Control Message "Rollover Protection Fault" Service Action: Reprogram Control Modules for Backrest Lock Microswitch
Safety Restraint Systems Safety Restraint Systems	72 09 05 72 02 06	November-05 June-06	ALL	Airbag Warning Lamp for OC3 Seat Mat Fault (Supercedes Mar 06 w/new parts info)
Safety Restraint Systems Safety Restraint Systems	72 02 06 72 03 06	June-06 January-06	E64 (Cabrio)	Airbag Warning Lamp for OC3 Seat Mat Fault (Supercedes Mar 06 W/new parts Info) Airbag Warning Lamp Illuminated for Backrest Microswitch
Safety Restraint Systems Safety Restraint Systems	72 03 06 72 04 06	January-06 January-06	E64 (Cabrio) E90	Rear Belt Tensioners Deploy in Accident
Safety Restraint Systems	72 04 06 72 05 06	February-06	E60	Airbag Warning Illuminated, FC 9B2D in SFZ
Safety Restraint Systems	72 03 06	April-06	E90	OC3 Occupancy Status does not Change
Safety Restraint Systems	72 09 06	August-06	E90	Airbag Warning Lamp, FC93EB (Update to Apr -06)
Safety Restraint Systems	72 10 06	November-06	E90	Airbag Warning Lamp Illuminates - No Fault Codes (Replaces Apr 06)
Safety Restraint Systems	72 18 06	October-06	E60	Various Telegram Errors in Satellites
Safety Restraint Systems	72 19 06	October-06	E63	Various Fault Memory Entries in the SBE
Safety Restraint Systems	72 20 06	October-06	E60	SBSL/SBSR FC 9845/98C5, implausible crash severity
Safety Restraint Systems	72 24 06	October-06	E60	Rear Side Airbags Come Activated
Safety Restraint Systems	72 25 06	October-06	E60	FC 96CA: Passenger Thorax Airbag Resistance too Great
Safety Restraint Systems	72 26 06	October-06	E60	SGM FC 9413 "Signal Lamp Airbag Deactivation"
Safety Restraint Systems	72 28 06	December-06	E92	Seatbelt Assistant "hand" Portion Breaks Off
Safety Restraint Systems	72 29 06	December-06	E60/E63/E65	DIS Test Plan Error While Performing SIM/SGM Self Test
Safety Restraint Systems	72 01 07	January-07	E90/E91	Airbag Warning Lamp Illuminated, FC 93C1/93C3
Safety Restraint Systems	72 03 07	August-07	E92	Seat Belt Assistant Pinch Protection (updates 3/07)
Safety Restraint Systems	72 04 07	May-07	E63/64	Recall Campaign 07V-178: Replace the Seat Occupancy Detection Mat
Safety Restraint Systems	72 05 07	April-07	E92	Seat Belt Assistant Malfunction
Safety Restraint Systems	72 01 08	May-08	E92	Passenger Seat Belt Assistant Extends Unexpectedly
	-07 other model			
	or other model			
Communication Systems			E00/E00	Telephone Installation on New Vehicles Replaces Mar 05)
	84 14 01	November-06	E60/E63	
Communication Systems	84 01 03	December-05	E60/E63	CPT9000 Telephone (Supercedes Aug 05 w/new info)
Communication Systems	84 01 03 B840103E60Telephone	December-05 P/O 84 01 03	E60/E63 E60/E63	CPT9000 Telephone (Supercedes Aug 05 w/new info) E60/E63 TCU Wiring Diagram
Communication Systems Communication Systems	84 01 03 B840103E60Telephone 84 15 03	December-05 P/O 84 01 03 March-08	E60/E63 E60/E63	CPT9000 Telephone (Supercedes Aug 05 w/new info) E60/E63 TCU Wiring Diagram BMW Assist Initialization (now usimg GSM Rpl 11/06)
Communication Systems	84 01 03 B840103E60Telephone	December-05 P/O 84 01 03	E60/E63 E60/E63	CPT9000 Telephone (Supercedes Aug 05 w/new info) E60/E63 TCU Wiring Diagram

Category	SIBs (SI B## ## ##)	Date	Application	<u>Title</u>
Communication Systems	84 214 04	September-05	E60/E63	Linked Sequence calls Fail on Bluetooth (REPLACED BY 84 18 05)
Communication Systems	84 02 04	May-05	E60/E63	Navigation Map DVD for Vehicles with CCC
Communication Systems	84 03 04	July-04	E60	MFL Button Dials "911", or Last Number Dialed
Communication Systems	84 10 04	July-04	E60	CCC Navigation Retrofit Kit
Communication Systems	B841004Installer	P/O 84 10 04	E60	Installation Instructions
Communication Systems	B841004SalesBulletin	P/O 84 10 04	E60	Product Planning MY 04 5 Series
Communication Systems	84 12 04	September-07	E60/E63	Diagnosis and Repair of the CCC (updates 2/06)
Communication Systems	84 12 04 Attachment	September-07	E60/E63	DVD Screws attachment
Communication Systems	84 13 04	November-07 P/O 84 13 04	E60/E63 E60/E63	BMW Assist with Integrated Bluetooth (Rpl Mar 07)
Communication Systems Communication Systems	B841304BluetoothDiagnosis B841304BluetoothUserManuallBus.	P/O 84 13 04 P/O 84 13 04	E60/E63	Diagnostic Instructions for Bluetooth Telephone Systems Bluetooth Users Manual for Business Phone
Communication Systems	B841304BluetoothUserManualE60E63	P/O 84 13 04	E60/E63	Bluetooth Users Manual for CPT9000 and Bluetooth
Communication Systems	84 14 04	October-04	E60/E63	Service Action: Activate SVS (Voice Recognition System)
Communication Systems	B841404Q&A	P/O 84 14 04	E60/E63	FAQ
Communication Systems	84 01 05	July-05	E60/E63	Service Action: Reactivate TCUs for specified Production models that were accidently deactivated
Communication Systems	84 04 05	January-07	E60/E63	Nav system missing or incorrect data (Replaces April 05)
Communication Systems	84 07 05	June-05	E60/E63	Motorola v710 Handset Phonebook does not download
Communication Systems	84 08 05	April-07	E60 /E90	CID switches between BMW banner and blank screen (Rpl 3/06 - adds E90 & new procedure)
Communication Systems	84 09 05	June-05	E60/E63	CCC NAV places of interest (POIs)
Communication Systems	B800905POICategories	P/O 84 09 05	E60/E63	PDF of categories and sub categories
Communication Systems	B800905POI_ICONS	P/O 84 09 05	E60/E63	PDF of ICON symbols
Communication Systems	84 10 05	May-06	E60/E63/E90	Nav Displays incorrect Vehicle Position (Supercedes Mar 06) - Replaced with 65 23 07
Communication Systems	84 11 05	June-05	E60/E63	CCC CD/DVD disc does not eject
Communication Systems	84 12 05	April-06	E60/E63	DVD Drive makes clicking noise (Supercedes Aug 05 w/E90)
Communication Systems	84 13 05	May-07	E60/E63/E90	Bluetooth Phone call may still be displayed as active after the call has ended (Rpl 3/07 - adds E90)
Communication Systems	84 14 05	August-08	All	Retrofitting a Telematics Control Unit (TCU) with Bluetooth® Technology (update to 9/07)
Communication Systems	84 14 05 Attachment	September-07	All	Special Inst for E6x
Communication Systems	84 18 05 84 19 05	September-05	E60/E63	Linked Sequence calls Fail on Bluetooth and CPT9000 Handsets
Communication Systems		September-05		Teleservice does not place call for CBS due
Communication Systems Communication Systems	84 24 05 84 25 05	August-06 January-06	E60/E63/E90 E90	CCC Voice Input System Incorrectly States Speed Limit in "km" (Supercedes Nov 05) Software error in the Telematics Control Unit (TCU). (Supercedes Dec 05)
Communication Systems	84 02 06	January-06	All	Hands free Bluetooth® Phone Call May be Lost if a Call Waiting Call is Received
Communication Systems	84 03 06	March-07	All	Enhanced Support for CCC Car Communication Computer (Supercedes Dec 06)
Communication Systems	84 04 06	July-06	All	Service Action: Reactivation of Telematics Control Unit (TCU) (Replace Mar 06)
Communication Systems	84 05 06	March-07	All	Diagnosis of Bluetooth® Handset Related Complaints (Rpl Mar 06)
Communication Systems	84 06 06	March-06	All	Information Displayed in the BMW Assist Menu is Incorrect or Unknown
Communication Systems	84 08 06	March-06	All	CCC Navigation is Inoperative at Low Ambient Temperatures
Communication Systems	84 09 06	October-07	All	Bluetooth® Inoperative, TCU FC# A379 or 79 (update to 04/07)
Communication Systems	84 10 06	August-07	E60/E63/E90	BMW Assist or Bluetooth® Inoperative, TCU FC# A379 (rpl 4/06)
Communication Systems	84 14 06	May-07	E60/E63/E90	Service Action: Reactivation of Telematics Control Unit (TCU) - (superceded Dec 06)
Communication Systems	84 15 06	May-06	E60/E63/E90	CCC Navigation Address Book Shows Duplicate Entries after Programming
Communication Systems	84 18 06	June-06	E60/E63/E90	Low Bluetooth Signal is Displayed in the Handset or the Bluetooth® Connection is Lost
Communication Systems	84 20 06	September-06	E60/E63/E90	CCC Navigation Stuck on "Accept" Screen(Superedes Jun 06)
Communication Systems	84 23 06	May-07	E60/E63/E90	Service Action: Telematics Control Unit (TCU) – MOST-bus Vehicles Supercedes Dec 06)
Communication Systems	84 25 06	June-08		NAD Check, Recovery or Deactivation Procedure (MOST-Bus vehicles) Supercedes Dec 06
Communication Systems	84 26 06	July-08	E60/E63/E90/E65	Cannot Enable BMW Assist Services (Supercedes Aug 06)
Communication Systems	84 27 06	July-08		BMW Assist Inactive Warning Message Displayed (Supercedes Aug 06)
Communication Systems	84 48 06	October-06	E60/E63	CPT9000 (V60s) Telephone Switches to Silent Mode when Connected to Vehicle
Communication Systems Communication Systems	84 49 06 84 50 06	October-07 October-06	E60/E63 E60/E63	Vehicle Dials BMW Assist on its Own (update to 10/06) CPT9000 Handset Phone does not Load into Vehicles
Communication Systems	84 51 06	October-06	E60/E63	The BMW Assist "Embedded" Phone Rings Erroneously in the Vehicle
Communication Systems	84 58 06	November-06	E60/E63/E90/E92	Real Time Traffic Information w/PDF attachment (Updated in Nov 06)
Communication Systems	84 59 06	October-06	E90/E92	CCC Telephone Address Book Not in Alphabetical Order
Communication Systems	84 61 06	March-07		CCC Navigation System Pop-up Arrow Display Missing During Route Guidance (rpl 10/06)
Communication Systems	84 62 06	July-08	E60/E63/E90/E92	Progran Displays 'The TEL Control Module is Malfunctioning' on the Final Report
Communication Systems	84 01 07	January-07	E60/E63/E90/E92	CCC SVS: Letter and Number Inputs by Voice are Misinterpreted
Communication Systems	84 02 07	March-07	E60/E63/E90/E92	Service Action: Activation of Telematics Control Unit (TCU)
Communication Systems	84 04 07	March-07	E60/E63/E90/E92	Bluetooth® Handsets No Longer Pairs to the Vehicle
Communication Systems	84 05 07	August-07	E60/E63/E70/E90/E92	Checking NAD Signal Strength for BMW Assist
Communication Systems	84 06 07	March-07	E90	Call Cannot be Answered if the Voice Recognition System (SVS) is Active
Communication Systems	84 07 07	July-08	E60/E63/E90	NAD was Found to be Faulty when Performing SI B84 22 05 (Reactivation of BMW Assist Services)
Communication Systems	84 08 07	August-07	E60/E63/X5/Z4	Service Action: Activation of Telematics Control Unit (TCU)
Communication Systems	84 09 07	July-07	E60/E63/E90	Echo on Landline Side of Phone Call
Communication Systems	84 11 07	April-08	E60/E90	Service Action: Replace the Hands-Free Charging Electronics (MULF2-High) rpl 7/07
Communication Systems	84 12 07	July-07		Voice Only Call, No Data Transmitted When Placing a BMW Assist Call
Communication Systems	84 13 07	July-07	E60/E63/E90/E92	BMW Assist Location (GPS) Unknown or Inaccurate, When Placing a BMW Assist Call
Communication Systems	84 16 07	September-07	E60/E63/E90/E92	Erroneous SOS Inactive Warning Message (rpl 7/07)
Communication Systems Communication Systems	84 17 07 84 18 07	July-08 August-07	E60/E63/E90/E92 E60/E63/E90/E92	SOS Inactive Warning Message, No Communication with TCU (rpl 09/07) Enable Services Status Bar Does NOT Progress
Communication Systems	84 19 07	October-07		One Way Audio when Using a Bluetooth Enabled Handset
Communication Systems	84 20 07	October-08	All w/TCU	Upgrading BMW Assist to Support New Bluetooth Handsets (rpl 11/07)
Communication Systems	84 21 07	November-07	All w/TCU	Diagnosis When an Unapproved Handset is Paired to a Vehicle
Communication Systems	84 01 08	June-08	3/5/6/7/X series	Pairing between the iPhone and the Vehicle Fails
Communication Systems	84 02 08	March-08	All w/TCU	Service Action: Initialize BMW Assist Services (SC VPC on 3/3/08)
Communication Systems	84 03 08	November-08	Х3	Echo and Poor Voice Quality on the Landline Side of a Call (rpl 05/08)
Communication Systems	84 04 08	June-08	E60	Service Action: Update BMW Assist Services
Communication Systems	84 05 08	September-08	E60/E90/E83	Service Action: Reactivation of Telematics Control Unit (TCU)
Communication Systems	84 06 08	September-08	3 Series	CIC: Unable to Select an Address via the Contact Book
Communication Systems	84 07 08	September-08	1/3/5/6 series	Echo and Reverberation on the Landline during a Hands-free Call
Communication Systems	84 08 08	September-08	1/3/5/6/X series	BMW Assist Menu Item
Communication Systems	84 09 08	October-08	1/3 series	Service Due CC Message Appears Before Handover Inspection
Communication Systems	84 11 08	January-09	All	BMW Assist Inoperative in Certain Areas (rpl 10/08)
Communication Systems	84 12 08	November-08	All	TCU Symptom Diagnosis
Communication Systems	84 13 08	December-08	Z4	Poor Voice Quality on the Receiving End When Placing a Telephone Call
Communication Systems	84 02 09	February-09	All	Telephone - Incomplete Contact List Available in Vehicle
Communication Systems	84 03 09	February-09	All	Telephone Contacts Cannot Be Deleted from the CIC
Communication Systems	84 04 09	March-09	All	The Landside Person Finds the Caller Speaking from an iPhone 3G Hard to Understand

01, 03, 10, other models or minor