

Error memory

Date: 3/4/22, 7:05 PM
VIN: WBAVA335X8FV66653

12 Motor electronics

2 errors

2EF5: 0x2EF5 map thermostat, control

2EFE: 0x2EFE electric fan, control

20 Tyre pressure control

2 errors

604E: Error RDC system

6054: Error wheel sensor VL

29 Dynamic stability control MK60 E5

3 errors

5E51: 5E51 - F-CAN SZL serial number invalid.

5DE1: 5DE1 - Brake pad wear HA not initialized / incorrectly.

5E5B: 5E5B - DSC button pressed longer than 10sec or error.

40 Car access system

1 error

A0B5: Signalerkennung_Geschwindigkeit_Fehler

55 Language processing

1 error

DE50: Ring fracture diagnosis was carried out (Error_Ring_Diagnose)

56 Roof function centre

1 error

A669: Error interior light front 0xA669

56 Rain/driving lights sensor

1 error

A669: Error interior light front 0xA669

60 Instrument panel

2 errors

A559: KL30g_f shutdown

931B: TEMPERATURE SENSOR

72 Basic body module

3 errors

E594: Telegram steering angle timeout

9CAB: a terminal 15 is missing

A8AC: Limiting light left defective

29 ABSKWP

3 errors

5E51: 5E51 - F-CAN SZL serial number invalid.

5DE1: 5DE1 - Brake pad wear HA not initialized / incorrectly.

5E5B: 5E5B - DSC button pressed longer than 10sec or error.