

SIB Date (If known)*	Application	ISTA/P (formerly PROGMAN/formerly CIP) to Vehicle data Status	Comments/Fix list	Features Added/Changed
		Reference (Edited and compiled by Cobradav) Courtesy of KoTR @ bimmerdrivers.com		
Announced and available in Jun 10, other BMW source	E90/91/92/93/82/83	ISTA/P 2.38.1 (Vehicle data Status E89X-10-06-501) Online	SIB 650610 - fixes RAD2+ radio inop if programmed w/ISTA/P 2.37.0, radio also has to be replaced	For Service Techs Adjustment of DSC Compressor breakin protection Initialization of slide/tilt roof
Announced and available in Jun 10, other BMW source	E90/91/92/93/82/83	ISTA/P 2.38.0 (Vehicle data Status E89X-10-06-500) DVD	SIB 130610 - M57Y w/Fault 4CAF stored (SEL) SIB 130710 - M57Y erroneous fault codes Required to program new retrofit SIRIUS head units (non-hardware)	UNK
Announced and available in Apr 10, other BMW source	E90/91/92/93/82/83	ISTA/P 2.37.2 (Vehicle data Status E89X-10-03-504) Online	SIB 125506 - N54 HDP long crank issue - if DME P/N is lower than 7611xxx May fix RAD2+ coding issues	UNK
Announced and available in Mar 10, other BMW source	E90/91/92/93/82/83	ISTA/P 2.37.1 (Vehicle data Status E89X-10-03-502) Online		UNK
Announced and available in Mar 10, other BMW source	E90/91/92/93/82/83	ISTA/P 2.37.0 (Vehicle data Status E89X-10-03-501) DVD	Diagnostic error in E90 (335d) Fixes M57Y erroneous fault codes SIB 125506 - N54 HDP long crank issue Known issues: Coding faults when trying to program vehicles with retrofitted Satellite Radio (Options 655 and 693 in VO)	UNK
Announced and available in Dec 09, other BMW source	E90/91/92/93/82/83	ISTA/P 2.36.1 (Vehicle data Status E89X-09-12-512) Online		UNK
Announced and available in Dec 09, other BMW source	E90/91/92/93/82/83	ISTA/P 2.36.0 (Target data Status E89X-09-12-510) DVD		UNK
Being used in Mid November 09	E90/91/92/93/82/83	ISTA/P 2.35.4 (Target data Status E89X-09-09-516) Online	Issues identifying current vehicle configuration	UNK
Announced and available in mid Oct 09, other BMW source	E90/91/92/93/82/83	ISTA/P 2.35.3 (Target data Status E89X-09-09-516) Online		UNK
Announced and available in end of Sept 09, other BMW source	E90/91/92/93/82/83	ISTA/P 2.35.2 (Target data Status E89X-09-09-516) Online		UNK
Announced and available in Sept 09, other BMW source	E90/91/92/93/82/83	ISTA/P 2.35.1 (Target data Status E89X-09-09-500) Online	SIB 651009 - Vehicle Position Is Missing or Incorrect On the Navigation Map SIB 651109 - Satellite Radio:	UNK
Announced and available in 15 Sept - do not use has issues, other BMW source	E90/91/92/93/82/83	ISTA/P 2.35.0 (Target data Status E89X-09-09-500) DVD		UNK
Released in July 09 for future release, other BMW source	E90/91/92/93/82/83	ISTA/P 2.34.1 (Target data Status E89X-09-06-510) Online		UNK
Announced in May 09 available in Jun, other BMW source	E90/91/92/93/82/83	ISTA/P 2.34.0 (Target data Status E89X-09-06-510) DVD	SIB 510608 - window short drop or anti trap expected fix when released	UNK
Announced and available in May 09, other BMW source	E90/91/92/93/82/83	ISTA/P 2.33.3 (Target data Status E89X-09-03-520) Online		UNK

SIB Date (If known)*	Application	ISTA/P (formerly PROGMAN/formerly CIP) to Vehicle data Status	Comments/Fix list	Features Added/Changed
		Reference (Edited and compiled by Cobradav) Courtesy of KoTR @ bimmerdrivers.com		
Announced and available in May 09, other BMW source	E90/91/92/93/82/83	ISTA/P 2.33.2 (Target data Status E89X-09-03-520) Online	UNK	UNK
Announced and available in Apr 09, other BMW source	E90/91/92/93/82/83	ISTA/P 2.33.1 (Target data Status E89X-09-03-520) DVD	SIB 120709 - Service engine soon light is on - DME software calibration error SIB 120909 - Service engine soon DME software error diesel engine SIB 651009 w/CIC - Nav error - recode and recal CIC SIB 651109 - SAT Radio Plan 3 hours to load ISTA/P software - ALL / ANY version	UNK
Announced and available in Apr 09, other BMW source	E90/91/92/93/82/83	ISTA/P 2.33.0 (Target data Status E89X-09-03-510) DVD	SI B12 06 09 - fix DME (service engine soon caused by misfires) errors in Turbo engine SIB 280109 - M3 w/DCT warning lamp SIB 611208 - sunroof, interior lights, rain sensor - Improved driveability for DCT equipped M3	UNK
Announced and available in Feb 09, other BMW source	E90/91/92/93/82/83	ISTA/P 2.32.2 (Target data Status E89X-08-09-530) Online	Fix GWS (New shifter) software	UNK
Announced in Nov 08, and available in Jan 09 other BMW source	E90/91/92/93/82/83	ISTA/P 2.32.1 (Target data Status E89X-08-09-530) Online	Fix "Turbo lag" by going back to original setup (see PROGMAN 29.02.00), fix TCU error in certain build dates, fix DME (service engine soon caused by misfires) errors in Turbo engine (but SIB 120609 is relative) SIB 841108 - BMW assist inop in some areas - full and final fix	UNK
<u>First use of ISTA/P designation</u>	E90/91/92/93/82/83	ISTA/P 2.32.0 (Target data Status E89X-08-09-530) DVD	UNK	UNK
Announced in Nov 08, other BMW Source	E90/91/92/93/82/83	PROGMAN 31.02.00 (Target data Status E89X-08-09-530) DVD	SIB841108-BMW assist inop in some areas only partial fix ofr some symptoms	UNK
Announced in Sep 08, for rel in Oct other BMW Source	E90/91/92/93/82/83	PROGMAN 31.01.00 (Target data Status E89X-08-09-520) Online-update	Fix M3 w/DCT and M3 DME - Fix E90/92 EGS w/N54	UNK
Rel Sep 08, other BMW Source	E90/91/92/93/82/83	PROGMAN 31.00.00 (Target data Status E89X-08-09-515) Online-update	Coding and Programming	UNK
Rel May 08, other BMW Source	E90/91/92/93/82/83	PROGMAN 30.00.02 (Target data Status E89X-08-03-540) Online-update	Coding and Programming	UNK
Rel May 08, other BMW Source	E90/91/92/93/82/83	PROGMAN 30.00.01 (Target data Status E89X-08-03-540) Online-update	Coding and Programming	UNK
Rel May 08, other BMW Source	E90/91/92/93/82/83	PROGMAN 30.00.00 (Target data Status E89X-08-03-530) DVD	Programming	UNK
Rel Apr 08, other BMW Source	E90/91/92/93/82/83	PROGMAN 29.02.00 (Target data Status E89X-08-03-530) Online Update	Introduced "Turbo lag" in attempt to fix some complaints on "noise"	UNK
Rel Mar 08, other BMW Source	E90/91/92/93/82/83	PROGMAN 29.01.01 (Target data Status E89X-08-03-520) Online-update	Coding and Programming	UNK
Rel Mar 08, other BMW Source	E90/91/92/93/82/83	PROGMAN 29.01.00 (Target data Status E89X-08-03-510) Online-update	Coding and Programming	UNK
Rel Mar 08, other BMW Source	E90/91/92/93/82/83	PROGMAN 29.00.00 (Target data Status E89X-08-03-510) DVD Only	Coding and Programming	UNKNOWN
Rel Jan 08, other BMW Source	E90/91/92/93/82/83	PROGMAN 28.00.02 (Target data Status E89x-07-12-515) Online Update	Coding only to include M3 and 1 Series	
Rel Jan 08, other BMW Source	E90/91/92/93	PROGMAN 28.00.01 (Target data Status E89x-07-12-515) Online Update	Coding only	
Rel Dec, other BMW Source	E90/91/92/93	PROGMAN 28.00.00 (Target data Status E89x-07-12-515) DVD	Fix CA locking on e93	

SIB Date (If known)*	Application	ISTA/P (formerly PROGMAN/formerly CIP) to Vehicle data Status	Comments/Fix list	Features Added/Changed
		Reference (Edited and compiled by Cobradav) Courtesy of KoTR @ bimmerdrivers.com		
Reported on e90post by member - Nov 3	E90/91/92/ 93	PROGMAN 27.02.02 (Target data Status E89x-07-09-521) Delivery method not stated	Improvements in iPod, climate and acceleration. Not verified as yet. BMW indicate there was NOT a 27.02.02 ever released	
Rel Oct, other BMW Source	E90/91/92/ 93	PROGMAN 27.02.01 (Target data Status E89x-07-09-521) Delivery method not stated	No changes for 3 series	
Rel Oct, other BMW Source	E90/91/92/ 93	PROGMAN 27.02.00 (Target data Status E89x-07-09-521) Delivery method not stated	Coding and Programming changes	
Rel Sep, other BMW Source	E90/91/92/ 93	PROGMAN 27.01.01 (Target data Status E89x-07-09-521) Online-Update	Programming changes	
Rel Sep, other BMW Source	E90/91/92/ 93	PROGMAN 27.01.00 (Target data Status E89x-07-09-520) DVD/Online-Update	Programming changes	
Posted on TIS 25 Sept 07	E90/91/92/ 93	PROGMAN 27.00.00 (Target data Status E89x-07-09-518) DVD	Fix Radio Sta switching, iPod to FM, Xexon headlights cal mode, Brake wear indication	
Released in June	E90/91/92/ 93	PROGMAN 26.02.00 (Target data Status E89x-07-06-520). Online-Update	Nothing for US Market	
Released in June	E90/91/92/ 93	PROGMAN 26.01.02 (Target data Status E89x-07-06-520). Online-Update	No coding or programming for 3 series	
Released in June	E90/91/92/ 93	PROGMAN 26.01.01 (Target data Status E89x-07-06-520). Online-Update	Application update only	
Released in June	E90/91/92/ 93	PROGMAN 26.01.00 (Target data Status E89x-07-06-510). Online-Update	Application update only	
Released in June	E90/91/92/ 93	PROGMAN 26.00.00 (Target data Status E89x-07-06-510). Via DVD Media only	Coding & programming changes. Only to be used with DIS v48 or v49 & SSS Base Xpe v3.1	
Rel Apr, other BMW Source	E90/91/92/ 93	PROGMAN 25.02.00 (Target data Status E89x-07-03-525) Online-Update	Never listed on TIS No coding or programming for 3 series	
Rel Mar, other BMW Source	E90/91/92/ 93	PROGMAN 25.01.01 (Target data Status E89x-07-03-515) Online-Update		
3/7/2007 (posted on TIS ~ 22 April)	E90/91/92/ 93	PROGMAN 25.01.00 (Target data Status E89x-07-03-520) DVD +Online-Update	Fix RTTI/SAT Radio/PDC error/may fix VR broken in 515	
Rel Mar, other BMW Source	E90/91/92/ 93	PROGMAN 25.00.02 (Target data Status E89x-07-03-516) Online-Update	Programming changes	
Rel Mar, other BMW Source	E90/91/92/ 93	PROGMAN 25.00.01 (Target data Status E89x-07-03-515) Online-Update	Programming changes	
3/7/2007 (posted on TIS ~ 4 April)	E90/91/92/ 93	PROGMAN 25.00.00 (Target data Status E89x-07-03-515) DVD	Fix CD Run on/Nav Pop up arrows, many other CCC fixes, may have VR issues	POI Search, colors changed in display, faster response time
Rel Jan 07, other BMW Source	E90/91/92	PROGMAN 24.02.01 (Target data Status E89x-06-12-510) Online Update	3 series programming	
Rel Jan 07, other BMW Source	E90/91/92	PROGMAN 24.02.00 (Target data Status E89x-06-12-510) Online Update	No 3 series changes	
Rel Dec 06, other BMW Source	E90/91/92	PROGMAN 24.01.01 (Target data Status E89x-06-12-510) Online Update	No 3 series changes	
Rel Dec 06, other BMW Source	E90/91/92	PROGMAN 24.01.00 (Target data Status E89x-06-12-510) Online Update	No 3 series changes	
December-06	E90/91/92	PROGMAN 24.00.00 (Target data Status E89x-06-12-510) DVD	PDC, Headlight leveling, VR for Nav	
Rel Nov 06, other BMW Source	E90/91/92	Progman 23.02.02 (Target data Status E89x-06-09-540) Online Update	No 3 series changes	
Rel Nov 06, other BMW Source	E90/91/92	Progman 23.02.01 (Target data Status E89x-06-09-540) Online Update	Programming and DWA retrofit	
Rel Oct 06, other BMW Source	E90/91/92	Progman 23.02.00 (Target data Status E89x-06-09-540) Online Update	3 series programming	
Rel Oct 06, other BMW Source	E90/91/92	Progman 23.01.03 (Target data Status E89x-06-09-530) Online Update	Update RAD2 for SDARS issue (SIB 092106), fix DRL to permit deactivation after programming with 23.01.00	
Rel Oct 06, other BMW Source	E90/91/92	Progman 23.01.02 (Target data Status E89x-06-09-530) Online Update	No 3 series changes	
Rel Oct 06, other BMW Source	E90/91/92	Progman 23.01.01 (Target data Status E89x-06-09-530) Online Update	Documentation update only	
Rel Sep 06, other BMW Source	E90/91/92	Progman 23.01.00 (Target data Status E89x-06-09-530) Online Update	DME software calibration - bucking while cold	

SIB Date (If known)*	Application	ISTA/P (formerly PROGMAN/formerly CIP) to Vehicle data Status	Comments/Fix list	Features Added/Changed
		Reference (Edited and compiled by Cobradav) Courtesy of KoTR @ bimmerdrivers.com		
Rel Sep 06, other BMW Source	E90/91/92	Progman 23.00.01 (Target data Status E89x-06-09-530) Online Update	DWA Retrofit - all sirens accepted	
September-06	E90/91/92	PROGMAN 23.00.00 (Target data Status E89x-06-09-520) DVD	Sun roof & gas cap	
June-06	E90/91	PROGMAN 22.00.02 (Target data Status E89x-06-06-540)	About 12 CCC fixes	
June-06	E90/91	PROGMAN 22.00.00 (Target data Status E89x-06-06-520)	Airbag Warning light	
March-06	E90/91	PROGMAN 21.01.00 (Target data Status E89x-06-03-510)	No Changes reported	
March-06	E90/91	PROGMAN 21.00.00 (Target data Status E89x-06-03-510)	NAV, Audio (CCC), battery, locking	
December-05	E90/91	PROGMAN 20.00.01 (Target data Status E89x-05-12-510)	BT Pairing	
November-05	E90/91	PROGMAN 20.00.00 (Target data Status E89x-05-12-500)	Engine juddering/idle when cold. N52 engine; Fuel gauge incorrect	
September-05	E90/91	CIP 19.02.00 (Target data Status E89x-05-09-530)	No Changes reported	
September-05	E90/91	CIP 19.01.00 (Target data Status E89x-05-09-530)	CCC (Car Communication Computer) poor AM reception.	
September-05	E90/91	CIP 19.00.00 (Target data Status E89x-05-09-521, E89x-05-06-520)	No Changes reported	
June-05	E90/91	CIP 18.00 (Target data Status E89x-05-06-520)		
June-05	E90/91	CIP 17.01 (Target data Status E89x-05-06-510)	Some DME recode	
Red = New since last report				
* First reported use date if the official SIB Bulletin date is unknown.				
Notes:				
1) Not ALL updates contain changes to a specific series. - i.e coding changes for new features on new models, changes to work with diagnostic software				
2) New features are not included in the SIB - may be available via other BMW source or from user reports on forums				
3) Service personnel often truncate version number based on diagnostic & update equipment that display the version info i.e. v30.00.02 might be reported as 30.2				
4) Nomenclature has changed through the years from CIP, PROGMAN and most recently ISTA/P. In some cases new dealer hardware was required to implement change				
5) Vehicle Data Status was previously known as Target Data Status - this is coded in the vehicle and is the only valid and reliable method of determining software level by BMW service center				