## **Software update information**

### File name: UPD01004.bin

### Content

The content of the software update depends on the status of the software installed in your vehicle. See the description below for details of the possible content of the update and the devices supported.

From those listed below, the version that is appropriate for your vehicle is installed:

- → TX-2.6.4

### **Conditions**

The software update is available only for certain vehicles equipped with a USB audio interface. In these vehicles, the main menu "Settings" includes the menu item "Software update". Further information is provided in the Owner's Handbook for Vehicle under Software Update.

Go to www.bmw.com/update or the compatibility matrix at www.bmw.com/bluetooth to find out whether your vehicle is supported.

#### Installation

Installation of the software update requires agreement with the terms and conditions of use. For further information, see www.bmw.com/update. For the purposes of installation, save the software update file in the main directory of a USB drive. Observe the additional instructions in the Owner's Handbook under Software Update. Following installation of the software update, the new software

status is shown in the vehicle under "Show current version".

#### **Notes**

Once the software has been updated, the software in the vehicle is restarted and data transferred from the USB drive resynchronised where necessary. Wait a few minutes until the USB drive is operational again. Tracks or playlists played before the software update must be selected again. This is also necessary is the previous version of the software is restored using "Restore previous version".

Before you start a Teleservice update, make sure that mobile wireless reception quality is good by checking the status indicator on the control display.

# Software update (MX-3.5.4, TX-3.5.4)

#### Content

- Office: Improved support for email messages.
- ▶ Telephone: Improved USB connectivity for iPhones with iOS 5. Improved connection setup with certain phones. Display and stability with calls ongoing improved with certain phones. Improved Bluetooth connectivity with HTC phones. Improved phone book sorting on Android phones in Japan.
- Multimedia: Improved display of additional alum and track information. Better connectivity for Bluetooth audio devices.

© 2011 Bayerische Motoren Werke Aktiengesellschaft Munich, Germany English 12/11 Readme\_UPD01004\_ENG.pdf Improved functionality, BMW TeleServices, BMW Online and Internet on iPhones with iOS 5.

### Supported devices

The software update improves the compatibility of the following devices:

### Multimedia

All USB devices

Apple: iPod touch, iPhone

Archos: 3 Vision

Creative: MuVo V100

▷ Iriver: E100▷ Palm: Pre

Sony Ericsson: C905

Symbian Foundation: S60

▶ Yari: U200

### **Phone**

▶ Apple: iPhone (iOS 5)

Au: IS03

▶ RIM: Blackberry Pearl (OS 6.x)

 DoCoMo: Galaxy S SC-02B, NEC MEDIUS N-04C, Samsung Galaxy S II SC-02C, Sharp Aquos Phone SH-12C, Xperia Acro SO-02C, Xperia Arc SO-01C

HTC: SensationNokia: C7. N8. X7

Verizon Wireless: ZTE F450

### **Notes**

Following installation of the software update, the following software status is shown in the vehicle under "Show current version":

MX-3.5.4

► TX-3.5.4

### Software update (TX-2.6.4)

### Content

- Office: Improved support for email messages.
- Telephone: Improved connection setup with certain phones. Display with calls ongoing improved with certain phones. Improved Bluetooth connectivity with HTC phones. Improved phone book sorting on Android phones in Japan.

### **Supported devices**

The software update improves the compatibility of the following devices:

#### **Phone**

▶ Apple: iPhone (iOS 5)

▶ Au: IS03

▶ RIM: Blackberry Pearl (OS 6.x)

 DoCoMo: Galaxy S SC-02B, NEC MEDIUS N-04C, Samsung Galaxy S II SC-02C, Sharp Aquos Phone SH-12C, Xperia Acro SO-02C, Xperia Arc SO-01C

HTC: Sensation

Nokia: C7, N8, X7

Verizon Wireless: ZTE F450

### Notes

Following installation of the software update, the following software status is shown in the vehicle under "Show current version":

► TX-2.6.4

### Software update (MX-1.12.0)

### Content

Improves the speed and stability of music playback from a USB drive that is connected to the USB audio interface in the centre armrest and contains multiple playlists.

### **Supported devices**

The software update improves the compatibility of the following devices:

### Multimedia

▶ All USB media

### **Notes**

Following installation of the software update, the following software status is shown in the vehicle under "Show current version":