



fatjoez +56



FORUMS

1 2 3 4 5 6 7 M2 M3 M4 M5 M6 Z4 X1 X3 / X4 X5 / X6 i3 / i8



Logged in as: fatjoez [Log Out] Private Messages: 0 unread, 194 total.

USER CP BMW GARAGE BMW MEETS NEW POSTS SEARCH QUICK LINKS

BMW 3-Series (E90 E92) Forum > E90 / E92 / E93 3-series Technical Forums > BMW Coding > FLA Coding issues, please help

POST REPLY

BimmerPost Submissions Thread Tools Search this Thread Rate Thread

01-22-2016, 03:22 AM

#1

M3mo

New Member

1 REP 19 POSTS

Drives: M3 2011 ZCP
Join Date: Dec 2015
Location: UK

iTrader: (0)

FLA Coding issues, please help

Guys,

I'm desperate here, if you can please help.

I have retrofitted **FLA** to E92 and accidentally swapped Can High and Low in the mirror.

Noticed that, when I was trying to code this with Expert Profile and the module didn't respond.

After swapping those two cables, I was able to code this correctly, noticed also different VIN and tried to change it with Tools32, but it doesn't seem to be doing anything as INPA sees this still with the old VIN (if it see it)

I didn't drive the car, but I can enable the **FLA** without any issues, but I have fault now as SOS system failure.

Now I'm also having issues, INPA doesn't see all modules, if I run UIF it is showing only few modules, and usually different modules every time.

Also modules I have seen before with VIN are showing 000000 instead of VIN and date back 2006 instead of 2011, I have noticed PGS module with this behaviour.



Appreciate 1

QUOTE



01-22-2016, 09:13 AM

#2

808AWD325xi

Ballin' out of control.



132
REP

945
POSTS

Drives: 2009 335i
Join Date: Jul 2007
Location: Hillsboro, OR

iTrader: [\(0\)](#)

Quote:

Originally Posted by **M3mo**

Guys,

I'm desperate here, if you can please help.

*I have retrofitted **FLA** to E92 and accidentally swapped Can High and Low in the mirror.*

Noticed that, when I was trying to code this with Expert Profile and the module didn't respond.

After swapping those two cables, I was able to code this correctly, noticed also different VIN and tried to change it with Tools32, but it doesn't seem to be doing anything as INPA sees this still with the old VIN (if it see it)

*I didn't drive the car, but I can enable the **FLA** without any issues, but I have fault now as SOS system failure.*

Now I'm also having issues, INPA doesn't see all modules, if I run UIF it is showing only few modules, and usually different modules every time.

Also modules I have seen before with VIN are showing 000000 instead of VIN and date back 2006 instead of 2011, I have noticed PGS module with this behaviour.

Check the Latency Timer under the Advanced Settings for your COM port in Windows Device Manager. I've seen the Latency Timer revert to 16ms and when it happened, INPA acted wonky as you described. (i.e. not identifying all installed modules)



Appreciate 0

QUOTE



01-23-2016, 06:00 AM

#3

M3mo

New Member

1
REP

19
POSTS

Drives: M3 2011 ZCP
Join Date: Dec 2015
Location: UK

iTrader: [\(0\)](#)

Quote:


Originally Posted by **808AWD325xi**

Check the Latency Timer under the Advanced Settings for your COM port in Windows Device Manager. I've seen the Latency Timer revert to 16ms and when it happened, INPA acted wonky as you described. (i.e. not identifying all installed modules)



Thank you, that was it




Appreciate < 0
QUOTE +"

01-23-2016, 06:35 AM

#4

808AWD325xi

Ballin' out of control.




132
REP


945
POSTS


Drives: 2009 335i
Join Date: Jul 2007
Location: Hillsboro, OR


iTrader: (0)

Quote:


Originally Posted by **M3mo** 



Thank you, that was it 



You're welcome, I'm glad that I was able to assist.
Thank you for reporting back!


Appreciate < 0
QUOTE +"

01-23-2016, 07:05 AM

#5

M3mo

New Member


1
REP

19
POSTS

Drives: M3 2011 ZCP
Join Date: Dec 2015
Location: UK

iTrader: (0)

Quote:

Originally Posted by **808AWD325xi** 


You're welcome, I'm glad that I was able to assist. Thank you for reporting back!

Funny enough, I have had couple of laptops, even this one I'm using for about 2 years and never happend.

As I have been actually ding two jobs in same time (**FLA** and AHL) I wasn't sure if something is not faulty.





Really great help




thank you again.


Appreciate < 0
QUOTE +"

 POST REPLY

Bookmarks

 twitter
  Facebook
  Digg
  Google

 StumbleUpon
  del.icio.us
  My Yahoo!

Tags [Edit Tags](#)

None

Quick Reply

Message:

Options

Quote message in reply?

Post Quick Reply

Go Advanced

[« Previous Thread](#) | [Next Thread »](#)

Posting Rules

Forum Jump

[BMW Coding](#)

Go

All times are GMT +10. The time now is 06:20 PM.

[Contact Us](#) - [BIMMERPOST](#) - [BMW Forums](#) - [Archive](#) - [Top](#)



Powered by vBulletin® Version 3.7.0

Copyright ©2000 - 2016, Jelsoft Enterprises Ltd.

1Addicts.com, BIMMERPOST.com, E90Post.com, F30Post.com, M3Post.com, ZPost.com, 5Post.com, 6Post.com, 7Post.com, XBimmers.com
logo and trademark are properties of BIMMERPOST

[Privacy Policy](#) - [Terms of Service](#)