

COMPILED AND EDITED BY COBRADAV - COURTESY OF KoTR @ bimmerdrivers.com

Category	SIBs (SI B## ## ##)	Date	Application	Title
Maintenance and General Hints	00 04 02	March-08	All	BMW Group Technical Hotline (rpl 1/08)
Maintenance and General Hints	00 06 03	November-03	All	General info on TIS Website
Maintenance and General Hints	00 01 05	June-06	All	New Vehicle Preparation and Maintenance Requirements (Supercedes Jan 06)
Maintenance and General Hints	B000105ATT_VehChk	P/O 00 01 05	525/530	Quality Certification Form
Maintenance and General Hints	00 02 06	March-07	All	New Vehicle Preparation and Maintenance Requirements (MY07) (Rpl 11/06)
Maintenance and General Hints	00 01 07	May-08	ALL	New Vehicle Preparation and Maintenance Requirements (rpl 3/8 adds M3 DCT and 1 series)
Maintenance and General Hints	00 03 07	August-07	ALL	PuMA Enhancements for TeileClearing Process
Maintenance and General Hints	00 04 07	March-08	X3, X5	New Vehicle Preparation and Maintenance Requirements (rpl 12/07 adds X6)
Maintenance and General Hints	00 08 07	October-07	All	Construction Group Changes
Maintenance and General Hints	00 01 08	March-08	BMW Centers	BMW Center Technical Support Overview
Maintenance and General Hints	00 02 08	March-08	E82/E88	E82, E88 (1 Series) Quality Control Information
Maintenance and General Hints	00 03 08	April-08	E71 (X6)	E71 (X6) Quality Control Information
Maintenance and General Hints	00 04 08	July-09	ALL	New Vehicle Preparation and Maintenance Requirements (add new Z4)
Maintenance and General Hints	00 05 08	January-09	ALL	New Vehicle Preparation and Maintenance Requirements
Maintenance and General Hints	00 06 08	September-08	ALL	Information Tags
Maintenance and General Hints	00 07 08	October-08	3 series	E90, E91 (3 Series) LCI Quality Control Information
Maintenance and General Hints	00 08 08	December-08	335d & X5d	E90, E70 Diesel Quality Control Information
Maintenance and General Hints	00 01 09	November-09	5, 6 Series	New Vehicle Preparation and Maintenance Requirements (add F01/02, F07)
Maintenance and General Hints	00 02 09	February-09	7 series	F01, F02 Quality Control Information
Maintenance and General Hints	00 04 09	May-09	Z4 (e89)	E89 Quality Control Information
Maintenance and General Hints	00 05 09	June-09	All	CBS Service Maintenance Substitute Checklists
Maintenance and General Hints	00 07 09	November-09	X3/X5/X6/M	2010 Model Year New Vehicle Preparation and Maintenance Requirements
Maintenance and General Hints	00 08 09	September-09	F01/02	After Programming, the CBS Due Date is Reset to 01/2000
Maintenance and General Hints	00 10 09	December-09	F01/02	Navigation Graphic Incorrect in Quick Reference Guide
	09 na			
Warranty	01 02 03	September-03	BMW Centers	BMW Maintenance Program 4 Years - 50,000 Miles
Warranty	01 07 03	January-07	BMW Centers	BMW Center Administered Customer Assistance Program (CACAP)
Warranty	01 02 04	November-06	BMW Centers	BMW Tire Center Target Satisfaction Program
Warranty	01 06 05	March-05	BMW Centers	BMW Maintenance Program 2005 Laminated Reference Chart and Mouse Pad
Warranty	B010605Attachment.	P/O 01 06 05	BMW Centers	Chart of Warranty Codes/Services
Warranty	01 07 05	March-05	BMW Centers	Warranty Claims Processing – "Overnight Payments"
Warranty	01 10 05	August-05	BMW Centers	TCU ESN Registration via DCSnet
Warranty	B011005Attachment.	P/O 01 10 05	BMW Centers	FAQ's for TCU Claims
Warranty	01 01 06	January-08	BMW Centers	BMW Warranty Policy and Procedures Manual – Updates from 01/01/05 through 12/21/07
Warranty	B010106Attachment	P/O 01 01 06	BMW Centers	BMW Warranty Policy and Procedures Manual – Updates from 01/01/05 through 12/21/05 rev notes
Warranty	01 02 06	February-06	BMW Centers	BMW Electronic Archiving System (EAS) Evaluation and Certification
Warranty	B010206EAS_Flowchart.	February-06	BMW Centers	EAS Flowchart
Warranty	01 03 06	February-07	BMW Centers	Warranty Claims for Software Update Programming (Progman) (Replace NOV 06)
Warranty	01 04 06	April-06	BMW Centers	Reasons for Vehicle Update Programming Reminder Magnet
Warranty	01 09 06	February-07	BMW Centers	Defect Code for Programming Prior to Accessory Retrofit (Supercedes 12/06)
Warranty	01 03 07	June-07	BMW Centers	New Pricing Plan and Program Enhancements - Maintenance Program Upgrade
Warranty	01 02 08	February-08	BMW Centers	BMW Performance Line of Accessories
Warranty	01 03 08	May-08	BMW Centers	OEM Tire Manufacturer Warranty Coverage CD-ROM
Warranty	01 05 08	July-08	BMW Centers	Certified Pre-Owned (CPO) Reconditioning Changes
Warranty	01 06 08	December-08	BMW Centers	Warranties Knowledge Portal (WKP)
Warranty	01 07 08	December-08	BMW Centers	Labor Rate Calculation on all Reimbursed Labor as of 1/1/09
After Sales Business Development	02 01 05	October-05	All	BMW Assist changes for September 2005
After Sales Business Development	B020105KeyBenefitChart	P/O 02 01 05	All	BMW Assist - Key Benefits
After Sales Business Development	02 01 06	February-06	All	Updated DCSnet Vehicle History Inquiry Information on BMW Assist™ (Supercedes Jan 06)
After Sales Business Development	02 02 06	November-06	All	BMW Assist™ Service Extension Incentive Program (Supercedes 02/06)
After Sales Business Development	02 01 07	February-07	All	Mobile Assistance Program
Tools and Equipment	04 02 05	January-05	E60/E63	Zero-Coded Cover
Tools and Equipment	04 04 05	January-05	E60	Antenna Knife
Tools and Equipment	04 07 05	April-05	N52 Engine	N52 Special Tools
Tools and Equipment	04 08 05	February-05	E60/E63	Aluminum Body Tools
Tools and Equipment	04 13 05	March-05	E61	Tailgate Support
Tools and Equipment	04 14 05	April-05	E60/E63	CD Eject Tool
Tools and Equipment	04 15 05	May-05	E90	DME Test Cable
Tools and Equipment	04 29 05	November-05	E60/E63	AC Sprayer Wand
Tools and Equipment	04 02 06	January-06	M - S85 engine	Backlash Gauge
Tools and Equipment	04 04 07	April-07	Turbocharged	Turbocharger Diagnostic Tool
Tools and Equipment	04 07 07	December-07	All	Fuel Injection and Induction System Cleaning
Tools and Equipment	04 01 08	January-08	S65/M3	New Special Tools
	thru - 2106 no value			
	0107-0307/0507-0607/ & 0807-2807 no value			
Information Systems	05 01 05 end	September-05	All	Teleservice Changing a Customer's Preferred Home Dealer
General	07 02 96	June-07	BMW Centers	CD42: Updated DISplus & GT1 Software (update to Mar 07)
General	07 03 02	June-04	BMW Centers	Optical Testing & Programming System - OPPS
General	07 05 02	June-05	BMW Centers	Online Update
General	07 02 04	November-04	BMW Centers	Optical Programming System - OPS
General	07 01 05	December-05	BMW Centers	Software Service Station r2 (SSSr2)
General	07 01 06	August-06	BMW Centers	Next Generation Workshop Technology – iBase Server Readiness Project
General	07 03 06	October-06	BMW Centers	Next Generation Workshop Technology 3G
General	07 04 06	January-07	BMW Centers	Use Agreement for 3G Workshop Technology
General	07 01 07	March-07	BMW Centers	DIS V49 Corrections Based on Diagnosis Feedback
General	B070107_Feedback PDF	March-07	BMW Centers	B070107Diagnosis_Feedback_Corrected_DIS_V49.
General	07 03 07	June-07	BMW Centers	DIS V50 Corrections Based on Diagnosis Feedback
General	B070307_Feedback PDF			
General	07 04 07	August-07	BMW Centers	DIS V51 Corrections Based on Diagnosis Feedback (Update to June 07)
General	07 05 07	June-07	BMW Centers	DIS V50 Release Notes
General	07 06 07	August-07	BMW Centers	Diagnosis Process
General	07 08 07	August-07	BMW Centers	DIS V51 Release Notes
General	07 10 07	October-07	BMW Centers	Importance of Using the Most Current Diagnostic / Programming Software
General	07 11 07	November-07	BMW Centers	DIS V52 Corrections Based on Diagnosis Feedback (December 2007 Release)
General	07 13 07	December-07	BMW Centers	DIS V52 Release Notes
General	07 15 07	January-08	E60/E63/E90/E92/E70	Diagnosis via D-CAN Not Possible
General	07 01 08	March-08	BMW Centers	DIS V53 Changes Based on Diagnosis Feedback (March 2008 Release)
General	07 02 08	March-08	BMW Centers	DIS V53 Release Notes
General	07 05 08	May-08	BMW Centers	DIS V54 Changes Based on Diagnosis Feedback (June 2008 Release)
General	07 06 08	August-08	BMW Centers	Diagnosis Feedback with ISTA
General	07 07 08	August-08	BMW Centers	ISTA Technical Data 2.8.0 Changes Based on Diagnosis Feedback
General	07 08 08	September-08	BMW Centers	DIS V55 Release Notes
General	07 09 08	October-08	BMW Centers	New ISTA/P Software

Category	SIBs (SI B## ## ##)	Date	Application	Title
General	07 10 08	November-09	BMW Centers	ISTA Does Not Automatically ID the Vehicle
General	07 11 08	December-09	BMW Centers	DIS V56 Release Notes
General	07 01 09	April-09	BMW Centers	DIS V57 Release Notes
General	07 02 09	July-09	BMW Centers	Activating ISTA in Offline Mode when ISIS Is Not Available
Programming/Coding Explanations	09 03 98	May-06	E60/E63/E90	Car & Key Memory (Updated date with additional E90 info Supercedes Nov 05)
Programming/Coding Explanations	B090398_Att5_CKM_E60	P/O 09 03 98	E60/E63	PDF of car and Key memory settings
Programming/Coding Explanations	09 05 01	March-06	E60/E63	CIP General Info (Supercedes Dec 05)
Programming/Coding Explanations	Att3_CBSCheck	P/O 09 05 01	E60/E63	Condition Based Service Plausibility Check
Programming/Coding Explanations	Att4_CBSCorrct	P/O 09 05 01	E60/E63	Condition Based Service Adjustments based on previous service
Programming/Coding Explanations	ProgCoding	P/O 09 05 01	E60/E63	Detailed Description of programming and coding using CIPs
Programming/Coding Explanations	09 07 02	March-03	E65	CIP 7.0
Programming/Coding Explanations	09 01 04	January-05	BMW Centers	Programming Manager
Programming/Coding Explanations	09 01 05	May-05	All	CIP 17.0 Release Notes
Programming/Coding Explanations	09 02 05	July-05	All	OBD Replacement Cables for GTI/DISplus Diagnostic Heads
Programming/Coding Explanations	09 03 05	January-07	E90	Personal Profile (Replaces 8/05)
Programming/Coding Explanations	09 04 05	July-05	All	CIP 18.0 release notes
Programming/Coding Explanations	09 05 05	July-05	E60 w/o NAV	After Programming, CIP shows MASK-H to be replaced
Programming/Coding Explanations	09 06 05	August-05	E60/E63	CIP Shows IHKA (Automatic heating & AC) to be Replaced
Programming/Coding Explanations	09 07 05	September-05	All	CIP 19.0 and 19.1 release notes
Programming/Coding Explanations	09 08 05	October-05	E64 Cabrio	Service Action: Correction to Integration Level
Programming/Coding Explanations	09 09 05	November-05	BMW Centers	CIP: Report Recurring Irregularities
Programming/Coding Explanations	09 11 05	October-06	E60/E63/E90	CCC Fails to Program with CIP 19.x (Supercedes Dec 05, Feb 06, May 06, Aug 06)
Programming/Coding Explanations	09 01 06	February-06	E90	JBE Fails to Program (supercedes Jan 06)
Programming/Coding Explanations	09 02 06	January-06	E90	Replacement FZD Not Accepted by CIP/PROGMAN
Programming/Coding Explanations	09 03 06	January-06	All	Deciphering and Troubleshooting the Vehicle Order
Programming/Coding Explanations	09 05 06	January-06	E60/E63/E90	Release Notes Progran V20.0 and V20.0.1
Programming/Coding Explanations	09 06 06	February-06	E90	RAD2 Cannot be Programmed after Programming Abort (Supercedes Jan 06 - Online 20.02.00)
Programming/Coding Explanations	09 07 06	January-06	E90/x drives	DSC Cannot be Encoded
Programming/Coding Explanations	09 08 06	February-06	E90	DWA LED on Rearview Mirror Cannot be Activated
Programming/Coding Explanations	09 09 06	March-06	All	Release Notes Progran 21.0
Programming/Coding Explanations	09 10 06	May-06	All	Release Notes Progran V21.02 and V21.02.01
Programming/Coding Explanations	09 11 06	May-06	E60	Replacement SZL Not Accepted By Progran
Programming/Coding Explanations	09 13 06	June-06	All	Release Notes Progran V22.0 and V22.0.1
Programming/Coding Explanations	09 14 06	July-06	E60/E63/E90	Maintenance Interval Retrofit is Not Used in US Market Vehicles
Programming/Coding Explanations	09 15 06	July-06	E90	Personal Profile Settings for Alarm System Missing
Programming/Coding Explanations	09 16 06	August-06	E60/E63/E90	Release Notes Progran V22.1 and V22.1.1 and V22.1.2
Programming/Coding Explanations	09 17 06	December-06	ALL	Vehicle Order (VO) Cannot be Adapted Using CIP
Programming/Coding Explanations	09 20 06	October-06	E90	Daytime Running Lamps Switched On after Update with Progran V23
Programming/Coding Explanations	09 21 06	October-06	E90	Satellite Radio Inoperable after Programming with Progran V23 - Need 23.01.03
Programming/Coding Explanations	09 22 06	October-06	E60/E63/E90	Coding Function for Headunit Available in Progran V23
Programming/Coding Explanations	09 01 07	January-07	E60/E63/E90	CCC: Programming or Coding Fails with Progran V24
Programming/Coding Explanations	09 02 07	October-07	All w/CCC	CCC: Enabling Code (FSC) Required for Voice Recognition System(update to May 07
Programming/Coding Explanations	B090207Attachment.	P/O 09 02 07	BMW Centers	B090207Parts_Info_V1_1
Programming/Coding Explanations	09 03 07	June-07	E92	FRM Fails Coding
Programming/Coding Explanations	09 04 07	August-07	ALL w/CCC	Programming Failure Due to CD or DVD in Drives
Programming/Coding Explanations	09 05 07	September-07	E90	CAS2 Programming with Special Measure not Possible
Programming/Coding Explanations	09 07 07	December-09	ALL	Progran Version vs. Vehicle Data Status (update to 1/09) 2.33.02 latest shown
Programming/Coding Explanations	09 01 09	April-09	F01/02	Programming Fails for the IHKA, FKA, or CON
Programming/Coding Explanations	09 02 09	August-09	1/3 Series	RAD2 Programming with ISTA/P 2.34.2 - No MOST Communication
06 other model				
Engine System	11 08 98	June-06	All	BMW Engine Oils (Includes Annual Change Coverage) (Supercedes Oct 05)
Engine System	11 04 03	February-07	E60	Recurring Noise Complaints From Mechanical Alternator Belt Tensioners (Replaces 7/05)
Engine System	11 02 05	January-06	E60/E63	N62 - Rough Idle, Misfire faults after cold start (Supercedes May 05)
Engine System	11 03 05	June-05	E60/E63	N62 and N62TU Valve Cover and Valve Cover Gasket Replacement
Engine System	11 05 05	December-06	E60	N52 Engine Runs Poorly with Camshaft Sensor and VANOS Faults (Supercedes Novr 06)
Engine System	11 07 05	July-05	E60/E63	N62 and N62TU Water Pump Replacement - corrects installation procedure
Engine System	11 09 05	April-06	E60/E63	Non-Return Valve Parts Found In Engine Oil Filter During Engine Oil Service Supercedes Dec 05)
Engine System	11 10 05	February-06	E60 (M5)	Service Action: S85 Replace VANOS High Pressure Line (Supercedes Jan 06)
Engine System	11 01 06	March-06	M5/M6	S85 Engine Oil Level and Oil Service Information
Engine System	Replaced by 11 06 09	December-06	E60	NG6 Engines - Front and Rear Radial Crankshaft Seal Replacement
Engine System	11 03 06	June-06	All w/N62 Engine	Voluntary Emissions Recall 06E-A02: N62 - Crankcase Ventilation Valves Replacement
Engine System	11 04 06	June-06	All	Engine, Transmission, or Clutch Related Complaints
Engine System	11 06 06	June-06	M54/M54TU	Head Bolt Threads Pulling Out of Block During Engine Reassembly
Engine System	11 07 06	October-06	All w/N62 Engine	N62 Engine - Rough Idle at Operating Temperature
Engine System	11 13 06	January-08	E90/E92 w N54	N54 Engine Compression and Cylinder Leakage Test Procedures (rpl 11/06)
Engine System	11 01 07	October-07	All with N62 (4.4l)	N62 Crankcase Ventilation System - Cold Climate Conditions (rpl 6/07)
Engine System	11 05 07	April-07	All S85 (V10)	Service Action: Replace Front Crankshaft Radial Seal
Engine System	11 09 07	July-07	All N52 Engine	Intermittent Hydraulic Valve Adjuster (HVA) "Ticking" or "Rattling" Noises
Engine System	11 12 07	October-07	N62/N62TU	N62 and N62TU Engine Replacement (after an engine has been replaced)
Engine System	11 13 07	May-08	N54	N54 Rattle Noise from Turbocharger Area
Engine System	11 14 07	November-07	N54	N54 Turbocharger Waste Gate Control Noises and Operation
Engine System	11 01 08	April-08	E60/E70/E83/3 series	Service Action: Replace the Chain Tensioning Rail Bearing Bolt
Engine System	11 02 08	February-08	N54	N54: Power Reduction - DME Fault 2A82 VANOS Inlet is Stored
Engine System	11 03 08	November-08	All engines	Crankcase Ventilation System Specification
Engine System	11 04 08	July-08	All	TeileClearing for Engine Components
Engine System	11 05 08	August-08	1, 3 Series	N51 Engine: Cylinder Head Bolt Torque Is not Available via TIS
Engine System	11 07 08	August-08	E46	Overheated Engine - Diagnostic Tips
Engine System	11 09 08	October-08	1 & 3 Series w/N54	Alternator Drive Belt Broken
Engine System	11 10 08	October-08	S62 (E39 M5 & Z8)	S62 VANOS Assembly Mode Test Plan
Engine System	11 01 09	March-09	All	CPO Inspection Guidelines - Engine Inspection on Vehicles with Extended ("Overdue") Oil Service Intervals
Engine System	11 03 09	March-09	M3 w/S65	Engine Oil Residue Found Near Oil Filler Cap
Engine System	11 04 09	April-09	3 & X5 w/diesel	Soot Deposits Found Around Turbocharger Waste Gate Shaft Pivot
Engine System	11 06 09	July-09	All w/N52, N54	NG6 Crankshaft Seal and Bed Plate Sealer
Engine System	11 07 09	August-09	M3 w/S65	Service Action: M3 S65 - Thermostat Housing Inspection
Engine System	11 08 09	September-09	All w/N51/N52/N52K	Engine Oil Leak
06 - Alpina B7				
Engine Electrical System	12 01 99	June-06	All	High Performance Platinum Spark Plug/Spark Plug Application Chart
Engine Electrical System	12 01 04	October-04	N62 in E60	E60 with N62: DME Reprogramming
Engine Electrical System	12 03 04	September-04	M54 in E60	Voluntary Emissions Recall Campaign 04E-A02: Emission Readiness Codes Not Completely Setting
Engine Electrical System	12 04 04	July-04	E60/E63	Safety Recall Campaign 04V-344: DME Replacement on N62/N73 Engines
Engine Electrical System	12 05 04	October-05	E60/E63	Voluntary Emissions Recall 04E-A04: Reprogram DME for Oxygen Sensor Diagnostics on E53, E60,
Engine Electrical System	12 09 04	August-06	All	Special DME Programming - Shipping Procedure (Replaces 12/04)
Engine Electrical System	12 10 04	December-04	M54 in E60	Intermittent Hesitation While Driving or Intermittent Crank, No Start Situation
Engine Electrical System	12 01 05	March-08	N52 in E60	High Perf Iridium spark Plugs (rpl 06/06)
Engine Electrical System	12 03 05	September-05	N62 in E60/E63	CBS Oil Message
Engine Electrical System	12 04 05	July-07	N52 in E60	Check Engine light or engine overheats (Supercedes Mar 06)
Engine Electrical System	12 06 05	June-05	N52 in E60	DME FC CDA7 CAN Message

Category	SIBs (SI B## ## ##)	Date	Application	Title
Engine Electrical System	12 08 05	July-05	E60	Oxygen Sensor
Engine Electrical System	12 11 05	January-06	N62 in E60/E63	Service Action: Reprogramming for Incorrect Oil Service (Supercedes August 05)
Engine Electrical System	12 15 05	March-08	N62 in E60/E63	Map Thermostat faults (rpl 12/07)
Engine Electrical System	12 16 05	September-05	E60	Mixture is too Lean, Fault codes 2882, 2883
Engine Electrical System	12 17 05	September-05	E60	Engine Power drops at 4000 RPM
Engine Electrical System	12 19 05	October-05	N52 in E60/E90	Service Action: Reprogram for OBD Diagnostic
Engine Electrical System	12 20 05	October-05	E60/E63	Loss of Power while decelerating & turning or coming to stop
Engine Electrical System	12 25 05	December-05	E90	CBS Oil formula (different but similar to E60/63)
Engine Electrical System	12 27 05	April-07	E60/E63	N62TU (4.8L) Pinging and Surging (Supercedes Jul 06)
Engine Electrical System	12 29 05	March-06	M5	S85 Engine Diagnosis Test Plan Updates (Supercedes Dec 05 - minor change)
Engine Electrical System	12 03 06	February-06	E60/M52	Loss of Power or Intermittent Crank, No Start Situation
Engine Electrical System	12 04 06	February-06	E60/M52	DMTL Diagnosis Test Plan Error
Engine Electrical System	12 06 06	April-07	E60/E90/N52	Voluntary Emissions Recall 06E-A01: N52 - Reprogramming Vehicle for OBD Diagnostic (Supercedes 5/06)
Engine Electrical System	12 07 06	January-07	E60/E90/N52	Service Engine Soon Light Illuminated: FC 2EF4 Map Thermostat (Replaces 5/06)
Engine Electrical System	12 10 06	September-06	E60/E90/N52	Service Engine Soon Lamp Illuminated: FC 2C2D, 2C3D, 2C2E, 2C3E
Engine Electrical System	12 12 06	April-07	E60/E63/N62TU	N62TU - Diagnosis for DME FC 2A90 (Supercedes Dec 06)
Engine Electrical System	12 16 06	September-06	E90/E92 w N54	E90, E92 with N54 - Diagnostic for DME FC 29F1/29F2
Engine Electrical System	12 18 06	November-06	M5	Voluntary Emissions Recall 06E-A04: S85 - DME Reprogramming for OBD Monitoring
Engine Electrical System	12 19 06	October-06	E60/E63/E90	Check Gas Cap Warning with DME FC 2A17 – DMTL, System Error
Engine Electrical System	12 25 06	November-06	All	Fuel Quality Determination (Supercedes August 06)
Engine Electrical System	12 27 06	November-06	E60/N62	DME Fault Codes 278B and 278D
Engine Electrical System	12 28 06	October-06	E60	DME Fault Code 27CD
Engine Electrical System	12 29 06	November-06	E60/M54	DME Fault Codes 2896, 2877, 2766
Engine Electrical System	12 33 06	October-06	E60/E63	Various Complaints Caused by Defective Oil Level Sensor - Diagnostic Hints
Engine Electrical System	12 34 06	October-06	E60/M54	E60, M54 - Various Oxygen Sensor FC's Caused by Defective Transmission Harness
Engine Electrical System	12 38 06	October-06	E90	MSV70 - DME, FC 29DA Segment Adaptation
Engine Electrical System	12 40 06	October-06	E60	MS45.1 – Various O2 Sensor Faults Stored in DME
Engine Electrical System	12 42 06	November-06	E60	E60, MS45.1 – DME FC 28A2 and FC 2783
Engine Electrical System	12 43 06	October-06	E60/E63	N62 DME ME9.2.1 Engine Difficult to Restart at Operating Temperatures
Engine Electrical System	12 46 06	November-06	E90/E92 w N54	N54 – Slight Bucking is Felt During Acceleration With a Cold Engine
Engine Electrical System	12 47 06	November-06	E60/E63	Break Out Box Overlay Identification
Engine Electrical System	12 49 06	April-07	E60/M54	DME MS45 - FC28B2, 28AA, 28AC; Internal RAM Faults (Rpl 11/06)
Engine Electrical System	12 50 06	November-06	E60/E63/E90	OBD II Fault Codes List in TIS
Engine Electrical System	12 51 06	December-06	E92	MSD80 N54 Engine Diagnostic Test Plans Inoperative
Engine Electrical System	12 54 06	December-06	E90/92	N54 CBS4 Oil Service Indicates 25,000 Miles
Engine Electrical System	12 55 06	January-07	E90/92	E90, E92 with N54 - Diagnosis for DME FC 29DC/2FBF (Replaces 1/07)
Engine Electrical System	12 58 06	January-08	E90	Service Action: Replace the Alternator
Engine Electrical System	12 05 07	January-08	E60/E90	Erroneous Low Oil Level Warning Message While Driving (rpl 120/07)
Engine Electrical System	12 06 07	September-07	E90/E92	Voluntary Emissions Recall 07E-A01: N54 - Reprogramming Vehicle (DME) for OBD Diagnostic
Engine Electrical System	12 07 07	June-07	E90/E92	N51 - Fault 2A43: Valvetronic, Thermal Overload Protection
Engine Electrical System	12 09 07	May-07	M5/M6	Service Engine Soon Light Illuminated: S85 - Various VANOS Related Faults Stored
Engine Electrical System	12 10 07	October-07	E60/E63/N62TU	Service Action: N62TU - Retrofit Engine Compartment Ground Cables - rpl 7/07 (now recall)
Engine Electrical System	12 11 07	July-07	E60/E63/N62TU	N62TU: EDK Throttle Faults - Diagnostic
Engine Electrical System	12 15 07	October-07	3 Series	N52K - Loss of Power
Engine Electrical System	12 16 07	October-07	3 Series	N51 - EAC Sensor Fault 2AD8 is Stored
Engine Electrical System	12 18 07	October-07	3/5 w N54	N54: Running Issues with Various Faults in DME
Engine Electrical System	12 22 07	November-07	All	TeileClearing (Enhanced Technical Support) for DME
Engine Electrical System	12 23 07	November-07	E70 (X5)	FC 2EF4 Characteristic Map Thermostat
Engine Electrical System	12 25 07	November-07	E70 (X5)	E70 N62TU: Pressure Sensor Fault 2D32
Engine Electrical System	12 28 07	December-07	3/5 w N54	N54 Engine Fallsafe: FC 3100, FC 30FE and/or FC 30FF is stored in DME Fault Memory
Engine Electrical System	12 01 08	January-08	3/5 w N52	N52 EDK Throttle Jamming Faults 2D09, 2CED and 2CEC
Engine Electrical System	12 02 08	January-08	3/5 w N54	N54 - Diagnosis for DME Fuel Injector Faults
Engine Electrical System	12 03 08	January-08	X5 w N54	N52K - Diagnosis of DME FC 2E97
Engine Electrical System	12 05 08	February-08	X5 w N62TU	N62TU: Fault 2A17 - DMTL System Error is Stored
Engine Electrical System	12 06 08	July-08	1/3 series, X5	CBS4 Oil Service Forecast Displays Due in 25,000 miles
Engine Electrical System	12 09 08	February-08	E60/63/70	Driveability Complaints due to Cooling Fan Relay Failure
Engine Electrical System	12 10 08	April-08	All w N54	N54 – Aftermarket "Engine Performance Tuning" Kits
Engine Electrical System	12 12 08	February-09	3 Series/N52/N52K	DME FC 2A15 Minor Leak and 2A16 Superfine Leak in Evaporation System (rpl 3/08)
Engine Electrical System	12 13 08	March-08	3/5 ser w/M54/N52	After Vehicle Repair, Service Engine Soon Lamp Cannot Be Switched Off
Engine Electrical System	12 14 08	May-08	new M3 /S65	Service Engine Soon Lamp Is Illuminated, EKP FC 2786, 2787, 2788 (rpl 3/08)
Engine Electrical System	12 15 08	August-08	E65/66	E65, E66 with N62TU - Various Driveability Complaints
Engine Electrical System	12 16 08	June-08	M5/M6 V10	Voluntary Emissions Recall 08E-A02: M5 and M6 with S85 – OBD Communication
Engine Electrical System	12 17 08	June-08	E65/66	Service Action: E65 and E66 with N62, N62TU, or N73 – OBD Communication
Engine Electrical System	12 18 08	June-08	All w/N54	Service Action: N54 Oil Level Programming
Engine Electrical System	12 19 08	June-08	M5/M6 V10	S85 - Power Reduction with Idle Actuator Faults Stored
Engine Electrical System	12 20 08	August-09	All w/N54	N54 - Various Complaints Caused by Aftermarket "Tuning Kits" (rpl 6/08)
Engine Electrical System	12 21 08	April-09	M5/M6	S85 - DME Fault 2742/2743 for O2 Sensor
Engine Electrical System	12 23 08	July-08	E65/66/B7	Service Action: E65 and E66 with N62, N62TU, or N73 – OBD Communication
Engine Electrical System	12 24 08	September-08	E65/66/B7	Service Action: E65 and E66 with N62TU or N73 – OBD Communication
Engine Electrical System	12 25 08	September-08	1/3/5 series & X6	Charge Air Pressure Control B1214_D16LDRN Test Plan Is Inoperative
Engine Electrical System	12 26 08	October-08	All w/N54 & N63 engine	Injector Removal, Installation, and Replacement Procedures
Engine Electrical System	12 27 08	October-08	All w/N54 & N63 engine	Ignition Coil Faults
Engine Electrical System	12 28 08	December-08	S65 / S85	S65 / S85 Rough Running During the Catalyst Heating Phase
Engine Electrical System	12 01 09	June-09	1,3,5/X5	Service Engine Soon Lamp or Check Gas Cap Warning Illuminated
Engine Electrical System	12 02 09	May-09	1,3,5,6/X5,X3	Service Engine Soon or Check Gas Cap Warning Is Illuminated: Tank Leakage
Engine Electrical System	12 03 09	March-09	X5 (E70)	The Engine Oil Level Is Displayed as Overfilled
Engine Electrical System	12 04 09	February-09	M3 w/S65	M3 S65 - Diagnosis for DME Fault Code 2AFD
Engine Electrical System	12 05 09	July-09	5 Series	N54 E60, E61 - Misfire Faults Are Stored due to DME Software Errors (rpl 4/09)
Engine Electrical System	12 06 09	July-09	1, 3 series	N54 E9x, E82, E88 - Misfire Faults Are Stored due to a DME Software Error (rpl 4/09)
Engine Electrical System	12 07 09	July-09	1, 3 series	N51 – Service Engine Soon Lamp Is On with Fault Code 2A38 Stored (rpl 4/09)
Engine Electrical System	12 09 09	December-09	3 & X5 w/diesel	M57Y – The Service Engine Soon Lamp (ML) Is On with Fault Codes 46CE, 4D11, or 4D12 Stored
Engine Electrical System	12 10 09	February-09	3 & X5 w/diesel	E90, E70 M57Y Diesel - Diagnosis for DDE FC 4521/4530
Engine Electrical System	12 11 09	April-09	F01/02 w/N63	Service Action: Program Control Units (DME)
Engine Electrical System	12 12 09	April-09	X6 w/N63	Service Action: Program Control Units (DME)
Engine Electrical System	12 13 09	March-09	M3 w/S65	M3 S65 - Various Oxygen Sensor Faults Stored in DME Memory
Engine Electrical System	12 14 09	June-09	M57Y Eng	M57Y Diesel; Service Engine Soon Lamp Illuminated - No Faults Stored
Engine Electrical System	12 17 09	May-09	X5/X6	Water Is Leaking into the Electronics Box
Engine Electrical System	12 18 09	May-09	X5	Service Action: Program Control Units (DME – DMTL Diagnosis)
Engine Electrical System	12 21 09	June-09	F01/02 w/N63	Loss of Power, Extended Engine Cranking, or Engine Cranks But Does Not Start
Engine Electrical System	12 22 09	September-09	X5/X6/F01/02	Service Action: Replace Spark Plugs (N63, S63)
Engine Electrical System	12 23 09	September-09	E60/61	Service Action: Program Control Units – DME (OBD)
Engine Electrical System	12 24 09	October-09	E82/88	Service Action: Retrofit Oil Level Sensor Ground Strap
Engine Electrical System	12 25 09	October-09	1/5/X6/Z4	TeileClearing for N54 Engine Drivability Concerns
Engine Electrical System	12 26 09	October-09	5/6 series, X5	N62TU: EDK Throttle Potentiometer Faults - Diagnosis

no 04, 06, 07, 08

02, 03, 04, 12, 13, 20, 24, 26 other models, 01, 14, 19, 21, 27 NU

Fuel Systems	13 01 04	July-04	E60/E63 (V8)	Recall Campaign 04V- 303: Retaining Clip Retrofit for the Fuel Line Quick Release Coupling
Fuel Systems	B130104Q&A	P/O 13 01 04	E60/E63 (V8)	Q&A
Fuel Systems	13 01 06	September-06	All	Alcohol Fuel Blends in BMW Vehicles (replaces March 06)
Fuel Systems	13 02 06	September-06	All	TOP TIER Detergent Gasoline in BMW Vehicles (Replaces 03/06)
Fuel Systems	13 03 06	May-06	All	Fuel Pump Failure after Refueling with Ethanol Fuel Blend
Fuel Systems	13 04 06	August-06	All	Alcohol Detection Procedure
Fuel Systems	13 05 06	September-06	All	BMW Group Fuel System Cleaner Plus (Supercedes Aug 06)
Fuel Systems	13 06 06	November-06	E90/E92	High Precision Injection (HPI) Information and Service Procedures

Category	SIBs (SI B## ## ##)	Date	Application	Title
Fuel Systems	13 07 06	November-06	ALL	Gasoline Quality & Detergent Additives - Customer Information Brochure
Fuel Systems	13 01 07	March-09	ALL/ex turbo	Fuel Injection and Induction System Cleaning (rpl 12/07)
Fuel Systems	13 01 09	January-08	M3 S54 (E46)	M3 S54 - Crank/No-Start on 1st Cold Start Attempt
Fuel Systems	13 02 08	September-08	E90/92/93/w/N54	Service Action: Replace the High Pressure Pump
Fuel Systems	13 03 08	May-09	E90/92/93/w/N54	Service Action: Replace the High-Pressure Pump (older vehicles)
Fuel Systems	13 05 08	May-09	E90/92/93 M3	Rough Idle, Rough Running, Misfiring and Loss of Power (rpl 3/09)
Fuel Systems	13 02 09	October-09	X5d	E70 M57Y Diesel - Diagnosis for Low Pressure Fuel Supply Faults (rpl 3/09)
Fuel Systems	13 03 09	November-09	All w/N54	N54 Special Limited High-pressure Pump (HDP) Emissions Warranty of 10 Years/120,000 Miles
Fuel Systems	13 04 09	October-09	All w/N54	N54 - Cold Start Rough Running with Misfire Fault (rpl 3/09)
Fuel Systems	13 05 09	April-09	All w/N54	N54 - Diagnosis for FC 2AAF
Fuel Systems	13 06 09	June-09	All port inj	Fuel Injection and Induction System Cleaning - Customer Information Brochure
Fuel Systems	13 07 09	October-09	All w/N54	N54 - Diagnosis for "Long Crank" Complaint (rpl 6/09)
Fuel Systems	13 08 09	December-09	All w/N54	TeileClearing for N54 Fuel System
Fuel Supply	16 02 05	March-05	E60/E63	Fuel Tank Difficult to Refuel
Fuel Supply	16 01 06	September-06	E90	Fuel Level Sensor Repair Procedure w/N54
Fuel Supply	16 03 06	October-06	E90	Vehicle is Difficult to Refuel
Fuel Supply	16 06 06	October-06	E60	Humming/Buzzing Noise from Center Dash Area When Accelerator is Depressed
Fuel Supply	16 08 06	February-07	E90	N51 PZEV - Erroneous Fuel Gauge Reading (Replaces 12/06)
Fuel Supply	16 01 07	August-07	All	Testing Evaporative Systems for Leaks
Fuel Supply	16 02 07	December-07	E70 (X5)	Service Action: Repair the Fuel Tank Level Sensor
Fuel Supply	16 01 08	September-08	All w/N54	DMTL Tank Leakage Test Module Provides Inaccurate Results
Fuel Supply	16 03 08	January-09	E90/X5 w/d	Diesel Misfueling Protection Bypass Adapter
Fuel Supply	16 01 09	May-09	X3/3 w/d	DEF Extraction and Refill
	- 02 other models			
Cooling Systems	17 01 07	October-07	ALL	BMW Long-Term Antifreeze/Coolant: Maintenance, Repairs and Replacement Requirements
Cooling Systems	17 01 08	July-08	E9x M3	Low Coolant Warning Lamp is Illuminated
Cooling Systems	17 01 09	July-09	X5 (E70)	Service Action: E70 N52K Coolant Hose Seal Plug Retrofit
Cooling Systems	17 02 09	July-09	E70/E90 w/d	Oil Leak from Turbocharger Charge Air Hose
Cooling Systems	17 03 09	October-09	E70/E90 w/d	N63 Turbocharger Auxiliary Water Pump Faults (rpl 7/09)
Clutch	21 02 06	October-06	E60 (M5)	S85 - SMG Transmission Faults 4FA0, 4F80 and Clutch is Damaged
Clutch	07 for Z4	May-07	Z4	Service Action: Clutch Fork Lever Inspection
Drive Shaft	26 01 06	June-07	E65/E66	Noise from Driveshaft Area (Rpl 06/06)
Drive Shaft	26 01 08	July-08	3 Series Xi	Service Action: Replace Front Propeller Shaft Bolts (Build 12/07)
Manual Transmission	23 01 05	November-05	E60/M5	E60 M5 - CAN Communication Fault FFFF
Manual Transmission	23 01 06	February-06	M Cars	SMG III: Fault Code 5101 Analyze Hydraulic Sensor (Supercedes Jan 06)
Manual Transmission	23 02 06	January-06	SMG Tranny	Towing Vehicles with SMG Transmissions
Manual Transmission	23 03 06	April-07	M Cars	Getrag SMG Transmission Repair & Replacement Information (SMG II and III) (Rpl 02/06)
Manual Transmission	23 04 06	April-06	E60/E63	ZF SMG FC 4F6F - Hydraulic Pump Failure (Supercedes Mar 06)
Manual Transmission	23 07 06	February-07	M Cars	M5, M6 with SMG III; FC 4F42/4F43 - Hydraulic Unit Faults (Replaces 12/06)
Manual Transmission	23 08 06	January-07	All SMG Cars	SMG - Service Functions Performed after Drivetrain Repairs
Manual Transmission	23 09 06	January-07	All non M SMG	ZF SMG - Replacement Parts Availability
Manual Transmission	23 01 07	August-07	S85 M5	Service Action: Replace SMG Hydraulic Unit Electric Motor on M5 Vehicles (rpl 7/07)
Manual Transmission	23 02 07	March-08	E60/E63	Voluntary Emissions Recall 07E-A02: SMG Reprogramming
Manual Transmission	23 03 07	December-07	ZF SMG	TeileClearing (Enhanced Technical Support) for ZF SMG Transmissions
Manual Transmission	23 01 08	May-08	Many	Vehicles equipped with Manual Transmissions manufactured by Getrag:
Manual Transmission	23 02 08	July-08	E46	E46, E85 with M54 and ZF SMG - OBD Communication
Manual Transmission	23 03 08	December-08	M5/M6	M5, M6 with SMG III; FC 4F82/4F83/4F84/4F85 - Gear Blocking Faults (rpl 10/08)
Manual Transmission	23 01 09	May-09	1/3 series	Gears Difficult to Select in 6-Speed Manual Transmission - Diagnostic Hints
	- 06 other model			
Automatic Transmission	24 08 03	November-04	E60	EGS Fault 4F6A
Automatic Transmission	24 02 05	April-06	E60	Service Action: Replace Mechatronic Adapter (Supercedes May 05)
Automatic Transmission	24 03 05	February-07	E60/E63	Harsh 2-1 Downshift (Replaces 6/05)
Automatic Transmission	24 06 05	November-05	E60/E63	Safety Recall Campaign 05V-504: Parking Lock Guide Plate
Automatic Transmission	B240605CustomerLetter	P/O 24 06 05	E60/E63	Recall Letter
Automatic Transmission	B240605Q&A.	P/O 24 06 05	E60/E63	Q&A
Automatic Transmission	24 06 06	October-06	E90	A Slight Bump is Felt Shortly after the Vehicle Comes to a Stop (Supercedes Aug 06)
Automatic Transmission	24 11 06	October-06	E92	E92: N54 with 6HP16 - Diagnosis for EGS FC 511B
Automatic Transmission	24 04 07	April-07	E90/E91/E92	ZF 6HP19TU in Failsafe Mode with Fault 4F8D Stored
Automatic Transmission	24 09 07	April-07	E90/E91/E92	The Service Engine Soon Light is on and EGS Fault CF1C Stored
Automatic Transmission	24 10 07	May-08	E60/3 Series	The Transmission is in "Failsafe" mode with EGS Fault CF33 Stored - rpl 4/07
Automatic Transmission	24 11 07	April-07	3 Series	GM6 - 6L46R Transmission Adaptations and Terminology (info only)
Automatic Transmission	24 13 07	June-07	All STEP Equipped	Various Complaints Due to Poor Connection at Transmission Connector
Automatic Transmission	24 19 07	December-08	E60	Drive Position "D" Cannot be Engaged - rpl 6/08
Automatic Transmission	24 20 07	October-07	3 Xi	6L45R Transmission with AWD Leaks from the Selector Shaft Seal
Automatic Transmission	24 21 07	January-09	3 Series	Diagnosis - DME Fault CDB4: No Message (transmission data 3, 3B1)
Automatic Transmission	24 22 07	October-07	3 Series	6HP19TU (6HP21) - Fault 5087: One-Touch Hardware is Stored
Automatic Transmission	24 23 07	February-08	All STEP Equipped	6-Speed Automatic Transmissions Diagnosis and Troubleshooting Hints (rpl 12/07)
Automatic Transmission	24 01 08	December-08	E65/66	E65, E66 with 6HP26 - Diagnosis for EGS FC 4F81 - rpl 2/08
Automatic Transmission	24 02 08	September-08	E60/63/70	Driveability Complaints due to Cooling Fan Relay Failure - rpl 2/08
Automatic Transmission	24 03 08	June-09	E9x/E60	E60, E9x with N54 and 6HP19TU - Jolt and Delay when Pulling Away (rpl 1/09)
Automatic Transmission	24 04 08	September-08	E70 (X5)	E70, X5 3.0i with N52K and 6HP19TU - Transmission Driveability Complaints - rpl 7/08
Automatic Transmission	24 05 08	August-08	E65/66	E65, E66 with N62TU - Various Driveability Complaints
Automatic Transmission	24 06 08	October-08	E65/66	E70, X5 4.8i with N62TU and 6HP26TU - Various Driveability Complaints
Automatic Transmission	24 08 08	December-08	E60/61/X5(E70)	E6x with 6HP19TU - Transmission Clunks after Engine Start - rpl 10/08
Automatic Transmission	24 09 08	October-08	E60/61 & X5	GWS - Transmission Jumps Back to Neutral
Automatic Transmission	24 01 09	May-09	X5	E70 with ZF 6HP26TU - Delayed Up-shift in Hill Program
Automatic Transmission	24 03 09	April-09	E60/E63	550i and 650i with N62TU and 6HP26 - Various Drivability Complaints
Automatic Transmission	24 05 09	August-09	3 Series	Service Action: Program Control Units (EGS) - Gearshift Comfort
	24 process info			
Gear Shift Mechanism	25 01 07	January-07	E70	Service Action: Gear Shift Knob Replacement
Gear Shift Mechanism	25 02 07	November-07	E60	Diagnostic for GWS Faults - Drive Position "D" Cannot be Engaged
Gear Shift Mechanism	25 03 07	November-07	E60/E63	Sport Transmission Paddle Shifters Inoperative - Diagnosis
Gear Shift Mechanism	25 01 08	June-08	M5/M6	M5, M6 with SMG III - Gear Selector Display Position Changes from N to R (3-7/07)
Gear Shift Mechanism	25 01 09	February-09	E6x	E6x GWS: Gears D or R Cannot Be Selected
Gear Shift Mechanism	25 02 09	April-09	X5/X6	E70, E71 GWS - Gears Intermittently Cannot Be Engaged
Gear Shift Mechanism	25 03 09	October-09	X5M/X6M	X5 M, X6 M - Gears D or R Intermittently Cannot Be Engaged

Category	SIBs (SI B## ## ##) 14 - 18 other models	Date	Application	Title
Double-clutch Transmission with Drivel	28 01 08	June-09	M3	M Double-clutch Transmission with Drivelogic Fluid Requirements (rpl 5/08)
Double-clutch Transmission with Drivel	28 02 08	May-09	M3	TeileClearing for M DCT Drivelogic (double-clutch) Transmission (rpl 7/08)
Double-clutch Transmission with Drivel	28 03 08	July-08	M3	M Double-Clutch Transmission with Drivelogic - Transmission Filling and Fluid Level Checking Procedure
Double-clutch Transmission with Drivel	28 04 08	November-08	M3	M Double-Clutch Transmission with Drivelogic Transmission Replacement Procedure
Double-clutch Transmission with Drivel	28 05 08	October-08	M3	M3 with DCT with Drivelogic – Gearbox Emergency Program with FC 5060
Double-clutch Transmission with Dri	28 06 08	November-08	M3	Recall Campaign 08V-595: M3 with M DCT – Reprogramming for Incorrect DCT Clutch Operation
Double-clutch Transmission with Drivel	28 07 08	June-09	M3	M3 with M DCT - Complaint of Delayed Throttle Response
Double-clutch Transmission with Drivel	28 01 09	March-09	M3	M3 with M DCT – Gearbox Warning Lamp with FC 5A87, 5A81 or 5A5B
Double-clutch Transmission with Dri	28 02 09	September-09	M3	M3 with M DCT - Diagnosis for GWS Faults 5062 or 5139
Front Axle	31 02 04	August-04	All	Rattling Noise From Front or Rear Axle
Front Axle	31 02 06	June-06	E60/E63	Recall Campaign 06V-187 : Front Axle Control Arm and Tension Strut Fasteners
Front Axle	31 03 06	November-06	E90	Recall Campaign 06V-400: Check Tightening Torque of Front Axle Control Arms and Tie Rods
Front Axle	31 01 07	January-08	E70 (X5)	Knocking Noise from Front Suspension
Front Axle	31 01 08	November-08	E53 (X5)	E53 (X5) - Replacement of Front Outer CV Joint (rpl 10/08)
Front Axle	31 01 09	February-09	1, 3 ser not M3	Creaking or Groaning Noise During Compression and/or Rebound of Front Axle
Front Axle	31 02 09	June-09	E46/x	E46 All-wheel Drive - Replacement of Front Outer CV Joint
Front Axle	31 03 09	December-09	E70, E71	Clicking Noise when Turning Wheels while Vehicle Is Stationary
Steering and Wheel Alignment	32 01 05	July-05	E60	Power Steering Assist Enhancement
Steering and Wheel Alignment	32 04 05	June-05	E60	Steering Column Comfort Exit Feature
Steering and Wheel Alignment	32 07 05	September-05	E60/E63	Active Front Steering, Noise Fault Code 613E
Steering and Wheel Alignment	32 13 05	October-05	E60/E63	Active Front Steering, Fault Code 6141
Steering and Wheel Alignment	32 14 05	October-05	E60/E63	Active Front Steering Sensitivity
Steering and Wheel Alignment	32 01 06	February-06	E90	Service Action: Install Clip for Power Steering Line
Steering and Wheel Alignment	32 04 06	February-06	E60/E63	AFS Programming
Steering and Wheel Alignment	32 05 06	March-06	E90	Steering Wheel Offset
Steering and Wheel Alignment	32 06 06	March-06	E60/E63	Steering Angle Sensor Adjustment
Steering and Wheel Alignment	32 07 06	April-06	E90/91	Steering Column Clicking Noise
Steering and Wheel Alignment	32 04 07	May-08	ALL	TeileClearing (Enhanced Technical Support) for Steering Systems
Steering and Wheel Alignment	32 07 07	January-08	E60/E70	Active Front Steering (AFS) Warning Lamp; Fault Code 6141 stored
Steering and Wheel Alignment	32 01 08	January-08	E70 (X5)	Active Steering Troubleshooting Procedures
Steering and Wheel Alignment	32 02 08	August-08	M5/M6	Repair Instructions for Power Steering Pump and Pressure Line
Steering and Wheel Alignment	32 04 08	January-09	1,3,5,6 & X5	Active Steering (AL) Warning Lamp Illuminated, Fault Code 6149 Stored
Steering and Wheel Alignment	32 06 08	October-08	X5/X6	Clicking Noise during Steering Column Adjustment
Steering and Wheel Alignment	32 07 08	March-09	E46/53/60/61/83	Squeaking Noise from the Steering Gear
Steering and Wheel Alignment	32 08 08	November-08	X5/X6	Steering Column Position Is Lost with Easy Entry
Steering and Wheel Alignment	32 10 08	August-08	All	Wheel Alignment Data
Steering and Wheel Alignment	31 01 09	October-09	3 series	Heated Steering Wheel Malfunction (rpl May/09)
		no 05, 06		
Rear Axle	33 01 02	March-08	M Cars	Grinding Noise from the Differential during Slow Cornering
Rear Axle	33 01 06	April-06	E60 (M5)	Grating Noise from Differential During Slow Cornering
Rear Axle	33 02 06	September-06	E60/E63/E65	Recall Campaign 06V-277: Inspect Rear Shock Absorbers (Supercedes Aug 06)
Rear Axle	33 01 07	October-07	E60 - M5	E60 M5 Howling Noise from Rear Axle Area
Rear Axle	33 01 08	March-08	3 series M/S65	E90, E92, E93 M3 - "Clunk Noise" on Load Reversal
Rear Axle	33 02 08	April-08	E70 (X5)	Recall Campaign 08V-170: Replace Rear Stabilizer Bar (mfr March 08)
Rear Axle	33 03 08	April-08	All models	Differential Cover Sealer
Rear Axle	33 04 08	October-08	1,3,5,6,7 ser & Z4	Clicking or Cracking Noise from Rear Differential
Rear Axle	33 05 08	August-08	X5, X6	Cracking or Banging Noise from Rear Axle
Rear Axle	33 07 08	December-08	E36/46/Z4/9x/82	Rear Spring Repair Procedures
Rear Axle	33 08 08	December-08	X6	Oil Ageing
Rear Axle	33 09 08	December-08	X6	No Communication with ICM After Programming
Rear Axle	33 01 09	May-09	X6	Differential Output Flange Loose (QMVH)
Rear Axle	33 02 09	May-09	X6	Rattle from Rear Suspension
Brakes	34 06 05	July-05	E90	DSC MK60E5 Fault Codes: 5DB6, 5DC6, 5E30, 5D8F
Brakes	34 02 06	March-06	E60/E63	Brake Squeals
Brakes	34 04 06	April-07	E60/E63/E90	DSC Warning - Various SZL FCs Stored (Supercedes Jun 06)-Changed to e90 only??
Brakes	34 05 06	September-06	E60/E63	Service Action: Replace SZL Optical Element (Made Svc Action)
Brakes	34 02 07	September-07	E70 (X5)	Recall Campaign 07V-391: Inspect the Brake Fluid Reservoir Cap
Brakes	34 03 07	September-07	E70 (X5)	DSC Warning Lamp Illuminated
Brakes	34 04 07	October-07	E60/E63	DSC/DXC Warning Lamp, Fault Code 5EBA (may - June 07 production)
Brakes	34 05 07	October-07	E70 (X5)	Replacement of the Parking Brake Module (EMF)
Brakes	34 06 07	November-07	E90/91/92/93	Additional Effort Required to Press Brake Pedal Prior to Engine Initial Start
Brakes	34 07 07	November-07	M5/M6	M5, M6 - DSC Disabling Function
Brakes	34 01 08	April-08	E70 (X5)	The Parking Brake Warning Is Illuminated and Fault Code 6032 Is Stored
Brakes	34 02 08	April-08	3 Series	Erroneous Brake Pad Replacement Message
Brakes	34 03 08	May-08	E65/66	Parking Brake Repair Instructions
Brakes	34 05 08	August-08	All	Brake Rotor Minimum Thickness (Insp Only Spec 2.4mm non-M)
Brakes	34 07 08	August-08	X5/X6	Parking Brake Warning Illuminated; Fault Code 600D and/or 600B Is Stored
Brakes	34 08 08	October-08	X5/X6	Brake Squeal from Pad Wear Sensor (rpl 8/08)
Brakes	34 09 08	October-08	E60/E63	Brake Squeak from Pad Wear Sensor
Brakes	34 10 08	November-08	E9x & M3	Rattle Noise from Front Wheel Area
Brakes	34 11 08	December-08	1, 3 series & Z4	TeileClearing for Dynamic Stability Control (DSC)
Brakes	34 12 08	August-09	X6	TeileClearing for Integrated Chassis Management (ICM) (rpl 4/09)
Wheels and Tires	36 01 04	August-05	BMW Center	Hunter GSP97BMW Wheel Balancer - Features and Operator Training
Wheels and Tires	36 02 05	July-05	E60	Noise and/or Vibration Caused by Irregular Tire Wear
Wheels and Tires	36 04 05	October-05	E60	Erroneous Flat Tire Monitor Warning
Wheels and Tires	36 05 05	June-05	All	Tire Pressure Monitoring Systems (TPMS)
Wheels and Tires	36 06 05	May-05	E60	Wheels - Different between X models and regular models
Wheels and Tires	36 04 06	April-06	E60	Nitrogen Inflated Tires
Wheels and Tires	36 02 07	September-07	3 Series	Service Action: Reprogram the Control Module for the Tire Pressure Monitoring System (RDC)
Wheels and Tires	36 03 07	September-07	All	Flat Tire Monitor System (FTM) Diagnosis
Wheels and Tires	36 01 08	August-08	All	Tire Pressure Warning Caused by Damaged Wheel Electronics
Wheels and Tires	36 02 09	June-09	5 series	Retrofit Spare Tire and Jack Kit
Suspension	37 02 05	August-05	E60/E63	Anti-Roll Stabilization Noise
Suspension	37 01 06	March-06	E61	Chafed Ride Height Sensor Cable
Suspension	37 01 07	November-07	E70 (X5)	Knocking Noise from Front Suspension
Suspension	37 02 07	October-07	E70 (X5)	The Electronic Dampening Control (EDC) Warning Lamp is Illuminated; No Faults Stored

Category	SIBs (SI B## ## ##)	Date	Application	Title
Suspension	37 03 07	January-08	E70 (X5)	Dynamic Drive (ARS) Front Sway Bar Repairs
Suspension	37 01 09	April-09	E61	Self-leveling Suspension Faults
Suspension	37 02 09	May-09	X6	Rattle from Rear Axle
Suspension	37 03 09	October-09	F01/02	Droning or Whistling Noise from Front Axle Area
Body	41 01 05	May-05	E60/E63	Structural Aluminum Repair Precautions
Body	41 05 06	February-06	E60/E63	Trunk Lid Opens Too Fast/Slow
Body	41 02 07	October-07	E70(X5)	Water Leak from the Upper Tailgate Area
Body	41 01 08	April-08	E90/91	Rear Door Brake Connection Pulls out of the B-pillar
Body	41 02 08	March-09	X5, X6	Service Action: Remove Excessive Underbody Coating
Body	41 01 09	June-09	E46	Rear Axle Support Inspection
Body	41 02 09	October-09	E46	Rear Axle Carrier (Sub-frame) Support Proposed Class Action Settlement (rpl 6/09)
01 other model				
Body Equipment	51 13 04	August-07	E60/E63	Rattling Noise from Center Display (Replaces 06/07)
Body Equipment	51 02 05	February-07	E60	Squeaking Noise from Door Frame area While Driving (Replaces 12/06)
Body Equipment	51 04 05	June-05	E60/E61 (xi, xiT)	Incorrect or Missing Floor Mats (deliveries before May 16, 05)
Body Equipment	51 08 05	July-05	E60/E63	Door Mirror Glass Discolored after Programming
Body Equipment	51 17 05	July-05	E60	Replacement Windshield - VIN Window in Wrong Position
Body Equipment	51 30 05	October-05	E90	Cracking or Ticking Noise from Lower B-Pillar
Body Equipment	51 31 05	March-06	E90	Center Console Heats Up In Knee Contact Area (Supercedes Nov 05)
Body Equipment	51 32 05	October-05	E90	Clicking Noise from Upper B-pillar Trim
Body Equipment	51 33 05	October-05	E90	Water Ingress from A/C Blower Housing
Body Equipment	51 37 05	December-05	E90	The cup holder jams when retracted
Body Equipment	51 10 06	May-07	E60	Anti-trap is Activated when Raising the Front Window (rpl 2/06)
Body Equipment	51 14 06	March-08	3 series/X5	Outside Door Handles Hanging up in the Pulled Position (rpl 2/08)
Body Equipment	51 18 06	May-07	E9x series	Interior Door Grab Handle Finish Peeling (rpl 8/06)
Body Equipment	51 24 06	November-06	E61	Luggage Compartment Roller Cover Malfunction
Body Equipment	51 27 06	January-07	E92	Rattle Noise from B-Pillar Trim
Body Equipment	51 06 07	March-07	E60 - M5	Service Action: Replace Underbody Panel
Body Equipment	51 08 07	March-07	E90/E91/E92	Erroneous Trunk Lid Open Check Control Message
Body Equipment	51 10 07	April-07	E90/E92/E93	Rear Window will not Fully Defrost
Body Equipment	51 12 07	May-07	E93	Service Action: Install Luggage Compartment Labels
Body Equipment	51 14 07	June-07	E93	Center Console Lock Inoperative
Body Equipment	51 16 07	July-07	E93	Rear Roundel Emblem Comes Loose
Body Equipment	51 17 07	July-07	E93	Rear Window(s) Inoperative
Body Equipment	51 19 07	November-07	E90	Doors will not Unlock Using the Key Fob or Central Locking Button (rpl 09/07)
Body Equipment	51 22 07	September-07	E91	Creaking Noise from the C-Pillar Area
Body Equipment	51 24 07	November-07	E93	Water Leaks into the Sides of the Luggage Compartment
Body Equipment	51 25 07	November-07	3 series	Floor Mat Retainer in Wrong Location
Body Equipment	51 28 07	December-07	E93	Compass Changes Direction when Operating the RHT
Body Equipment	51 29 07	December-07	E61	Luggage Compartment Roller Cover Symptom Diagnosis
Body Equipment	51 30 07	December-07	E91	Noises from the Roller Cover Retainers
Body Equipment	51 31 07	December-07	E70 (X5)	Tailgate Soft-close Malfunction
Body Equipment	51 32 07	January-08	E70 (X5)	Rattle from the Upper Tailgate Trim
Body Equipment	51 35 07	January-08	E70 (X5)	Tailgate Latch Noisy when Closing
Body Equipment	51 02 08	February-08	3 series	Compass is Difficult to Read at High Temperatures
Body Equipment	51 03 08	February-08	E91	Luggage Compartment Roller Cover Symptom Diagnosis
Body Equipment	51 04 08	April-08	E93	RHT Rear Roof Shell Headliner Eliminated
Body Equipment	51 05 08	April-08	E60/63	Door Opening/Closing Symptom Diagnosis
Body Equipment	51 06 08	March-09	1 Series	Window Short-drop or Anti-trap Malfunctions
Body Equipment	51 07 08	May-08	E93	Rear Windows Inoperative After Junction Box Replacement
Body Equipment	51 08 08	May-08	E60/63	Power Window Drives: Symptom Diagnosis
Body Equipment	51 09 08	May-08	1 Series	Instrument Panel Symptom Diagnosis
Body Equipment	51 10 08	May-08	E60/63	Noises from the Front Doors - Symptom Diagnosis
Body Equipment	51 11 08	May-08	E63	Water Ingress at the Doors: Symptom Diagnosis
Body Equipment	51 12 08	May-08	1 Series	Rattle from the Armrest Hinge
Body Equipment	51 16 08	June-08	3 series	Hood Insulation Pad Discontinued
Body Equipment	51 17 08	August-08	X5/X6	Grating Noise from the Instrument Panel
Body Equipment	51 18 08	June-08	3 series	Instrument Panel Symptom Diagnosis
Body Equipment	51 19 08	July-08	3 series	Passenger Side Floor Mat Curling
Body Equipment	51 20 08	July-08	X3	Doors Will Not Unlock with the Remote or Central Locking Switch
Body Equipment	51 21 08	July-08	1 Series vert	Squeak from Rear Trim with the Convertible Top Open
Body Equipment	51 23 08	July-08	1 Series vert	Clicking Noise from the Bottom of the A-pillar
Body Equipment	51 24 08	September-08	M3	Washer Fluids Leaking out of the Right Side M Vent
Body Equipment	51 25 08	September-08	1 Series	Buzzing Noise from the Center Vent Area
Body Equipment	51 26 08	September-08	E64	Service Action: Modifying the Rear Water Drain Hoses
Body Equipment	51 27 08	October-08	E60/61	The Front and Rear Doors Do Not Unlock at the Same Time
Body Equipment	51 28 08	September-08	3 series	Door Mirrors Do Not Fold When Using "Convenient Closure"
Body Equipment	51 29 08	November-08	E64	Water Leak into the Trunk Area
Body Equipment	51 30 08	November-08	X5, X6	Water Leak in the Front Right Footwell Area
Body Equipment	51 34 08	November-08	1 series	Wind Noise from the B-pillar at High Speeds
Body Equipment	51 35 08	January-09	All	Cracked or Damaged Windshields
Body Equipment	51 36 08	February-09	All	Outside Mirror Moves when Unlocking the Vehicle
Body Equipment	51 01 09	January-09	X6	Rear Bumper Cover Sticks Out Below the Tail Lamp
Body Equipment	51 02 09	January-09	1 Series	Buzzing Noise from the Door Panel Pocket
Body Equipment	51 04 09	February-09	X5/X6	Gas Strut for Spare Wheel Cover Deleted
Body Equipment	51 05 09	February-09	E90/91	Buzzing Noise from the Door Speaker Area
Body Equipment	51 06 09	February-09	5 Series	Squeaking Noise from the Top of the B-pillar
Body Equipment	51 07 09	March-09	1 Series	Creaking Noise from the Center Armrest
Body Equipment	51 08 09	March-09	X5/X6	Ashtray Does Not Pop Out When the Release is Pressed
Body Equipment	51 09 09	April-09	X5/X6	Rattle from the Luggage Compartment
Body Equipment	51 11 09	April-09	F01/02	Wind Noise from the A-pillar Area
Body Equipment	51 13 09	July-09	F01/02	Rattling Noises from Around the Glove Box
Body Equipment	51 14 09	March-09	F01/02	Automatic Trunk Lid Does Not Close Properly
Body Equipment	51 16 09	April-09	3 series	Rattle Noise from the Radio Area
Body Equipment	51 17 09	April-09	3 series	Replacing Front Cup Holders - part numbers
Body Equipment	51 18 09	May-09	1 series	Noises from the Glove Box Area
Body Equipment	51 19 09	May-09	1 series	Water Leaking into the Luggage Compartment
Body Equipment	51 20 09	June-09	3/5 touring	Tailgate Does Not Open Fully in Cold Temperatures
Body Equipment	51 21 09	June-09	1 series	Rattle Noise from the Center Vent on the Instrument Panel
Body Equipment	51 22 09	June-09	Z4 (E89)	Creaking Noise from the Glove Box
Body Equipment	51 23 09	July-09	F01/02	Service Action: Replace the Front Door Handle Bowden Cables
Body Equipment	51 24 09	July-09	3 series	Smoker's Package, Option Code 441
Body Equipment	51 25 09	July-09	X5/X6	Rattle Noise from the Front Door
Body Equipment	51 27 09	July-09	F01/02	The DVD Changer Cover Doesn't Open Fully
Body Equipment	51 28 09	July-09	F01/02	Roof Rack Cannot Be Installed
Body Equipment	51 29 09	September-09	All	1-Hour Windshield Urethane
Body Equipment	51 30 09	November-09	X5/X6	Permanent Discoloration on the Running Boards
Body Equipment	51 31 09	September-09	1/3/5/6/7/Z4	Power Fold Mirror Position Incorrect
Body Equipment	51 32 09	October-09	X5/X6	Noise from the Door Panel when Closing the Door
Body Equipment	51 33 09	November-09	5 series	Ashtray Cover Sticking
Body Equipment	51 36 09	November-09	X5/X6	Rear Window One-touch Feature Is Inoperative

Category	SIBs (SI B## ## ##)	Date	Application	Title
Body Equipment	51 37 09	December-09	E61	Rattle from the Luggage Compartment
Body Equipment	51 39 09	December-09	All	Damage to the Interior Trim and/or Vents
Seats	52 02 04	April-05	E60/E63	Recall Campaign 04V-575: Modification of the Front Seat Heater Circuit
Seats	52 05 07	August-07	E93	Lumbar Support Inoperative
Seats	52 01 08	February-08	E60/E61	Active Backrest Width Adjustment Inoperative
Seats	52 02 08	January-08	Z4	Knocking Noise from the Seat Frame
Seats	52 03 08	March-08	X5	Lateral Seat Movement and/or Noises
Seats	52 04 08	June-08	E93	Backrest Seat Cover Material Loose
Seats	52 05 08	June-08	E92	Seat Frame Design Change
Seats	52 06 08	August-08	1/3 series	Raised Area on the Seat Bottom
Seats	52 07 08	November-08	E90/91	Stiffness in the Fore and Aft Adjustment of the Seat
Seats	52 09 08	April-09	X5, X6	Seat Heater Does Not Feel Hot Enough (rpl 11/08)
Seats	52 01 09	June-09	E64	Seat Adjustment when Unlocking (rpl 1/09)
Seats	52 02 09	March-09	E70/71 (X5/6)	Thigh Support Cover Loose
Seats	52 05 09	June-09	E70/71 (X5/6)	Rattle from the Front Seat Head Restraints
Seats	52 06 09	July-09	X5/X6	Squeaking Noise from the Passenger Seat
Seats	52 07 09	July-09	X5/X6	Noise from the Active Head Restraint Connecting Cable
Seats	52 08 09	July-09	X5/X6	Noises From the Forward/Back Seat Adjuster Drive Shaft
Seats	52 09 09	August-09	X5/X6	Seat Backrest Panel Creaks
Seats	52 10 09	September-09	X5/X6	Front Seat Backrest Panel Gap
Seats	52 12 09	September-09	X5/X6	Removal Procedure of Front Seat Side Cover
Seats	52 13 09	October-09	E60/61/X5/X6/F01/02	Front Seat Noise Symptom Diagnosis
Seats	52 14 09	December-09	Z4	Backrest Upholstery Dirty due to Contact with Upper Seat Belt
Seats	52 15 09	December-09	X5/X6	Front Seat Backrest Noise when the Seat is Occupied

01, 02, 04-07 all X5

Special Roofs	54 03 05	July-05	E64 (Cabrio)	Convertible Top will not Lower
Special Roofs	54 13 06	May-06	E60	SHD Coding Error - Progman V21.1
Special Roofs	54 17 06	November-06	E64 (Cabrio)	Convertible Top Does Not Completely Open or Close
Special Roofs	54 01 07	July-07	E93	Service Action: Replace Roof Shell Trim Strips (rpl 4/07)
Special Roofs	54 02 07	April-07	E93	RHT Opens but Trunk Lid will not Close
Special Roofs	54 03 07	April-07	E93	Convenience Open/Close Function
Special Roofs	54 06 07	March-08	E93	Roof Shell 1 Slams Down on the Cowl when Closing the RHT (rpl 5/07)
Special Roofs	54 08 07	May-07	E93	RHT Statuses Reversed in DIS/GT1
Special Roofs	54 09 07	June-07	E93	RHT Status Request Supplement
Special Roofs	54 10 07	August-07	E93	RHT Stops Opening in the Stacked/Extended Position
Special Roofs	54 11 07	September-07	E93	Headliner is Loose in the C-pillar Area
Special Roofs	54 12 07	September-07	E93	Rattle from the Front Latch of the RHT
Special Roofs	54 15 07	April-08	E93	RHT Symptom Diagnosis Update (rpl 11/07)
Special Roofs	54 16 07	November-07	E93	Headliner Loose Near A-pillar
Special Roofs	54 17 07	January-08	E93	Headliner Fabric is Creased and/or Stretched
Special Roofs	54 01 08	January-08	E61/91	Wind Noise from the Panoramic Sunroof
Special Roofs	54 02 08	January-08	E60	Water Leak from Sunroof
Special Roofs	54 03 08	February-08	E93	RHT Seal Replacement Update
Special Roofs	54 04 08	August-09	E93	Wind Buffeting/Pressure Noise at Highway Speeds (rpl 10/08)
Special Roofs	54 05 08	March-08	E83 (X3)	Rattle from Panoramic Roof when Fully Open
Special Roofs	54 06 08	May-08	(E70) X5	Clicking Noise From Sunroof
Special Roofs	54 07 08	September-08	E88 (1 Series)	Convertible Top Material Loose at Rear Bow (rpl 6/08)
Special Roofs	54 08 08	March-09	(E70) X5	The Sunroof's Rear Glass Panel Does Not Close from the Vent Position (rpl 8/08)
Special Roofs	54 09 08	August-08	E93	Cleaning Excess Butyl from RHT Roof Shells
Special Roofs	54 11 08	April-09	All w/Pan Roof	TeileClearing for Panoramic Roof (rpl 10/08)
Special Roofs	54 12 08	August-09	(E70) X5	Water Leak from the Front of the Sunroof (rpl 11/08)
Special Roofs	54 01 09	February-09	E88 (1 Series)	Service Action: Repair of the Convertible Top
Special Roofs	54 03 09	May-09	1,3,6 Verts	Soft Top Switch Function and Window Operation (rpl 3/09)
Special Roofs	54 04 09	May-09	5, 7, X5/X6	Wind Noise or Water Leak from the Sunroof
Special Roofs	54 05 09	June-09	1 Series	Soft Top Does Not Close Fully
Special Roofs	54 06 09	July-09	1 Series	Soft Top Hydraulic System Inoperative
Special Roofs	54 07 09	July-09	X & Touring	Squeaking Noise from the Sliding Headliner
Special Roofs	54 10 09	September-09	1 Series Cabrio	Seam Separated on the Soft Top Cover
Special Roofs	54 11 09	October-09	Z4	RHT Hydraulic Unit Failure
Special Roofs	54 12 09	December-09	3 cabrio	Water Leaks from the RHT
Special Roofs	54 14 09	December-09	1 Series Cabrio	Wear Marks on the Soft Top Cover

18, 19 other model

General Electrical Systems	61 07 88	December-06	All	Battery Maintenance Requirements (Replaces 10/06)
General Electrical Systems	61 08 00	June-07	All	Closed-Circuit Current Measurement (Replaces 1/07 - new cars)
General Electrical Systems	61 15 02	February-06	E60/E63	MOST Bus Diagnosis (Supercedes July 04 with new diagnostics & models)
General Electrical Systems	B611502F-Description.	P/O 61 15 02	E60/E63	MOST Bus Diagnosis Description
General Electrical Systems	B611502ChartsA&B.	P/O 61 15 02	E60/E63	MOST Bus Diagnosis Troubleshooting Chart
General Electrical Systems	61 03 03	January-06	E60/E63	CAN/Byteflight Bus Diagnostics (Supercedes June 05 - Adds E61 & E91)
General Electrical Systems	61 13 02	December-05	E65	CIP 16.0 - 2002 MY Electrical complaints (Supercedes April 05 w/new info)
General Electrical Systems	61 14 03	September-07	E60/E63	CIP Updates (CIP 27.00.00) - (Supercedes Apr 07 - 25.01.00)
General Electrical Systems	61 01 04	June-05	E65	CIP 17.01 - MY02-05 various complaints
General Electrical Systems	61 01 04	September-06	E65	Various Complaints Caused by Software Errors (21.02.01) (Supercedes Mar 06 / CIP 20.00)
General Electrical Systems	61 01 05	December-05	E60/E63	Special Survey for CAS related problems (Supercedes Apr 05 - Survey completed)
General Electrical Systems	61 03 05	October-07	E90	CIP 27.00.00 - Software errors corrected with PROGMAN (Rpl 25.01.00 4/07)
General Electrical Systems	61 06 05	September-05	E60	High Drain Battery Message in CIP (N52 Engine)
General Electrical Systems	61 07 05	January-06	E60/E63	PDC Light Flashing after SZM Replacement (Supercedes info in August 05)
General Electrical Systems	61 08 05	August-05	E90	Roof Functions Center Causes Various System Malfunctions
General Electrical Systems	61 09 05	August-05	E90	Remote Key Sticks In/Falls Out of CAS Holder
General Electrical Systems	61 10 05	August-05	E90	Various Electrical Problems
General Electrical Systems	61 11 05	October-05	E60	Battery Safety Terminal
General Electrical Systems	61 12 05	November-05	E60/E63	Dead Battery by MPM
General Electrical Systems	61 13 05	May-08	E60/E63	Dead Battery - Perform Energy Diagnosis (update to 10/07 - added models)
General Electrical Systems	61 01 06	February-06	E90	Trunk Opens without Request
General Electrical Systems	61 02 06	February-06	E60/E63/E90	Key Falls Out of, or Gets Stuck in Key Holder (Supercedes 2/06 adding models)
General Electrical Systems	61 04 06	February-06	ALL	Exiting a Vehicle that is Double-Locked from the Outside
General Electrical Systems	61 05 06	September-07	E65	Various Customer Complaints Corrected With Progman
General Electrical Systems	61 06 06	May-06	E90	Junction Box Pin Assignment Change
General Electrical Systems	61 07 06	August-06	E60/E63/E90	No Crank, No Start, CAS FC A111
General Electrical Systems	61 10 06	October-06	E63	Windows Convenience Open When Door is Opened
General Electrical Systems	61 13 06	October-06	E60	Various Electrical Problems Caused by Water Ingress
General Electrical Systems	61 14 06	October-06	E60/E63	One-Touch Close Inoperative after Door Module Replacement
General Electrical Systems	61 15 06	October-06	E64	Rear Windows Close First, or Anti-trap Activates During Convenience Closing
General Electrical Systems	61 20 06	October-06	E60	Rear Windows Move in Small Increments
General Electrical Systems	61 22 06	October-06	E60	iDrive Controller Malfunction (Low Version)
General Electrical Systems	61 23 06	October-06	E60	Battery Charger Causes Faults to be Set
General Electrical Systems	61 24 06	October-06	E60	Starts only once following EWS calibration
General Electrical Systems	61 26 06	September-06	E90	Central Electronics Failure, K-CAN bus Fault Codes Stored
General Electrical Systems	61 27 06	October-06	E92	Replacement CAS3 - Calibration Error Message
General Electrical Systems	61 28 06	May-07	E92	Red ELV Warning in Instrument Cluster (Replaces 1/07)

Category	SIBs (SI B## ## ##)	Date	Application	Title
General Electrical Systems	61 29 06	April-08	E60/E63/E90	CAS / ELV Diagnostics (rpl 10/07)
General Electrical Systems	61 31 06	September-07	X5	Software Errors Corrected with Progran (update to 5/07) PROGRAM 27.01.00
General Electrical Systems	61 32 06	December-06	E90/91/92	Sunroof Moves in Small Steps or Interior Lights not Working
General Electrical Systems	61 33 06	December-06	E60/E63/E90	Battery Warning Displayed when Deleting Transport Mode
General Electrical Systems	61 34 06	August-07	E90/91/92	Engine Fails to Start after CAS Replacement (update to 9/06)
General Electrical Systems	61 04 07	May-07	E60/E63	SZL Functions Lock Up after Deleting Transport Mode
General Electrical Systems	61 08 07	August-07	E60/E63	Electric Steering Lock Inoperative
General Electrical Systems	61 09 07	August-07	E60/E65/E90	OBD Socket Housing Cover Missing
General Electrical Systems	61 12 07	November-07	E90	No Crank after CAS3 Replacement
General Electrical Systems	61 13 07	November-07	E70 (X5)	Electronic Malfunction CC Message Caused by Shorted Wiring
General Electrical Systems	61 14 07	December-07	E60/E63	Battery Discharged KGM FC 93AB MPM Relay Sticking
General Electrical Systems	61 01 08	January-08	E60/E63/E90/E70	CC Message "Increased battery discharge while stationary"
General Electrical Systems	61 02 08	February-08	3 series	Gong Warning Without Visual Check Control Message
General Electrical Systems	61 03 08	February-08	E93	Doors Will Not Lock Using Comfort Access Handles
General Electrical Systems	61 05 08	May-08	Service Center	TeileClearing for General Electrical Systems
General Electrical Systems	61 05 08	May-08	E90/91/92	Windshield Wiper Parks out of Position
General Electrical Systems	61 06 08	May-08	X5/X6	Sliding Sunroof, Interior Lights, and Rain Sensor Are Inoperative
General Electrical Systems	61 07 08	June-08	E60	Rear Window Functional Problems
General Electrical Systems	61 09 08	August-08	1, 3, X5, X6	Controller Fault Code A2CB Internal Control Module Fault
General Electrical Systems	61 10 08	August-08	3 Series w/DCT	CAS3 Fault Code A0B1
General Electrical Systems	61 11 08	August-08	E60/61	Steering Wheel or Seat Adjustment Inoperative
General Electrical Systems	61 12 08	April-09	1 & 3 Series	Sliding Sunroof, Interior Lights, and Rain Sensor Are Inoperative
General Electrical Systems	61 14 08	September-08	E60	Intermittently, the Rear Doors Do Not Lock
General Electrical Systems	61 16 08	November-08	3er w CIC & N51	N51 PZEV - JBE Repeat Failures Due to Shorted Fuel Sender Harness
General Electrical Systems	61 17 08	November-08	E83 (X3)	Service Action: Reprogram General Module
General Electrical Systems	61 18 08	December-08	BMW Centers	Battery Maintenance Requirements
General Electrical Systems	61 01 09	March-09	All	Windshield Washer Malfunction
General Electrical Systems	61 02 09	March-09	7 Series (F01)	Engine Does Not Start
General Electrical Systems	61 03 09	May-09	7 Series (F01)	ZGM Fault Code 801C20 (Hex) or 8395808 (Dec)
General Electrical Systems	61 05 09	April-09	1,3,5,6,7,X5/6	CC Message "Vehicle Battery! Increased Battery Discharge" After Vehicle Is Stationary
General Electrical Systems	61 06 09	April-09	F01/02	Service Action: Program Control Units (Central Gateway Module)
General Electrical Systems	61 07 09	April-09	5,6, E46, E53	One-touch Windows Inoperative After General Module Replacement
General Electrical Systems	61 08 09	May-09	1 series	Rattle Noise from the Washer Fluid Reservoir
General Electrical Systems	61 09 09	May-09	X6	Service Action: Check and Replace Battery
General Electrical Systems	61 10 09	May-09	F01/02	Erroneous FC 801C05 (Hex), 8395781 (Dec) in ZGM
General Electrical Systems	61 11 09	June-09	All	Battery Charging and Testing Procedure
General Electrical Systems	61 12 09	June-09	F01/02	System Analysis: signal fault Diagnostics - Important Information
General Electrical Systems	61 13 09	July-09	1 series	Missing "Year One of the 1" Start/Stop Ring
General Electrical Systems	61 14 09	September-09	X5M/X6M	Service Action: Install ICM Anti-Rattle Damper
General Electrical Systems	61 15 09	October-09	E70-X5	Various Electrical Problems
General Electrical Systems	61 16 09	September-09	E93/3 Cabrio	Various Electrical Problems
General Electrical Systems	61 17 09	November-09	E65/66	Diagnosis Gateway Module (OGW)
General Electrical Systems	61 18 09	December-09	1, 3, X5, X6	Various Simultaneous Electrical Problems

01, 02, 03 , 05, 06, 07, 10, 11 X5 or other models

Instruments	62 01 06	May-07	E60/E63	Instrument Cluster Needles Vibrate (Replaces 1/07)
Instruments	62 02 06	May-06	E60/E63	Engine Oil Level Menu Option is Displayed After Reprogramming
Instruments	62 04 06	October-06	E60/E63	Instrument Cluster: Failure of Displays/Functions
Instruments	62 01 07	January-07	E90/92	Warning Chime Inoperative for Check Control and/or Directionals
Instruments	62 02 07	January-07	E60/E63/E92	No Communication or Diagnosis Possible With Instrument Cluster
Instruments	62 03 07	May-07	E90/92	On-Board Computer Functions Cannot Be Displayed (rpl 1/07)
Instruments	62 06 07	March-07	BMW Centers	Check Control Messages (With PDF list)
Instruments	62 07 07	May-08	E70 (X5)/E71 (X6)	TeileClearing (Enhanced Technical Support) for Instrument Cluster
Instruments	62 01 08	May-08	1 Series	Cruise Control Display in Instrument Cluster Increments Incorrectly
Instruments	62 02 08	August-08	M3 w/DCT	Instrument Cluster Center Displays Go Blank
Instruments	62 04 08	September-08	E6x	Instrument Cluster Mileage Display Switches to Kilometers when Key Is Switched
Instruments	62 01 09	April-09	E6x	All Instrument Dials Inoperative and Display in Instrument Cluster Is Bright
Instruments	62 02 09	May-09	M3 w/DCT	Shift Lights on M3 Instrument Cluster Cannot Be Permanently Activated
Instruments	62 03 09	July-09	All	Outside Temperature Display Is Incorrect

04 07 note to dealer

05 - 09 other models

Lights	63 02 04	July-04	E60	Replace Lamp Module
Lights	63 02 05	June-05	E60	Brake Force Display (BFD) Inoperative
Lights	63 03 05	July-05	E60	Eyebrow Lights are Inoperative after Programming
Lights	63 05 05	September-05	E64 Cabrio	Third Brake Light Cracked
Lights	63 06 05	November-05	E60	Service Action: Check the Adaptive Headlights for Proper Operation
Lights	63 01 06	May-06	Z4	Front Lighting Configuration
Lights	63 05 06	October-06	E60/E63	Automatic Headlamps: Lights Do Not Switch Off
Lights	63 06 06	October-06	E60	LED Flashing On Headlight Switch, No Faults Stored
Lights	63 08 06	October-06	E60	Lights Flash Briefly When Vehicle Wakes Up; Battery May Become Discharged
Lights	63 09 06	October-06	E60	Brake Lighting Pulsates Intermittently
Lights	63 12 06	October-06	E63	Adaptive Headlamp Does Not Turn
Lights	63 13 06	October-06	E60/E63	Automatic Headlamp System Does Not Switch Off the Lights
Lights	63 15 06	October-06	E60	Headlamp Leak (Replaces 12/04)
Lights	63 16 06	November-06	E60	3rd Brake Light Comes Loose From Rear Window
Lights	63 17 06	January-07	E60/63/90	Eyebrow Lights are Inoperative after Programming (Replaces 12/06)
Lights	63 02 07	January-07	E90/91/92	Bulb Out Symbol Displayed in BC
Lights	63 03 07	February-07	E90/91/92	Daytime Running Lights are Inoperative
Lights	63 04 07	March-07	E60/E63	Fault Code 9CAD in LM
Lights	63 05 07	April-07	X5 (E70)	Rear Turn Signal is Inoperative
Lights	63 06 07	April-07	E92/93	Cornering lights failure Displayed in Check Control
Lights	63 09 07	June-07	X5 (E70)	Taillight Partially Inoperative
Lights	63 10 07	October-07	E92/93	Headlight Vibrates when Vehicle is in Motion
Lights	63 13 07	August-07	E90/91/92	Headlight Vibrations
Lights	63 15 07	October-07	E70 (X5)	Interior Light Switch Illumination
Lights	63 16 07	December-07	E60/E63	Option Code 08S4 - Variable Light Decoding
Lights	63 01 08	March-08	E63/E64	Side Marker Lamp not Working in Conjunction with Welcome Light
Lights	63 02 08	March-08	E92/93	Rear Bulb Failure
Lights	63 03 08	March-08	3 Series	Flashlight Deleted as a Running Change
Lights	63 04 08	June-08	1/3/5/6/7/X series	Headlamp Moisture: Fault Diagnostics
Lights	63 05 08	May-08	E60	CC Message Missing/Incorrect when Front Parking Light Faulty
Lights	63 06 08	July-08	X3	Bulb-Out Warning, FC 2F or 3E
Lights	63 07 08	August-08	E60/E63	Adaptive Headlights Intermittently Inoperative (SW fix coming in Oct)
Lights	63 08 08	August-08	X5 (E70)	Contact Between Inner and Outer Rear Lamps
Lights	63 09 08	August-08	X3	Interior Lamps "Soft ON/OFF" Inoperative
Lights	63 10 08	November-08	1 series, X3	Cracked Third Brake Light (rpl 9/08)
Lights	63 11 08	November-08	All w/MOST	Automatic Headlamps: Adjust Sensitivity
Lights	63 12 08	January-09	E60/E63	Changes to Panel Illumination (58G)
Lights	63 03 09	March-09	7 Series (F01)	High-beam Assistant (FLA): Erratic Operation
Lights	63 04 09	March-09	7 Series (F01)	Headlamp Flashes Several Times, Then Switches Off
Lights	63 06 09	May-09	3 Series	Front LED Turn Signal Not Working or Malfunctioning
Lights	63 07 09	July-09	5, 6, 7 series	Lights Do Not Switch Off Automatically after replacing light module
Lights	63 08 09	September-09	E60	Replace Both Halogen Low-beam Headlamp Bulbs

Category	SIBs (SI B### ## #)	Date	Application	Title
Lights	63 09 09	November-09	3 Series, Z4	Bulb Out Warning: "Turn Indicator Defective"
08 09 for X5 (E63 and E70) 07 NU				
Heating and Air Conditioning	64 08 91	October-06	All	Musty Odors
Heating and Air Conditioning	64 02 05	August-05	E64 (Cabrio)	Poor Temperature Regulation from Center Vents
Heating and Air Conditioning	64 03 05	June-08	E60/E63	Air Conditioning Delayed Startup (Supersedes 4/07 w/new info)
Heating and Air Conditioning	64 04 05	August-07	E60/E63	Air Conditioning Stops Cooling after Long Drive (Replaces 12/06)
Heating and Air Conditioning	64 21 05	May-08	All	Troubleshooting Air Conditioning Compressor Noise (Supersedes Dec 06)
Heating and Air Conditioning	64 01 06	January-06	E60	Blower Motor Stays On with Key Off
Heating and Air Conditioning	64 02 06	June-06	E60	Water Droplets are Blown from Center Vents with A/C On (Supersedes Jan 06)
Heating and Air Conditioning	64 04 06	May-07	E90	Air Conditioning Does not Cool (Replaces 1/07)
Heating and Air Conditioning	64 06 06	May-06	E90	Front Defroster Performance Poor at Mid-Blower Speeds
Heating and Air Conditioning	64 07 06	May-07	E90	Air Conditioning System does not Cool (Refrigerant Charge Good) (rpl 6/06)
Heating and Air Conditioning	64 09 06	October-06	E90	Air Conditioning System Blows Warm Air After Long Drive (Replaces 8/06)
Heating and Air Conditioning	64 10 06	July-06	E60/61	Water Droplets Blown from Right Side Center Vents with A/C On
Heating and Air Conditioning	64 14 06	November-07	E60/61	A/C Compressor Noise "Droning, Howling or Ticking" at Low Engine Speed (update to 10/06)
Heating and Air Conditioning	64 03 07	October-07	E92	Banging Noise from Air Conditioner Compressor (update to 3/07)
Heating and Air Conditioning	64 04 07	May-08	All	Heating and Air Conditioning Symptom Diagnosis (update to 1/08)
Heating and Air Conditioning	64 06 07	May-08	E60/E63	Air Conditioning Compressor Does Not Switch On
Heating and Air Conditioning	64 08 07	August-07	All	Important Information about Heating and Air Conditioning
Heating and Air Conditioning	64 10 07	January-08	E60/E63	Air Conditioning Delayed Startup
Heating and Air Conditioning	64 12 07	June-08	3 Series	White Flakes/Powder Coming from the Air Conditioning Vents
Heating and Air Conditioning	64 13 07	February-08	3 Series	CID or IHKA Total Failure Because F61 Blown
Heating and Air Conditioning	64 14 07	November-07	E70 (X5)	Water Leak on Carpet During Air Conditioning Usage
Heating and Air Conditioning	64 02 08	June-08	1 & 3 Series	Whistling from the Heating/Air Conditioning Unit at Speeds over 50 MPH
Heating and Air Conditioning	64 03 08	August-08	All	TeileClearing for Air Conditioning Systems
Heating and Air Conditioning	64 04 08	September-08	E70 (X5)	Different Delivery Temperature from Each Side of the Rear Compartment Blower
Heating and Air Conditioning	64 05 08	October-08	All	Damage to the Air Conditioning Control Panel
Heating and Air Conditioning	64 06 08	October-08	E71 (X6)	Cold Air Is Leaking from Center Console Area
Heating and Air Conditioning	64 01 09	March-09	E70 (X5)	Whirring Noise from the Auxiliary Water Pump
Heating and Air Conditioning	64 02 09	May-09	F01/02	Rear Air Conditioning is Automatically Reactivated After Sleep Cycle
Heating and Air Conditioning	64 03 09	June-09	F01/02	Heating and Air Conditioning Conversions Available in ISTA/P
Heating and Air Conditioning	64 05 09	September-09	1, 3 series	Water from the Air Conditioning System in Footwell
Heating and Air Conditioning	64 06 09	August-09	1, 3 series	Droning From the Engine Compartment When Using Air Conditioner
07 09 for (X5)				
Audio, Navigation, Monitors, Alarms, SI	65 06 04	July-04	E60/E63	Consumption Set to mpg UK instead of mpg US
Audio, Navigation, Monitors, Alarms, SI	65 10 04	January-05	E60/E63	Audio Stays On
Audio, Navigation, Monitors, Alarms, SI	65 01 05	June-05	E90	Radio Seek/Scan Inoperative
Audio, Navigation, Monitors, Alarms, SI	65 02 05	April-06	E60/E63/E90	SIRIUS Satellite Radio - General Info (Supersedes May 05 - Added E90)
Audio, Navigation, Monitors, Alarms, SI	65 06 05	July-05	E60/E63	CID Fault Analysis Guide
Audio, Navigation, Monitors, Alarms, SI	65 07 05	April-06	E90	MOST Bus is Inoperative or Central Information Display has Reduced Brightness (Jul 05)
Audio, Navigation, Monitors, Alarms, SI	65 08 05	October-05	E90	Temperature Display in RAD2 Shows Dashes
Audio, Navigation, Monitors, Alarms, SI	65 09 05	February-06	E60/E63/E90	No Audio Sound in any Mode (Supersedes Aug 05 with new info)
Audio, Navigation, Monitors, Alarms, SI	65 10 05	November-07	E60/E63/E90	CCC: Loss of all Audio (update to 8/06)
Audio, Navigation, Monitors, Alarms, SI	65 16 05	September-05	E60/E63/E90	RDS Function Causes Confusing Station Names when in "All stations" Screen
Audio, Navigation, Monitors, Alarms, SI	65 18 05	January-06	E60/E63/E90	MP3 Compatibility Overview (Supersedes October 2006)
Audio, Navigation, Monitors, Alarms, SI	B651805MP3_Compatibility_Chart	P/O 65 18 05	E60/E63/E90	MP3 Compatibility Chart
Audio, Navigation, Monitors, Alarms, SI	65 19 05	October-05	E60	Weather Band Available on Multi Audio System Controller
Audio, Navigation, Monitors, Alarms, SI	65 20 05	January-06	E90	RAD2 - CD Mode Malfunctions (In-Dash CD skips or does not play - Business Radio)
Audio, Navigation, Monitors, Alarms, SI	65 21 05	March-07	E63/E64	SIRIUS Satellite Radio Cuts Out in Certain Geographic Areas (May 06 -)
Audio, Navigation, Monitors, Alarms, SI	65 22 05	November-05	E60	' Favorites' Function is Selectable in the Entertainment Menu
Audio, Navigation, Monitors, Alarms, SI	65 23 05	November-05	E60	Disclaimer Screen Disappears Automatically after 10 Seconds
Audio, Navigation, Monitors, Alarms, SI	65 24 05	October-05	E60/E63/E90	Static Between Words on AM Radio
Audio, Navigation, Monitors, Alarms, SI	65 25 05	August-07	E60/E63	HD-Radio™ - Functionality and Diagnosis (Supersedes Mar 07)
Audio, Navigation, Monitors, Alarms, SI	65 26 05	March-06	E60/E63/E90	Audio Switches off Briefly when Listening to FM Stations (Supersedes Jan 06 w/new info)
Audio, Navigation, Monitors, Alarms, SI	65 27 05	November-05	E60/E63/E90	CID Screen Image Not Displayed Correctly Since CCC Replacement
Audio, Navigation, Monitors, Alarms, SI	65 28 05	March-06	E60/E63/E90	CCC: Radio Station Preset List Intermittently Empty (Supersedes Nov 05)
Audio, Navigation, Monitors, Alarms, SI	65 30 05	March-06	E60/E63/E90	CCC: MP3 CD Playback Not Available (Supersedes Jan 06- minor changes)
Audio, Navigation, Monitors, Alarms, SI	65 32 05	March-07	E60/E63/E90	CCC: CD/CDC Track Counter Advances After Mute Selected (Replaces 1/07)
Audio, Navigation, Monitors, Alarms, SI	65 02 06	March-06	E60/E63/E90	CCC: Loss of Audio in All Modes (Supersedes Feb 06)
Audio, Navigation, Monitors, Alarms, SI	65 04 06	March-06	E60/E63/E90	KL-R Stays On After Ignition Off - Comfort Access Only
Audio, Navigation, Monitors, Alarms, SI	65 05 06	April-06	E60/E63/E90	CCC: CD Drive Errors
Audio, Navigation, Monitors, Alarms, SI	65 06 06	November-07	E60/E63/E90	Various Problems with CCC Following Replacement (update to 4/06)
Audio, Navigation, Monitors, Alarms, SI	65 08 06	September-06	E60/E63/E90	CCC with Top HiFi Loses Surround Sound after Navigation Announcement (Supersedes May 06)
Audio, Navigation, Monitors, Alarms, SI	65 10 06	May-06	E60/E63/E90	New Audio-Test-CD for Diagnosing a Faulty CD/Audio-DVD Drive or Media
Audio, Navigation, Monitors, Alarms, SI	65 12 06	July-08	E60/E63/E90	Popping/Crackling Noise from Audio System (rpl 12/06)
Audio, Navigation, Monitors, Alarms, SI	65 16 06	September-06	E60/E63	CCC: Acoustic Warning Gong Sounds at Times, No CC Message
Audio, Navigation, Monitors, Alarms, SI	65 18 06	October-06	E63/E64	DWA (Theft Deterant System) Causes Excessive Closed Circuit Current Draw
Audio, Navigation, Monitors, Alarms, SI	65 25 06	August-08	ALL w / CCC	Enhanced Technical Support for Audio System (Replaces 6/07)
Audio, Navigation, Monitors, Alarms, SI	65 26 06	October-06	E60/E63/E90	CCC Disclaimer Screen Disappears Automatically after 10 Seconds
Audio, Navigation, Monitors, Alarms, SI	65 27 06	October-06	E60/E63/E90	CCC Does Not Play All MP3 Formats
Audio, Navigation, Monitors, Alarms, SI	65 28 06	October-06	E60/E63/E90	CCC Radio Station RDS Information Missing After Programming
Audio, Navigation, Monitors, Alarms, SI	65 29 06	April-07	E60/E63/E90	CCC Next Entertainment Source Not Selectable Via MFL (rpl 10/06)
Audio, Navigation, Monitors, Alarms, SI	65 33 06	December-06	E60/E63/E90	CD Changer is Inoperative; Magazine is Jammed or Broken
Audio, Navigation, Monitors, Alarms, SI	65 35 06	June-07	E60	Poor Radio Reception in FM Mode (rpl 12/06)
Audio, Navigation, Monitors, Alarms, SI	65 36 06	August-07	E60	Poor Radio Reception in AM Mode (rpl 6/07)
Audio, Navigation, Monitors, Alarms, SI	65 37 06	December-06	E60	RDS Function
Audio, Navigation, Monitors, Alarms, SI	65 43 06	May-07	E60/E63/E90	CCC: High Frequency Noises from the DVD drive (rpl 12/06)
Audio, Navigation, Monitors, Alarms, SI	65 44 06	December-06	E60/E63/E90	CCC: AUX-IN Loud Hissing if no Device Connected
Audio, Navigation, Monitors, Alarms, SI	65 45 06	December-06	E60/E63/E90	CCC: Poor Radio Reception after Software Update
Audio, Navigation, Monitors, Alarms, SI	65 46 06	May-07	E60/E63/E90	CCC: Radio Continues to Play after Ignition off (rpl 12/06)
Audio, Navigation, Monitors, Alarms, SI	65 48 06	December-06	E60/E63/E90	SIRIUS Satellite Radio Is No Longer Accessible
Audio, Navigation, Monitors, Alarms, SI	65 01 07	March-07	E60/E63/E90	CID Changes Introduced March 2007
Audio, Navigation, Monitors, Alarms, SI	65 03 07	April-07	E60/E63/E90	M-ASK also available
Audio, Navigation, Monitors, Alarms, SI	65 04 07	January-07	E90/91	CCC: Slow Response from System when using Controller (Rpl Jan 07)
Audio, Navigation, Monitors, Alarms, SI	65 06 07	March-07	All CCC equipped	SDARS Sirius Radio is Inoperative After Programming
Audio, Navigation, Monitors, Alarms, SI	65 07 07	March-08	E60/E63/E90/E92	CCC Symptom Troubleshooting
Audio, Navigation, Monitors, Alarms, SI	65 08 07	May-08	E60/E63/E90/E92	SDARS SIRIUS Radio is Intermittently Inoperative
Audio, Navigation, Monitors, Alarms, SI	65 15 07	May-07	E90/91	USB Audio Interface
Audio, Navigation, Monitors, Alarms, SI	65 18 07	January-08	E64 Cabrio	Airbag Warning Lamp Illuminated, FC 93C1/93C3
Audio, Navigation, Monitors, Alarms, SI	65 19 07	May-07	E63/E64	Radio or Speakers Inoperative (rpl 6/06)
Audio, Navigation, Monitors, Alarms, SI	65 21 07	January-08	E93	Recall Campaign 07V-178: Replace the Seat Occupancy Detection Mat
Audio, Navigation, Monitors, Alarms, SI	65 22 07	August-07	E60/E63/E90/E92	Whistling Noise From the Radio in AM Mode Only
Audio, Navigation, Monitors, Alarms, SI	65 23 07	August-07	E60/E63/E90/E92	CCC CD Text not Updated When CD is Swapped
Audio, Navigation, Monitors, Alarms, SI	65 24 07	August-07	E60/E63/E90/E92	CCC Navigation Displays Incorrect Vehicle Position
Audio, Navigation, Monitors, Alarms, SI	65 25 07	November-07	E60	CCC Navigation Map DVD not Detected
Audio, Navigation, Monitors, Alarms, SI	65 26 07	June-08	E60/E63/E90/E92	Recode or Replace OC3 Seat Mat
Audio, Navigation, Monitors, Alarms, SI	65 27 07	December-07	X5 (E70)	CCC: Volume Differences between CD/AUX and FM after Programming
Audio, Navigation, Monitors, Alarms, SI	65 28 07	September-07	E60/E63/E90/E92	Airbag Warning Lamp Illuminated - FC 93D2
Audio, Navigation, Monitors, Alarms, SI	65 30 07	October-07	E90/91/92/93/E70	CCC: Radio Does Not Resume With Previously Selected Station
Audio, Navigation, Monitors, Alarms, SI	65 30 07	October-07	E90/91/92/93/E70	iPod mode is Switching to FM Mode

Category	SIBs (SI B## ## ##)	Date	Application	Title
Audio, Navigation, Monitors, Alarms, SI	65 31 07	September-07	E60/E70	CHAMP: Intermittently No Audio Output in FM Mode Only After Restart
Audio, Navigation, Monitors, Alarms, SI	65 32 07	December-07	X5 (E70)	Rear Seat Entertainment System (RSE) is Not Working Correctly
Audio, Navigation, Monitors, Alarms, SI	65 33 07	August-08	X5 (E70)	Airbag Warning Illuminated, FC 93D2
Audio, Navigation, Monitors, Alarms, SI	65 34 07	November-07	E90/91/92/93	Service Action: Program the MULF2-High Control Module
Audio, Navigation, Monitors, Alarms, SI	65 35 07	December-07	X5 (E70)	No Audio Output After Turning the Ignition On
Audio, Navigation, Monitors, Alarms, SI	65 36 07	January-08	E60/E63	Radio Turns Off After 8 Minutes and Time and Date Display is Cleared (rpl 12/07)
Audio, Navigation, Monitors, Alarms, SI	65 37 07	November-07	E93	No AM Reception During Convertible Top Operation
Audio, Navigation, Monitors, Alarms, SI	65 39 07	December-07	E60/E63/E90/E92/E70	CCC Navigation Not Working -September 24, 2007 to October 29, 2007
Audio, Navigation, Monitors, Alarms, SI	65 41 07	June-09	E60/E63/E90/E92/E70	CCC Loss of Audio and CID Blanks Out (rpl 07/08)
Audio, Navigation, Monitors, Alarms, SI	65 42 07	January-08	All w/Alarm	Alarm Triggers Unexpectedly - Troubleshooting
Audio, Navigation, Monitors, Alarms, SI	65 01 08	May-08	All w/SAT RAD	SIRIUS Radio Stations Missing in "All Channels" List
Audio, Navigation, Monitors, Alarms, SI	65 02 08	August-08	All w/6FL (USB)	iPod Classic Doesn't Get Charged through USB Connection
Audio, Navigation, Monitors, Alarms, SI	65 03 08	March-08	3 & 5 Series	Interference with Radio Reception on all Bands (FM, AM, HD Radio)
Audio, Navigation, Monitors, Alarms, SI	65 04 08	April-08	All w/SAT RAD	Call SIRIUS Is Displayed
Audio, Navigation, Monitors, Alarms, SI	65 05 08	April-08	7 Series	SIRIUS Radio Station List Is Not Displayed in the RSE Monitor
Audio, Navigation, Monitors, Alarms, SI	65 06 08	February-09	1 & 3 series	RAD2: The Audio Volume is Briefly Muted or Reduced (4/08)
Audio, Navigation, Monitors, Alarms, SI	65 07 08	April-08	3 series	USB Device Is Not Detected
Audio, Navigation, Monitors, Alarms, SI	65 08 08	May-08	3 series	Fault Code "E190" stored in the RAD2_GW
Audio, Navigation, Monitors, Alarms, SI	65 09 08	March-09	X6/X5 (E70)	Anti-theft Alarm System Triggers a False Alarm rpl 11/08)
Audio, Navigation, Monitors, Alarms, SI	65 10 08	May-08	1 & 3 Series	RAD2: Intermittently No Audio after Check Control Message
Audio, Navigation, Monitors, Alarms, SI	65 11 08	May-08	All w/6FL	iPod Classic is Discharged after an Extended Period of Inactivity
Audio, Navigation, Monitors, Alarms, SI	65 12 08	June-08	E60	SRS Warning Lamp Illuminated, but No Fault Codes Stored
Audio, Navigation, Monitors, Alarms, SI	65 14 08	October-08	X5 (E70)	Controller Scrolling Function Not Responsive
Audio, Navigation, Monitors, Alarms, SI	65 15 08	June-09	1 Series	Volume of Warning Gong too Quiet (9/08)
Audio, Navigation, Monitors, Alarms, SI	65 16 08	September-08	E83 (X3)	Airbag Warning Lamp Illuminated, FC A1
Audio, Navigation, Monitors, Alarms, SI	65 17 08	December-08	E60/63	CD Changer Is Inoperative; Magazine Is Jammed
Audio, Navigation, Monitors, Alarms, SI	65 18 08	September-08	MY09 1 & 3 series	TeileClearing for Car Information Computer (CIC)
Audio, Navigation, Monitors, Alarms.	65 19 08	July-09	E60/E90/E83 (X3)	Recall Campaign 08V-384: Modify Seat Occupancy Detection Mat (6/09)
Audio, Navigation, Monitors, Alarms, SI	65 20 08	November-08	1 & 3 Series	Interference Noises and/or Reception Varies in Certain Areas
Audio, Navigation, Monitors, Alarms, SI	65 21 08	November-08	E93	Airbag Warning Illuminated, FC 9402
Audio, Navigation, Monitors, Alarms, SI	65 22 08	November-08	1 series	Loss of Navigation GPS Position
Audio, Navigation, Monitors, Alarms, SI	65 24 08	December-08	M3/M5	Audio System Is Intermittently Inoperative
Audio, Navigation, Monitors, Alarms, SI	65 27 08	February-09	1,3,5,6 ser X5,X6	Entertainment and Communication Systems are Inoperative
Audio, Navigation, Monitors, Alarms, SI	65 01 09	January-09	1,3,6 ser	Incorrect Message in the USB Audio Interface Diagnosis
Audio, Navigation, Monitors, Alarms, SI	65 02 09	January-09	1 Series	Audio Interference Noises in All Modes When Vehicle Is in Motion
Audio, Navigation, Monitors, Alarms, SI	65 03 09	March-09	7 Series (F01)	Side View Camera Has Blurred Image
Audio, Navigation, Monitors, Alarms, SI	65 05 09	July-09	All w/CIC	Navigation System Road Map (rpl 3/09)
Audio, Navigation, Monitors, Alarms, SI	65 06 09	February-09	5, X5, X6 LSI	CID Is Blank, No Audio, CHAMP Resets and Is Then Inoperative
Audio, Navigation, Monitors, Alarms.	65 08 09	November-09	X5, X6	Ultrasonic Passenger Compartment Motion Detector Triggers False Alarm (rpl 3/09)
Audio, Navigation, Monitors, Alarms.	65 10 09	September-09	1,3,7 series	Vehicle Position Is Missing or Incorrect on the Navigation Map (rpl 5/09)
Audio, Navigation, Monitors, Alarms, SI	65 11 09	May-09	1,3,7 series	Satellite Radio: Channel List May Be Empty or Channels Are Missing
Audio, Navigation, Monitors, Alarms.	65 12 09	September-09	1, 3 series	RAD2: Audio Is Intermittently Inoperative (rpl 6/09)
Audio, Navigation, Monitors, Alarms, SI	65 13 09	March-09	X5, X6	Incorrect Test Plan for CID FC A48B Power Supply
Audio, Navigation, Monitors, Alarms, SI	65 14 09	April-09	3 series	Active Head Restraint Cannot Be Locked Back into Position
Audio, Navigation, Monitors, Alarms, SI	65 15 09	June-09	X5, X6	DWA Siren Too Quiet When Locking and Unlocking (rpl 4/09)
Audio, Navigation, Monitors, Alarms.	65 16 09	September-09	1, 3 series	RAD2: Audio and/or Radio Display Is Intermittently Inoperative (rpl 6/09)
Audio, Navigation, Monitors, Alarms, SI	65 18 09	May-09	E60/61	Service Action: HD® Radio Activation
Audio, Navigation, Monitors, Alarms, SI	65 19 09	June-09	E65/66	ISTA/P Prompts to Replace CDC
Audio, Navigation, Monitors, Alarms, SI	65 20 09	June-09	X5	Airbag Warning Lamp Illuminated, FC 93C6
Audio, Navigation, Monitors, Alarms, SI	65 21 09	June-09	All w/CIC	Artist and Song Title are Not Displayed
Audio, Navigation, Monitors, Alarms, SI	65 23 09	July-09	1, 3 series	RAD2: Audio Volume Fluctuates
Audio, Navigation, Monitors, Alarms.	65 24 09	September-09	1 series	Recall Campaign 09V-257: Repair Airbag Harness
Audio, Navigation, Monitors, Alarms.	65 26 09	September-09	All w/6FL	iPhone Doesn't Charge When Connected To The USB Audio Interface
Audio, Navigation, Monitors, Alarms.	65 28 09	September-09	E83 (X3)	Not Possible to Delete Faults in the MRS5K Using Quick Delete
Audio, Navigation, Monitors, Alarms.	65 29 09	October-09	1, 3, X, F01, F07	Satellite Radio: Favorite Cannot Be Stored in Certain Cases
Audio, Navigation, Monitors, Alarms.	65 30 09	October-09	All since 9/1/9	Navigation System is Inoperative
Audio, Navigation, Monitors, Alarms.	65 32 09	November-09	All	Interference Noise from the Loudspeakers
Audio, Navigation, Monitors, Alarms.	65 33 09	October-09	F01, F07	Satellite Radio Cannot Be Operated via the Rear Entertainment System
Audio, Navigation, Monitors, Alarms.	65 36 09	November-09	1, 3 series X5/X6	Airbag Warning Lamp Illuminated, FC 93D2
Audio, Navigation, Monitors, Alarms.	65 37 09	November-09	1, 3 series, Z4	RAD2+: Intermittently, "acquiring" Is Displayed in SDARS Mode
Audio, Navigation, Monitors, Alarms.	65 39 09	December-09	7 (F01/02), 5GT(F07)	No Audio Output in All Modes

01, 11, 14, 20 other model, 05, 09, 10, 12, 13, 29, 38, 40 NU,

Distance Systems, Cruise Control, Rerr	- 01 other model		E65	
Distance Systems, Cruise Control, Rerr	66 01 04	March-08	X3	315MHz Remote Control Range Is Inadequate or Inoperative
Distance Systems, Cruise Control, Rerr	66 03 05	November-05	E60/E63	PDC and Gong Volume Cannot be Adjusted
Distance Systems, Cruise Control, Rerr	66 01 06	February-06	E90	PDC Button not Installed (Supersedes Feb 06 with added info)
Distance Systems, Cruise Control, Rerr	66 04 06	March-07	E60/E63	Night Vision Malfunctions and Parts Replacement (update to 11/06)
Distance Systems, Cruise Control, Rerr	66 05 06	September-06	E61	Vehicle Does Not Start
Distance Systems, Cruise Control, Rerr	66 07 06	December-06	All	Remote Control Key Not Working
Distance Systems, Cruise Control, Rerr	66 02 07	March-07	All	Comfort Access: Replacement ID Transmitter Initialization
Distance Systems, Cruise Control, Rerr	66 04 07	September-07	E60/E63	Unexpected Lane Departure Warning
Distance Systems, Cruise Control, Rerr	66 06 07	October-07	ALL	Universal Garage Door Opener Cannot be Programmed
Distance Systems, Cruise Control, Rerr	66 01 08	February-08	E91	PDC Gong volume low
Distance Systems, Cruise Control, Rerr	02 for e65			
Distance Systems, Cruise Control, Rerr	66 03 08	March-08	X5 (E70)	Seal Must Be Replaced when Rear View Camera Is Removed
Distance Systems, Cruise Control, Rerr	66 05 08	May-08	1 Series	PDC and Warning Gong Volume too Low
Distance Systems, Cruise Control, Rerr	66 06 08	October-08	E61	Remote Control Malfunction or Radio Reception Problem
Distance Systems, Cruise Control, Rerr	66 07 08	January-09	E63/E64 M6	PDC Malfunction
Distance Systems, Cruise Control, Rerr	66 01 09	March-09	3 Series	PDC Ultrasonic Sensor(s) Become Discolored
Distance Systems, Cruise Control, Rerr	66 02 09	April-09	F01/02	Windows or Sunroof Do Not Open with Remote Control
Distance Systems, Cruise Control, Rerr	66 04 09	April-09	F01/02	Night Vision: Pedestrian Recognition Is Intermittently Inoperative
Distance Systems, Cruise Control, Rerr	66 05 09	April-09	F01/02	Night Vision System Is Intermittently Inoperative
Distance Systems, Cruise Control, R	66 06 09	August-09	F01/02	Side View Camera Has Blurred Image (rpl 4/09)
Distance Systems, Cruise Control, Rerr	66 07 09	April-09	F01/02	Erroneous Fault Code Entries in the TRSVC Module
Distance Systems, Cruise Control, R	66 09 09	September-09	X5 (E70)	Failure of Remote Control Locking (rpl 6/09)

03, 06 for other model 02 other model

Vehicle Tools	71 01 07	September-07	W/Sunroof	Sunroof Emergency Operation Tool Eliminated
Vehicle Tools	71 01 08	March-08	3/5/6/Z series	Combination Wrench Eliminated from the Vehicle Tool Kit
Safety Restraint Systems	72 05 04	June-04	E60/E63	Various "Self-Test" Faults Stored in "Byteflight" Modules
Safety Restraint Systems	72 02 05	August-06	E60/E65/E90	Passenger Airbag Status Lamp Goes ON/OFF During Driving (Replaces 1/06)
Safety Restraint Systems	72 03 05	June-05	E64 (Cabrio)	Check Control Message "Rollover Protection Fault"
Safety Restraint Systems	72 09 05	November-05	E64 (Cabrio)	Service Action: Reprogram Control Modules for Backrest Lock Microswitch
Safety Restraint Systems	72 02 06	June-06	ALL	Airbag Warning Lamp for OC3 Seat Mat Fault (Supersedes Mar 06 w/new parts info)
Safety Restraint Systems	72 03 06	January-06	E64 (Cabrio)	Airbag Warning Lamp Illuminated for Backrest Microswitch
Safety Restraint Systems	72 04 06	January-06	E90	Rear Belt Tensioners Deploy in Accident
Safety Restraint Systems	72 05 06	February-06	E60	Airbag Warning Illuminated, FC 9B2D in SFZ
Safety Restraint Systems	72 08 06	April-06	E90	OC3 Occupancy Status does not Change

Category	SIBs (SI B## ## ##)	Date	Application	Title
Safety Restraint Systems	72 09 06	August-06	E90	Airbag Warning Lamp, FC93EB (Update to Apr -06)
Safety Restraint Systems	72 10 06	November-06	E90	Airbag Warning Lamp Illuminates - No Fault Codes (Replaces Apr 06)
Safety Restraint Systems	72 18 06	October-06	E60	Various Telegram Errors in Satellites
Safety Restraint Systems	72 19 06	October-06	E63	Various Fault Memory Entries in the SBE
Safety Restraint Systems	72 20 06	October-06	E60	SBSL/SBSR FC 9845/98C5, implausible crash severity
Safety Restraint Systems	72 24 06	October-06	E60	Rear Side Airbags Come Activated
Safety Restraint Systems	72 25 06	October-06	E60	FC 96CA: Passenger Thorax Airbag Resistance too Great
Safety Restraint Systems	72 26 06	October-06	E60	SGM FC 9413 "Signal Lamp Airbag Deactivation"
Safety Restraint Systems	72 28 06	December-06	E92	Seatbelt Assistant "hand" Portion Breaks Off
Safety Restraint Systems	72 29 06	December-06	E60/E63/E65	DIS Test Plan Error While Performing SIM/SGM Self Test
Safety Restraint Systems	72 01 07	January-07	E90/E91	Airbag Warning Lamp Illuminated, FC 93C1/93C3
Safety Restraint Systems	72 03 07	August-07	E92	Seat Belt Assistant Pinch Protection (updates 3/07)
Safety Restraint Systems	72 04 07	May-07	E63/64	Recall Campaign 07V-178: Replace the Seat Occupancy Detection Mat
Safety Restraint Systems	72 05 07	April-07	E92	Seat Belt Assistant Malfunction
Safety Restraint Systems	72 01 08	May-08	E92	Passenger Seat Belt Assistant Extends Unexpectedly
Safety Restraint Systems	72 01 09	March-09	F01/02	Front Seat Belt Electric Motor Driven Reel Activates Unexpectedly
Safety Restraint Systems	72 02 09	Z4	E89	Service Action: Belt Tensioner Harnesses
	-07 other model			
Communication Systems	84 14 01	November-06	E60/E63	Telephone Installation on New Vehicles Replaces Mar 05)
Communication Systems	84 01 03	December-06	E60/E63	CPT9000 Telephone (Supercedes Aug 05 w/new info)
Communication Systems	B840103E60Telephone	P/O 84 01 03	E60/E63	E60/E63 TCU Wiring Diagram
Communication Systems	84 15 03	March-08	E60/E63	BMW Assist Initialization (now using GSM Rpl 11/06)
Communication Systems	B841503Diagnosis	P/O 85 15 03	E60/E63	Troubleshooting Guide (Flowchart)
Communication Systems	84 214 04	September-05	E60/E63	Linked Sequence calls Fail on Bluetooth (REPLACED BY 84 18 05)
Communication Systems	84 02 04	May-05	E60/E63	Navigation Map DVD for Vehicles with CCC
Communication Systems	84 03 04	July-04	E60	MFL Button Dials "911", or Last Number Dialed
Communication Systems	84 10 04	July-04	E60	CCC Navigation Retrofit Kit
Communication Systems	B841004Installer	P/O 84 10 04	E60	Installation Instructions
Communication Systems	B841004SalesBulletin	P/O 84 10 04	E60	Product Planning MY 04 5 Series
Communication Systems	84 12 04	September-07	E60/E63	Diagnosis and Repair of the CCC (updates 2/06)
Communication Systems	84 12 04 Attachment	September-07	E60/E63	DVD Screws attachment
Communication Systems	84 13 04	November-07	E60/E63	BMW Assist with Integrated Bluetooth (Rpl Mar 07)
Communication Systems	B841304BluetoothDiagnosis	P/O 84 13 04	E60/E63	Diagnostic Instructions for Bluetooth Telephone Systems
Communication Systems	B841304BluetoothUserManualBus.	P/O 84 13 04	E60/E63	Bluetooth Users Manual for Business Phone
Communication Systems	B841304BluetoothUserManualE60E63	P/O 84 13 04	E60/E63	Bluetooth Users Manual for CPT9000 and Bluetooth
Communication Systems	84 14 04	October-04	E60/E63	Service Action: Activate SVS (Voice Recognition System)
Communication Systems	B841404Q&A	P/O 84 14 04	E60/E63	FAQ
Communication Systems	84 01 05	July-05	E60/E63	Service Action: Reactivate TCUs for specified Production models that were accidentally deactivated
Communication Systems	84 04 05	January-07	E60/E63	Nav system missing or incorrect data (Replaces April 05)
Communication Systems	84 07 05	June-05	E60/E63	Motorola v710 Handset Phonebook does not download
Communication Systems	84 08 05	April-07	E60 /E90	CID switches between BMW banner and blank screen (Rpl 3/06 - adds E90 & new procedure)
Communication Systems	84 09 05	June-05	E60/E63	CCC NAV places of interest (POIs)
Communication Systems	B800905POICategories	P/O 84 09 05	E60/E63	PDF of categories and sub categories
Communication Systems	B800905POL_ICONS	P/O 84 09 05	E60/E63	PDF of ICON symbols
Communication Systems	84 10 05	May-06	E60/E63/E90	Nav Displays incorrect Vehicle Position (Supercedes Mar 06) - Replaced with 65 23 07
Communication Systems	84 11 05	June-05	E60/E63	CCC CD/DVD disc does not eject
Communication Systems	84 12 05	April-06	E60/E63	DVD Drive makes clicking noise (Supercedes Aug 05 w/E90)
Communication Systems	84 13 05	May-07	E60/E63/E90	Bluetooth Phone call may still be displayed as active after the call has ended (Rpl 3/07 - adds E90)
Communication Systems	84 14 05	August-08	All	Retrofitting a Telematics Control Unit (TCU) with Bluetooth® Technology (update to 9/07)
Communication Systems	84 14 05 Attachment	September-07	All	Special Inst for E6x
Communication Systems	84 18 05	September-05	E60/E63	Linked Sequence calls Fail on Bluetooth and CPT9000 Handsets
Communication Systems	84 19 05	September-05	E90	Teleservice does not place call for CBS due
Communication Systems	84 24 05	August-06	E60/E63/E90	CCC Voice Input System Incorrectly States Speed Limit in "km" (Supercedes Nov 05)
Communication Systems	84 25 05	January-06	E90	Software error in the Telematics Control Unit (TCU). (Supercedes Dec 05)
Communication Systems	84 02 06	January-06	All	Hands free Bluetooth® Phone Call May be Lost if a Call Waiting Call is Received
Communication Systems	84 03 06	March-07	All	Enhanced Support for CCC Car Communication Computer (Supercedes Dec 06)
Communication Systems	84 04 06	July-06	All	Service Action: Reactivation of Telematics Control Unit (TCU) (Replace Mar 06)
Communication Systems	84 05 06	March-07	All	Diagnosis of Bluetooth® Handset Related Complaints (Rpl Mar 06)
Communication Systems	84 06 06	March-06	All	Information Displayed in the BMW Assist Menu is Incorrect or Unknown
Communication Systems	84 08 06	March-06	All	CCC Navigation is Inoperative at Low Ambient Temperatures
Communication Systems	84 09 06	October-07	All	Bluetooth® Inoperative, TCU FC# A379 or 79 (update to 04/07)
Communication Systems	84 10 06	August-07	E60/E63/E90	BMW Assist or Bluetooth® Inoperative, TCU FC# A379 (rpl 4/06)
Communication Systems	84 14 06	May-07	E60/E63/E90	Service Action: Reactivation of Telematics Control Unit (TCU) - (superceded Dec 06)
Communication Systems	84 15 06	May-06	E60/E63/E90	CCC Navigation Address Book Shows Duplicate Entries after Programming
Communication Systems	84 18 06	June-06	E60/E63/E90	Low Bluetooth Signal is Displayed in the Handset or the Bluetooth® Connection is Lost
Communication Systems	84 20 06	September-06	E60/E63/E90	CCC Navigation Stuck on "Accept" Screen(Supercedes Jun 06)
Communication Systems	84 23 06	May-07	E60/E63/E90	Service Action: Telematics Control Unit (TCU) – MOST-Bus Vehicles Supercedes Dec 06)
Communication Systems	84 25 06	January-09	E60/E63/E90/E65	NAD Check, Recovery or Deactivation Procedure (MOST-Bus vehicles) (rpl 6/08)
Communication Systems	84 26 06	July-08	E60/E63/E90/E65	Cannot Enable BMW Assist Services (Supercedes Aug 06)
Communication Systems	84 27 06	July-08	E60/E63/E90/E65	BMW Assist Inactive Warning Message Displayed (Supercedes Aug 06)
Communication Systems	84 48 06	October-06	E60/E63	CPT9000 (V60s) Telephone Switches to Silent Mode when Connected to Vehicle
Communication Systems	84 49 06	October-07	E60/E63	Vehicle Dials BMW Assist on its Own (update to 10/06)
Communication Systems	84 50 06	October-06	E60/E63	CPT9000 Handset Phone does not Load into Vehicles
Communication Systems	84 51 06	October-06	E60/E63	The BMW Assist "Embedded" Phone Rings Erroneously in the Vehicle
Communication Systems	84 58 06	November-06	E60/E63/E90/E92	Real Time Traffic Information w/PDF attachment (Updated in Nov 06)
Communication Systems	84 59 06	June-09	3 Series	CCC Telephone Address Book Not in Alphabetical Order (rpl 10/06)
Communication Systems	84 61 06	March-07	E60/E63/E90/E92	CCC Navigation System Pop-up Arrow Display Missing During Route Guidance (rpl 10/06)
Communication Systems	84 62 06	July-08	E60/E63/E90/E92	Program Displays 'The TEL Control Module is Malfunctioning' on the Final Report
Communication Systems	84 01 07	January-07	E60/E63/E90/E92	CCC SVS: Letter and Number Inputs by Voice are Misinterpreted
Communication Systems	84 02 07	March-07	E60/E63/E90/E92	Service Action: Activation of Telematics Control Unit (TCU)
Communication Systems	84 04 07	March-07	E60/E63/E90/E92	Bluetooth® Handsets No Longer Pairs to the Vehicle
Communication Systems	84 05 07	August-07	E60/E63/E70/E90/E92	Checking NAD Signal Strength for BMW Assist
Communication Systems	84 06 07	March-07	E90	Call Cannot be Answered if the Voice Recognition System (SVS) is Active
Communication Systems	84 07 07	July-08	E60/E63/E90	NAD was Found to be Faulty when Performing SI B84 22 05 (Reactivation of BMW Assist Services)
Communication Systems	84 08 07	June-09	E60/E63/X5/Z4	Service Action: Activation of Telematics Control Unit (TCU) (rpl 8/07)
Communication Systems	84 09 07	July-07	E60/E63/E90	Echo on Landline Side of Phone Call
Communication Systems	84 11 07	April-08	E60/E90	Service Action: Replace the Hands-Free Charging Electronics (MULF2-High) rpl 7/07
Communication Systems	84 12 07	July-07	E60/E63/E90/E92	Voice Only Call, No Data Transmitted When Placing a BMW Assist Call
Communication Systems	84 13 07	July-07	E60/E63/E90/E92	BMW Assist Location (GPS) Unknown or Inaccurate, When Placing a BMW Assist Call
Communication Systems	84 16 07	September-07	E60/E63/E90/E92	Erroneous SOS Inactive Warning Message (rpl 7/07)
Communication Systems	84 17 07	July-08	E60/E63/E90/E92	SOS Inactive Warning Message, No Communication with TCU (rpl 09/07)
Communication Systems	84 18 07	June-09	E60/E63/E90/E92	Enable Services Status Bar Does NOT Progress (rpl 8/07)
Communication Systems	84 19 07	October-07	E60/E63/E90/E92	One Way Audio when Using a Bluetooth Enabled Handset
Communication Systems	84 20 07	October-08	All w/TCU	Upgrading BMW Assist to Support New Bluetooth Handsets (rpl 11/07)
Communication Systems	84 21 07	November-07	All w/TCU	Diagnosis When an Unapproved Handset is Paired to a Vehicle
Communication Systems	84 01 08	June-08	3/5/6/7/X series	Pairing between the iPhone and the Vehicle Fails
Communication Systems	84 02 08	March-08	All w/TCU	Service Action: Initialize BMW Assist Services (SC VPC on 3/3/08)
Communication Systems	84 03 08	November-08	X3	Echo and Poor Voice Quality on the Landline Side of a Call (rpl 05/08)
Communication Systems	84 04 08	June-08	E60	Service Action: Update BMW Assist Services
Communication Systems	84 05 08	September-08	E60/E90/E83	Service Action: Reactivation of Telematics Control Unit (TCU)
Communication Systems	84 06 08	September-08	3 Series	CIC: Unable to Select an Address via the Contact Book
Communication Systems	84 07 08	September-08	1/3/5/6 series	Echo and Reverberation on the Landline during a Hands-free Call
Communication Systems	84 08 08	September-08	1/3/5/6/X series	BMW Assist Menu Item
Communication Systems	84 09 08	October-08	1/3 series	Service Due CC Message Appears Before Handover Inspection
Communication Systems	84 11 08	January-09	All	BMW Assist Inoperative in Certain Areas (rpl 10/08)

Category	SIBs (SI B## ## ##)	Date	Application	Title
Communication Systems	84 12 08	June-09	All	TCU Symptom Diagnosis (rpl 11/08)
Communication Systems	84 13 08	December-08	Z4	Poor Voice Quality on the Receiving End When Placing a Telephone Call
Communication Systems	84 02 09	February-09	All	Telephone - Incomplete Contact List Available in Vehicle
Communication Systems	84 03 09	February-09	All	Telephone Contacts Cannot Be Deleted from the CIC
Communication Systems	84 04 09	June-09	All	The Landside Person Finds the Caller Speaking from an iPhone 3G Hard to Understand (rpl 3/9)
Communication Systems	84 06 09	May-09	All	Telephone: Humming or Pulsing Noise Coming from the Vehicle Loudspeakers
Communication Systems	84 08 09	May-09	1, 3, 5, 6, 7 series	Telephone: Poor Voice Quality at Landside End
Communication Systems	84 09 09	June-09	1, 3, 5, 6, 7, X5/6	BMW Assist Services - Vehicle Position Incorrect
Communication Systems	84 10 09	June-09	All	BMW Assist " MyInfo " Troubleshooting Tips
Communication Systems	84 11 09	August-09	All w/NAV	BMW Assist "BMW Search" Troubleshooting Tips
Communication Systems	84 12 09	November-09	All	BMW Assist System Capabilities and Services by Model Year

01, 03, 10, other models or minor

Rev 22 published

NOTE: Text in Maroon represents new data or updated since previous edition (SIB_List_rev_21, published 18 August 2009)

Red = Safety recall notice

Bold = Service Action or Recall campaigns

Another Service Bulletin resource --> Checkout periodically to see if they keep current

This link seems to have been closed to non-subscribers sometime in January 2007

Most Recent

No Longer available free: <http://www.alldata.com/tsb/BMW/index-post.html>
<http://www.alldata.com/tsb/BMW/index-issue.html>