

oo	Module	Function value	2007	Description
a	2RAD	STANDHEIZUNG	X	Enables the parked car ventilation option, just set to aktiv. Tested on non-idrive professional HU. Gives you 2 programmable timers to set when you would like the cabin fan to switch on.
	ABG	SBR_FAHRER_1	X	Disables seat belt chime for driver side
Seat Belt Chime	ABG	SBR_BEIFAHRER_1	X	Disables seat belt chime for passenger side
Key Fob Ejected from Socket upon Engine Stop	CAS	KOMFORT_EJECT	X	When turning the engine off key fob will be ejected from socket. (Need to hold start/stop for extra 2 seconds) -- Does this prevent the door from chiming if you leave the key in the slot?
Unlock Doors	CAS	ER_KEYOUT_AUTOVR	X	Unlocks all doors when you remove key (2009: Only unlocks driver door if FOB set to unlock driver door only. Set FOB to unlock all doors, and this will unlock all doors, too) (also works with Comfort Access when engine is shut off, might need KOMFORT_EJECT activated) **Automatic door lock when you drive off must be enabled and must be the reason the doors locked for this feature to work, i.e. if you press the Central Lock button before the drive-off lock kicks in, the doors will not auto-unlock.
Close Windows/Roof with Fob	CAS	KOMFORTSCHLIESSUNG_FB	X	Closes windows + moon roof through Key Fob
Panic Mode	CAS	SONDERTASTE_PANIKALARM	X	Enables panic alarm. Must have alarm installed. Hold trunk botton on FOB for 5 secs to activate. Change from "nicht_aktiv" to "panikalarm"
Disable Auto Dim Mirrors	CAS	SPIEGEL_ELEKTROCHROM	X	Switch to nicht_aktiv
Alarm beep on lock	DWAI	QUIT_AKUST_SCHAERF	X	Alarm beep on lock (one beep) (must have alarm installed)
Disable windows safety feature	FRM (NFRM)	TUERAUF_STOP_MAUT	X	Opening doors will not interrupt window roll up operation. Normally, if you open a door while the window is automatically rolling up, it will stop the operation. This feature disables it.
Side Marker Delete	FRM (NFRM)	SIDEMARKER_US (see Note)	X	Disables side marker/signal light when headlights are on. Change the value to "nicht_aktiv". Module value might be longer than SIDEMARKER_US. Here are some examples: SIDEMARKER_US_NFRM, SIDEMARKER_US_NF, or SIDEMARKER_US_MIT_FRA_V. On some cars disabling this one value is enough to turn off everything and making the changes below will also disable your angel eyes, so check after making this one change and only continue if you find your side markers are still on.
mirrors w/ FOB	FRM (NFRM)	SPIEGEL_KOMFORT_EINKLAPP	X	Fold side mirrors with FOB (CA also works 2009/01 E92). Mirrors folded with the button inside the car cannot be unfolded via the FOB.
Bulb Testing Warning	FRM (NFRM)	KALTUEBERWACHUNG_BLK_HI	X	Cold testing bulbs in turn signal rear - change setting to nicht_aktiv
Bulb Testing Warning	FRM (NFRM)	KALTUEBERWACHUNG_BLK_VO	X	Cold testing bulbs in turn signal - change setting to nicht_aktiv
Bulb Testing Warning	FRM (NFRM)	KALTUEBERWACHUNG_NSW	X	Cold testing bulbs in number plate - change setting to Nnicht_aktiv
Bulb Testing Warning	FRM (NFRM)		X	Cold testing bulbs in foglights - change setting to nicht_aktiv
Bulb Testing Warning	FRM (NFRM)	KALTUEBERWACHUNG_RL	X	Cold testing bulbs in reversing light - change setting to nicht_aktiv
Bulb Testing Warning	FRM (NFRM)	WARMUEBERWACHUNG_KZL_LI	X	Warm testing bulbs in number plate light bulb - change setting to nicht_aktiv (For my 2006, it was just WARMUEBERWACHUNG_KZL)
Corner Delete Mod	FRM (NFRM)		X	Disables side marker/signal light when headlights are on. Module value might be longer than SIDEMARKER_US. Here are some examples: SIDEMARKER_US_NFRM or it could be SIDEMARKER_US_NF. Change to nicht_aktiv.
DRL_TFL_MIT	FRM (NFRM)	DRL_V_GEDIMMT	X	Disables the Daytime Running Lights (DRL) on Canadian models. This is sub-module FRM, my car did not have an NFRM sub-module.
Right Parking lamp malfunction error message	FRM (NFRM)	FEHLERMELDUNG_CC_SL_V_R	X	remove the warning from your BMW idrive when you install HID's or angel eyes
Auto Dimming Mirrors	FRM (NFRM)	SPIEGEL_ELEKTROCHROM	X	nicht_aktiv to turn off autodim mirror or aktiv to enable mirror
Bulb Testing Warning	FRM (NFRM)	KALTUEBERWACHUNG_BLK_HI	X	Cold testing bulbs in turn signal rear - change setting to nicht_aktiv
Bulb Testing Warning	FRM (NFRM)	KALTUEBERWACHUNG_BLK_VO	X	Cold testing bulbs in turn signal - change setting to nicht_aktiv
Bulb Testing Warning	FRM (NFRM)	KALTUEBERWACHUNG_KZL	X	Cold testing bulbs in number plate - change setting to Nnicht_aktiv
Bulb Testing Warning	FRM (NFRM)	KALTUEBERWACHUNG_NSW	X	Cold testing bulbs in foglights - change setting to nicht_aktiv
Bulb Testing Warning	FRM (NFRM)	KALTUEBERWACHUNG_RL	X	Cold testing bulbs in reversing light - change setting to nicht_aktiv
Bulb Testing Warning	FRM (NFRM)	WARMUEBERWACHUNG_BLK_HI	X	Warm testing bulbs in rear turn signals - change setting to nicht_aktiv
Bulb Testing Warning	FRM (NFRM)	WARMUEBERWACHUNG_KZL_LI	X	Warm testing bulbs in number plate light bulb - change setting to nicht_aktiv (For my 2006, it was just WARMUEBERWACHUNG_KZL)
Right Parking lamp malfunction error message	FRM (NFRM)	FEHLERMELDUNG_CC_SL_V_R	X	remove the warning from your BMW idrive when you install HID's or angel eyes
Corner Activate on French E87	FRM (NFRM)	PWM_FRA_V_FKT_SIDEMARKER and SIDEMARKER_US_MIT_FRA_V	X	You must set PWM_FRA_V_FKT_SIDEMARKER to wert_02 and SIDEMARKER_US_MIT_FRA_V to aktiv.
Climate don't turn ON in Auto mode	IHK	KLIMA_MIT_AUTO_0	X	Set to nicht_aktiv. A/C will not automatically turn on when Auto is pressed.
Climate don't turn ON in Auto mode	IHK	KLIMA_MIT_AUTO_1	X	Set to nicht_aktiv. A/C will not automatically turn on when Auto is pressed.
Climate don't turn ON in Auto mode	IHK	KLIMA_MIT_AUTO_10/15	X	Set to nicht_aktiv. A/C will not automatically turn on when Auto is pressed.
Climate don't turn ON in Auto mode	IHK	KLIMA_MIT_AUTO_2	X	Set to nicht_aktiv. A/C will not automatically turn on when Auto is pressed.
Climate don't turn ON in Auto mode	IHK	KLIMA_MIT_AUTO_0	X	Set to nicht_aktiv. A/C will not automatically turn on when Auto is pressed.
Climate don't turn ON in Auto mode	IHK	KLIMA_MIT_AUTO_1	X	Set to nicht_aktiv. A/C will not automatically turn on when Auto is pressed.
Climate don't turn ON in Auto mode	IHK	KLIMA_MIT_AUTO_10/15	X	Set to nicht_aktiv. A/C will not automatically turn on when Auto is pressed.
Climate don't turn ON in Auto mode	IHK	KLIMA_MIT_AUTO_2	X	Set to nicht_aktiv. A/C will not automatically turn on when Auto is pressed.
Wiper wipes to End position after turning engine off	JBBF (2JBBF)	ZYCLUS_VOLLEND_KLR_AUS	X	When Wiper is Wiping, and you turn engine off, it will now keep on going until it returns to the home (bottom) position.
Auto Headlight Sensitivity adjustment from BC Button	KOMBI	LICHT_AUT_WERT_1, LICHT_AUT_WERT_2, LICHT_AUT_WERT_3	X	Set all 3 to aktiv, change the sensitivity of your automatic light sensor in your Dash! Only works if you do NOT have iDrive. If you have CCC iDrive, see the option higher up in the spreadsheet. If you have CIC iDrive, there is not yet a known way to do this.
Digital Speed	KOMBI	BC_DIGITAL_V	X	Displays digital speed in cluster (2011: DOES NOT Resets ECU and service counter/dates. Only reset trip odometer, MPG, and time, I did it many times on my 2011)
Door Dong	KOMBI	CC_ZUENDSCHLUESSEL	X	Disables dong when driver's door is open and key is in slot. May reset ECU and service counter/dates.
Instant MPG	KOMBI	DIGITAL_KVA	X	Displays digital instant-read MPG in cluster
Display cruise control set speed	KOMBI	TEMPOMAT_SETZ_ANZ_DAUER	X	Change the value from wert_01 to wert_02 On vehicles that do not briefly indicate the speed the cruise control is set at, changing this value will enable the display.
Driver seat memory options in cluster	KOMBI	SITZ_AUT_VERST_AUS, SITZ_AUT_VERST_ENT and SITZ_AUT_VERST_ENT_T	X	Enable driver seat memory options in cluster when retrofitting powered seats (3 parameters must be aktiv) + VO \$459 added to CAS and FRM
Display cruise control set speed	KOMBI	TEMPOMAT_SETZ_ANZ_DAUER	X	Change the value from wert_1 to wert_2 On vehicles that do not briefly indicate the speed the cruise control is set at, changing this value will enable the display.
Enable SMS management from Professional Radio	RAD2	SMS_RAD2	X	Enable SMS management from RAD2. Change nicht_aktiv to aktiv. Note: RAD2 prod date 2010, MULF2 High Basis SVS prod. date 2009, installed on e91 2006.
Rain Close from full open	SHD (FZD)	REGENSCHLIESSEN	X	Auto wipers have be on for this to work. Once it closes, you wont be able to re-open sunroof until car power down for about 10 minutes. spaz (CasperSYTFU Verified 07 E92)
Rain Close Sunroof from Tilt	SHD (FZD)	REGENSCHLIESSENTILT	X	(CasperSYTFU Verified 07 E92)
				This is for those installing OEM xenons without the self leveling feature. Add \$522 to VO (telling the car your adding xenon headlights). Disable self leveling for xenon headlights by saying nicht_aktiv to line AUTO_LWR_ENABLE (in FRM). To enable inner halogen light as high beam (in FRM):
				PWM_ANST_FL_BIXENON wert_01 wert_01
Xenon retrofit	VO in FA string (see notes)	ASP_KOMFORT_EINKLAPP (or SPIEGEL_KOMFORT_EINKLAPP)	522 X	More details: http://www.e90post.com/forums/showpost.php?p=8982434&postcount=1666
Fold/unfold mirrors with fob			X	Folds side mirrors with FOB and CA. Requires that closing windows/moonroof with fob also be enabled (KOMFORTSCHLIESSUNG_FB).