



SI B01 02 12  
Warranties

May 2012  
Warranties

#### **SUBJECT**

**Turbocharger (Wastegate Only): Emissions Warranty Extension to 8 Years/82,000 Miles**

#### **MODEL**

2008, 2009, 2010 E60, E61 (535i) including xDrive with N54 engine

2008, 2009, 2010 E71 (X6 xDrive35i) with N54 engine

2008, 2009, 2010 E82, E88 (135i) with N54 engine

2009, 2010 E89 (Z4 sDrive35i) with N54 engine

2007, 2008, 2009, 2010 E90, E92, E93 (335i) including xDrive with N54 engine

#### **SITUATION**

A court-approved settlement provides the following relief to the Settlement Class Members' vehicles listed above.

#### **INFORMATION**

BMW NA has agreed to extend the emissions warranty to a total of 8 years or 82,000 miles, whichever comes first and starting from the eligible vehicle's original in-service date, for Settlement Class Members' vehicles that have a failure of a turbocharger which is caused by a defect of the turbocharger's wastegate.

#### **PARTS INFORMATION**

| <b>Part Number</b> | <b>Description</b> | <b>Quantity</b> |
|--------------------|--------------------|-----------------|
| Refer to ETK       | Turbocharger       | 1 or 2          |
|                    |                    | As applicable   |

#### **WARRANTY INFORMATION**

For the eligible vehicles listed above, the extended Emissions Warranty coverage of 8 years/82,000 miles specifically applies to the turbocharger's wastegate:

Pivot arm

Pivot arm and valve shaft

Pivot arm and valve shaft housing

Valve cover flap and valve seat

- The terms of the original New Vehicle/SAV Limited Warranty and applicable emissions warranty still apply.
- BMW NA's repair procedures, such as TeileClearing, must be followed.

- Please refer to the current version of ISTA/D for applicable test plans and repair instructions.
- BMW NA will not provide warranty coverage to any Settlement Class Member's vehicle containing modifications or alterations to the turbocharger or its wastegates (software, hardware or otherwise), or evidencing other conditions not normally covered under the original New Vehicle/SAV Limited Warranty or applicable emissions warranty.
- The applicable warranty coverage for all other parts **has not** changed.
- This emission warranty extension is applicable to eligible vehicles that are registered and operated in all 50 states and Puerto Rico.

The turbocharger wastegates' 8 year/82,000 miles warranty must be applied to eligible vehicles first, before applying any coverage that is provided under the BMW Certified Pre-Owned program or any BMW Group Vehicle Service Contract in effect on the vehicle.

**Note:** The labor operations listed below and corresponding FRU allowances will be available in a future release of the KSD2.

**Defect Code:** 11 65 91 15 00

**E60, E61, E82, E88, E89, E90, E92 and E93**

#### **Replacing Exhaust Turbocharger (Cylinders 1-3)**

|                         |                                                                                                          |
|-------------------------|----------------------------------------------------------------------------------------------------------|
| <b>Labor Operation:</b> | <b>Description:</b>                                                                                      |
| 00 60 141               | Replacing the exhaust turbocharger for cylinders 1-3 (Main Work)<br>(includes performing a Vehicle Test) |

| <b>Model</b> | <b>Labor Allowance</b> | <b>Model</b> | <b>Labor Allowance</b> |
|--------------|------------------------|--------------|------------------------|
| E89          | 80 FRUs                | E92          | 84 FRUs                |
| E82          | 82 FRUs                | E93          | 86 FRUs                |
| E88          | 83 FRUs                | E60 xDrive   | 100 FRUs               |
| E90 xDrive   | 96 FRUs                | E60          | 93 FRUs                |
| E90          | 84 FRUs                | E61 xDrive   | 99 FRUs                |
| E92 xDrive   | 96 FRUs                |              |                        |

or

|                         |                                                                                                          |
|-------------------------|----------------------------------------------------------------------------------------------------------|
| <b>Labor Operation:</b> | <b>Description:</b>                                                                                      |
| 00 60 869               | Replacing the exhaust turbocharger for cylinders 1-3 (Plus Work)<br>(includes performing a Vehicle Test) |

| <b>Model</b> | <b>Labor Allowance</b> | <b>Model</b> | <b>Labor Allowance</b> |
|--------------|------------------------|--------------|------------------------|
|--------------|------------------------|--------------|------------------------|