



Head bolt (notice that the head of the bolt is sheered off.)

The image shows a close-up of a mechanical assembly, likely an engine. A large, dark, circular component with a central hole and a torque specification of 25 Nm is visible. Above it, a bolt is shown with its head sheered off. An orange arrow points from the text label to the broken bolt head. Another orange arrow points from the text label to the filter housing, which is a dark, curved component on the right side of the image.

Filter housing