

1
2
3
☰
🏠
📄
🔧
?
📄
✖

## ISTA+

📄
⚙️
✉️
✖

VIN **0B91063**
Vehicle **X/E70/off-road vehicle/X5 xDrive35d/M57/AUTO/US/LL/2012/07**
KL 15: --
KL 30: --

DDE 00480A DDE: Particulate-filter system
📄
✖

Description
Details

**Fault code**  
480A

**Fault text**  
DDE: Particulate-filter system

**Fault types**  
Fault currently not present  
Particulate filter heavily clogged (exhaust backpressure high)  
Fault does not trigger a driver information at the moment.

Occurrence [km]: 161336 Occurrence time [s]:

**Environment conditions**

Condition	First fault memory entry
Frequency	1
Logistics counter	37
Mileage/km reading	161336 km
SAE diagnostic trouble code	--
Engine speed	2235 1/min
Coolant temperature	89 degC
Rail pressure	964.71 bar
Injection rate	37.65 mg/Hub
Charging pressure	1788.24 mbar
Battery voltage	14600 mV
Ambient pressure	804.71 mbar
Engine status	Engine in normal operation
Differential pressure on the diesel particulate filter	258 mbar
Regeneration status	02040002 hex

Back
Forward
Refresh
Close

